

§ 850.13

§ 850.13 Compliance.

(a) The responsible employer must conduct activities in compliance with its CBDPP.

(b) The responsible employer must achieve compliance with all elements of its CBDPP no later than January 7, 2002.

(c) With respect to a particular beryllium activity, the contractor in charge of the activity is responsible for complying with this part. If no contractor is responsible for a beryllium activity, DOE must ensure implementation of, and compliance with, this part.

Subpart C—Specific Program Requirements

§ 850.20 Baseline beryllium inventory.

(a) The responsible employer must develop a baseline inventory of the locations of beryllium operations and other locations of potential beryllium contamination, and identify the workers exposed or potentially exposed to beryllium at those locations.

(b) In conducting the baseline inventory, the responsible employer must:

(1) Review current and historical records;

(2) Interview workers;

(3) Document the characteristics and locations of beryllium at the facility; and

(4) Conduct air, surface, and bulk sampling.

(c) The responsible employer must ensure that:

(1) The baseline beryllium inventory is managed by a qualified individual (e.g., a certified industrial hygienist); and

(2) The individuals assigned to this task have sufficient knowledge and experience to perform such activities properly.

§ 850.21 Hazard assessment.

(a) If the baseline inventory establishes the presence of beryllium, the responsible employer must conduct a beryllium hazard assessment that includes an analysis of existing conditions, exposure data, medical surveillance trends, and the exposure potential of planned activities. The exposure determinants, characteristics and ex-

10 CFR Ch. III (1–1–10 Edition)

posure potential of activities must be prioritized so that the activities with the greatest risks of exposure are evaluated first.

(b) The responsible employer must ensure that:

(1) The hazard assessment is managed by a qualified individual (e.g., a certified industrial hygienist); and

(2) The individuals assigned to this task have sufficient knowledge and experience to perform such activities properly.

§ 850.22 Permissible exposure limit.

The responsible employer must assure that no worker is exposed to an airborne concentration of beryllium greater than the permissible exposure limit established in 29 CFR 1910.1000, as measured in the worker's breathing zone by personal monitoring, or a more stringent TWA PEL that may be promulgated by the Occupational Safety and Health Administration as a health standard.

§ 850.23 Action level.

(a) The responsible employer must include in its CBDPP an action level that is no greater than 0.2 µg/m³, calculated as an 8-hour TWA exposure, as measured in the worker's breathing zone by personal monitoring.

(b) If an airborne concentration of beryllium is at or above the action level, the responsible employer must implement §§ 850.24(c) (periodic monitoring), 850.25 (exposure reduction and minimization), 850.26 (regulated areas), 850.27 (hygiene facilities and practices), 850.28 (respiratory protection), 850.29 (protective clothing and equipment), and 850.38 (warning signs) of this part.

§ 850.24 Exposure monitoring.

(a) *General.* The responsible employer must ensure that:

(1) Exposure monitoring is managed by a qualified individual (e.g., a certified industrial hygienist); and

(2) The individuals assigned to this task have sufficient industrial hygiene knowledge and experience to perform such activities properly.

(b) *Initial monitoring.* The responsible employer must perform initial monitoring in areas that may have airborne