

compare management's calculations to the amount of any dividend declared to determine whether it exceeded the amount.

6. Dividends Declared by Banks.

a. Information. Obtain the computations by the management of each national and state member bank concerning the bank's compliance with 12 U.S.C. 56, "Capital Limitation Test", 12 U.S.C. 60, "The Earnings Limitation Test", and transfers from surplus to undivided profits after declaration of the dividends referenced in paragraph 4.a. of this section. In a state with substantially similar laws, obtain the corresponding computations by the management of each state nonmember bank.

b. Procedures. Recalculate management's computations (for mathematical accuracy) and compare management's calculations to the standards defined in the tests set forth in paragraph 6.a. of this section to ascertain whether the dividends declared fall within the permissible levels under these standards. If dividends are not permissible in the amounts declared under such standards, ascertain whether the dividends were declared with the approval of the appropriate federal banking agency or under any other exception to the standards. If not, report the findings.

7. Dividends Declared by Savings Associations.

a. Information. Obtain management's documentation of the OTS determination whether the institution is a Tier 1, Tier 2, or Tier 3 savings association and management's computations of its capital ratio after declarations of dividends under the Tier determined by the OTS. For dividends declared, obtain copies of the savings association's notifications to the OTS to ascertain whether notifications were made at least 30 days before payment of any dividends.

b. Procedures: Recalculate management's computations (for mathematical accuracy) and trace amounts used by management in its calculations to the institution's TFRs.

Section II—Procedures for the Independent Public Accountant

If the internal auditor has performed the procedures set forth in section I for either or both Designated Laws, the following procedures may be performed by the independent public accountant for the appropriate designated law(s) if neither the FDIC nor the appropriate federal banking agency has objected in writing. The report of procedures performed and list of exceptions found by the internal auditor, identifying the institution with respect to which any exception was found, should be submitted to the audit committee of the board of directors. Management should file a summary of the internal auditor's significant findings and management's response to those findings with the FDIC at the same time as the independent public accountant's attestation report is filed.²

²Since this summary supplements the independent public accountant's attestation on the Designated Laws, the FDIC has determined that the summary is exempt from public disclosure consistent with the guidance in Guideline 18 in Appendix A to this part 363.

A. Review of Designated Laws. Read either or both of the Designated Insider Laws and Designated Dividend Laws applicable to the institution, as appropriate to the engagement.

B. Information and Procedures. Perform the procedures indicated as follows:

1. Designated Laws. Read Section I of this schedule. Obtain management's assessment contained in its management report on the institution's or holding company's compliance with the Designated Laws for the fiscal year.

2. Internal Auditor's Workpapers.

a. Information. If an internal auditor performed the procedures in Section I, obtain the internal auditor's workpapers documenting the performance of those procedures on the institution and the chief internal auditor's written representation that:

(1) The internal auditor or audit staff, if applicable, performed the procedures listed in section I on the institution;

(2) The internal auditor tested a sufficient number of transactions governed by the Designated Laws so that the testing was representative of the institution's volume of transactions;

(3) The workpapers accurately reflect the work performed by the internal auditor and, if applicable, the internal audit staff;

(4) The workpapers obtained are complete; and

(5) The internal auditor's report, which describes the procedures performed for the fiscal year as well as the internal auditor's findings and exceptions noted, has been presented to the institution's audit committee.

b. Procedures.

(1) Compare the workpapers to the procedures that are required to be performed under section I. Report as an exception any procedures not documented and any procedures for which the sample size is not sufficient.

(2) Compare the exceptions and errors listed by the internal auditor in its report to the audit committee to those found in the workpapers, and report as an exception any exception or error found in the internal auditor's workpapers and not listed in the internal auditor's list of exceptions.

3. Testing. **a.** The independent public accountant should perform the procedures listed in Section I on representative samples of the insiders and/or transactions of the institution to which the Designated Law applies. If the institution's internal auditor is performing the procedures in Section I, the samples tested by the independent public accountant should be at least 30 percent of the size of the samples tested by the internal auditor although samples selected by the accountant should be from the population at large. However, if there are so few transactions in any area that the internal auditor cannot use sampling, but must test all transactions, the independent public accountant should also test all transactions.

b. If the testing is being performed on a holding company with more than one subsidiary institution that is subject to this part 363 (covered subsidiary), the samples tested should include a combination of insiders and transactions from each covered subsidiary with total assets (after deductions

of intercompany amounts that would be eliminated in consolidation) in excess of 25 percent of the holding company's total assets every fiscal year. Samples should be tested for each smaller covered subsidiary at least every other fiscal year unless the holding company has more than eight covered subsidiaries, in which case the samples to be tested for each Designated Law should be drawn from each smaller covered subsidiary at least every third fiscal year.

4. Reports Concerning Holding Companies.

Only one report of any exceptions noted from application of the procedures in section II performed by the independent public accountant should be filed as required by guideline 3 in Appendix A to this part 363, but the report should identify, for each exception or error noted, the identity of the covered subsidiary to which it relates.

By order of the Board of Directors.

Dated at Washington, D.C. this 31st day of January, 1995.

Federal Deposit Insurance Corporation.

Robert E. Feldman,

Acting Executive Secretary.

[FR Doc. 95-3176 Filed 2-14-95; 8:45 am]

BILLING CODE 6174-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 94-NM-251-AD]

Airworthiness Directives; Boeing Model 747-400 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the superseding of an existing airworthiness directive (AD), applicable to certain Boeing Model 747-400 series airplanes, that currently requires a revision to the input wiring for the flap control unit. This action would require a new systems test for the wiring of the trailing edge flap. The proposal would also expand the applicability of the existing AD to include additional airplanes. This proposal is prompted by a report indicating that a wiring error was not detected by the system test required by the existing AD. The actions specified by the proposed AD are intended to prevent the possibility of an all-flaps-up landing due to the loss of control of all flap operations.

DATES: Comments must be received by April 10, 1995.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-103,

Attention: Rules Docket No. 94-NM-251-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Kristin Larson, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, Seattle Aircraft Certification Office, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (206) 227-1760; fax (206) 227-1181.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 94-NM-251-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-103, Attention: Rules Docket No.

94-NM-251-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

On July 1, 1994, the FAA issued AD 94-14-21, amendment 39-8970 (59 FR 35240, July 11, 1994), applicable to certain Boeing Model 747-400 series airplanes, to require a revision to the input wiring for the flap control unit (FCU). That action was prompted by reports of disconnection of the Landing Gear Module electrical connectors, which can result in the loss of the primary, secondary, and alternate control of the flaps. The requirements of that AD are intended to prevent the possibility of an all-flaps-up landing due to the loss of control of all flap operations.

Since issuance of that AD, an operator has reported a wiring error of the Landing Gear Module that was not detected by the system test (Work Package I) required by AD 94-14-21, and described in Boeing Service Bulletin 747-27A2346, Revision 1, dated May 19, 1994. This wiring error could allow the connectors to become disconnected, and all FCU modes of flap operation (primary, secondary, and alternate control of flaps) could be lost. This condition, if not corrected, could result in all-flaps-up landing due to the loss of control of all flap operations.

The FAA has reviewed and approved Boeing Service Bulletin 747-27A2346, Revision 2, dated January 12, 1995, which provides procedures for a systems test (Work Package II) of the trailing edge flap to detect incorrect wiring. It also expands the effectivity listing to include additional affected airplanes.

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would supersede AD 94-14-21 to continue to require revision of the input wiring for the flap control unit, but would include the addition of a new systems test for the wiring of the trailing edge flap. The proposed AD also would expand the applicability of the existing AD to include additional airplanes. The actions would be required to be accomplished in accordance with the service bulletin described previously.

As a result of recent communications with the Air Transport Association (ATA) of America, the FAA has learned that, in general, some operators may misunderstand the legal effect of AD's on airplanes that are identified in the applicability provision of the AD, but that have been altered or repaired in the area addressed by the AD. The FAA points out that all airplanes identified in

the applicability provision of an AD are legally subject to the AD. If an airplane has been altered or repaired in the affected area in such a way as to affect compliance with the AD, the owner or operator is required to obtain FAA approval for an alternative method of compliance with the AD, in accordance with the paragraph of each AD that provides for such approvals. A note has been included in this notice to clarify this requirement.

There are approximately 310 Model 747-400 series airplanes of the affected design in the worldwide fleet. The FAA estimates that 36 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately .5 work hours per airplane to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Based on these figures, the total cost impact of the proposed AD on U.S. operators is estimated to be \$1,080, or \$30 per airplane.

The total cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. App. 1354(a), 1421 and 1423; 49 U.S.C. 106(g); and 14 CFR 11.89.

39.13 [Amended]

2. Section 39.13 is amended by removing amendment 39-8970 (59 FR 35240, July 11, 1994), and by adding a new airworthiness directive (AD), to read as follows:

Boeing: Docket 94-NM-251-AD. Supersedes AD 94-14-21, Amendment 39-8970.

Applicability: Model 747-400 series airplanes having line numbers 696 through 1036 inclusive; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (d) to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition; or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any airplane from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

Note 2: Paragraph (a) of this AD merely restates the requirements of paragraph (a) of AD 94-14-21, amendment 39-8970. As allowed by the phrase, "unless accomplished previously," if those requirements of AD 94-14-21 have already been accomplished, this AD does not require that those actions be repeated.

To prevent the possibility of an all-flaps-up landing due to the loss of control of flap operations, accomplish the following:

(a) For airplanes having serial numbers 696 through 1019 inclusive, and 1021 through 1026 inclusive: Within 30 days after August 10, 1994 (the effective date of AD 94-14-21, amendment 39-8970), revise the input wiring for the flap control unit (FCU) in accordance with Boeing Service Bulletin 747-27A2346, Revision 1, dated May 19, 1994, or Revision 2, dated January 12, 1995.

(b) For airplanes having serial numbers 1020, and 1027 through 1036 inclusive:

Within 30 days after the effective date of this AD, revise the input wiring for the FCU in accordance with Boeing Service Bulletin 747-27A2346, Revision 2, dated January 12, 1995.

(c) For airplanes having serial numbers 696 through 1036 inclusive: Within 120 days after the effective date of this AD, perform the additional systems test for the wiring of the trailing edge flap in accordance with Boeing Service Bulletin 747-27A2346, Revision 2, dated January 12, 1995.

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Transport Aircraft Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished. Issued in Renton, Washington, on February 9, 1995.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 95-3752 Filed 2-14-95; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 39

[Docket No. 94-NM-218-AD]

Airworthiness Directives; Jetstream Aircraft Limited Model 4101 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes to revise an existing airworthiness directive (AD), applicable to all Jetstream Model 4101 airplanes, that currently requires modification of the mounting structure of the elevator controls on the rear pressure bulkhead. That proposal was prompted by results of a structural analysis which indicate that certain structure in the elevator control system may be subject to deformation when maximum load is exerted by the pilot(s) in the event of a jam in the elevator control cables. This action would limit the applicability of the rule. The actions specified by the proposed AD are intended to prevent reduced controllability of the airplane due to structural deformation in the elevator control system.

DATES: Comments must be received by March 27, 1995.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 94-NM-218-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Jetstream Aircraft, Inc., P.O. Box 16029, Dulles International Airport, Washington, DC 20041-6029. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: William Schroeder, Aerospace Engineer, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (206) 227-2148; fax (206) 227-1320.

SUPPLEMENTARY INFORMATION:**Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 94-NM-218-AD." The postcard will be date stamped and returned to the commenter.