

Additionally, the FAA has recently reviewed the figures it has used over the past several years in calculating the economic impact of AD activity. In order to account for various inflationary costs in the airline industry, the FAA has determined that it is necessary to increase the labor rate used in these calculations from \$55 per work hour to \$60 per work hour. The cost impact information, below, has been revised to reflect this increase in the specified hourly labor rate.

After careful review of the available data, including the comments noted above, the FAA has determined that air safety and the public interest require the adoption of the rule with the changes previously described. The FAA has determined that these changes will neither increase the economic burden on any operator nor increase the scope of the AD.

Cost Impact

There are approximately 892 Model DC-9-10, -20, -30, -40, and -50 series airplanes, and Model C-9 (military) airplanes of the affected design in the worldwide fleet. The FAA estimates that 557 airplanes of U.S. registry will be affected by this AD.

It will take approximately 6 work hours per airplane to accomplish the required replacement actions, at an average labor rate of \$60 per work hour. Required parts will vary in price, depending upon whether they are purchased from the manufacturer, manufactured locally, or procured from the operator's existing stocks. If all required parts (36 bearing plates and 38 bolts) are purchased from the manufacturer, the cost could be as much as \$15,184 per airplane. However, if the bearing plates are manufactured locally and bolts are retrieved from the operator's current stock, the estimated costs will be considerably lower, approximately \$1,900 per airplane.

Based on these figures, the total cost impact of the AD on U.S. operators is estimated to be between \$1,258,820 (or \$2,260 per airplane) and \$8,658,008 (or \$15,544 per airplane). This total cost impact figure is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various

levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. App. 1354(a), 1421 and 1423; 49 U.S.C. 106(g); and 14 CFR 11.89.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

95-02-14 McDonnell Douglas: Amendment 39-9133. Docket 94-NM-144-AD.

Applicability: Model DC-9-10, -20, -30, -40, and -50 series airplanes, and Model C-9 (military) airplanes; as listed in McDonnell Douglas DC-9 Alert Service Bulletin A71-63, dated July 21, 1994; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (b) to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition; or different

actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any airplane from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

To prevent separation of the engine nose cowl from the airplane, accomplish the following:

(a) Within 18 months after the effective date of this AD, replace the left and right engine nose cowl attaching bolts and install bearing plates, in accordance with McDonnell Douglas DC-9 Alert Service Bulletin A71-63, dated July 21, 1994; or Revision 1, dated December 15, 1994.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

(c) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

-(d) The replacement shall be done in accordance with McDonnell Douglas DC-9 Alert Service Bulletin A71-63, dated July 21, 1994; or McDonnell Douglas DC-9 Alert Service Bulletin A71-63, Revision 1, dated December 15, 1994. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from McDonnell Douglas Corporation, P.O. Box 1771, Long Beach, California 90801-1771, Attention: Business Unit Manager, Technical Administrative Support, Dept. L51, M.C. 2-98. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, Transport Airplane Directorate, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street NW., suite 700, Washington, DC.

(e) This amendment becomes effective on March 17, 1995.

Issued in Renton, Washington, on January 24, 1995.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 95-2176 Filed 2-14-95; 8:45 am]

BILLING CODE 4910-13-U