

Issued in Burlington, Massachusetts, on February 15, 1995.

James C. Jones,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 95-4545 Filed 3-6-95; 8:45 am]

BILLING CODE 4910-13-P

14 CFR Part 39

[Docket No. 94-NM-157-AD; Amendment 39-9158; AD 95-04-06]

Airworthiness Directives; British Aerospace Model Avro 146-RJ Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to all British Aerospace Model Avro 146-RJ series airplanes, that requires inspections to detect cracking of the upper main fitting of the nose landing gear (NLG), and replacement or repair of cracked parts. This amendment is prompted by reports of cracking of the upper main fitting of the NLG. The actions specified by this AD are intended to prevent failure of the main fitting, which could lead to collapse of the NLG during landing.

DATES: Effective on April 6, 1995.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of April 6, 1995.

ADDRESSES: The service information referenced in this AD may be obtained from British Aerospace Holdings, Inc., Avro International Aerospace Division, P.O. Box 16039, Dulles International Airport, Washington DC 20041-6039. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: William Schroeder, Aerospace Engineer, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (206) 227-2148; fax (206) 227-1320.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to all British Aerospace Model Avro 146-RJ series airplanes was published in the Federal

Register on November 7, 1994 (59 FR 55380). That action proposed to require repetitive eddy current or ultra high sensitivity penetrant inspections, and replacement or repair of cracked parts.

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the single comment received.

The commenter supports the proposed rule.

As a result of recent communications with the Air Transport Association (ATA) of America, the FAA has learned that, in general, some operators may misunderstand the legal effect of AD's on airplanes that are identified in the applicability provision of the AD, but that have been altered or repaired in the area addressed by the AD. The FAA points out that all airplanes identified in the applicability provision of an AD are legally subject to the AD. If an airplane has been altered or repaired in the affected area in such a way as to affect compliance with the AD, the owner or operator is required to obtain FAA approval for an alternative method of compliance with the AD, in accordance with the paragraph of each AD that provides for such approvals. A note has been added to this final rule to clarify this requirement.

After careful review of the available data, including the comments noted above, the FAA has determined that air safety and the public interest require the adoption of the rule with the change previously described. The FAA has determined that this change will neither increase the economic burden on any operator nor increase the scope of the AD.

The FAA estimates that 3 airplanes of U.S. registry will be affected by this AD, that it will take approximately 2.5 work hours per airplane to accomplish the required actions, and that the average labor rate is \$60 per work hour. Based on these figures, the total cost impact of the AD on U.S. operators is estimated to be \$450, or \$150 per airplane.

The total cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does

not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. App. 1354(a), 1421 and 1423; 49 U.S.C. 106(g); and 14 CFR 11.89.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

95-04-06 British Aerospace Regional Aircraft Limited, Avro International Aerospace Division (Formerly British Aerospace, plc; British Aerospace Commercial Aircraft, Limited): Amendment 39-9158. Docket 94-NM-157-AD.

Applicability: All Model Avro 146-RJ series airplanes, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (c) to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition; or different actions necessary to address the unsafe condition described in this AD. Such a

request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any airplane from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

To prevent the failure of the main fitting, which could lead to collapse of the nose land gear (NLG) during landing, accomplish the following:

(a) For airplanes on which NLG part number 200876001 or 200876003 has been installed:

(1) Prior to the accumulation of 4,000 total landings or within 30 days after the effective date of this AD, whichever occurs later, conduct an eddy current or ultra high sensitivity penetrant inspection of the NLG, in accordance with British Aerospace Service Bulletin S.B. 32-131, Revision 2, dated July 10, 1993. Repeat the inspection thereafter at intervals not to exceed 4,000 landings.

(2) If cracking is detected during any inspection required by this paragraph, prior to further flight, replace the currently installed NLG with a new or serviceable unit, or repair the crack, in accordance with a method approved by the Manager, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate. After replacement or repair, repeat the inspection at intervals not to exceed 4,000 landings.

(b) For airplanes on which NLG part number 200876002, 200876004, or 201138002 has been installed:

(1) Prior to the accumulation of 16,000 total landings or within 30 days after the effective date of this AD, whichever occurs later, conduct an eddy current or ultra sensitivity penetrant inspection of the NLG, in accordance with British Aerospace Service Bulletin S.B. 32-131, Revision 2, dated July 10, 1993. Repeat the inspection thereafter at intervals not to exceed 8,000 landings.

(2) If cracking is detected during any inspection required by this paragraph, prior to further flight, replace the currently installed NLG with a new or serviceable unit, or repair the crack, in accordance with a method approved by the Manager, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate. After replacement or repair, repeat the inspection at intervals not to exceed 8,000 landings.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM-113.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Standardization Branch, ANM-113.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to

a location where the requirements of this AD can be accomplished.

(e) The inspections shall be done in accordance with British Aerospace Service Bulletin S.B. 32-131, Revision 2, dated July 10, 1993, which contains the following effective pages:

Page No.	Revision level shown on page—	Date shown on page
1	2	July 10, 1993.
2-4	1	Nov. 12, 1992.
Appendix A-1 1-4.	Original— ..	Dec. 6, 1991.

The replacement and repair shall be done in accordance with a method approved by the Manager, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from British Aerospace Holdings, Inc., Avro International Aerospace Division, P.O. Box 16039, Dulles International Airport, Washington DC 20041-6039. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(f) This amendment becomes effective on April 6, 1995.

Issued in Renton, Washington, on February 15, 1995.

Darrell M. Pederson,
Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 95-4254 Filed 3-6-95; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 39

[Docket No. 92-ANE-11; Amendment 39-9151; AD 95-03-15]

Airworthiness Directives; Textron Lycoming ALF502R Series Turbofan Engines

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to Textron Lycoming ALF502R series turbofan engines, that reduces the service life for the No. 2 stage turbine disk, reduces the service lives for No. 1 and No. 3 through No. 7 stage compressor rotor disks, and requires a scheduled removal of these disks from service. This amendment is prompted by reports of cracks in disks returned from the field and in disks tested by the manufacturer. The actions specified by this AD are intended to

prevent disk failure resulting in a possible uncontained engine failure.

DATES: Effective on May 8, 1995.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of May 8, 1995.

ADDRESSES: The service information referenced in this AD may be obtained from AlliedSignal Engines, 550 Main Street, Stratford, CT 06497. This information may be examined at the Federal Aviation Administration (FAA), New England Region, Office of the Assistant Chief Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Eugene Triozzi, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone (617) 238-7148, fax (617) 238-7199.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to Textron Lycoming ALF502R series turbofan engines was published in the Federal Register on March 16, 1993 (58 FR 14185). That action proposed to reduce the service life for the No. 2 stage turbine disk, reduce the service lives for No. 1 and No. 3 through No. 7 stage compressor rotor disks, and require a scheduled removal of these disks from service in accordance with Textron Lycoming Service Bulletin (SB) ALF502R 72-281, dated February 7, 1992.

The compliance section of this final rule has been revised to specify the reduced service lives for each affected disk, to clarify that the reduced service lives are the new life limits.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposal or the FAA's determination of the cost to the public. The FAA has determined that air safety and the public interest require the adoption of the rule with the changes described previously.

On October 28, 1994, AlliedSignal Inc. purchased the turbine engine product line of Textron Lycoming, but as of this date the anticipated name change on the type certificate for the ALF502R series engines has not occurred.

There are approximately 700 Textron Lycoming ALF502R series turbofan