

radioactive waste in an electronic recordkeeping system.

(1) The manifest information that must be electronically stored is—

(i) That required in 10 CFR part 20, appendix G, with the exception of shipper and carrier telephone numbers and shipper and consignee certifications; and

(ii) That information required in paragraph (f) of this section.

(2) As specified in facility license conditions, the licensee shall report the stored information, or subsets of this information, on a computer-readable medium.

Dated at Rockville, MD this 20th day of March 1995.

For the Nuclear Regulatory Commission.
John C. Hoyle,
Secretary of the Commission.

[FR Doc. 95-7302 Filed 3-24-95; 8:45 am]
BILLING CODE 7590-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 93-CE-35-AD; Amendment 39-1180; AD 93-15-02 R1]

Airworthiness Directives; Fairchild Aircraft SA226 and SA227 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment revises Airworthiness Directive (AD) 93-15-02, which requires the following on Fairchild Aircraft SA226 and SA227 series airplanes that are equipped with a certain Simmonds-Precision pitch trim actuator: repetitively measuring the freeplay of the pitch trim actuator and repetitively inspecting the actuator for rod slippage; immediately replacing any actuator if certain freeplay limitations are not met or rod slippage is evident; and eventually replacing the actuator regardless of the inspection results. This action maintains these requirements, but reduces the hours time-in-service (TIS) before the initial inspection is required, and shortens both the time period between repetitive inspections and the actuator replacement compliance time (unless the replacement actuator is new or if the nut tube assemblies have been replaced during overhaul). An in-flight incident where the referenced actuator on one of the affected airplanes failed after

accomplishment of the 5,000-hour initial inspection (with satisfactory results) prompted this action. The actions specified by this AD are intended to prevent the horizontal stabilizer from going nose-down or jamming because of pitch trim actuator failure, which could result in loss of control of the airplane.

DATES: Effective April 17, 1995.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of April 17, 1995.

Comments for inclusion in the Rules Docket must be received on or before June 5, 1995.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Central Region, Office of the Assistant Chief Counsel, Attention: Rules Docket 93-CE-35-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Service information that applies to this AD may be obtained from Field Support Engineering, Fairchild Aircraft, P.O. Box 790490, San Antonio, Texas 78279-0490; telephone (210) 824-9421; facsimile (210) 820-8609. This information may also be examined at the FAA, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

FOR FURTHER INFORMATION CONTACT: Mr. Werner Koch, Aerospace Engineer, FAA, Airplane Certification Office, 2601 Meacham Boulevard, Fort Worth, Texas 76193-0150; telephone (817) 222-5150; facsimile (817) 222-5959.

SUPPLEMENTARY INFORMATION: AD 93-15-02, Amendment 39-8648 (59 FR 40734, July 30, 1993), currently requires the following on Fairchild Aircraft SA226 and SA227 series airplanes that are equipped with a Simmonds-Precision pitch trim actuator, part number (P/N) DL5040M5: repetitively measuring the freeplay of the pitch trim actuator and repetitively inspecting the actuator for rod slippage; and, if certain freeplay limitations are not met or rod slippage is evident, replacing any actuator with a new actuator of the same part number or with a part of improved design, P/N 27-19008-01 or 27-19008-02. The requirements of the AD will no longer apply when an actuator of improved design is installed. Accomplishment of the freeplay measurements and inspections is in accordance with the instructions in Fairchild Aircraft SA226 Series Service Letter (SL) 226-SL-005, and Fairchild Aircraft SA227 Series SL 227-SL-011, both Issued: April 8, 1993, Revised: April 28, 1993, as applicable. Accomplishment of the pitch trim

actuator replacement is in accordance with the applicable maintenance manual.

AD 93-15-02 was issued based on reports of two in-flight incidents where the above-referenced pitch trim actuator failed on Fairchild Aircraft SA226 and SA227 series airplanes. In one case, the horizontal stabilizer went full-nose down, and in the other instance, the horizontal stabilizer jammed. Fortunately, the pilots were able to safely land in both of these instances. Upon removal and inspection of each of these pitch trim actuators, fatigued barrel nuts were found and the actuator usage time was well over 5,000 hours TIS.

Since AD 93-15-02 became effective, the FAA received a report of an in-flight incident where the referenced actuator on one of the affected airplanes failed. The airplane operator had accomplished the 5,000-hour TIS initial inspection (with satisfactory results), but had not reached the 6,500-hour TIS mandatory replacement threshold.

Fairchild Aircraft has revised SA226 Series SL 226-SL-005 and SA227 Series SL 227-SL-011 to reflect the revised compliance times and a change to the inspection procedure. The revision date of this service information is March 2, 1995.

After examining the circumstances and reviewing all available information related to the incident described above, the FAA has determined that AD 93-15-02 should be revised by (1) reducing the number of hours TIS before the initial inspection is required; and (2) shortening both the time period between repetitive inspections and the actuator replacement compliance time, unless the replacement actuator is new or if the tube nut assemblies have been replaced during overhaul.

Since an unsafe condition has been identified that is likely to exist or develop in other Fairchild Aircraft SA226 and SA227 series airplanes of the same type design that are equipped with a Simmonds-Precision pitch trim actuator, P/N DL5040M5, this AD requires the same repetitive inspections and actuator replacement as AD 93-15-02, but revises the compliance times as previously specified. The inspections will be accomplished in accordance with the instructions in Fairchild Aircraft SA226 Series Service Letter (SL) 226-SL-005, and Fairchild Aircraft SA227 Series SL 227-SL-011, both Issued: April 8, 1993, Revised: March 2, 1995, as applicable.

Since a situation exists that requires the immediate adoption of this regulation, it is found that notice and opportunity for public prior comment

hereon are impracticable, and that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

Although this action is in the form of a final rule that involves requirements affecting immediate flight safety and, thus, was not preceded by notice and opportunity to comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 93-CE-35-AD." The postcard will be date stamped and returned to the commenter.

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

The FAA has determined that this regulation is an emergency regulation and that it is not considered to be significant under Executive Order 12866. It is impracticable for the agency to follow the procedures of Executive Order 12866 with respect to this rule since the rule must be issued

immediately to correct an unsafe condition in aircraft. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket (otherwise, an evaluation is not required). A copy of it, if filed, may be obtained from the Rules Docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. App. 1354(a), 1421 and 1423; 49 U.S.C. 106(g); and 14 CFR 11.89.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing Amendment 39-8648 (59 FR 40734, July 30, 1993), and by adding a new airworthiness directive to read as follows:

93-15-02 R1 Fairchild Aircraft:

Amendment 39-9180; Docket No. 93-CE-35-AD. Revises AD 93-15-02, Amendment 39-8648.

Applicability: All SA226 and SA227 series airplanes (all models and serial numbers) that are equipped with a Simmonds-Precision pitch trim actuator, part number (P/N) DL5040M5, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (d) of this AD to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition, or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition

addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any aircraft from the applicability of this AD.

Compliance: Required as indicated in the body of this AD, unless already accomplished.

To prevent the horizontal stabilizer from going nose down or jamming because of pitch trim actuator failure, which could result in loss of control of the airplane, accomplish the following:

Note 2: The paragraph structure of this AD is as follows:

Level 1: (a), (b), (c), etc.

Level 2: (1), (2), (3), etc.

Level 3: (i), (ii), (iii), etc.

Level 2 and Level 3 structures are designations of the Level 1 paragraph they immediately follow.

(a) Upon accumulating 3,000 hours time-in-service (TIS) on a Simmonds-Precision pitch trim actuator, P/N DL5040M5, or within the next 50 hours TIS accumulated on this type pitch trim actuator after the effective date of this AD, whichever occurs later, unless already accomplished, and thereafter at intervals not to exceed 250 hours TIS until paragraph (b) is complied with, accomplish the following:

Note 3: If hours TIS accumulated on the pitch trim actuator are not maintained, then hours TIS accumulated on the airplane may be substituted.

(1) Measure the freeplay of the pitch trim actuator and inspect the actuator for rod slippage in accordance with the INSTRUCTIONS section of Fairchild Aircraft SA226 Series Service Letter (SL) 226-SL-005, and Fairchild Aircraft SA227 Series SL 227-SL-011, both issued: April 8, 1993, revised: March 2, 1995, as applicable.

(2) If certain freeplay limitations specified in the service letters are not met or rod slippage is evident, prior to further flight, accomplish the replacement specified in either paragraph (b)(1) or (b)(2) of this AD.

(b) Within 500 hours TIS after the inspection specified in paragraph (a) of this AD or upon accumulating 5,000 hours TIS on a Simmonds-Precision pitch trim actuator, P/N DL5040M5, whichever occurs later, accomplish one of the following:

(1) Replace the pitch trim actuator with a new part of the same design and part number in accordance with the instructions in the applicable maintenance manual. Reinspect as specified in paragraph (a) of this AD at intervals not to exceed 300 hours TIS, and replace the actuator as specified in paragraph (b) of this AD at intervals not to exceed 5,000 hours TIS.

(2) Replace the pitch trim actuator with an overhauled, zero-timed part of the same design and part number. Accomplish this replacement in accordance with the instructions in the applicable maintenance manual, and reinspect and replace as specified below (paragraphs (b)(2)(i) and (b)(2)(ii) of this AD):

(i) If both nut tube assemblies, P/N AA56142, were replaced with new assemblies during overhaul, reinspect as specified in paragraph (a) of this AD at intervals not to exceed 300 hours TIS, and

replace the actuator as specified in paragraph (b) of this AD at intervals not to exceed 6,500 hours TIS;

(ii) If both nut tube assemblies, P/N AA56142, were not replaced with new assemblies during overhaul, reinspect as specified in paragraph (a) of this AD at intervals not to exceed 250 hours TIS, and replace the actuator as specified in paragraph (b) of this AD at intervals not to exceed 5,000 hours TIS.

(3) Replace the pitch trim actuator with a new part of improved design, P/N 27-19008-01 or 27-19008-02, in accordance with the instructions in the applicable maintenance manual.

(i) This replacement eliminates the repetitive inspection requirement of this AD.

(ii) This replacement may be accomplished at any time to eliminate the inspection requirement of this AD.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) An alternative method of compliance or adjustment of the initial or repetitive compliance times that provides an equivalent level of safety may be approved by the Manager, Airplane Certification Office (ACO), FAA, 2601 Meacham Boulevard, Fort Worth, Texas 76193-0150. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Fort Worth ACO.

Note 4: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Fort Worth ACO.

(e) The inspections and modification required by this AD shall be done in accordance with Fairchild Aircraft SA226 Series Service Letter 226-SL-005, and Fairchild Aircraft SA227 Series Service Letter 227-SL-011, both Issued: April 8, 1993, Revised: March 2, 1995, as applicable. This incorporation by reference is approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Field Support Engineering, Fairchild Aircraft, P.O. Box 790490, San Antonio, Texas 78279-0490. Copies may be inspected at the FAA, Central Region, Office of the Assistant Chief Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(f) This amendment (39-9180) becomes effective on April 17, 1995.

Issued in Kansas City, Missouri, on March 17, 1995.

Dwight A. Young,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 95-7113 Filed 3-24-95; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 71

[Airspace Docket No. 94-AGL-23]

Establishment of Class D Airspace; Akron-Canton, OH

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; correction.

SUMMARY: This action corrects an error in the airspace designation of the Akron-Canton, OH Class D airspace area legal description published in a final rule on February 23, 1995, (60 FR 10014) establishing Class D airspace for Akron-Canton Regional Airport, Akron, OH.

EFFECTIVE DATE: 0901 UTC, May 25, 1995.

FOR FURTHER INFORMATION CONTACT:

Nancy Cibic, Air Traffic Division, System Management Branch, AGL-530, Federal Aviation Administration, 2300 East Devon Avenue, Des Plaines, Illinois 60018, telephone (708) 294-7573.

SUPPLEMENTARY INFORMATION:

History

Federal Register Document 95-4439, published on February 23, 1995 (60 FR 10014), established Class D airspace for Akron-Canton Regional Airport, Akron, Ohio. The Class D surface and radius area indicated in the legal description were published incorrectly. This action corrects those errors.

Correction to Final Rule

Accordingly, pursuant to the authority delegated to me, the airspace designation for Akron, Ohio, Class D airspace, as published in the **Federal Register** on February 23, 1995, (60 FR 10014), (Federal Register Document 95-4439, page 10014, column 2), is corrected in the final rule to the incorporation by reference 14 CFR 71.1 as follows:

§ 71.1 [Corrected]

Paragraph 5000 General

* * * * *

AGL OH D Akron-Canton, OH [Corrected]
(Lat. 40°54'59"N., long. 81°26'32"W.)

That airspace extending upward from the surface to and including 5,200 feet MSL within a 5-mile radius of the Akron-Canton Regional Airport, OH. This Class D airspace area is effective during the specific dates and times established in advance by a Notice to Airmen. The effective date and time will thereafter be published in the Airport Facility Directory.

* * * * *

Issued in Des Plaines, Illinois on March 16, 1995.

Roger Wall,

Manager, Air Traffic Division.

[FR Doc. 95-7498 Filed 3-24-95; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF COMMERCE

Bureau of Export Administration

15 CFR Part 777

[Docket No. 930653-4299]

RIN 0694-AA70

Exports of Certain California Crude Oil

AGENCY: Bureau of Export Administration, Commerce.

ACTION: Final rule.

SUMMARY: The Bureau of Export Administration (BXA) is amending the short supply provisions of the Export Administration Regulations (EAR) by revising the restrictions on exports of crude oil produced in the lower 48 states to allow exports, under individual validated licenses, of up to 25,000 barrels per day (MB/D) of California heavy crude oil having a gravity of 20.0 degrees API or lower.

This final rule revises the licensing requirements and procedures that apply to exports of California heavy crude oil by removing a number of significant restrictions, e.g., the prohibition against transporting crude oil by pipeline over rights-of-way granted pursuant to the Mineral Leasing Act of 1920 and the requirement that any export of crude oil must be offset by importing an equal or greater volume of crude oil of equal or higher quality.

In order to minimize procedural delays in licensing exports of California heavy crude oil, BXA's Office of Chemical and Biological Controls and Treaty Compliance (CBTC) will issue licenses on a first-come, first-served, basis. Based on comments received on the March 24, 1994, proposed rule, this rule allows CBTC to issue licenses contingent upon the exporter submitting, prior to any export under a license, documentation showing that the exporter has title to the oil (or a contract to purchase the oil) and a contract to export the oil. This change in documentation requirements should provide exporters with greater flexibility in completing small cargo transactions on the spot market. Such transactions are likely to account for the bulk of California heavy crude oil exports.

EFFECTIVE DATE: March 27, 1995.