

later, install reinforcement plates at left and right fuselage stations 14911 and 17011, in accordance with Fokker Service Bulletin SBF100-53-072, dated March 12, 1993.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM-113.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Standardization Branch, ANM-113.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this OAD can be accomplished.

(d) The installation shall be done in accordance with Fokker Service Bulletin SBF100-53-072, dated March 12, 1993. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Fokker Aircraft USA, Inc., 1199 North Fairfax Street, Alexandria, Virginia 22314. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(e) This amendment becomes effective on July 7, 1995.

Issued in Renton, Washington, on May 26, 1995.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 95-13502 Filed 6-6-95; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 39

[Docket No. 94-CE-26-AD; Amendment 39-9249; AD 95-11-16]

Airworthiness Directives; SOCATA Groupe AEROSPATIALE TBM 700 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that applies to certain SOCATA Groupe AEROSPATIALE (Socata) TBM 700 airplanes. This action requires installing pneumatic deicers on the elevator horn leading edges. Ice accumulation on one of the affected airplanes during flight testing in icing conditions prompted the required action. The actions specified

by this AD are intended to prevent ice accumulation on the elevator horn, which could lead to loss of control of the airplane.

DATES: Effective July 19, 1995.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of July 19, 1995.

ADDRESSES: Service information that applies to this AD may be obtained from the SOCATA Groupe AEROSPATIALE, Socata Product Support, Aeroport Tarbes-Ossun-Lourdes, B P 930, 65009 Tarbes Cedex, France; telephone 62.41.74.26; facsimile 62.41.74.32; or the Product Support Manager, U.S. AEROSPATIALE, 2701 Forum Drive, Grand Prairie, Texas 75053; telephone (214) 641-3614; facsimile (214) 641-3527. This information may also be examined at the FAA, Central Region, Office of the Assistant Chief Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Mr. Raymond A. Stoer, Program Officer, Brussels Aircraft Certification Office, FAA, Europe, Africa, and Middle East Office, c/o American Embassy, B-1000 Brussels, Belgium; telephone (322) 513.38.30; facsimile (322) 230.68.99; or Mr. Mike Kiesov, Aerospace Engineer, FAA, Small Airplane Directorate, 1201 Walnut Street, suite 900, Kansas City, Missouri 64106; telephone (816) 426-6934; facsimile (816) 426-2169.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to certain Socata TBM 700 airplanes was published in the **Federal Register** on January 20, 1995 (60 FR 4117). The action proposed to require installing pneumatic deicers on the elevator horn leading edges. Accomplishment of the proposed installation would be in accordance with Socata Technical Instruction of Modification No. OPT70 K020-30, dated February 1993.

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the one comment received.

Socata recommends that AD action is not justified because it believes all owners/operators of the affected airplanes have installed pneumatic deicers on the elevator horn leading edges. The FAA does not concur that AD action is not justified even if all owners/operators may have already complied. AD's are issued to assure that

each affected airplane is in compliance with the action, and that those airplanes continue to be in compliance. Even if all owners/operators have complied with this action, the AD will ensure that these airplanes continue to have these pneumatic deicers installed and that any airplanes added to the U.S. registry will have pneumatic deicers installed. The AD is unchanged as a result of this comment.

No comments were received on the FAA's determination of the cost to the public.

After careful review of all available information including the comment discussed above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed except for minor editorial corrections. The FAA has determined that these minor corrections will not change the meaning of the AD and will not add any additional burden upon the public than was already proposed.

The FAA estimates that 20 airplanes in the U.S. registry will be affected by this AD, that it will take approximately 25 workhours per airplane to accomplish the required action, and that the average labor rate is approximately \$60 an hour. Parts cost \$3,710 per airplane. Based on these figures, the total cost impact of this AD on U.S. operators is estimated to be \$104,200. This figure is based upon the assumption that no affected airplane/operator has accomplished the required action. Socata has informed the FAA that it believes all affected airplane owners/operators have already accomplished the required installation. With this in mind, this action will impose no cost impact upon U.S. operators.

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory

Flexibility Act. A copy of the final evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. App. 1354(a), 1421 and 1423; 49 U.S.C. 106(g); and 14 CFR 11.89.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new AD to read as follows:

95-11-16 SOCATA Groupe

AEROSPATIALE: Amendment 39-9249; Docket No. 94-CE-26-AD.

Applicability: TBM 700 airplanes, serial numbers 1 to 49, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (c) of this AD to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition, or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any airplane from the applicability of this AD.

Compliance: Required within the next 100 hours time-in-service after the effective date of this AD, unless already accomplished.

To prevent ice accumulation on the elevator horn, which could lead to loss of control of the airplane, accomplish the following:

(a) Install pneumatic deicers on the elevator horn leading edges in accordance with Socata Technical Instruction of Modification No. OPT70 K020-30, dated February 1993. This installation is referenced in Socata TBM Service Bulletin SB 70-020-30, dated February 1993.

(b) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(c) An alternative method of compliance or adjustment of the compliance time that provides an equivalent level of safety may be approved by the Manager, Brussels Aircraft Certification Office (ACO), FAA, Europe, Africa, and Middle East Office, c/o American Embassy, B-1000 Brussels, Belgium. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Brussels ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Brussels ACO.

(d) The installation required by this AD shall be done in accordance with Socata Technical Instruction of Modification No. OPT70 K020-30, dated February 1993. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from SOCATA Groupe AEROSPATIALE, Socata Product Support, Aeroport Tarbes-Ossun-Lourdes, B P 930, 65009 Tarbes Cedex, France; or the Product Support Manager, U.S. AEROSPATIALE, 2701 Forum Drive, Grand Prairie, Texas 75053. Copies may be inspected at the FAA, Central Region, Office of the Assistant Chief Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(e) This amendment (39-9249) becomes effective on July 19, 1995.

Issued in Kansas City, Missouri, on May 23, 1995.

Henry A. Armstrong,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 95-13126 Filed 6-6-95; 8:45 am]

BILLING CODE 4910-13-U

RAILROAD RETIREMENT BOARD

20 CFR Part 200

RIN 3220-AB12

General Administration

AGENCY: Railroad Retirement Board.

ACTION: Final rule.

SUMMARY: The Railroad Retirement Board (Board) amends its regulations to explain when the Board will provide custom tailored information to a member of the public and to set forth the charges for such special services. In addition, the Board amends its regulations to explain when custom tailored information will be provided without charging for that service.

EFFECTIVE DATE: June 7, 1995.

ADDRESSES: Secretary to the Board, Railroad Retirement Board, 844 Rush Street, Chicago, Illinois 60611.

FOR FURTHER INFORMATION CONTACT: Michael C. Litt, Bureau of Law, Railroad Retirement Board, 844 Rush Street, Chicago, Illinois 60611, (312) 751-4929, TDD (312) 751-4701.

SUPPLEMENTARY INFORMATION: OMB Circular A-25 establishes Federal policy regarding fees to be assessed for special benefits. In the case of the Railroad Retirement Board those benefits would be the provision of custom tailored or non-routine information services. The regulation requires payment of the Board's actual costs, as defined in the regulation, for the provision of such services. Consistent with OMB Circular A-25, the regulation provides that if it is determined that the identity of the specific beneficiary is obscure and that provision of the information can be considered primarily as benefiting broadly the general public, then the Board may determine in a particular case not to charge for the service. However, consistent with the authority contained in section 12(d) of the Railroad Unemployment Insurance Act (which is incorporated into the Railroad Retirement Act by section 7(b)(3) of that Act), the regulation provides that charges may be assessed in any specific case. This regulation does not cover information which is required to be disclosed by statute or regulation such as information required to be disclosed under the Freedom of Information Act.

On March 2, 1995, the Board published this rule as a proposed rule (60 FR 11639), inviting comments on or before May 1, 1995. One comment was received. The commentor suggested three amendments to the proposed regulation: (1) Railroad employers should be allowed to seek custom-tailored information without charge as such services are paid by railroad employers through employer taxes which pay for the administrative expenses of the Board; (2) if fees are charged, the Board should be required to provide the estimated cost within a specified period; and (3) the limit of \$1,000.00 for waiver of fees without approval of the three-member Board is too low. In response thereto: (1) The Board believes that, although the costs of administration of the agency as a whole are borne by the railroad industry, it is more equitable to shift the costs for providing information to those elements of that industry which use the service in question than to have the entire industry pay for those services indirectly through employment taxes;