

total flight cycles; then perform the inspections required by paragraph (b)(4) of this AD.

(4) If, at the time of the most recent inspection required by paragraph (c) or (d) of this AD, the airplane had accumulated 70,000 or more total flight cycles: Perform the next inspection within 3,000 flight cycles. Repeat the inspection thereafter at intervals not to exceed 3,000 flight cycles.

(e) If any crack is found in the outboard chord of stringer 18A during any inspection required by this AD, repair prior to further flight, in accordance with either paragraph (e)(1) or (e)(2) of this AD.

(1) Boeing Service Bulletin 737-53A1166, Revision 1, dated May 25, 1995, or

(2) A method approved by the Manager, Seattle Aircraft Certification Office, FAA, Transport Airplane Directorate.

(f) If any crack is found in the outboard chord of the frame at BS 727 during any inspection required by this AD, accomplish paragraph (f)(1) or (f)(2) of this AD, as applicable, in accordance with either Boeing Alert Service Bulletin 737-53A1166, dated June 30, 1994; or Boeing Service Bulletin 737-53A1166, Revision 1, dated May 25, 1995.

(1) For any crack that extends from the forward edge of the chord or from the forward fastener hole, but that does not extend past the second fastener hole, accomplish either paragraph (f)(1)(i) or (f)(1)(ii) of this AD. Thereafter, perform initial and repetitive inspections in accordance with paragraphs (a) and (b) of this AD.

(i) Prior to further flight, install the time limited repair. Prior to the accumulation of 4,500 flight cycles or within 18 months, after accomplishing the time-limited repair, whichever occurs first, replace the outboard chord. Or

(ii) Prior to further flight, replace the outboard chord.

Note 2: Boeing Alert Service Bulletin 737-53A1166 references Boeing Service Bulletin 737-53-1088 as an additional source of service information for procedures to replace the chord.

(2) For any crack that extends from the forward edge of the chord, or from the forward fastener hole, and that extends past the second fastener hole, prior to further flight, replace the outboard chord in accordance with the alert service bulletin. Thereafter, perform initial and repetitive inspections in accordance with paragraphs (a) and (b) of this AD.

(g) Accomplishment of the following actions in accordance with either Boeing Alert Service Bulletin 737-53A1166, dated June 30, 1994, or Revision 1, dated May 25, 1995, constitutes terminating actions for the requirements of this AD:

(1) For airplanes on which no crack is found: Install the preventative modification in accordance with the alert service bulletin.

(2) For airplanes on which any crack is found: Prior to further flight, replace the cracked chord and install the preventative modification in accordance with the alert service bulletin.

(h) An alternative method of compliance or adjustment of the compliance time that

provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

(i) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(j) The inspections and replacement shall be done in accordance with either Boeing Alert Service Bulletin 737-53A1166, dated June 30, 1994, including Addendum, or Boeing Service Bulletin 737-53A1166, Revision 1, dated May 25, 1995, including Addendum. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street NW., suite 700, Washington, DC.

(k) This amendment becomes effective on August 18, 1995.

Issued in Renton, Washington, on June 5, 1995.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 95-14167 Filed 7-18-95; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 39

[Docket No. 94-NM-110-AD; Amendment 39-9302; AD 95-14-08]

Airworthiness Directives; British Aerospace Model Viscount 744, 745D, and 810 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to all British Aerospace Model Viscount 744, 745D, and 810 airplanes, that requires repetitive inspections to detect discrepancies of certain fittings and the actuator beam structure of the nose landing gear, and replacement of discrepant parts. This amendment is prompted by reports of fatigue cracking of the undercarriage bracing of the nose wheel. The actions specified by this AD are intended to

prevent such fatigue cracking, which could result in the failure of the structure and fittings, and subsequent collapse of the nose landing gear.

DATES: Effective August 18, 1995.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of August 18, 1995.

ADDRESSES: The service information referenced in this AD may be obtained from British Aerospace Regional Aircraft Ltd., Engineering Support Manager, Military Business Unit, Chadderton Works, Greengate, Middleton, Manchester M24 1SA, England. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: William Schroeder, Aerospace Engineer, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (206) 227-2148; fax (206) 227-1149.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to all British Aerospace Model Viscount 744, 745D, and 810 airplanes was published in the **Federal Register** on April 26, 1995 (60 FR 20458). That action proposed to require repetitive inspections to detect discrepancies of certain fittings and the actuator beam structure of the nose landing gear, and replacement of discrepant parts.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public. The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

The FAA estimates that 29 airplanes of U.S. registry will be affected by this AD, that it will take approximately 15 work hours per airplane to accomplish the required actions, and that the average labor rate is \$60 per work hour. Based on these figures, the total cost impact of the AD on U.S. operators is estimated to be \$26,100, or \$900 per airplane, per inspection cycle.

The total cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of

the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. App. 1354(a), 1421 and 1423; 49 U.S.C. 106(g); and 14 CFR 11.89.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

95-14-08 British Aerospace Regional Aircraft Limited (Formerly British Aerospace Commercial Aircraft Limited, Vickers-Armstrongs Aircraft Limited): Amendment 39-9302. Docket 94-NM-110-AD.

Applicability: All Model Viscount 744, 745D, and 810 airplanes, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (c) of this AD to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition; or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any airplane from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

To prevent collapse of the nose landing gear, accomplish the following:

(a) Prior to the accumulation of 2,050 landings after the effective date of this AD, or within 12 months after the effective date of this AD, whichever occurs first: Perform a visual inspection and non-destructive testing (NDT) inspection to detect discrepancies of the actuator beam structure and actuator attachment fittings of the nose landing gear, in accordance with Viscount Alert Preliminary Technical Leaflet (PTL) 331 VIS 1 Doc 12 (for Model 744 and 745D airplanes), or PTL 202, VIS 1 Doc. 4 (for Model Viscount 810 airplanes), both dated November 1, 1991, as applicable. Thereafter, repeat these inspections at intervals not to exceed 2,050 landings.

(b) If any discrepancy is found, prior to further flight, replace the discrepant part with a new part, in accordance with Viscount Alert PTL 331, VIS 1 Doc 12 (for Model 744 and 745D airplanes), or PTL 202, VIS 1 Doc. 4 (for Model 810 airplanes), both dated November 1, 1991, as applicable.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM-113.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Standardization Branch, ANM-113.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(e) The inspections and replacement shall be done in accordance with Viscount Alert Preliminary Technical Leaflet (PTL) 331 VIS 1 Doc 12, including Appendix 1, dated

November 1, 1991; or Viscount Alert PTL 202, VIS 1 Doc. 4, dated November 1, 1991; as applicable. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from British Aerospace Regional Aircraft Ltd., Engineering Support Manager, Military Business Unit, Chadderton Works, Greengate, Middleton, Manchester M24 1SA, England. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(f) This amendment becomes effective on August 18, 1995.

Issued in Renton, Washington, on June 27, 1995.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 95-16261 Filed 7-18-95; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 39

[Docket No. 95-NM-119-AD; Amendment 39-9303; AD 95-14-09]

Airworthiness Directives; Learjet Model 60 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to certain Learjet Model 60 airplanes. This action requires inspection to detect bends in or damage to the fuel crossflow tube; inspection to determine clearance between the fuel crossflow tube and the flight control cables; and replacement or repair of the tube, if necessary. This amendment is prompted by reports of damage to the fuel crossflow tube and inadequate clearance between the fuel crossflow tube and the flight control cables due to bends in the fuel crossflow tube. The actions specified in this AD are intended to prevent chafing and eventual failure of the fuel crossflow tube due to inadequate clearance between the tube and the flight control cables; this condition could result in loss of fuel from one fuel tank during normal operating conditions or loss of fuel from both main fuel tanks during fuel cross feeding operations.

DATES: Effective August 3, 1995.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of August 3, 1995.