

Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 USC 106(g), 40101, 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive (AD) to read as follows:

Jetstream Aircraft Limited: Docket No. 95-CE-44-AD.

Applicability: HP 137 Mk1, Jetstream Series 200, and Jetstream Models 3101 and 3201 airplanes (all serial numbers), certificated in any category, that are equipped with one of the following main landing gear (MLG) part numbers:

1863, 1863/4A, 1863/4B, 1863/4C, 1864, 1864/4A, 1864/4B, 1864/4C, BOOA702850A, BOOA702851A, BOOA702925A, BO1A702925A, BOOA703065A, BO1A703065A, BOOA703030A, BOOA702926A, BO1A702926A, BOOA703066A, BO1A703066A, BOOA703031A,

Note 1: This AD applies to each airplane identified in the preceding applicability revision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required initially upon the accumulation of 8,500 landings on an affected MLG or within the next 100 landings after the effective date of this AD, whichever occurs later, unless already accomplished, and thereafter as indicated.

Note 2: If the number of MLG landings is unknown, hours time-in-service (TIS) may be used by multiplying the number of hours TIS times 0.75. If hours TIS are utilized to come

up with the number of landings, this would make the AD effective "initially upon the accumulation of 11,333 hours TIS or within the next 133 hours TIS after the effective date of this AD, whichever occurs later."

To prevent failure of the MLG caused by cracks in the pintle to cylinder interface area, which, if not detected and corrected, could result in loss of control of the airplane during landing operations, accomplish the following:

(a) Using non-destructive testing (NDT) eddy current methods, inspect the MLG pintle to cylinder interface for cracks in accordance with the following:

(1) Jetstream Alert Service Bulletin 32-A-JA 941245, Revision 2, dated March 28, 1995; and

(2) AP Precision Hydraulics Ltd. Service Bulletin 32-56, Revision 3, dated February 1995.

(b) Based on the inspection results, accomplish the following, as applicable:

(1) If any crack is found that is .05 inch or more in length, prior to further flight, replace the cylinder with a new part, and reinspect at intervals not to exceed 4,000 landings provided the MLG pintle to cylinder interface is crack-free.

(2) If any crack is found that is less than .05 inch, reinspect at intervals not to exceed 40 landings provided the crack remains less than .05 inch or replace the cylinder with a new part and reinspect at intervals not to exceed 4,000 landings provided the MLG pintle to cylinder interface is crack-free.

(3) If no cracks are found, reinspect at intervals not to exceed 4,000 landings provided the MLG pintle to cylinder interface is crack-free.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) An alternative method of compliance or adjustment of the initial and repetitive compliance times that provides an equivalent level of safety may be approved by the Manager, Brussels Aircraft Certification Office (ACO), Europe, Africa, Middle East office, FAA, c/o American Embassy, B-1000 Brussels, Belgium. The request should be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Brussels ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Brussels ACO.

(e) All persons affected by this directive may obtain copies of the documents referred to herein upon request to Jetstream Aircraft Limited, Manager Product Support, Prestwick Airport, Ayrshire, KA9 2RW Scotland; or Jetstream Aircraft Inc., Librarian, P.O. Box 16029, Dulles International Airport, Washington, DC, 20041-6029; or may examine these documents at the FAA, Central Region, Office of the Assistant Chief Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Issued in Kansas City, Missouri, on September 13, 1995.

Gerald W. Pierce,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 95-23218 Filed 9-18-95; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 39

[Docket No. 95-CE-40-AD]

Airworthiness Directives; Fairchild Aircraft SA226 and SA227 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes to adopt a new airworthiness directive (AD) that would apply to certain Fairchild Aircraft SA226 and SA227 series airplanes. The proposed action would require drilling inspection access holes in the elevator torque tube arm, inspecting the elevator torque tube for corrosion, replacing any corroded elevator torque tube, and applying a corrosion preventive compound. Several reports of corrosion found in the elevator torque tube area on the affected airplanes prompted the proposed action. The actions specified by the proposed AD are intended to prevent failure of the flight control system caused by a corroded elevator torque tube, which, if not detected and corrected, could result in loss of control of the airplane.

DATES: Comments must be received on or before November 17, 1995.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Central Region, Office of the Assistant Chief Counsel, Attention: Rules Docket No. 95-CE-40-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106. Comments may be inspected at this location between 8 a.m. and 4 p.m., Monday through Friday, holidays excepted.

Service information that applies to the proposed AD may be obtained from Fairchild Aircraft, P.O. Box 790490, San Antonio, Texas 78279-0490; telephone (210) 824-9421. This information also may be examined at the Rules Docket at the address above.

FOR FURTHER INFORMATION CONTACT: Mr. Hung Viet Nguyen, Aerospace Engineer, FAA, Airplane Certification Office, 2601 Meacham Boulevard, Fort Worth, Texas 76193-0150; telephone (817) 222-5155; facsimile (817) 222-5960.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 95-CE-40-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Central Region, Office of the Assistant Chief Counsel, Attention: Rules Docket No. 95-CE-40-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Discussion

The FAA has received reports of internal corrosion found in the elevator torque tube on over 20 Fairchild Aircraft SA226 and SA227 series airplanes. This condition, if not detected and corrected, could result in failure of the airplane flight control system and subsequent loss of control of the airplane.

Fairchild Aircraft Service Bulletin (SB) 226-27-050 and SB 227-27-028, both issued: January 22, 1990, specify procedures for the following:

- Drilling inspection access holes in the elevator torque tube arm;
- Inspecting the elevator torque tube for corrosion; and
- Applying a corrosion preventive compound.

After examining the circumstances and reviewing all available information related to the incidents described above including the referenced service information, the FAA has determined that AD action should be taken to prevent failure of the flight control system caused by a corroded elevator torque tube, which, if not detected and corrected, could result in loss of control of the airplane.

Since an unsafe condition has been identified that is likely to exist or develop in other Fairchild Aircraft SA226 and SA227 series airplanes of the same type design, the proposed AD would require drilling inspection access holes in the elevator torque tube arm, inspecting the elevator torque tube for corrosion, replacing any corroded elevator torque tube, and applying a corrosion preventive compound. Accomplishment of the proposed inspection access hole drilling, the inspection, and the corrosion preventive compound application would be in accordance with either Fairchild SB 226-27-050 or SB 227-27-028, both issued: January 22, 1990.

The compliance time for the proposed AD is presented in calendar time instead of hours time-in-service (TIS). The FAA has determined that a calendar time for compliance would be the most desirable method because the unsafe condition described by the proposed AD is caused by corrosion. Corrosion can occur on airplanes regardless of whether the airplane is in service or on the ground.

The FAA estimates that 390 airplanes in the U.S. registry would be affected by the proposed AD, that it would take approximately 10 workhours to accomplish the proposed actions, and that the average labor rate is approximately \$60 an hour. Based on these figures, the total cost impact of the proposed AD on U.S. operators is estimated to be \$234,000. This figure is based on the assumption that no owner/operator of the affected airplanes has accomplished the proposed inspection access hole drilling, inspection, or corrosion preventive compound application. It also is based on the assumption that no elevator torque tube would be found corroded and need replaced. The FAA has no way of determining how many owners/operators of the affected airplanes may have already complied with the proposed AD.

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the

various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action has been placed in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 USC 106(g), 40101, 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive (AD) to read as follows:

Fairchild Aircraft: Docket No. 95-CE-40-AD.

Applicability: The following airplane models and serial numbers, certificated in any category:

Model	Serial Nos.
SA226-T	T201 through T275 and T277 through T291.
SA226-T(B)	T(B)276 and T(B)292 through T(B)417.
SA226-AT	AT001 through AT074.
SA226-TC	TC201 through TC419.
SA227-TT	TT421 through TT541.
SA227-AT	AT423 through AT695.
SA227-AC	AC406, AC415, AC416, and AC420 through AC772.

Note 1: This AD applies to each airplane identified in the preceding applicability

revision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it. Compliance: Required within the next 6 calendar months after the effective date of this AD, unless already accomplished.

To prevent failure of the flight control system caused by a corroded elevator torque tube, which, if not detected and corrected, could result in loss of control of the airplane, accomplish the following:

(a) Drill two .5 inch diameter holes in the inboard side of the elevator torque tube arm in accordance with the ACCOMPLISHMENT INSTRUCTIONS section of and as specified in Figure 1 of Fairchild Aircraft Service Bulletin (SB) 226-27-050 or SB 227-27-028, both Issued: January 22, 1990, as applicable.

(b) Inspect the elevator torque tube in accordance with the ACCOMPLISHMENT INSTRUCTIONS section of Fairchild Aircraft SB 226-27-050 or SB 227-27-028, both Issued: January 22, 1990, as applicable. Prior to prior further flight, replace any corroded elevator torque tube with a new part of like design in accordance with the applicable maintenance manual.

(c) Apply a corrosion preventive compound in accordance with the ACCOMPLISHMENT INSTRUCTIONS section of Fairchild Aircraft SB 226-27-050 or SB 227-27-028, both Issued: January 22, 1990, as applicable.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(e) An alternative method of compliance or adjustment of the compliance time that provides an equivalent level of safety may be approved by the Manager, Airplane Certification Office (ACO), FAA, 2601 Meacham Boulevard, Fort Worth, Texas 76193-0150. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Fort Worth ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Fort Worth ACO.

(f) All persons affected by this directive may obtain copies of the service bulletins referred to herein upon request to Fairchild Aircraft, P.O. Box 790490, San Antonio, Texas 78279-0490; or may examine these service bulletins at the FAA, Central Region, Office of the Assistant Chief Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Issued in Kansas City, Missouri, on September 13, 1995.

Gerald W. Pierce,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 95-23216 Filed 9-18-95; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 39

[Docket No. 95-CE-35-AD]

Airworthiness Directives; The New Piper Aircraft, Inc. (Formerly Piper Aircraft Corporation) Models PA23, PA23-150, PA23-160, PA23-235, and PA23-250 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes to supersede Airworthiness Directive (AD) 92-13-04, which currently requires preflight draining procedures on The New Piper Aircraft, Inc. (Piper) Models PA23-150 and PA23-160 airplanes. This proposed action would require installing external fuel ramp assemblies on Piper Models PA23, PA23-150, PA23-160, PA23-235, and PA23-250 airplanes, and incorporating pilots' operating handbook (POH) revisions for Piper Models PA23, PA23-150, and PA23-160 airplanes. Reports of water-in-the-fuel on the affected airplanes, regardless of whether the airplane owners/operators have accomplished preflight draining procedures, prompted the proposed action. The actions specified by the proposed AD are intended to prevent rough engine operation or complete loss of engine power caused by water-in-the-fuel.

DATES: Comments must be received on or before December 26, 1995.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Central Region, Office of the Assistant Chief Counsel, Attention: Rules Docket No. 95-CE-35-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106. Comments may be inspected at this location between 8 a.m. and 4 p.m., Monday through Friday, holidays excepted.

FFC Engineering Specification 2810-002, Revision A, dated March 21, 1995, may be obtained from Floats & Fuel Cells, 4010 Pilot Drive, suite 3, Memphis, Tennessee 38118. Piper Service Bulletin (SB) No. 827A, dated November 4, 1988, may be obtained from The New Piper Aircraft, Inc., Customer Services, 2926 Piper Drive, Vero Beach, Florida 32960. This

information also may be examined at the Rules Docket at the address above.

FOR FURTHER INFORMATION CONTACT: Ms. Juanita Craft-Lloyd, Aerospace Engineer, FAA, Atlanta Aircraft Certification Office, Campus Building, 1701 Columbia Avenue, suite 2-160, College Park, Georgia 30337-2748; telephone (404) 305-7373; facsimile (404) 305-7348.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 95-CE-35-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Central Region, Office of the Assistant Chief Counsel, Attention: Rules Docket No. 95-CE-35-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Discussion

Sixteen accidents since 1975 involving Piper PA23 series airplanes where water-in-the-fuel was believed to cause engine stoppage prompted the FAA to issue AD 90-23-18, Amendment 39-6782 (55 FR 46787; November 7, 1990), and AD 92-13-04, Amendment 39-8274 (57 FR 24938;