

Rules and Regulations

Federal Register

Vol. 60, No. 231

Friday, December 1, 1995

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 94-ANE-47; Amendment 39-9437; AD 95-24-05]

Airworthiness Directives; McCauley Accessory Division, The Cessna Aircraft Company, Model C35, C72, C74, C75, C80, C86, C87, C92, and C93 Series Propellers

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to McCauley Accessory Division, The Cessna Aircraft Company, Model C35, C72, C74, C75, C80, C86, C87, C92, and C93 series propellers. This action requires initial and repetitive visual and dye penetrant inspections of the propeller hub for cracks. This action also requires a one-time eddy current inspection for cracks in the threaded areas of the propeller hub followed by modification of the hub to contain oil with red dye as a terminating action to the repetitive inspections. This amendment is prompted by reports of cracked propeller hubs. The actions specified in this AD are intended to prevent propeller blade separation due to a cracked propeller hub, which could result in separation of the engine from the aircraft and subsequent loss of aircraft control.

DATES: Effective December 18, 1995.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of December 18, 1995.

Comments for inclusion in the Rules Docket must be received on or before January 30, 1996.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), New England Region, Office of the Assistant Chief Counsel, Attention: Rules Docket No. 94-ANE-47, 12 New England Executive Park, Burlington, MA 01803-5299.

The service information referenced in this AD may be obtained from McCauley Accessory Division, The Cessna Aircraft Company, 3535 McCauley Dr., Vandalia, OH 45377-0430; telephone (513) 890-5246, fax (513) 890-6001. This information may be examined at the FAA, New England Region, Office of the Assistant Chief Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Patricia Bonnen, Aerospace Engineer, Chicago Aircraft Certification Office, FAA, Small Airplane Directorate, 2300 East Devon Ave., Room 232, Des Plaines, IL 60018; telephone (708) 294-7134, fax (708) 294-7834.

SUPPLEMENTARY INFORMATION: The Federal Aviation Administration (FAA) has received several reports of cracked propeller hubs on McCauley Accessory Division, The Cessna Aircraft Company, Model C35, C72, C74, C75, C80, C86, C87, C92, and C93 series propellers. Additionally, two incidents have occurred where the propeller blades separated during flight. This condition, if not corrected, could result in propeller blade separation due to a cracked propeller hub, which could result in separation of the engine from the aircraft and subsequent loss of aircraft control.

The FAA has reviewed and approved the technical contents of the following service documents:

(a) McCauley Accessory Division, The Cessna Aircraft Company, Service Bulletin (SB) No. 200C, dated January 20, 1994, that describes procedures for an initial and repetitive visual and dye penetrant inspections of propeller hubs for cracks, and

(b) McCauley Service Letter (SL) No. 1993-11A, dated June 20, 1995, that describes procedures for eddy current inspection for cracks in the threaded areas of the propeller hub and modification of the hub to contain oil

with red dye, which provides a built-in means of crack detection, as well as improved lubrication and corrosion protection.

Since an unsafe condition has been identified that is likely to exist or develop on other propellers of the same type design, this airworthiness directive (AD) is being issued to prevent propeller blade separation due to a cracked propeller hub, which could result in separation of the engine from the aircraft and subsequent loss of aircraft control. This AD requires initial and repetitive visual and dye penetrant inspections of the propeller hub for cracks. This AD also requires a one-time eddy current inspection for cracks in the threaded areas of the propeller hub followed by modification of the hub to contain oil with red dye, which constitutes terminating action to the repetitive visual and dye-penetrant inspections. The actions are required to be accomplished in accordance with the service documents described previously.

Since a situation exists that requires the immediate adoption of this regulation, it is found that notice and opportunity for prior public comment hereon are impracticable, and that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

Although this action is in the form of a final rule that involves requirements affecting flight safety and, thus, was not preceded by notice and an opportunity for public comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of

the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 94-ANE-47." The postcard will be date stamped and returned to the commenter.

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the

Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 USC 106(g), 40101, 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

95-24-05 McCauley Accessory Division, The Cessna Aircraft Company: Amendment 39-9437. Docket 94-ANE-47.

Applicability: McCauley Accessory Division, The Cessna Aircraft Company, Model C35, C72, C74, C75, C80, C86, C87, C92, and C93 series propellers, incorporating the following Hub Models:

- D3AF32C35-()
- 3AF32C72-()
- 3AF34C74-()
- 3AF32C75-()
- D3AF32C80-()
- 3AF34C86-()
- 3AF32C87-()
- D3AF32C87-()
- 3AF34C92-()
- 3AF32C93-()

The parentheses used in the above list indicate the presence or absence of an additional letter(s) which vary the basic propeller hub model designation. These letter(s) define minor changes that do not affect interchangeability or eligibility, and therefore, this airworthiness directive (AD) still applies regardless of whether these letters are present or absent on the propeller hub model designation.

These propellers are installed on but not limited to the following aircraft: Beech 58, 58A, 95-C55, -C55A, -D55, -D55A, -E55, -E55A.

British Aerospace B-206 Series 2.
Cessna 310K, 310L, 310N, 310P, 310Q, 310R, T310P, T310Q, T310R, 320D, 320E, 320F, 335, 340, 340A, 401, 401A, 401B, 402, 402A, 402B, 402C, 411, 411A, 414, 414A, 421, 421A, 421B.

Colemill Executive 600 (Conversion of Cessna 310I, 310J, 310K, 310L, 310N).
RAM Conversion of Cessna 340.

Note 1: The above is not an exhaustive list of aircraft which may contain the affected McCauley Model C35, C72, C74, C75, C80, C86, C87, C92, and C93 series propellers, incorporating Models D3AF32C35, 3AF32C72, 3AF34C74, 3AF32C75, D3AF32C80, 3AF34C86, 3AF32C87,

D3AF32C87, 3AF34C92, and 3AF32C93 propeller hubs because of installation approvals made by Supplemental Type Certificate or Federal Aviation Administration (FAA) Form 337 "Major Repair and Alteration," etc. It is the responsibility of the owner, operator and person returning the aircraft to service to determine if an aircraft has an affected propeller

Note 2: This AD applies to each propeller identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For propellers that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (g) to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition, or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any propeller from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

To prevent propeller blade separation due to a cracked propeller hub, which could result in separation of the engine from the aircraft and subsequent loss of aircraft control, accomplish the following:

(a) Within the next 25 hours time in service (TIS) after the effective date of this AD, unless already accomplished within the last 35 hours TIS, and thereafter at intervals not to exceed 60 hours TIS, perform a visual and dye penetrant inspection for cracks in propeller hubs in accordance with McCauley Accessory Division, The Cessna Aircraft Company, Service Bulletin (SB) No. 200C, dated January 20, 1994. Any propeller hubs found cracked during this inspection are to be permanently retired from service and replaced with a serviceable hub modified in accordance with paragraph (c) of this AD, or with an equivalent initial production propeller which has incorporated a hub containing oil with red dye.

(b) For affected propellers identified with the change letter "R" following the hub model designation and having an oil-fill plug in the side of the hub, compliance is required only with paragraphs (d) and (f) of this AD.

(c) Perform a one-time eddy current inspection and modify serviceable propeller hubs in accordance with the following schedule and requirements:

Propeller Time-In-Service (TIS) on the effective date of this AD	Compliance required
Greater than 900 hours or 59 calendar months since last overhaul/penetrant inspection or installed new, or prior TIS unknown.	Within the next 300 hours or at the next annual inspection or within 12 months after the effective date of this AD, whichever occurs first.
Less than or equal to both 900 hours and 59 calendar months since last overhaul/penetrant inspection or installed new.	Prior to the accumulation of 1,200 hours or 60 calendar months since last overhaul/penetrant inspection or installed new, whichever occurs first.

(1) Perform a one-time eddy current inspection for cracks in the threaded areas of the propeller hubs in accordance with McCauley Accessory Division, The Cessna Aircraft Company, Service Letter (SL) No. 1993-11A, dated June 20, 1995.

(2) Any propeller hubs found cracked during the eddy current inspection are to be permanently retired from service and replaced with a serviceable hub modified in accordance with paragraph (c) of this AD, or with an equivalent initial production propeller which has incorporated a hub containing oil with red dye.

(3) Modify affected propeller hubs to contain oil with red dye, in accordance with McCauley Accessory Division, The Cessna Aircraft Company, SL No. 1993-11A, dated June 20, 1995. Completion of this modification of the hub to contain oil with red dye constitutes terminating action to the repetitive inspections required by paragraph (a) of this AD.

Note: The modification of the propeller hub assembly to contain oil with a red dye provides an "on-condition" (in-service) means of early crack detection of the propeller assembly and also improves lubrication and corrosion protection. The oil will add approximately 4.0 lbs. to the weight of the propeller assembly.

(4) Previous compliance with McCauley Accessory Division SL 1993-11, dated September 15, 1993, also constitutes compliance with paragraphs (a) and (c) of this AD.

(5) Install Decal-Warning "Oil Filled", part number B-6493, in accordance with McCauley Accessory Division, The Cessna Aircraft Company, SL No. 1993-11A, dated June 20, 1995, Figure F-9.

(d) If leakage of oil containing red dye is detected in service (whether during flight or while on the ground), determine, prior to further flight, the source of leakage in accordance with the procedures specified in section A-7 of McCauley SL No. 1993-11A, dated June 20, 1995. Remove from service, prior to further flight, propeller assemblies that exhibit cracks and replace with a serviceable unit, modified in accordance with paragraph (c) of this AD, or with an equivalent initial production propeller that has incorporated a hub containing oil with red dye. Oil-filled propellers are identified with the change letter "R" following the Hub Model Designation and have an oil-fill plug in the side of the hub.

(e) The "calendar month" compliance times stated in this AD allow the performance of the required action up to the last day of the month in which compliance is required. For example, a required eddy current inspection and modification 60 calendar months from last overhaul/penetrant inspection that was performed on December 15, 1991, would allow the eddy current inspection and modification to be performed no later than December 31, 1996.

(f) Report in writing any cracks found during the accomplishment of paragraphs (a), (c) or (d) of this AD to the Manager, Chicago Aircraft Certification Office, FAA, Small Airplane Directorate, 2300 East Devon Avenue, Room 232, Des Plaines, IL 60018; telephone (708) 294-7134, fax (708) 294-

7834, within 10 days of the inspection. Information collection requirements contained in the regulation have been approved by the Office of Management and Budget (OMB) under the provisions of the Paperwork Reduction Act of 1980 (P.L. 96-511) and has been assigned OMB Control Number 2120-0056.

(g) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Chicago Aircraft Certification Office. The request should be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Chicago Aircraft Certification Office.

Note: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the Chicago Aircraft Certification Office.

(h) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the aircraft to a location where the requirements of this AD can be accomplished.

(i) The inspections and modification required by this AD shall be done in accordance with the following McCauley Accessory Division, The Cessna Aircraft Company, service documents:

Document No.	Pages	Date
SB 200C	1-4	January 20, 1994.
Total pages: 4.		
SL 1993-11A:		
Cover Page	1	June 20, 1995.
Section A	1-4	June 20, 1995.
Section B	1	June 20, 1995.
Section C	1	June 20, 1995.
Section D	1-7	June 20, 1995.
Section E	1-10	June 20, 1995.
Section F	1-15	June 20, 1995.
Section G	1	June 20, 1995.
Section H	1-4	June 20, 1995.
Section I	1-4	June 20, 1995.
Total pages: 48.		

This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from McCauley Accessory Division, The Cessna Aircraft Company, 3535 McCauley Dr., Vandalia, OH 45377-0430; telephone (513) 890-5246, fax (513) 890-6001. Copies may be inspected at the FAA, New England Region, Office of the Assistant Chief Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(j) This amendment becomes effective on December 18, 1995.

Issued in Burlington, Massachusetts, on November 7, 1995.

James C. Jones,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 95-28957 Filed 11-30-95; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 39

[Docket No. 95-NM-219-AD; Amendment 39-9444; AD 95-24-14]

Airworthiness Directives; de Havilland Model DHC-8 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to certain de Havilland Model DHC-8 series airplanes. This action requires eddy current inspections to detect cracking of the pivot tubes in the drag strut of the nose landing gear (NLG), and repair or replacement of any cracked tube with a serviceable or new tube. This amendment is prompted by reports that the pivot tubes cracked or failed completely due to fatigue. The actions specified in this AD are intended to prevent such fatigue cracking and subsequent failure of the pivot tube, which could result in a nose gear-up landing.

DATES: Effective December 18, 1995.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of December 18, 1995.

Comments for inclusion in the Rules Docket must be received on or before January 30, 1996.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 95-NM-219-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

The service information referenced in this AD may be obtained from Bombardier, Inc., Bombardier Regional Aircraft Division, Garratt Boulevard, Downsview, Ontario M3K 1Y5, Canada. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, New York Aircraft Certification Office, Engine and Propeller Directorate, 10 Fifth Street, Third Floor, Valley Stream, New York; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.