

owner/operator must use the authority provided in paragraph (d) to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition, or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the

unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any engine from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

To prevent power turbine (PT) overspeed and uncontained engine failure, accomplish the following:

(a) Install the improved PT rotor with retention capability at the next shop visit when the PT rotor is removed after the effective date of this AD, but prior to December 31, 1997, in accordance with the following Textron Lycoming Service Bulletins (SB):

Engine model	SB No.	Rev.	Date
LTS101-650B1	LTS101B-72-50-0122	4	June 17, 1991.
LTS101-750B1 or -650B1	LTS101B-72-50-0116	6	August 14, 1992.
LTS101-650C and -750C Series	LTS101C-72-50-0119	2	June 17, 1991.

(b) Install the improved electronic PT rotor overspeed controller concurrently with the PT rotor installation required by paragraph

(a) of this AD, or at the next airframe 600 hour inspection point after the effective date of this AD, whichever occurs later, in

accordance with the following Textron Lycoming SB:

Engine model	SB No.	Rev.	Date
LTS101-650B1	LTS101B-73-10-0127	2	August 14, 1992.
LTS101-750B1	LTS101B-73-10-0127	2	August 14, 1992.
LTS101-650C and -750C Series	LTS101C-73-10-0129	3	August 14, 1992.

(c) Installation of the improved PT rotor with retention capability and the improved electronic PT rotor overspeed controller in accordance with paragraphs (a) and (b) of this AD constitutes terminating action to the inspection requirements of AD 88-14-01.

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine

Certification Office. The request should be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Engine Certification Office.

Note: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the Engine Certification Office.

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the aircraft to a location where the requirements of this AD can be accomplished.

(f) The actions required by this AD shall be done in accordance with the following service bulletins:

Document No.	Pages	Revision	Date
LTS101B-72-50-0122	1-11	4	June 17, 1991.
Total pages:	11		
LTS101B-72-50-0116	1-10	6	August 14, 1992.
Total pages:	10		
LTS101C-72-50-0119	1-11	2	June 17, 1991.
Total pages:	11		
LTS101B-73-10-0127	1-13	2	August 14, 1992.
Total pages:	13		
LTS101C-73-10-0129	1-14	3	August 14, 1992.
Total pages:	14		

This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from AlliedSignal Inc., 550 Main Street, Stratford, CT 06497. Copies may be inspected at the FAA, New England Region, Office of the Assistant Chief Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street NW., suite 700, Washington, DC.

(g) This amendment becomes effective on April 22, 1996.

Issued in Burlington, Massachusetts, on January 24, 1996.

Jay J. Pardee,
 Manager, Engine and Propeller Directorate,
 Aircraft Certification Service.

[FR Doc. 96-2589 Filed 2-21-96; 8:45 am]
BILLING CODE 4910-13-P

14 CFR Part 39

[Docket No. 95-CE-32-AD; Amendment 39-9510; AD 96-03-13]

Airworthiness Directives; Beech Aircraft Corporation 90, 99, 100, and 200 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that applies to Beech Aircraft Corporation (Beech) 90, 99, 100, and 200 series airplanes. This action requires inspecting the main landing gear drag leg lock link to ensure that the hole for the roll pin is drilled completely through both walls of the main landing gear drag leg lock link and, if not drilled completely through both link walls, replacing any main landing gear drag leg lock link. An incident in which the left main landing gear collapsed on one of the affected airplanes prompted this action. Investigation revealed that the roll pin hole was not completely drilled

through both walls of the drag leg lock link. The actions specified by this AD are intended to prevent main landing gear collapse caused by drag leg lock link failure, which could result in loss of control of the airplane.

DATES: Effective April 1, 1996.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of April 1, 1996.

ADDRESSES: Service information that applies to this AD may be obtained from Beech Aircraft Corporation, P.O. Box 85, Wichita, Kansas 67201-0085. This information may also be examined at the Federal Aviation Administration (FAA), Central Region, Office of the Assistant Chief Counsel, Attention: Rules Docket 95-CE-32-AD, room 1558, 601 E. 12th Street, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Mr. Steve Potter, Aerospace Engineer, Wichita Aircraft Certification Office, FAA, 1801 Airport Road, Mid-Continent Airport, Wichita, Kansas 67209; telephone (316) 946-4124; facsimile (316) 946-4407.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to Beech Aircraft Corporation 90, 99, 100, and 200 series airplanes was published in the Federal Register on August 16, 1995 (60 FR 42479). The action proposed to require inspecting the main landing gear drag leg lock link to ensure that the hole for the roll pin is drilled through both walls of the link and, if not drilled completely through both link walls, replacing any main landing gear drag leg lock link. Accomplishment of the proposed action would be in accordance with Beech Service Bulletin No. 2607, Revision 1, dated April 1995.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposed rule or the FAA's determination of the cost to the public.

After careful review of all available information related to the subject presented above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed except for minor editorial corrections. The FAA has determined that these minor corrections will not change the meaning of the AD and will not add any additional burden upon the public than was already proposed.

The FAA estimates that 2,229 airplanes in the U.S. registry will be affected by this AD action, that it will take approximately 5 work hours per airplane to accomplish this action, and that the average labor rate is approximately \$60 an hour. Parts cost approximately \$100 per airplane. Based on these figures, the total cost impact of this AD on U.S. operators is estimated to be \$891,600. This figure is based on the assumption that all of the affected airplanes have incorrectly drilled drag leg lock links and that none of the owners/operators of the affected airplanes have replaced the incorrectly drilled links.

Beech has informed the FAA that parts have been distributed to equip approximately 648 airplanes. Assuming that these distributed parts are incorporated on the affected airplanes, the cost of the proposed AD would be reduced by \$259,200 from \$891,600 to \$632,400. In addition, the FAA believes that a majority of the affected airplanes will not have incorrectly drilled links, thereby further reducing the cost impact of the proposed AD upon the public.

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the final evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the

Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:
Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive (AD) to read as follows:

AD No.96-03-13 Beech Aircraft Corporation: Amendment 39-9510; Docket No. 95-CE-32-AD.

Applicability: The following airplane models and serial numbers, certificated in any category:

Models	Serial Numbers
F90	LA-2 through LA-236.
99, 99A, A99A, B99, and C99.	U-1 through U-239.
100 and A100	B-1 through B-94 and B-100 through B-247.
B100	BE-1 through BE-137.
200 and B200	BB-2, BB-6 through BB-1157, BB-1159 through BB-1166, and BB-1168 through BB-1192.
200T and B200T	BT-1 through BT-30.
200C and B200C	BL-1 through BL-72.
200CT and B200CT ..	BN-1 through BN-4.
65-A90-2(RU-21B) ..	LS-1 through LS-3.
65-A90-3(RU-21C) ..	LT-1 through LT-2.
200 (A100-1)	BB-3 through BB-5.
A100 (U-21F)	B-95 through B-99.
A200 (C-12A and C-12C).	BC-1 through BC-75, and BD-1 through BD-30.
A200C (UC-12B)	BJ-1 through BJ-66.
A200CT (C-12D)	BP-1, BP-22, and BP-24 through BP-45.
A200CT (FWC-12D) .	BP-7 through BP-11.
A200CT (RC-12D)	GR-1 through GR-13.
A200CT (RC-12H)	GR-14 through GR-19.
A200CT (RC-12G) ...	FC-1 through FC-3.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not

been eliminated, the request should include specific proposed actions to address it.

Compliance: Required within the next 100 hours time-in-service (TIS) after the effective date of this AD, unless already accomplished.

To prevent main landing gear collapse caused by drag leg lock link failure, which could result in loss of control of the airplane, accomplish the following:

(a) Inspect the main landing gear drag leg lock link to ensure that the hole for the roll pin is drilled completely through both walls of the link in accordance with the ACCOMPLISHMENT INSTRUCTIONS section of Beech Service Bulletin No. 2607, Revision 1, dated April 1995.

(b) Prior to further flight, replace any drag leg lock link that does not have the roll pin hole drilled through both walls of the link. Accomplish this replacement in accordance with the applicable maintenance manual.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) An alternative method of compliance or adjustment of the compliance time that provides an equivalent level of safety may be approved by the Manager, Wichita Aircraft Certification Office, FAA, 1801 Airport Road, Mid-Continent Airport, Wichita, Kansas 67209. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Wichita Aircraft Certification Office.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Wichita Aircraft Certification Office.

(e) The inspections and replacements required by this AD shall be done in accordance with Beech Service Bulletin No. 2607, Revision 1, dated April 1995. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Beech Aircraft Corporation, P.O. Box 85, Wichita, Kansas 67201-0085. Copies may be inspected at the FAA, Central Region, Office of the Assistant Chief Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW., 7th Floor, suite 700, Washington, DC.

(f) This amendment (39-9510) becomes effective on April 1, 1996.

Issued in Kansas City, Missouri, on January 31, 1996.

Michael Gallagher,
Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 96-2588 Filed 2-21-96; 8:45 am]

BILLING CODE 4910-13-P

14 CFR Part 39

[Docket No. 93-CE-02-AD; Amendment 39-9509; AD 96-03-12]

Airworthiness Directives; Glasflugel Model Mosquito Sailplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that applies to Glasflugel Model Mosquito sailplanes. This action requires modifying the mounting studs on the lifting/tilting frame of the canopy system, repetitively inspecting the mounting stud, and incorporating flight manual revisions that specify a warning on emergency canopy deployment failure. Canopy system problems discovered during routine checks and periodic inspections of these sailplanes prompted the proposed action. The actions specified in this proposed AD are intended to prevent canopy system failure, which could result in loss of control of the sailplane.

DATES: Effective April 1, 1996.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of April 1, 1996.

ADDRESSES: Service information that applies to this AD may be obtained from Glasflugel c/o Hansjorg Streifeneder, Glasfaser-Flugzeug Service, Hofener Weg, D 72582 Grabenstetten, Germany, telephone number 49.73.82.10.32. This information may also be examined at the Federal Aviation Administration (FAA), Central Region, Office of the Assistant Chief Counsel, Attention: Rules Docket 93-CE-02-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Mr. Herman C. Belderok, Project Officer, Sailplanes, Small Airplane Directorate, Aircraft Certification Service, FAA, 1201 Walnut, suite 900, Kansas City, Missouri 64106; telephone (816) 426-6932; facsimile (816) 426-2169.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that applies to Glasflugel Model Mosquito sailplanes was published in the Federal Register on September 15, 1995 (60 FR 47899). This action proposed to require the following:

- Inspecting the mounting studs on the canopy lifting/tilting frame for wear,

repetitively inspecting the mounting stud every 100 hours time-in-service (TIS) thereafter,

- Measuring the diameter of the mounting stud, and if it is less than 5 mm (0.2 inch) increasing the diameter to 6 mm (0.24 inch) and,

- Incorporating a change to the Mosquito flight manual on page 19, paragraph 3.3 by inserting the following language:

“Whenever the canopy emergency jettison knob is pulled and prior to each flight, if no locking thread is used, it should be ensured that the Pip pins are fully pushed home, so that the locking balls are clear of and behind their fittings.”

Initially, the compliance time of this AD is in calendar time instead of hours time-in-service (TIS). The average monthly usage of the affected sailplanes ranges throughout the fleet. For example, one owner may operate the sailplane 25 hours in one week, while another operator may operate the sailplane 25 hours in one year. For this reason, the FAA has determined that, in order to ensure that all of the owners/operators of the affected sailplanes initially inspect the canopy system and incorporate the flight manual revisions within a reasonable amount of time, a calendar compliance time is imposed.

Accomplishment of these actions will be in accordance with Glasflugel Technical Note (TN) 303-18, dated March 1, 1991.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposed rule or the FAA's determination of the cost to the public.

After careful review of all available information related to the subject presented above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed except for minor editorial corrections. The FAA has determined that these minor corrections will not change the meaning of the AD and will not add any additional burden upon the public than was already proposed.

The FAA estimates that 40 sailplanes in the U.S. registry will be affected by this AD, that it will take approximately 2 workhours per sailplane to accomplish this action, and that the average labor rate is approximately \$60 an hour. Parts cost approximately \$10 per sailplane. Based on these figures, the total cost impact of this AD on U.S. operators is estimated to be \$5,200. This figure is based on the assumption that no affected owner/operator of the affected sailplanes has incorporated the