

alternative method of compliance in accordance with paragraph (f) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated in the body of this AD, unless already accomplished.

To prevent failure of the aileron mass balance attachment, which could result in loss of control of the airplane, accomplish the following:

(a) Prior to the first flight of each day after the effective date of this AD (see NOTE 2 of this AD), inspect the attachment of the aileron mass balance clamp unit for looseness in accordance with the "Inspection" section of Britten-Norman Service Bulletin (SB) No. BN-2/SB.67, Issue 1, dated October 24, 1973.

Note 2: The "prior to first flight of each day after the effective date of this AD" compliance time required by paragraph (a) of this AD is exactly the same as required by AD 75-26-15 (superseded by this AD).

(b) If a loose attachment of the aileron mass balance clamp unit is found during any of the inspections required by this AD, prior to further flight, modify the aileron and mass balance clamp unit in accordance with the "b. Sequence of Operations" section of Britten-Norman SB No. BN-2/SB.67, Issue 1, dated October 24, 1973.

(c) Within the next 1,000 hours time-in-service after the effective date of this AD, unless already accomplished as specified and required by paragraph (b) of this AD, modify the aileron and mass balance clamp unit in accordance with the "b. Sequence of Operations" section of Britten-Norman SB No. BN-2/SB.67, Issue 1, dated October 24, 1973.

(d) Accomplishing the modification required by paragraph (b) or (c) of this AD is considered terminating action for the repetitive inspection requirement of this AD.

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(f) An alternative method of compliance or adjustment of the initial or repetitive compliance times that provides an equivalent level of safety may be approved by the Manager, Brussels Aircraft Certification Division, Europe, Africa, Middle East office, FAA, c/o American Embassy, 1000 Brussels, Belgium. The request should be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Brussels Aircraft Certification Division. Alternative methods of compliance approved in accordance with AD 75-26-15 (superseded by this action) are not considered approved as alternative methods of compliance with this AD.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Brussels Aircraft Certification Division.

(g) The inspections and modification required by this AD shall be done in accordance with Britten-Norman Service Bulletin No. BN-2/SB.67, Issue 1, dated October 24, 1973. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Pilatus Britten-Norman Limited, Bembridge, Isle of Wight, United Kingdom PO35 5PR. Copies may be inspected at the FAA, Central Region, Office of the Assistant Chief Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(h) This amendment (39-9748) supersedes AD 75-26-15, Amendment 39-2464.

(i) This amendment (39-9748) becomes effective on October 25, 1996.

Issued in Kansas City, Missouri, on August 29, 1996.

Henry A. Armstrong,

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 96-22687 Filed 9-5-96; 8:45 am]

BILLING CODE 4910-13-P

#### 14 CFR Part 39

[Docket No. 91-ANE-29; Amendment 39-9470; AD 91-21-01 R1]

RIN 2120-AA64

#### Airworthiness Directives; Textron Lycoming Model TIO-540-S1AD Reciprocating Engines

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule; correction.

**SUMMARY:** This document makes a correction to Airworthiness Directive (AD) 91-21-01 R1 applicable to Textron Lycoming Model TIO-540-S1AD reciprocating engines that was published in the Federal Register on June 7, 1996 (61 FR 29003). The reference to the New York Aircraft Certification Office in Note 3 following the paragraph describing the procedure for obtaining an alternative method of compliance was omitted. This document corrects that omission. In all other respects, the original document remains the same.

**EFFECTIVE DATE:** September 6, 1996.

**FOR FURTHER INFORMATION CONTACT:** Richard Fiesel, Aerospace Engineer, New York Aircraft Certification Office, FAA, Engine and Propeller Directorate, 10 Fifth St., 3rd Floor, Valley Stream, NY 11581-1200; telephone (516) 256-7504, fax (516) 568-2716.

**SUPPLEMENTARY INFORMATION:** A final rule airworthiness directive applicable to Textron Lycoming Model TIO-540-S1AD reciprocating engines, was

published in the Federal Register on June 7, 1996 (61 FR 29003). The following correction is needed:

#### § 39.13 [Corrected]

On page 29005, in the first column, in the Compliance Section, in Note 3 of paragraph (c), in the fourth line, "obtained from." is corrected to read "obtained from the New York Aircraft Certification Office".

Issued in Burlington, MA, on August 28, 1996.

Jay J. Pardee,

*Manager, Engine and Propeller Directorate, Aircraft Certification Service.*

[FR Doc. 96-22773 Filed 9-5-96; 8:45 am]

BILLING CODE 4910-13-P

#### 14 CFR Part 71

[Airspace Docket No. 96-ASO-12]

#### Amendment to Class E Airspace; Tampa, FL

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment modifies the Class E airspace area at Tampa, FL, to accommodate a GPS RWY 18 Standard Instrument Approach Procedure (SIAP) for the Vandenberg Airport. Additional controlled airspace extending upward from 700 feet above the surface (AGL) is needed to accommodate this SIAP and for instrument flight rules (IFR) operations at the airport. The operating status of the airport will change from VFR to include IFR operations concurrent with publication of this SIAP.

**EFFECTIVE DATE:** 0901 UTC, December 5, 1996.

**FOR FURTHER INFORMATION CONTACT:** Benny L. McGlamery, System Management Branch, Air Traffic Division, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305-5570.

#### SUPPLEMENTARY INFORMATION:

##### History

On June 24, 1996, the FAA proposed to amend Part 71 of the Federal Aviation Regulations (14 CFR Part 71) by modifying Class E airspace at Tampa, FL (61 FR 32374). This action would provide adequate Class E airspace for IFR operations at the Vandenberg Airport.

Interested parties were invited to participate in this rulemaking proceeding by submitting written comments on the proposal to the FAA.