

the condition addressed by the proposed AD is unsafe while the airplane is in flight, the condition is not a result of repetitive airplane operation; the potential of the unsafe condition occurring is the same on the first flight as it is for subsequent flights. The proposed compliance time of "30 days after the effective date of this AD" would not inadvertently ground airplanes and would assure that all owners/operators of the affected airplanes accomplish the proposed action in a reasonable time period.

Cost Impact

None of the SIAI Marchetti S.r.l. Models SF600 and SF600A airplanes affected by the proposed AD are on the U.S. Register, and are therefore, not directly affected by the proposed AD. However, the FAA considers the proposed rule necessary to ensure that the unsafe condition is addressed in the event that any of these subject airplanes are imported and placed on the U.S. Register.

Should an affected airplane be imported and placed on the U.S. Register, it would take approximately 1 workhour per airplane to incorporate the proposed AFM amendment, at an average labor rate of approximately \$60 an hour. Since an owner/operator who holds at least a private pilot's certificate as authorized by sections 43.7 and 43.11 of the Federal Aviation Regulations (14 CFR 43.7 and 43.11) can accomplish the proposed action, the only cost impact upon the public is the time it would take the affected airplane owner/operator to amend the AFM.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this

action has been placed in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

Section 39.13 is amended by adding a new airworthiness directive (AD) to read as follows:

SIAI Marchetti S.R.1.: Docket No. 97-CE-26-AD.

Applicability: Models AF600 and SF600A airplanes, all serial numbers, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required within the next 30 days after the effective date of this AD, unless already accomplished.

To prevent loss of airplane control or engine overspeed with consequent loss of engine power caused by the power levers being positioned below the flight idle stop while the airplane is in flight, accomplish the following:

(a) Amend the Limitations Section of the airplane flight manual (AFM) by inserting the following language:

"Positioning of power levers below the flight idle stop while the airplane is in flight is prohibited. Such positioning may lead to loss of airplane control or may result in an overspeed condition and consequent loss of engine power."

(b) This action may be accomplished by incorporating a copy of this AD into the Limitations Section of the AFM.

(c) Amending the AFM, as required by this AD, may be performed by the owner/operator holding at least a private pilot certificate as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7), and must be entered into the aircraft records showing compliance with this AD in accordance with section 43.11 of the Federal Aviation Regulations (14 CFR 43.11).

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(e) An alternative method of compliance or adjustment of the compliance time that provides an equivalent level of safety may be approved by the Manager, Small Airplane Directorate, FAA, 1201 Walnut, Kansas City, Missouri 64106. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Small Airplane Directorate.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Small Airplane Directorate.

(f) Information related to this AD may be examined at the FAA, Central Region, Office of the Assistant Chief Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Issued in Kansas City, Missouri, on June 25, 1997.

James E. Jackson,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 97-17262 Filed 7-1-97; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 97-NM-39-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 767 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the superseding of an existing airworthiness directive (AD), applicable to certain Boeing Model 767 series airplanes, that currently requires an inspection to detect damage of the wire bundles in the left side of the flight compartment in the vicinity of the stowage box for the captain's oxygen mask, and repair, if necessary; a continuity check on repaired wires; installation of sleeving over the wire bundles; and rerouting of

the wire bundles. This action would require modifications of the captain's and first officer's consoles in the flight compartment to ensure adequate clearance between oxygen equipment and adjacent wire bundles. This proposal is prompted by reports indicating that chafed wiring and wire insulation wear occurred in the vicinity of the stowage box for the captain's oxygen mask due to interference between oxygen line fittings and adjacent wire bundles. The actions specified by the proposed AD are intended to prevent such chafing and inadequate clearance, which could result in electrical arcing and consequent oxygen leakage in the vicinity of the stowage box; these conditions, if not corrected, could result in a fire in the flight compartment.

DATES: Comments must be received by August 11, 1997.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 97-NM-39-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Susan Letcher, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington; telephone (425) 227-2670; fax (425) 227-1181.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic,

environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 97-NM-39-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 97-NM-39-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

On October 2, 1995, the FAA issued AD 95-21-05, amendment 39-9390 (60 FR 52844, October 11, 1995), applicable to certain Boeing Model 767 airplanes, to require a one-time inspection to detect damage of the wire bundles in the left side of the flight compartment in the vicinity of the stowage box for the captain's oxygen mask, and repair, if necessary; a continuity check on repaired wires; installation of sleeving over the wire bundles; and rerouting of the wire bundles. That action was prompted by reports of chafed wiring and minimal clearance between the oxygen connector and the adjacent wire bundles in the vicinity of the stowage box for the captain's oxygen mask. The requirements of that AD are intended to prevent such chafing and inadequate clearance, which could result in electrical arcing and consequent oxygen leakage in the vicinity of the stowage box; these conditions, if not corrected, could result in a fire in the flight compartment.

Actions Since Issuance of Previous Rule

In the preamble to AD 95-21-05, the FAA indicated that the actions required by that AD were considered "interim action" and that further rulemaking action was being considered. The FAA now has determined that further rulemaking action is indeed necessary, and this AD follows from that determination.

Additionally, since the issuance of that AD, a number of reports have been received that indicate interference

between oxygen line fittings on the stowage box for the captain's oxygen mask and adjacent wire bundles. This condition, if not corrected, could cause wires on the oxygen line fittings to chafe, which could lead to possible electrical arcing with the fitting, a hole in the fitting, and an oxygen leak; and result in an uncontrolled fire in the flight compartment.

Explanation of Relevant Service Information

The FAA has reviewed and approved Boeing Alert Service Bulletin 767-35A0029, dated January 30, 1997, which describes procedures for modifications of the captain's and first officer's consoles in the flight compartment to ensure adequate clearance between oxygen equipment and adjacent wire bundles. At the disconnect panel on the captain's console, modification includes rerouting wires and installing certain components. At the first officer's console, modification includes installing certain components, such as a 90-degree backshell on the electrical connector to the dimmer module and a new bracket assembly. Ensuring adequate clearance between the oxygen system components and adjacent wire bundles will reduce the potential for future wire chafing on the consoles in the flight compartment.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would supersede AD 95-21-05 to continue to require an inspection to detect damage of the wire bundles in the left side of the flight compartment in the vicinity of the stowage box for the captain's oxygen mask, and repair, if necessary; a continuity check on repaired wires; installation of sleeving over the wire bundles; and rerouting of the wire bundles. The proposed AD also would require modifications of the captain's and first officer's consoles in the flight compartment to ensure adequate clearance between oxygen equipment and adjacent wire bundles. The actions would be required to be accomplished in accordance with the alert service bulletin described previously.

Cost Impact

There are approximately 568 Boeing Model 767 series airplanes of the affected design in the worldwide fleet. The FAA estimates that 185 airplanes of U.S. registry would be affected by this proposed AD.

The actions that are currently required by AD 95-21-05 take approximately 3 work hours per airplane to accomplish, at an average labor rate of \$60 per work hour. Required parts cost approximately \$50 per airplane. Based on these figures, the cost impact of the currently required actions on U.S. operators is estimated to be \$42,550, or \$230 per airplane.

The new actions that are proposed in this AD action would take approximately 11 work hours per airplane to accomplish, at an average labor rate of \$60 per work hour. Required parts would cost approximately \$479 per airplane. Based on these figures, the cost impact of the proposed requirements of this AD on U.S. operators is estimated to be \$210,715, or \$1,139 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the current or proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation

Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing amendment 39-9390 (60 FR 52844, October 11, 1995), and by adding a new airworthiness directive (AD), to read as follows:

Boeing: Docket 97-NM-39-AD. Supersedes AD 95-21-05, Amendment 39-9390.

Applicability: Model 767 series airplanes, as listed in Boeing Alert Service Bulletin 767-35A0029, dated January 30, 1997; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent wire chafing and subsequent electrical arcing in the vicinity of the stowage box for the captain's oxygen mask, which could result in a fire in the flight compartment, accomplish the following:

Restatement of Requirements of AD 95-21-05

(a) For Model 767 series airplanes having line positions 2 through 589 inclusive except VA801 through VA810 inclusive, VN684 through VN691 inclusive, and VW701: Within 45 days after October 26, 1995 (the effective date of AD 95-21-05, amendment 39-9390), inspect to detect damage of the wire bundles in the left side of the flight compartment in the vicinity of the stowage box for the captain's oxygen mask, in accordance with Boeing Alert Service Bulletin 767-35A0028, dated September 7, 1995.

(1) If no damage is detected, prior to further flight, install protective sleeving on the wiring, and reroute the wire bundles, in accordance with the alert service bulletin.

(2) If any damage is detected, prior to further flight, accomplish the requirements of paragraphs (a)(2)(i) and (a)(2)(ii) of this AD.

(i) Repair the wiring and perform a continuity check on each repaired wire, in accordance with the alert service bulletin. And

(ii) Install protective sleeving on the wiring and reroute the wire bundles, in accordance with the alert service bulletin.

New Requirements of This AD

(b) For all airplanes: Within 18 months after the effective date of this AD, modify the airplane wiring in the vicinity of the captain's and first officer's consoles, in accordance with Boeing Alert Service Bulletin 767-35A0029, dated January 30, 1997. Accomplishment of this modification constitutes terminating action for the inspection requirements of this AD.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on June 26, 1997.

S.R. Miller,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 97-17285 Filed 7-1-97; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 96-ASO-20]

RIN 2120-AA66

Proposed Modification of Multiple Federal Airways, Jet Routes and Reporting Points; Florida

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This proposal would modify the airspace designation for several jet routes, Federal airways, and the Other Domestic Reporting Point "COVIA" in the State of Florida. This action is necessary due to the Tallahassee, FL, Very High Frequency Omnidirectional Range/Tactical Air Navigation Aids (VORTAC) being renamed Seminole, FL, VORTAC. As a result, the airspace designations associated with that navigational aid must be modified. The effective date to change the name of the