

producers. In addition, as producers implement improved cultural and thinning practices, the overall size of the prunes will get larger. As a result, producer returns would increase because producers will no longer be receiving \$40–50 per ton for the small-sized fruit at a \$260–270 per ton loss, but be receiving the higher prices paid for the larger sizes.

For the 1992–93 through the 1996–97 crop years, the season average price received by the producers ranged from a high of \$1,121 per ton to a low of \$838 per ton during the 1996–97 crop year. The season average price received by producers averaged about 60 percent of parity during the 1992–93 through 1996–97 crop years. Based on available data and estimates of prices, production, and other economic factors, the season average producer price for the 1997–98 and 1998–99 seasons is expected to be below \$800 per ton, or about 40 percent of parity.

The Committee discussed alternatives to this change, including making no changes to the undersized prune regulation and allowing market dynamics to foster prune inventory adjustments through lower prices on the smaller prunes. While reduced grower prices for small prunes are expected to contribute toward a slow reduction in dried prune inventories, the Committee believed that the undersized rule change was needed to expedite that reduction. With the excess tonnage of dried prunes, the Committee also considered establishing a reserve pool and diversion program to reduce the oversupply situation. These initiatives were not supported because they would not specifically eliminate the smallest, least valuable prunes which are in oversupply. Instead the reserve pool and diversion program would eliminate larger size prunes from human consumption outlets. Reserve pools for prunes have historically been implemented on dried prunes regardless of the size of the prunes. While the marketing order also allows handlers to remove the larger prunes from the pool by replacing them with small prunes and the value difference in cash, this exchange would be cumbersome and expensive to administer compared to the proposal.

Section 8e of the Act requires that when certain domestically produced commodities, including prunes, are regulated under a Federal marketing order, imports of that commodity must meet the same or comparable grade, size, quality, or maturity requirements for the domestically produced commodity. This action does not impact the dried prune import regulation

because the action to be implemented is for volume control, not quality control, purposes. The smaller diameter openings of 23/32 of an inch for French prunes and 28/32 of an inch for non-French prunes were implemented for the purpose of improving product quality. The recommended increases to 24/32 of an inch in diameter for French prunes and 30/32 of an inch in diameter for non-French prunes are for purposes of volume control. Therefore, the increased diameters would not be applied to imported prunes.

This action would not impose any additional reporting or recordkeeping requirements on either small or large California dried prune handlers. As with all Federal marketing order programs, reports and forms are periodically reviewed to reduce information requirements and duplication by industry and public sector agencies.

The Department has not identified any relevant Federal rules that duplicate, overlap, or conflict with this rule.

In addition, the Committee's meeting was widely publicized throughout the prune industry and all interested persons were invited to attend the meeting and participate in Committee deliberations on all issues. Like all Committee meetings, the November 18, 1997, meeting was a public meeting and all entities, both large and small, were able to express views on this issue. The Committee itself is composed of twenty-two members, of which seven are handlers, fourteen are producers, and one is a public member. The majority of the producer and handler members are small entities. Moreover, the Committee and its Supply Management Subcommittee have been reviewing this supply management problem for almost a year, and this proposed rule reflects their deliberations completely. Finally, interested persons are invited to submit information on the regulatory and informational impacts of this action on small businesses.

A 30-day comment period is provided to allow interested persons to respond to this proposal. Thirty days is deemed appropriate because this rule, if adopted, needs to be in place as soon as possible so that handlers and producers will be informed of any regulation for the 1998–99 crop year (beginning August 1, 1998). Producers would need time to thin prune-plums in order to obtain larger sizes. Producers generally begin thinning in late April. All written comments timely received will be considered before a final determination is made on this matter.

List of Subjects in 7 CFR Part 993

Marketing agreements, Plums, Prunes, Reporting and recordkeeping requirements.

For the reasons set forth in the preamble, 7 CFR part 993 is proposed to be amended as follows:

PART 993—DRIED PRUNES PRODUCED IN CALIFORNIA

1. The authority citation for 7 CFR part 993 continues to read as follows:

Authority: 7 U.S.C. 601–674.

2. A new § 993.405 is added to read as follows:

§ 993.405 Undersized prune regulation for the 1998–99 crop year.

Pursuant to §§ 993.49(c) and 993.52, an undersized prune regulation for the 1998–99 crop year is hereby established. Undersized prunes are prunes which pass through openings as follows: for French prunes, 24/32 of an inch in diameter; for non-French prunes, 30/32 of an inch in diameter.

Dated: February 17, 1998.

Robert C. Keeney,

Deputy Administrator, Fruit and Vegetable Programs.

[FR Doc. 98–4595 Filed 2–23–98; 8:45 am]

BILLING CODE 3410–02–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 96–NM–248–AD]

RIN 2120–AA64

Airworthiness Directives; Airbus Model A310 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Airbus Model A310 series airplanes. This proposal would require repetitive inspections of the fuselage skin to detect corrosion or fatigue cracking around and under the chafing plates of the wing root; and corrective actions, if necessary. This proposal is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by the proposed AD are intended to detect and correct fatigue cracks and corrosion around and under chafing plates of the wing root,

which could result in reduced structural integrity of the airplane.

DATES: Comments must be received by March 26, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 96-NM-248-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Norman B. Martenson, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 96-NM-248-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-1114, Attention: Rules Docket No. 96-NM-248-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The Direction Générale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, notified the FAA that an unsafe condition may exist on certain Airbus Model A310 series airplanes. The DGAC advises that it has received reports from operators of the presence of corrosion under the chafing plates and around the fasteners of the wing root between fuselage frames (FR) 36 and FR 39. Investigation revealed that the corrosion damage was due to moisture penetrating into the sealant between the fuselage skin and the stainless steel chafing plates. This corrosion damage is accelerated by the galvanic activity created by the aluminum skin and the stainless steel plates. If corrosion is present, the area is susceptible to fatigue cracking. Such corrosion and fatigue cracking, if not detected and corrected in a timely manner, could result in reduced structural integrity of the airplane.

Explanation of Relevant Service Information

Airbus has issued Service Bulletin A310-53-2069, Revision 1, dated September 19, 1995, which describes procedures for repetitive inspections to detect corrosion and fatigue cracking around and under the chafing plates of the wing root between fuselage FR 36 and FR 39; and corrective actions, if necessary.

Airbus has also issued Service Bulletin A310-53-2070, dated October 3, 1994, which describes procedures for replacement of the stainless steel chafing plates with new chafing plates made of aluminum alloy. Accomplishment of the replacement would eliminate the need for the repetitive inspections described in the previous service bulletin.

Accomplishment of the actions specified in these service bulletins is intended to adequately address the identified unsafe condition. The DGAC classified Airbus Service Bulletin A310-53-2069, Revision 1, dated September 19, 1995, as mandatory, and issued French airworthiness directive 96-008-175(B), dated January 3, 1996, in order to assure the continued airworthiness of these airplanes in France.

FAA's Conclusions

This airplane model is manufactured in France and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require accomplishment of the actions specified in Airbus Service Bulletin A310-52-2070 described previously, except as discussed below. The proposed AD also provides for an optional replacement, which would constitute terminating action for the repetitive inspection requirements.

Differences Between the Proposed AD and the Related Service Bulletin

Airbus Service Bulletin A310-52-2070 specifies that appropriate corrective action may be obtained by contacting the manufacturer, Airbus, directly. However, this proposed AD would require that any such repair be accomplished in accordance with a method approved by the FAA.

Cost Impact

The FAA estimates that 36 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 68 work hours per airplane to accomplish the proposed inspection, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$146,880, or \$4,080 per inspection cycle.

Should an operator elect to accomplish the optional terminating action rather than continue the repetitive inspections, it would take approximately 45 work hours per airplane to accomplish the modification, at an average labor rate of \$60 per work hour. Required parts would cost approximately \$2,229 per airplane. Based on these figures, the cost impact of this optional terminating action is estimated to be \$4,929 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Airbus Industrie: Docket 96–NM–248–AD.

Applicability: Model A310 series airplanes on which Airbus Modifications 8888 and 8889 have not been accomplished; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability

provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To detect and correct fatigue cracking and corrosion around and under chafing plates of the wing root between fuselage frames (FR) 36 and FR 39, which could result in reduced structural integrity of the airplane, accomplish the following:

(a) Except as provided by paragraph (b) of this AD: Within 4 years since date of manufacture, or within 12 months after the effective date of this AD, whichever occurs later, perform an inspection to detect discrepancies around and under the chafing plates of the wing root, in accordance with paragraph B. of the Accomplishment Instructions of Airbus Service Bulletin A310–53–2069, Revision 1, dated September 19, 1995. If any discrepancy is found, prior to further flight, accomplish follow-on corrective actions (i.e. removal of corrosion, corrosion protection, high frequency eddy current inspection, x-ray inspection) as applicable, in accordance with the service bulletin. Repeat the inspections, as applicable, thereafter, at intervals specified in the service bulletin.

(b) If any discrepancy is found as a result of an inspection required by paragraph (a) of this AD, and Airbus Service Bulletin A310–53–2069, Revision 1, dated September 19, 1995, specifies to contact Airbus for an appropriate action: Prior to further flight, repair in accordance with a method approved by the Manager, International Branch, ANM–116, FAA, Transport Airplane Directorate. Where differences in the compliance times or corrective actions exist between the service bulletin and this AD, the AD prevails.

(c) Accomplishment of the replacement of the chafing plates in accordance with Airbus Service Bulletin A310–53–2070, dated October 3, 1994, constitutes terminating action for the repetitive inspection requirement of this AD.

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM–116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM–116.

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199

of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 3: The subject of this AD is addressed in French airworthiness directive 96–008–175(B), dated January 3, 1996.

Issued in Renton, Washington, on February 12, 1998.

Gilbert L. Thompson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98–4249 Filed 2–23–98; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF THE INTERIOR

Office of Surface Mining Reclamation and Enforcement

30 CFR Part 931

[SPATS No. NM–038–FOR]

New Mexico Regulatory Program

AGENCY: Office of Surface Mining Reclamation and Enforcement, Interior.

ACTION: Proposed rule; public comment period and opportunity for public hearing on proposed amendment.

SUMMARY: Office of Surface Mining Reclamation and Enforcement (OSM) is announcing receipt of a proposed amendment to the New Mexico regulatory program (hereinafter, the "New Mexico program") under the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The proposed amendment consists of recodification of the New Mexico Surface Coal Mining Regulations. The amendment is intended to revise the New Mexico program to improve operational efficiency and assure that the New Mexico Surface Coal Mining Regulations are codified according to the New Mexico administrative procedures.

DATES: Written comments must be received by 4 p.m., m.s.t., March 26, 1998. If requested, a public hearing on the proposed amendment will be held on March 23, 1998. Requests to present oral testimony at the hearing must be received by 4 p.m., m.s.t. on March 11, 1998.

ADDRESSES: Written comments should be mailed or hand delivered to Willis Gainer at the address listed below.

Copies of the New Mexico program, the proposed amendment, and all written comments received in response to this document will be available for public review at the addresses listed below during normal business hours, Monday through Friday, excluding holidays. Each requester may receive