

period must be based upon the cask design requirements.

\* \* \* \* \*

(i) *Instrumentation and control systems.* Instrumentation and control systems for wet spent fuel storage must be provided to monitor systems that are important to safety over anticipated ranges for normal operation and off-normal operation. Those instruments and control systems that must remain operational under accident conditions must be identified in the Safety Analysis Report. Instrumentation systems for dry spent fuel storage casks must be provided in accordance with cask design requirements to monitor conditions that are important to safety over anticipated ranges for normal conditions and off-normal conditions. Systems that are required under accident conditions must be identified in the Safety Analysis Report.

\* \* \* \* \*

8. In § 72.124, paragraph (b) is revised to read as follows:

**§ 72.124 Criteria for nuclear criticality safety.**

\* \* \* \* \*

(b) *Methods of criticality control.* When practicable the design of an ISFSI or MRS must be based on favorable geometry, permanently fixed neutron absorbing materials (poisons), or both. Where solid neutron absorbing materials are used, the design must provide for positive means of verifying their continued efficacy. For dry spent fuel storage systems, the continued efficacy may be confirmed by a demonstration and analysis before use, showing that significant degradation of the neutron absorbing materials cannot occur over the life of the facility.

\* \* \* \* \*

9. In § 72.140, paragraph (d) is revised to read as follows:

**§ 72.140 Quality assurance requirements.**

\* \* \* \* \*

(d) *Previously approved programs.* A Commission-approved quality assurance program which satisfies the applicable criteria of Appendix B to Part 50 of this chapter and which is established, maintained, and executed with regard to an ISFSI will be accepted as satisfying the requirements of paragraph (b) of this section except that a licensee using an Appendix B quality assurance program also shall meet the requirement of § 72.174 for recordkeeping. Prior to initial use, the licensee shall notify the Director, Office of Nuclear Material Safety and Safeguards, U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, of its intent to apply its previously approved Appendix B

program to ISFSI activities. The licensee shall identify the program by date of submittal to the Commission, docket number, and date of Commission approval.

10. In § 72.216, paragraph (c) is revised to read as follows:

**§ 72.216 Reports.**

\* \* \* \* \*

(c) The general licensee shall make initial and written reports in accordance with §§ 72.74 and 72.75, except for the events specified by § 72.75(b)(2) and (3) for which the initial reports will be made under paragraph (a) of this section.

Dated at Rockville, Maryland, this 3rd day of June, 1998.

For the Nuclear Regulatory Commission.

**John C. Hoyle,**

*Secretary of the Commission.*

[FR Doc. 98-15265 Filed 6-8-98; 8:45 am]

BILLING CODE 7590-01-P

---

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

[Docket No. 98-CE-02-AD]

RIN 2120-AA64

**Airworthiness Directives; Alexander Schleicher**

**Segelflugzeugbau Models K 8 and K 8 B Sailplanes**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes to adopt a new airworthiness directive (AD) that would apply to all Alexander Schleicher Segelflugzeugbau (Alexander Schleicher) Models K 8 and K 8 B sailplanes. The proposed AD would require inspecting the canopy hood lock assembly to assure that the height of the cam is at least 2 millimeters (mm), and modifying or replacing any canopy hood lock assembly where the cam is less than 2 mm in height. The proposed AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Germany. The actions specified by the proposed AD are intended to prevent the canopy from coming open in flight because the height of the locking cam is less than 2 mm, which could result in loss of the canopy with consequent pilot injury.

**DATES:** Comments must be received on or before July 13, 1998.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-CE-02-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106. Comments may be inspected at this location between 8 a.m. and 4 p.m., Monday through Friday, holidays excepted.

Service information that applies to the proposed AD may be obtained from Alexander Schleicher Segelflugzeugbau, 6416 Poppenhausen, Wasserkuppe, Federal Republic of Germany. This information also may be examined at the Rules Docket at the address above.

**FOR FURTHER INFORMATION CONTACT:** Mike Kiesov, Project Officer, Sailplanes/Gliders, FAA, Small Airplane Directorate, Aircraft Certification Service, 1201 Walnut, suite 900, Kansas City, Missouri 64106; telephone: (816) 426-6934; facsimile: (816) 426-2169.

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 98-CE-02-AD." The postcard will be date stamped and returned to the commenter.

**Availability of NPRMs**

Any person may obtain a copy of this NPRM by submitting a request to the

FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-CE-02-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

### Discussion

The Luftfahrt-Bundesamt (LBA), which is the airworthiness authority for Germany, notified the FAA that an unsafe condition may exist on all Alexander Schleicher Models K 8 and K 8 B sailplanes. The LBA reports that the fabrication of the canopy lock cam may be incorrect. In particular, the height of the canopy locking cam may be less than 2 mm. If the height of the locking cam is not at least 2 mm, then the canopy may come open in flight.

This condition, if not corrected, could result in loss of the canopy with possible pilot injury.

### Relevant Service Information

Alexander Schleicher has issued Technical Note No. 21, dated May 12, 1980, which specifies procedures for (1) inspecting the canopy locking cam to assure that a height of at least 2 mm exists; and (2) modifying any canopy locking cam where the height is less than 2 mm.

The LBA classified this service bulletin as mandatory and issued German AD 80-158, dated June 16, 1980, in order to assure the continued airworthiness of these sailplanes in Germany.

### The FAA's Determination

This sailplane model is manufactured in Germany and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the LBA has kept the FAA informed of the situation described above.

The FAA has examined the findings of the LBA; reviewed all available information, including the service information referenced above; and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

### Explanation of the Provisions of the Proposed AD

Since an unsafe condition has been identified that is likely to exist or develop in other Alexander Schleicher Models K 8 and K 8 B sailplanes of the same type design registered in the United States, the FAA is proposing AD action. The proposed AD would require inspecting the canopy hood lock

assembly to assure that the height of the cam is at least 2 mm, and modifying or replacing any canopy hood lock assembly where the cam is less than 2 mm in height. Accomplishment of the proposed action would be in accordance with Alexander Schleicher Technical Note No. 21, dated May 12, 1980.

### Compliance Time of the Proposed AD

Although the canopy opening would only be unsafe during flight, the condition specified in the proposed AD is not a result of the number of times the sailplane is operated. The chance of this situation occurring is the same for a sailplane with 10 hours time-in-service (TIS) as it would be for a sailplane with 500 hours TIS. For this reason, the FAA has determined that a compliance based on calendar time should be utilized in this AD in order to assure that the unsafe condition is addressed on all sailplanes in a reasonable time period.

### Cost Impact

The FAA estimates that 100 sailplanes in the U.S. registry would be affected by the proposed AD, that it would take approximately 1 workhour per sailplane to accomplish the proposed inspection, and that the average labor rate is \$60 per work hour. No parts would be required to accomplish the modification. Parts would cost \$50 per sailplane if the replacement option is chosen over the modification. Based on these figures, the total cost impact of the proposed AD on U.S. operators is estimated to be \$11,000, or \$110 per sailplane if the replacement option is chosen; or \$6,000, or \$60 per sailplane if the modification option is chosen.

### Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft

regulatory evaluation prepared for this action has been placed in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

### The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive (AD) to read as follows:

**Alexander Schleicher Segelflugzeugbau:**  
Docket No. 98-CE-02-AD.

*Applicability:* Models K 8 and K 8 B sailplanes, all serial numbers, certificated in any category.

**Note 1:** This AD applies to each sailplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For sailplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

*Compliance:* Required as indicated in the body of this AD, unless already accomplished.

To prevent the canopy from coming open in flight because the height of the locking cam is less than 2 millimeters (mm), which could result in loss of the canopy with consequent pilot injury, accomplish the following:

(a) Within the next 3 calendar months after the effective date of this AD, inspect the canopy hood lock assembly to assure that the height of the cam is at least 2 mm, in accordance with Alexander Schleicher Technical Note No. 21, dated May 12, 1980.

(b) Prior to further flight after the inspection required by paragraph (a) of this AD, accomplish one of the following, if applicable:

(1) Modify (file) any canopy hood lock assembly where the cam is less than 2 mm

in height, in accordance with Alexander Schleicher Technical Note No. 21, dated May 12, 1980; and apply a corrosion preventative (alodine or equivalent substitute); or

(2) Replace any canopy hood lock assembly where the cam is less than 2 mm in height, in accordance with the applicable maintenance manual.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the sailplane to a location where the requirements of this AD can be accomplished.

(d) An alternative method of compliance or adjustment of the compliance time that provides an equivalent level of safety may be approved by the Manager, Manager, Small Airplane Directorate, Aircraft Certification Service, 1201 Walnut, suite 900, Kansas City, Missouri 64106. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Small Airplane Directorate.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Small Airplane Directorate.

(e) Questions or technical information related to Alexander Schleicher Technical Note No. 21, dated May 12, 1980, should be directed to Alexander Schleicher Segelflugzeugbau, 6416 Poppenhausen, Federal Republic of Germany; telephone: 49.6658.890 or 49.6658.8920; facsimile: 49.6658.8923 or 49.6658.8940. This service information may be examined at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

**Note 3:** The subject of this AD is addressed in German AD No. 80-158, dated June 16, 1980.

Issued in Kansas City, Missouri, on June 1, 1998.

**Ronald K. Rathgeber,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 98-15204 Filed 6-8-98; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 97-CE-111-AD]

RIN 2120-AA64

#### **Airworthiness Directives; Pilatus Britten-Norman Ltd. BN-2, BN-2A, BN-2B, and BN-2A MK.III Series Airplanes.**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes to adopt a new airworthiness directive

(AD) that would apply to certain Pilatus Britten-Norman Ltd. (PBN) BN-2, BN-2A, BN-2B, and BN-2A MK.III series airplanes that are equipped with a PBN Modification NB/M/256, 50A generator system. The proposed action would require inspecting the airplanes that are equipped with a 50A generator system for a 70A generator. If a 70A generator is installed, the proposed action would require replacing the 70A generator with a 50A generator, or (for the BN-2, BN-2A, and BN-2B series only) upgrading the airplane generator system to a 70A system to match the 70A generator. The proposed AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for the United Kingdom. The actions specified by the proposed AD are intended to prevent damage to the components of the electrical system, which could result in electrical system failure during critical phases of flight.

**DATES:** Comments must be received on or before July 17, 1998.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 97-CE-111-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106. Comments may be inspected at this location between 8 a.m. and 4 p.m., Monday through Friday, holidays excepted.

Service information that applies to the proposed AD may be obtained from Pilatus Britten-Norman, Ltd., Bembridge, Isle of Wight, United Kingdom, PO35 5PR. This information also may be examined at the Rules Docket at the address above.

**FOR FURTHER INFORMATION CONTACT:** Mr. Roger Chudy, Project Officer, FAA, Small Airplane Directorate, 1201 Walnut, suite 900, Kansas City, Missouri, 64106; telephone (816) 426-6932, facsimile (816) 426-2169.

#### **SUPPLEMENTARY INFORMATION:**

##### **Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 97-CE-111-AD." The postcard will be date stamped and returned to the commenter.

##### **Availability of NPRMs**

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 97-CE-111-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

##### **Discussion**

The Civil Airworthiness Authority (CAA), which is the airworthiness authority for the United Kingdom, notified the FAA that an unsafe condition may exist on certain PBN BN-2, BN-2A, BN-2B, and BN-2A MK.III series airplanes. The CAA reports that some operators have had 70A generators installed on 50A systems, which may damage the electrical system's components. The 50A generator system, which is known as PBN Modification NB/M/256, is not designed to work with a higher ampere generator.

These conditions, if not corrected, could result in damage to the electrical systems with consequent failure during critical phases of flight.

##### **Relevant Service Information**

PBN has issued Service Bulletin No. BN-2/SB.229, dated October 17, 1996, which specifies procedures for inspecting for a 70A generator on PBN BN-2, BN-2A, BN-2B, and BN-2A MK.III series airplanes that are equipped with PBN Modification NB/M/256 (a 50A generator system). If a 70A generator is installed, the service information specifies procedures for replacing the 70A generator with a 50A generator, or (for the BN-2, BN-2A, and BN-2B series only) installing PBN Modification NB/M/1148, which incorporates a 70A generator system.

The CAA classified this service bulletin as mandatory and issued British