

subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To detect and correct cracking in the false spar of the wing, which could result in reduced structural integrity of the wing, accomplish the following:

(a) Within 1,200 flight hours after the effective date of this AD, perform a detailed visual inspection for cracking in the false spar of the wing, on the left and right sides of the airplane, in accordance with CASA Product Support Document COM 212-224, dated November 28, 1990.

(1) If no cracking is detected, repeat the detailed visual inspection thereafter at intervals not to exceed 1,200 flight hours.

(2) If any cracking is detected, prior to further flight, repair in accordance with a method approved by either the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate; or the Dirección General de Aviación (DGAC), which is the airworthiness authority for Spain (or its delegated agent). Repeat the detailed visual inspection thereafter at intervals not to exceed 1,200 flight hours.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116. Operators shall submit their request through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) The inspections shall be done in accordance with CASA Product Support Document COM 212-224, dated November 28, 1990. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Construcciones Aeronauticas, S.A., Getafe, Madrid, Spain. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in Spanish airworthiness directive 02/96, dated May 13, 1996.

(e) This amendment becomes effective on July 15, 1998.

Issued in Renton, Washington, on June 3, 1998.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-15254 Filed 6-9-98; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-NM-53-AD; Amendment 39-10581; AD 98-12-27]

RIN 2120-AA64

Airworthiness Directives; British Aerospace BAe Model ATP Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain British Aerospace BAe Model ATP airplanes, that requires repetitive magnetic particle inspections to detect cracking of the splined operating shaft of the internal door handle on the forward passenger door, rear passenger door, and rear baggage door; and corrective actions, if necessary. This amendment is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by this AD are intended to detect and correct cracking of the splined operating shaft of the internal door handle, which could result in failure of the internal door handle, inability to operate the door during an emergency evacuation, and consequent injury to airplane occupants.

DATES: Effective July 15, 1998.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of July 15, 1998.

ADDRESSES: The service information referenced in this AD may be obtained from AI(R) American Support, Inc., 13850 Mclearen Road, Herndon, Virginia 20171. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the

Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain British Aerospace BAe Model ATP airplanes was published in the **Federal Register** on April 9, 1998 (63 FR 17342). That action proposed to require repetitive magnetic particle inspections to detect cracking of the splined operating shaft of the internal door handle on the forward passenger door, rear passenger door, and rear baggage door; and corrective actions, if necessary.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

Conclusion

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

The FAA estimates that 10 airplanes of U.S. registry will be affected by this AD, that it will take approximately 18 work hours per airplane to accomplish the required magnetic particle inspection, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the magnetic particle inspection required by this AD on U.S. operators is estimated to be \$10,800, or \$1,080 per airplane, per inspection cycle.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does

not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

98-12-27 British Aerospace Regional Aircraft [Formerly Jetstream Aircraft Limited; British Aerospace (Commercial Aircraft) Limited]: Amendment 39-10581. Docket 98-NM-53-AD.

Applicability: BAe Model ATP airplanes, constructor's numbers 2002 through 2067 inclusive; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To detect and correct cracking of the splined operating shaft of the internal door handle on the forward passenger door, rear passenger door, and rear baggage door, which could result in failure of the internal door handle, inability to operate the door during an emergency evacuation, and consequent injury to airplane occupants; accomplish the following:

(a) Prior to the accumulation of 2,000 flight cycles on the splined operating shaft of the internal door handle on the forward passenger door, rear passenger door, and rear baggage door; or within 60 days after the effective date of this AD; whichever occurs later: Accomplish either paragraph (a)(1) or (a)(2) of this AD.

(1) Perform a magnetic particle inspection to detect cracking of the splined operating shaft of the internal door handle on the forward passenger door, rear passenger door, and rear baggage door, in accordance with British Aerospace Regional Aircraft BAe ATP Alert Service Bulletin ATP-A52-30, dated March 19, 1997.

(i) If any crack is found, prior to further flight, accomplish the actions required by paragraph (a)(2).

(ii) If no crack is found, repeat the actions required by paragraph (a) of this AD at intervals not to exceed 1,000 flight cycles.

(2) Replace the existing splined operating shaft with a new splined operating shaft, in accordance with the alert service bulletin. Repeat the actions required by paragraph (a) of this AD within 2,000 flight cycles after the replacement, and thereafter at intervals not to exceed 1,000 flight cycles.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their request through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) The actions shall be done in accordance with British Aerospace Regional Aircraft BAe ATP Alert Service Bulletin ATP-A52-30, dated March 19, 1997. This incorporation by reference was approved by the Director of the **Federal Register** in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from AI(R) American Support, Inc., 13850 McLearn Road, Herndon, Virginia 20171. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the **Federal Register**, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in British airworthiness directive 004-03-97.

(e) This amendment becomes effective on July 15, 1998.

Issued in Renton, Washington, on June 3, 1998.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-15253 Filed 6-9-98; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-SW-10-AD; Amendment 39-10576; AD 98-12-22]

RIN 2120-AA64

Airworthiness Directives; Bell Helicopter Textron Canada Model 407 Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to Bell Helicopter Textron Canada (BHTC) Model 407 helicopters that requires shimming the tail rotor drive system bearing supports (bearing supports). This amendment is prompted by reports of cracked bearing hangar support arms in the area of the fillet radius. The actions specified by this AD are intended to prevent failure of the bearing supports, which could result in excessive tail rotor drive system vibration, loss of tail rotor drive, and subsequent loss of control of the helicopter.

DATES: Effective July 15, 1998.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of July 15, 1998.

ADDRESSES: The service information referenced in this AD may be obtained from Bell Helicopter Textron Canada, 12,800 Rue de l'Avenir, Mirabel, Quebec JON1LO, telephone (800) 463-3036, fax (514) 433-0272. This information may be examined at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Mr. Jurgen Priester, Aerospace Engineer, FAA, Rotorcraft Directorate, Rotorcraft Certification Office, 2601 Meacham