

certification; 14 CFR part 36, effective December 1, 1969, as amended by Amendment 36-1 through the amendment in effect on the day of certification; The Noise Control Act of 1972; and special conditions for Protection from High Intensity Radiated Fields (HIRF); exemptions, if any; equivalent level of safety findings, if any; and the special conditions adopted by this rulemaking action.

If the Administrator finds that the applicable airworthiness regulations (part 23) do not contain adequate or appropriate safety standards for the Model 3000 because of a novel or unusual design feature, special conditions are prescribed under the provisions of § 21.16.

In addition to the applicable airworthiness regulations and special conditions, the Model 3000 must comply with the fuel vent and exhaust emission requirements of 14 CFR part 34 and the noise certification requirements of 14 CFR part 36, and the FAA must issue a finding of regulatory adequacy pursuant to § 611 of Public Law 92-574, the "Noise Control Act of 1972."

Special conditions, as appropriate, are issued in accordance with § 11.49 after public notice, as required by §§ 11.28 and 11.29(b), and become part of the type certification basis in accordance with § 21.17(a)(2).

Special conditions are initially applicable to the model for which they are issued. Should the type certificate for that model be amended later to include any other model that incorporates the same novel or unusual design feature, the special conditions would also apply to the other model under the provisions of § 21.101(a)(1).

Novel or Unusual Design Features

The Model 3000 will incorporate the following novel or unusual design features:

Digital Electronic Engine Controls

The Model 3000 design includes a digital electronic engine/propeller control, known as a Power Management Unit (PMU). Although the precedent for electronic engine controls has been previously established, the PMU utilized on the Model 3000 performs functions not envisaged when part 23 was developed. With the Model 3000, the (Power Control Lever) PCL is a single lever, which has a mechanical and electrical interface to the PMU in order to produce "jet-like" thrust characteristics during rapid power changes and at low power conditions. PCL movement is transmitted to the PMU, which, in turn, controls fuel flow,

gas generator speed, and propeller speed. Propeller pitch is not pilot controllable; therefore, a separate propeller control lever is not supplied. During normal operation, propeller pitch is governed at 100 percent Np. Low airspeed and power combinations result in propeller pitch going to the mechanical low pitch stop (similar to a fixed-pitch propeller). During large power transitions below 100 percent Np (idle to takeoff power), the PMU will control propeller pitch. The PMU is utilized to control the thrust response of the engine-propeller combination and it prohibits operation of the engine-propeller combination in propeller RPM ranges with adverse vibration characteristics. There is no guidance in part 23 concerning the protection of the PMU from the indirect effects of lightning.

Suction Defuel Capability

The Model 3000 design includes a suction defuel capability not envisaged when part 23 was developed. It is understood that suction defuel is a common feature in part 25 airplanes. The Model 3000 airplane will have pressure fuel and defuel as well as gravity fuel and defuel capability. Pressure defueling essentially entails reversing the pumps on the fueling vehicle and "sucking" fuel from the airplane through the servicing port. Section 23.979 addresses pressure fueling but not suction defueling. Any suction defuel system components, in addition to meeting the general requirements for part 23 fuel systems, must also function as intended.

Applicability

As discussed above, these special conditions are applicable to the Model 3000. Should Raytheon Aircraft Company apply at a later date for a change to the type certificate to include another model incorporating the same novel or unusual design feature, the special conditions would apply to that model as well under the provisions of § 21.101(a)(1).

Conclusion

This action affects only certain novel or unusual design features on one model of airplanes. It is not a rule of general applicability, and it affects only the applicant who applied for the FAA for approval of these features on the airplane.

List of Subjects in 14 CFR Part 23

Aircraft, Aviation safety, Signs and symbols.

Citation

The authority citation for these special conditions is as follows:

Authority: 49 U.S.C. (106(g), 40113 and 44701; 14 CFR part 21, §§ 21.16 and 21.17; and 14 CFR part 11, §§ 11.28 and 11.29(b).

The Proposed Special Conditions

Accordingly, the Federal Aviation Administration (FAA) proposes the following special conditions as part of the type certification basis for Raytheon Aircraft Company Model 3000 airplanes.

1. Digital Electronic Engine/Propeller Control (PMU)

(a) Any failure of the Power Management Unit must be annunciated to the crew.

(b) Failures of the Power Management Unit that affect flight characteristics must be identified and evaluated, and appropriate flight manual procedures developed, including possible prohibitions on continued flight or dispatch.

(c) The functioning of the Power Management Unit must be protected to ensure that the control will continue to perform critical functions (functions whose failure condition would prevent continued safe flight and landing) after the aircraft is exposed to lightning.

2. Suction Defuel

(a) The airplane defueling system (not including fuel tanks and fuel tank vents) must withstand an ultimate load that is 2.0 times the load arising from the maximum permissible defueling pressure (positive or negative) at the airplane fueling connection.

Issued in Kansas City, Missouri on August 14, 1998.

Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-23006 Filed 8-26-98; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-NM-195-AD]

RIN 2120-AA64

Airworthiness Directives; Raytheon Model Hawker 800XP Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Raytheon Model Hawker 800XP series airplanes. This proposal would require replacement of the fuel feed hose assemblies of the auxiliary power unit (APU) with new hose assemblies. This proposal is prompted by a report of the collapse of the inner casing of the fuel feed hose that supplies fuel to the APU. The actions specified by the proposed AD are intended to prevent failure of the fuel feed hose assemblies, which could result in fuel leakage and consequent risk of fire in the aft equipment bay.

DATES: Comments must be received by October 13, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 98-NM-195-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Raytheon Aircraft Company, Manager Service Engineering, Hawker Customer Support Department, P.O. Box 85, Wichita, Kansas 67201-0085. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Small Airplane Directorate, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas.

FOR FURTHER INFORMATION CONTACT: Randy Griffith, Aerospace Engineer, Systems and Propulsion Branch, ACE-116W, FAA, Small Airplane Directorate, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas 67209; telephone (316) 946-4145; fax (316) 946-4407.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained

in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 98-NM-195-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 98-NM-195-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

During a functional test of the auxiliary power unit (APU) on a Model Hawker 800XP series airplane, conducted by the manufacturer, the APU shut down automatically. Investigation of the incident revealed that the inner casing of the fuel feed hose that supplies fuel to the APU had collapsed. The inner casing of the hose had adhered to the hose end fittings because of the lack of lubrication during hose manufacture. When the hose end fittings were torqued during installation on the airplane, the inner casing became twisted and collapsed. Further inspection of other Model Hawker 800XP series airplanes revealed additional hoses with a similar condition. Such collapse of the fuel feed hose, if not corrected, could result in fuel leakage and consequent increased risk of fire in the aft equipment bay.

Explanation of Relevant Service Information

The FAA has reviewed and approved Raytheon Service Bulletin SB.49-3018, dated August 1997, which describes procedures for replacement of the fuel feed hose assemblies of the auxiliary power unit (APU) with new hose assemblies. The service bulletin also describes the procedures (shutdown of APU and display of warning notices prohibiting use) to be used if replacement fuel feed hose assemblies

are not immediately available for installation. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require accomplishment of the actions specified in the service bulletin described previously.

Cost Impact

The FAA estimates that 11 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 5 work hours per airplane to accomplish the proposed replacement, and that the average labor rate is \$60 per work hour. Required parts would be provided by the manufacturer at no cost to the operator. Based on these figures, the cost impact of the replacement proposed by this AD on U.S. operators is estimated to be \$3,300, or \$300 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Raytheon Aircraft Company (Formerly Beech): Docket 98–NM–195–AD.

Applicability: Model Hawker 800XP series airplanes, serial numbers 258297 through 258304 inclusive, and 258307 through 258309 inclusive; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of the fuel feed hose assemblies, which could result in fuel leakage and consequent risk of fire in the aft equipment bay, accomplish the following:

(a) Within 300 flight hours or 3 months after the effective date of this AD, whichever occurs later, replace the fuel feed hose assemblies of the auxiliary power unit (APU) with new hose assemblies in accordance with Raytheon Aircraft Service Bulletin SB.49–3018, dated August 1997.

(b) If replacement fuel feed hose assemblies are not immediately available for installation, shut down the APU and display warning notices prohibiting use of the APU in accordance with Raytheon Aircraft Service Bulletin SB.49–3018, dated August 1997, until the replacement required by paragraph (a) of this AD is accomplished.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Wichita Aircraft Certification Office (ACO), FAA,

Small Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Wichita ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Wichita ACO.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on August 20, 1998.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 98–22962 Filed 8–26–98; 8:45 am]

BILLING CODE 4910–13–U

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 98–NM–161–AD]

RIN 2120–AA64

Airworthiness Directives; Aerospatiale Model SN 601 (Corvette) Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Aerospatiale Model SN 601 (Corvette) series airplanes. This proposal would require repetitive inspections to detect discrepancies of the upper and lower reinforcement panels and panel fasteners of the wing roots; and corrective actions, if necessary. This proposal is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by the proposed AD are intended to prevent debonding of the upper and lower reinforcement panels of the wing roots, which could result in reduced structural integrity of the wing.

DATES: Comments must be received by September 28, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM–114, Attention: Rules Docket No. 98–NM–161–AD, 1601 Lind Avenue, SW.,

Renton, Washington 98055–4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Aerospatiale, 316 Route de Bayonne, 31060 Toulouse, Cedex 03, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Norman B. Martenson, Manager, International Branch, ANM–116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055–4056; telephone (425) 227–2110; fax (425) 227–1149.

SUPPLEMENTARY INFORMATION:**Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA–public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: “Comments to Docket Number 98–NM–161–AD.” The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM–114, Attention: Rules Docket No. 98–NM–161–AD, 1601 Lind Avenue, SW., Renton, Washington 98055–4056.