

federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action has been placed in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive (AD) to read as follows:

S.N. Centrair: Docket No. 98-CE-50-AD.

Applicability: Models 101, 101A, 101P, and 101AP gliders, all serial numbers, certificated in any category; that have modification 101-24 (major cockpit configuration equipped on all gliders manufactured since 1990) incorporated, and do not have modification 101-21 (minor modifications to this cockpit configuration) incorporated.

Note 1: This AD applies to each glider identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For gliders that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required within the next 3 calendar months after the effective date of this AD, unless already accomplished.

To prevent elevator flight control interference caused by an unsecured battery discharge warning device, which could result in reduced or loss of glider control, accomplish the following:

(a) Secure an attachment lug (part number SY986A or an FAA-approved equivalent part number) to the battery discharge warning device on the glider bracket, in accordance with CENTRAIR Service Bulletin No. 101-19, Revision 1, dated May 20, 1997.

(b) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the glider to a location where the requirements of this AD can be accomplished.

(c) An alternative method of compliance or adjustment of the compliance time that provides an equivalent level of safety may be approved by the Manager, Small Airplane Directorate, Aircraft Certification Service, 1201 Walnut, suite 900, Kansas City, Missouri 64106. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Small Airplane Directorate.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Small Airplane Directorate.

(d) Questions or technical information related to CENTRAIR Service Bulletin No. 101-19, Revision 1, dated May 20, 1997, should be directed to S.N. CENTRAIR, Aerodome—36300 Le Blanc, France; telephone: 02.54.37.07.96; facsimile: 02.54.37.48.64. This service information may be examined at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Note 3: The subject of this AD is addressed in French AD 97-149(A), dated July 16, 1997.

Issued in Kansas City, Missouri, on December 29, 1998.

Marvin R. Nuss,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 99-46 Filed 1-4-99; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-CE-104-AD]

RIN 2120-AA64

Airworthiness Directives; Raytheon Aircraft Company Models C90A, B200, B200C, B200T, B200CT, 300, B300, B300C, and A200CT Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes to adopt a new airworthiness directive (AD) that would apply to certain Raytheon Aircraft Company (Raytheon) Models C90A, B200, B200C, B200T, B200CT, 300, B300, B300C, and A200CT airplanes. The proposed AD would require installing a filter element in the landing gear hand pump suction line. The proposed AD is the result of reports of the potential for debris to enter the landing gear hand pump and interfere with its operation, which could prevent the nose landing gear from being extended manually. Two occurrences were reported of nose landing gear collapse after manual extension. The actions specified by the proposed AD are intended to prevent the inability to extend the landing gear with the hand pump caused by debris entering the landing gear hand pump, which could result in passenger injury or damage to the airplane if manual operation of the landing gear failed.

DATES: Comments must be received on or before March 8, 1999.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-CE-104-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106. Comments may be inspected at this location between 8 a.m. and 4 p.m., Monday through Friday, holidays excepted.

Service information that applies to the proposed AD may be obtained from the Raytheon Aircraft Company, P.O. Box 85, Wichita, Kansas 67201-0085. This information also may be examined at the Rules Docket at the address above.

FOR FURTHER INFORMATION CONTACT: Mr. Paul DeVore, Aerospace Engineer, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Mid-Continent Airport, Wichita, Kansas 67209; telephone: (316) 946-4142; facsimile: (316) 946-4407.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 98-CE-104-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-CE-104-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Discussion

The FAA has received reports of the potential for debris to enter the landing gear hand pump and interfere with its operation on certain Raytheon Models C90A, B200, B200C, B200T, B200CT, 300, B300, B300C, and A200CT airplanes. This could prevent the nose landing gear from being properly extended manually. Two occurrences were reported of nose landing gear collapse after manual extension.

This condition, if not corrected in a timely manner, could result in the inability to extend the landing gear with the hand pump with consequent passenger injury or damage to the airplane if manual operation of the landing gear failed.

Relevant Service Information

Raytheon has issued Mandatory Service Bulletin SB 32-3073, Revision 1, Issued: March, 1998, Revised: July 1998. This service bulletin includes procedures for installing a filter element in the landing gear hand pump suction line.

The FAA's Determination

After examining the circumstances and reviewing all available information related to the incidents described above, the FAA has determined that AD action should be taken to prevent the inability to extend the landing gear with the hand pump caused by debris entering the landing gear hand pump. This could result in passenger injury or damage to the airplane if manual operation of the landing gear failed.

Explanation of the Provisions of the Proposed AD

Since an unsafe condition has been identified that is likely to exist or develop in other Raytheon Models C90A, B200, B200C, B200T, B200CT, 300, B300, B300C, and A200CT airplanes of the same type design, the FAA is proposing AD action. The proposed AD would require installing a filter element in the landing gear hand pump suction line. Accomplishment of the proposed action would be required in accordance with the service information previously referenced.

Cost Impact

The FAA estimates that 991 airplanes in the U.S. registry would be affected by the proposed AD, that it would take approximately 5 workhours per airplane to accomplish the proposed action, and that the average labor rate is approximately \$60 an hour. Raytheon will give warranty credit for parts until July 31, 1999. Based on these figures, the total cost impact of the proposed AD on U.S. operators is estimated to be \$297,300, or \$300 per airplane.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a

"significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action has been placed in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive (AD) to read as follows:

Raytheon Aircraft Company (All type certificates of the affected airplanes previously held by the Beech Aircraft Corporation): Docket No. 98-CE-104-AD.

Applicability: The following airplane models and serial numbers, certificated in any category:

Models	Serial Numbers
C90A	LJ-1063 through LJ-1482.
B200	BB-1158, BB-1167, BB-1193 through BB-1532, and all serial numbers with Beech Kit 101-8018 incorporated.
B200C	BL-113 through BL-117, BL-124 through BL-140, and all serial numbers with Beech Kit 101-8018 incorporated
B200T	BT-31 through BT-38, and all serial numbers with Beech Kit 101-8018 incorporated.
B200CT	BN-2, BN-3, and BN-4 that have Beech Kit 101-8018 incorporated.
B200CT	FG-1 and FG-2.
300	FA-1 through FA-230.
300	FF-1 through FF-19.
B300	FL-1 through FL-138.
B300C	FM-1 through FM-9.
B300C	FN-1.

Models	Serial Numbers
A200CT (C-12D).	BP-46 through BP-51.
A200CT (C-12F).	BP-52 through BP-63.
A200CT (RC-12H).	GR-14 through GR-19.
A200CT (RC-12K).	FE-1 through FE-9.
A200CT (RC-12N).	FE-10 through FE-24.
A200CT (RC-12P).	FE-25 through FE-31, FE-33, and FE-35.
A200CT (RC-12Q).	FE-32, FE-34, and FE-36.
B200C (C-12F).	BL-73 through BL-112 and BL-118 through BL-123.
B200C (C-12F).	BP-64 through BP-71.
B200C (UC-12F).	BU-1 through BU-10.
B200CT (RC-12F).	BU-11 and BU-12.
B200C (UC-12M).	BV-1 through BV-10.
B200C (RC-12M).	BV-11 and BV-12.
B200C (C-12R).	BW-1 through BW-19.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required within the next 200 hours time-in-service (TIS) after the effective date of this AD, unless already accomplished.

To prevent the inability to extend the landing gear with the hand pump caused by debris entering the landing gear hand pump, which could result in passenger injury or damage to the airplane if manual operation of the landing gear failed, accomplish the following:

(a) Install a filter element in the landing gear hand pump suction line, in accordance with the ACCOMPLISHMENT INSTRUCTIONS section of Raytheon Mandatory Service Bulletin SB 32-3073, Revision 1, Issued: March, 1998, Revised: July 1998.

(b) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(c) An alternative method of compliance or adjustment of the compliance time that provides an equivalent level of safety may be approved by the Manager, Wichita Aircraft Certification Office (ACO), 1801 Airport

Road, Room 100, Mid-Continent Airport, Wichita, Kansas 67209. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Wichita ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Wichita ACO.

(d) All persons affected by this directive may obtain copies of the document referred to herein upon request to the Raytheon Aircraft Company, P.O. Box 85, Wichita, Kansas 67201-0085; or may examine this document at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Issued in Kansas City, Missouri, on December 28, 1998.

Marvin R. Nuss,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 99-44 Filed 1-4-99; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-CE-98-AD]

RIN 2120-AA64

Airworthiness Directives; Alexander Schleicher Segelflugzeugbau Model ASH 26E Sailplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes to adopt a new airworthiness directive (AD) that would apply to all Alexander Schleicher Segelflugzeugbau (Alexander Schleicher) Model ASH 26E sailplanes. The proposed AD would require inspecting the red silicone tube of the rotor interior air cooling (just in front of the carburetor) for oil leaks and the heat damping layer of the lower exhaust damper fairing for oil contamination, and replacing the applicable parts where oil leakage or contamination is found. The proposed AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Germany. The actions specified by the proposed AD are intended to detect and correct any oil-contaminated exhaust damper fairing caused by oil leakage in the red silicone tube of the rotor interior air cooling, which could result in an exhaust fire and/or an explosion.

DATES: Comments must be received on or before February 11, 1999.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-CE-98-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106. Comments may be inspected at this location between 8 a.m. and 4 p.m., Monday through Friday, holidays excepted.

Service information that applies to the proposed AD may be obtained from Alexander Schleicher GmbH & Co., Segelflugzeugbau, Postfach 60, 36163 Poppenhausen, Germany; telephone: ++49 (0) 6658-890; facsimile: ++49 (0) 6658-8923. This information also may be examined at the Rules Docket at the address above.

FOR FURTHER INFORMATION CONTACT: Mr. Mike Kiesov, Aerospace Engineer, FAA, Small Airplane Directorate, 1201 Walnut, suite 900, Kansas City, Missouri 64106; telephone: (816) 426-6932; facsimile: (816) 426-2169.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 98-CE-98-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the