

In this notice, we are soliciting information on whether there are alternative requirements that would assure an adequate level of experience and knowledge to achieve the purposes of the regulations.

9. Should therapy sessions (i.e., interactive sessions involving a therapist or established programs that deal with mentally or physically handicapped persons) be excluded from or covered by regulation? Why do you consider therapy sessions different from or the same as other shallow water interactive programs? Should regulation of therapy sessions be based on the frequency of sessions at the facility or other criteria? If based on frequency, what should be the threshold for regulation?

Accordingly, effective April 2, 1999, in 9 CFR part 1, § 1.1, the definitions of *buffer area*, *interactive area*, *interactive session*, *sanctuary area*, and *swim-with-the dolphin (SWTD) program* are suspended, and, in 9 CFR part 3, § 3.111 is suspended.

Authority: 7 U.S.C. 2131–2159; 7 CFR 2.22, 2.80, and 371.2(g).

Done in Washington, DC, this 29th day of March 1999.

Craig A. Reed,

Administrator, Animal and Plant Health Inspection Service.

[FR Doc. 99–8153 Filed 4–1–99; 8:45 am]

BILLING CODE 3410–34–P

NUCLEAR REGULATORY COMMISSION

10 CFR PART 2

RIN 3150–AF88

Procedures Applicable to Proceedings for the Issuance of Licenses for the Receipt of High-Level Radioactive Waste at a Geologic Repository; Correction

AGENCY: Nuclear Regulatory Commission.

ACTION: Final rule; correction.

SUMMARY: This document corrects a final rule published in the **Federal Register** on December 30, 1998 (63 FR 71729), that amended the Nuclear Regulatory Commission's regulations on procedures applicable to proceedings for the issuance of licenses for the receipt of high-level radioactive waste at a geologic repository. The action is necessary to correct a typographical error.

EFFECTIVE DATE: May 3, 1999.

FOR FURTHER INFORMATION CONTACT: Kathryn L. Winsberg, U.S. Nuclear

Regulatory Commission, Washington, DC 20555, telephone (301) 415–1641, e-mail KLW@nrc.gov.

SUPPLEMENTARY INFORMATION:

§ 2.1006 [Corrected]

On page 71738, first column, in § 2.1006, the first sentence of paragraph (a), the reference to “§ 2.1003(c)” should be corrected to read “§ 2.1003(a)(4).”

Dated at Rockville, Maryland, this 26th day of March, 1999.

For the Nuclear Regulatory Commission.

Annette Vietti-Cook,

Secretary of the Commission.

[FR Doc. 99–8161 Filed 4–1–99; 8:45 am]

BILLING CODE 7590–01–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99–NM–38–AD; Amendment 39–11107; AD 99–08–03]

RIN 2120–AA64

Airworthiness Directives; Boeing Model 737–600, –700, and –800 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to all Boeing Model 737–600, –700, and –800 series airplanes. This action requires an inspection of the power distribution panels (PDP) to verify proper installation of the power feeder terminals and associated hardware, and corrective actions, if necessary. This action also requires repetitive torque checks of the terminal attachment screws. This amendment is prompted by reports indicating the loss of electrical power from the engine-driven generators or the auxiliary power unit due to overheating, melting, and subsequent failure of the power feeder terminals. The actions specified in this AD are intended to prevent such conditions, which could result in increased risk of fire and the loss of electrical power from the associated alternating current power source.

DATES: Effective April 19, 1999.

Comments for inclusion in the Rules Docket must be received on or before June 1, 1999.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport

Airplane Directorate, ANM–114, Attention: Rules Docket No. 99–NM–38–AD, 1601 Lind Avenue, SW., Renton, Washington 98055–4056.

Information pertaining to this amendment may be obtained from or examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT:

Stephen S. Oshiro, Aerospace Engineer, Systems and Equipment Branch, ANM–130S, FAA, Transport Airplane Directorate, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055–4056; telephone (425) 227–2793; fax (425) 227–1181.

SUPPLEMENTARY INFORMATION: The FAA has recently received several reports indicating the loss of electrical power from the engine-driven generators or the auxiliary power unit on Boeing Model 737 series airplanes, due to failure of the power feeder terminals located in power distribution panels (PDP) P91 and P92. This failure is attributed to an overheat condition caused by loosening of the screws that fasten the power feeder terminals to the PDP rigid bus assembly. Investigation revealed that inadequate support of the power feeder terminal allows movement of the terminal during the power feeder wire installation and removal procedures. The consequent loosening of the screws may result in increased electrical resistance and the generation of heat between the power feeder terminal and the rigid busbar at the terminal-to-busbar interface. This condition, if not corrected, may cause overheating and melting of the power feeder terminals, which could result in increased risk of fire and the loss of electrical power from the associated alternating current (AC) power source.

Explanation of the Requirements of the Rule

Since an unsafe condition has been identified that is likely to exist or develop on other Boeing Model 737–600, –700, and –800 series airplanes of the same type design, this AD is being issued to prevent overheating, melting, and subsequent failure of the power feeder terminals, which could result in increased risk of fire and the loss of electrical power from the associated AC power source. This AD requires an inspection of the PDP's to verify proper installation of the power feeder terminals and associated hardware, and corrective actions, if necessary. This action also requires repetitive torque checks of the terminal attachment screws.