

assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc. may be used. Surface cleaning and elaborate access procedures may be required."

#### Terminating Action

(b) Except as specified in paragraph (c) of this AD, within 6,000 flight hours after the effective date of this AD, replace the existing bushings with new, staked bushings in the actuator fittings of the aileron trim tabs in accordance with Saab Service Bulletin 2000-57-011, dated October 1, 1998. Accomplishment of this replacement terminates the requirements of this AD.

#### Conditional Corrective Action

(c) If, during the accomplishment of the bushing installation inspection required by paragraph (a)(2) or the bushing replacement required by paragraph (b) of this AD, any radial play is detected between the small diameter flanged bushing and the fitting lug hole, and the radial play is 0.006 inch or less, prior to further flight, repair it in accordance with a method approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, or the Luftfartsverket (LFV) (or its delegated agent).

#### Alternative Methods of Compliance

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

**Note 3:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

#### Special Flight Permits

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

#### Incorporation by Reference

(f) Except as provided in paragraph (c) of this AD, the actions shall be done in accordance with Saab Service Bulletin 2000-57-011, dated October 1, 1998. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Saab Aircraft AB, SAAB Aircraft Product Support, S-581.88, Linköping, Sweden. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**Note 4:** The subject of this AD is addressed in Swedish airworthiness directive (SAD) 1-132, dated October 8, 1998.

(g) This amendment becomes effective on August 6, 1999.

Issued in Renton, Washington, on July 14, 1999.

**D.L. Riggins,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 99-18409 Filed 7-21-99; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 97-SW-59-AD; Amendment 39-11235; AD 99-15-14]

RIN 2120-AA64

#### Airworthiness Directives; Sikorsky Aircraft-Manufactured Model CH-54B Helicopters

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD), applicable to Sikorsky Aircraft-manufactured Model CH-54B helicopters, that requires initial and recurring inspections and rework or replacement, if necessary, of the second stage lower planetary plate (plate). This amendment is prompted by two reports of cracked plates that have been found during overhaul and inspections. The actions specified by this AD are intended to prevent failure of the main gearbox plate due to fatigue cracking, which could lead to failure of the main gearbox and subsequent loss of control of the helicopter.

**EFFECTIVE DATE:** August 26, 1999.

**FOR FURTHER INFORMATION CONTACT:** Uday Garadi, Aerospace Engineer, FAA, Rotorcraft Directorate, Rotorcraft Certification Office, Fort Worth, Texas 76193-0170, telephone (817) 222-5157, fax (817) 222-5959.

**SUPPLEMENTARY INFORMATION:** A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to Sikorsky Aircraft-manufactured Model CH-54B helicopters was published in the **Federal Register** on April 16, 1999 (64 FR 18835). That action proposed to require initial and recurring inspections, and rework or replacement, if necessary, of the plate.

Interested persons have been afforded an opportunity to participate in the

making of this amendment. No comments were received on the proposal or the FAA's determination of the cost to the public. The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

The FAA estimates that 4 helicopters of U.S. registry will be affected by this AD, that it will take approximately 8 work hours per helicopter to accomplish the borescope inspection, 1 work hour to inspect the main gearbox oil filter pack, 140 work hours to remove and replace the main gearbox assembly, if necessary, and 20 work hours to rework the plate, and that the average labor rate is \$60 per work hour. Required parts will cost approximately \$8,000 per helicopter. Based on these figures, the total cost impact of the AD on U.S. operators is estimated to be \$67,760; \$2,160 to accomplish the initial inspections and \$65,600 to replace the plate in the main gearbox assembly in all 4 helicopters, if necessary. Daily preflight inspections of the main gearbox oil filter pack will cost \$60 per helicopter for each day flight is conducted.

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the

Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

#### **PART 39—AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

##### **§ 39.13 [Amended]**

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

##### **AD 99-15-14 Blue Bird Helicopters:**

Amendment 39-11235. Docket No. 97-SW-59-AD.

**Applicability:** CH-54B helicopters with main gearbox second stage lower planetary plate (plate), part number (P/N) 6435-20516-101, installed, certificated in any category.

**Note 1:** This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent failure of the plate due to fatigue cracking, which could lead to failure of the main gearbox and subsequent loss of control of the helicopter, accomplish the following:


(a) For main gearbox assemblies containing plate, part number (P/N) 6435-20516-101, with 1,600 or more hours time-in-service (TIS):

**Note 2:** If the TIS hours of the plate is not known, use the main gearbox assembly's total operating time.

(1) Prior to the first flight of each day, inspect the main oil filter for magnesium contamination. If magnesium contamination is discovered, replace the main gearbox assembly.

(2) Within the next 100 hours TIS after the effective date of this AD, and thereafter at intervals not to exceed 200 hours TIS, conduct a borescope inspection of the plate for cracks in the area of the nine lightening holes (see Figure 1). If a crack is found, replace the plate with an airworthy plate. The plate, P/N 6435-20516-101, is part of the main gearbox second stage planetary set (P/N 6435-20514-041), which is a serialized matched set, and must be replaced as a set.

**BILLING CODE 4910-13-P**



Borecope Inspection of Second Stage  
Lower Planetary Plate Lightning Holes  
Figure 1

(b) At the next overhaul of the main gearbox assembly, inspect and rework the plate, P/N 6435-20516-101, as follows:

(1) Fluorescent magnetic particle inspect the plate per ASTM E1444 in circumferential and longitudinal directions using a wet continuous method. Pay particular attention

to the area around the nine 1.750-inch diameter lightening holes.

(2) If a crack is found, the plate is unairworthy. Replace it with an airworthy plate.


(3) If no crack is found, rework the plate as follows, ensuring that all plate surfaces are free of any crack, scratch, dent, or corrosion.

(i) Measuring from the center of each 1.750-inch diameter lightening hole, machine 0.015/0.020 inch from the radius of the hole (see Figure 2). Machined surface roughness shall not exceed 63 microinches AA rating.


**BILLING CODE 4910-13-P**

**Figure Notes**

1. Mask top and bottom areas to protect from liquid air-grit and shot peen.
2. Shaded area to be liquid air-grit blasted and shot peened includes plate top and bottom surfaces and I.D. of all lightening holes. Feather shot peened surface edges.
3. Use low-stress depth controlled impression-stamp with full fillet depth of no more than 0.003 inch.
4. Reworked machined surface roughness shall not exceed 63 microinches AA rating.



Identify Reworked Plates  
(See Figure Note 3)



Rework of Second Stage Lower Planetary Plate  
Figure 2

(ii) Apply a 0.030/0.050-inch radius on the top and bottom edge of each hole.

(4) Fluorescent magnetic particle inspect the reworked areas per ASTM E1444 in circumferential and longitudinal directions using a wet continuous method.

(5) If a crack is found, the plate is unairworthy. Replace it with an airworthy plate.

(6) If no crack is found, rework the plate as follows:

(i) Remove the protective finish from the specified areas on the top and bottom of the plate as follows:

(A) Mask the top and bottom of the plate leaving exposed a 3.20-inch minimum circumferential band centered on 13.75-inch diameter of plate (see Figure 2). Mask the area to protect the thrust washer and the surrounding areas from vapor blast.

(B) Using a vapor blast machine, remove the protective finish from the exposed circumferential band on the top and bottom of the plate. Use No. 220 aluminum oxide grit at a pressure of 80–90 pounds per square inch.

(ii) Shotpeen the specified areas on the plate by remasking the top and bottom of the plate leaving exposed the 3.20-inch minimum circumferential band centered on 13.75-inch diameter of the plate. Mask the area to protect the thrust washer and the surrounding areas from the shot peening process.

(iii) Shotpeen the inside diameter of the lightening holes and the upper and lower surfaces of the plate in the 3.20-inch minimum circumferential band to 0.008 to 0.012A intensity, ensuring 200% coverage per MIL-S-13165C or latest revision. Use cast steel shot, size 170. Use a tracer dye inspection method.

**Note 3:** Overspray is permitted to allow a feathering application during the peening process from the peened surface to the non-peened surface.

(iv) Finish the reworked surfaces as follows:

(A) Clean the surfaces thoroughly with acetone (Fed. Spec O-A-51, or equivalent).

(B) Apply Presto black or blueing touchup solution to the reworked surfaces with cotton swabs. The solution temperature must be between 21° C and 49° C (70° F to 120° F). Keep the surfaces wet for about three minutes to get a uniform dark color.

(C) Rinse the surface in cold running water and dry with forced air.

**Note 4:** A hot water rinse may be used after the cold water rinse to speed up drying time.

(D) Using steel wool, Grade 00 or finer, rub the surfaces lightly. Polish with a soft cloth and then coat with a preservative oil (MIL-C-15074).

(v) Identify the reworked plate by stamping the number of this AD after the part number. Use a low-stress depth-controlled impression-stamp with full fillet depth of no more than 0.003 inch (see Figure 2). Marking must be such that it cannot be construed as part of the part number.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Rotorcraft

Certification Office, FAA, Rotorcraft Directorate. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Rotorcraft Certification Office.

Note 5: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Rotorcraft Certification Office.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

(e) This amendment becomes effective on August 26, 1999.

Issued in Fort Worth, Texas, on July 15, 1999.

**Henry A. Armstrong,**

*Manager, Rotorcraft Directorate, Aircraft Certification Service.*

[FR Doc. 99-18683 Filed 7-21-99; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Airspace Docket No. 99-AWS-08]

#### Revocation of Class D Airspace; Dallas NAS, Dallas, TX

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action revokes the Class D airspace area at Dallas Naval Air Station (NAS), Dallas, TX. This action is prompted by the closure of Dallas NAS. The United States Navy no longer requires use of the airspace. The intended effect of this action is to revoke the Class D airspace at Dallas NAS since it is no longer needed.

**EFFECTIVE DATES:** 0901 UTC, September 9, 1999.

**FOR FURTHER INFORMATION CONTACT:**

Donald J. Day, Airspace Branch, Air Traffic Division, Southwest Region, Federal Aviation Administration, Fort Worth, TX 76193-0520, telephone: 817-222-5593.

**SUPPLEMENTARY INFORMATION:**

#### History

On April 1, 1999, a proposal to amend 14 CFR Part 71 to revoke the Class D airspace at Dallas NAS, Dallas, TX, was published in the **Federal Register** (64 FR 15709). The proposal was to revoke the Class D airspace area at Dallas NAS, Dallas, TX. This action is prompted by the closure of Dallas NAS. The United

States Navy no longer requires use of the airspace. The intended effect of this proposed is to revoke the Class D airspace at Dallas NAS since it is no longer needed.

Interested parties were invited to participate in this rulemaking proceeding by submitting written comments on the proposal to the FAA. No comments to the proposal were received. The rule is adopted as proposed.

The coordinates for this airspace docket are based on North American Datum 83. Designated Class D airspace areas are published in paragraph 5000 of FAA Order 74000F, dated September 10, 1998, and effective September 16, 1998, which is incorporated by reference in 14 CFR 71.1. The Class D airspace designation listed in this document will be published subsequently in the order.

#### The Rule

This amendment to 14 CFR Part 71 revokes the Class D airspace at Dallas NAS, Dallas, TX.

The FAA has determined that this regulation only involves an established body of technical regulations that requires frequent and routine amendments to keep them operationally current. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only effect air traffic procedures and air navigation, it is certified that this rule will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

#### Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR Part 71 as follows:

#### PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D, AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS

1. The authority citation for 14 CFR Part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854; 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.