

accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Boeing: Docket 99-NM-248-AD.

Applicability: Model 747-400 series airplanes, having line numbers 696 through 1187 inclusive, certificated in any category; equipped with Honeywell inertial reference units (IRU).

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or

repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent loss of multiple IRU's in flight, which could result in the loss of navigation data, and compromise the ability of the flight crew to maintain the safe flight and landing of the airplane, accomplish the following:

Replacement

(a) Within 12 months after the effective date of this AD, remove the left, center, and right IRU's, and install modified IRU's, in accordance with Boeing Alert Service Bulletin 747-34A2638, Revision 1, dated April 8, 1999.

Note 2: Removal of existing left, center, and right IRU's and replacement with modified IRU's in accordance with Boeing Alert Service Bulletin 747-34A2638, dated January 29, 1999, is considered acceptable for compliance with paragraph (a) of this AD.

Spare

(b) As of the effective date of this AD, no person shall install an IRU having Boeing part number S242T101-110, S242T101-111, or S242T101-112, on any airplane.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Avionics Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on September 29, 1999.

D.L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 99-25935 Filed 10-5-99; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-NM-233-AD]

RIN 2120-AA64

Airworthiness Directives; Lockheed Model L-1011-385 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the superseding of an existing airworthiness directive (AD), applicable to certain Lockheed Model L-1011-385 series airplanes, that currently requires repetitive inspections to detect cracking of the canted pressure bulkhead at fuselage station (FS) 1212, and repetitive inspections to detect cracking of the web at the fastener rows of the vertical stiffener-to-web; and repair or replacement of the web with a new web, if necessary. This action would require that the initial inspections be accomplished at a reduced threshold. This proposal is prompted by a report of fatigue cracking of the canted pressure bulkhead at FS 1212. The actions specified by the proposed AD are intended to detect and correct fatigue cracking of the canted pressure bulkhead at FS 1212, which could result in blowout of a panel between adjacent stiffeners and consequent cabin depressurization.

DATES: Comments must be received by November 22, 1999.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-233-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Lockheed Martin Aircraft & Logistics Center, 120 Orion Street, Greenville, South Carolina 29605. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Small Airplane Directorate, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia.

FOR FURTHER INFORMATION CONTACT: Thomas Peters, Program Manager,

Program Management and Services Branch, ACE-118A, FAA, Small Airplane Directorate, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia 30349; telephone (770) 703-6063; fax (770) 703-6097.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 99-NM-233-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-233-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

On September 26, 1996, the FAA issued AD 96-20-10, amendment 39-9776 (61 FR 53044, October 10, 1996), applicable to certain Lockheed Model L-1011-385 series airplanes, to require inspections to detect cracking of the canted pressure bulkhead at fuselage station (FS) 1212, and inspections to detect cracking of the web at the fastener rows of the vertical stiffener-to-web; and repair or replacement of the web with a new web, if necessary. That action was prompted by a report of fatigue cracking of the canted pressure

bulkhead at FS 1212. The requirements of that AD are intended to detect and correct fatigue cracking of the canted pressure bulkhead at FS 1212, which could result in blowout of a panel between adjacent stiffeners and consequent cabin depressurization.

Actions Since Issuance of Previous Rule

Since the issuance of that AD, the FAA has received an additional report of fatigue cracking in the subject area on one of these airplanes. The airplane on which the cracking occurred had accumulated fewer flight cycles at the time the cracking was detected than the number of flight cycles specified as the inspection threshold in AD 96-20-10.

Explanation of Relevant Service Information

The FAA has reviewed and approved Lockheed L-1011 Service Bulletin 093-53-277, Revision 1, dated November 19, 1998, which describes procedures for repetitive detailed visual inspections to detect cracking of the entire aft surface of the canted pressure bulkhead at FS 1212 between left buttock line (LBL) 103 and right buttock line (RBL) 103, and repetitive optical inspections (i.e., using a borescope or mirror) to detect cracking of the web at the fastener rows of the vertical stiffener-to-web; and repair or replacement of the web with a new web, if necessary. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would supersede AD 96-20-10 to continue to require repetitive inspections to detect cracking of the canted pressure bulkhead at FS 1212, and repetitive inspections to detect cracking of the web at the fastener rows of the vertical stiffener-to-web; and repair or replacement of the web with a new web, if necessary. The proposed AD would require that the initial inspections be accomplished at a reduced threshold. The actions would be required to be accomplished in accordance with the service bulletin described previously.

Explanation of Changes Made to Requirements of AD 96-20-10

The FAA has restated the compliance time in terms of flight cycles, instead of landings. This is consistent with the compliance times stated in the service bulletin. In addition, the inspection identified in AD 96-20-10 as a "close

visual inspection" is identified in this proposed AD as a "detailed visual inspection." Furthermore, the FAA has added a note to the proposed AD to clarify the definition of a detailed visual inspection.

Cost Impact

There are approximately 235 airplanes of the affected design in the worldwide fleet. The FAA estimates that 116 airplanes of U.S. registry would be affected by this proposed AD. The requirements of this proposed AD would not add any new additional economic burden on affected operators, other than the costs that are associated with beginning the inspections at an earlier time than would have been required by AD 96-20-10 (initial inspection is now required within 18,000 flight cycles, rather than 20,000 flight cycles).

The inspections that are currently required by AD 96-20-10, and retained in this proposed AD, take approximately 5 work hours per airplane to accomplish, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the currently required actions on U.S. operators is estimated to be \$34,800, or \$300 per airplane, per inspection cycle.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the current or proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by

contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing amendment 39-9776 (61 FR 53044, October 10, 1996), and by adding a new airworthiness directive (AD), to read as follows:

Lockheed: Docket 99-NM-233-AD.

Supersedes AD 96-20-10, Amendment 39-9776.

Applicability: Model L-1011-385 series airplanes; serial numbers 1013 through 1250 inclusive; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c)(1) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To detect and correct fatigue cracking of the canted pressure bulkhead at fuselage station (FS) 1212, which could result in blowout of a panel between adjacent stiffeners and consequent cabin depressurization, accomplish the following:

Repetitive Inspections

(a) Perform a detailed visual inspection to detect cracking of the entire aft surface of the canted pressure bulkhead at FS 1212 between left buttock line (LBL) 103 and right buttock line (RBL) 103; and perform an optical inspection using a borescope or other optical device to detect cracking of the web at the fastener rows of the vertical stiffener-to-web; in accordance with Lockheed L-1011 Service Bulletin 093-53-277, dated July 2, 1996, or Revision 1, dated November 19, 1998; at the

earlier of the times specified in paragraphs (a)(1) and (a)(2) of this AD. Thereafter, repeat these inspections at intervals not to exceed 1,000 flight cycles.

(1) Prior to the accumulation of 20,000 total flight cycles, or within 60 days after October 25, 1996 (the effective date of AD 96-20-10), whichever occurs later; or

(2) Prior to the accumulation of 18,000 total flight cycles, or within 60 days after the effective date of this AD, whichever occurs later.

Note 2: For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

Repair

(b) If any cracking is found during any inspection required by paragraph (a) of this AD, prior to further flight, accomplish either paragraph (b)(1) or (b)(2) of this AD.

(1) Accomplish either paragraph (b)(1)(i) or (b)(1)(ii) of this AD, as applicable.

(i) If the cracking is found in an area that is specified in Lockheed Repair Drawing LCC-7622-385, repair in accordance with Lockheed L-1011 Service Bulletin 093-53-277, dated July 2, 1996, or Revision 1, dated November 19, 1998. Accomplishment of a repair constitutes terminating action for the repetitive inspections required by paragraph (a) of this AD at the repaired location only. Or

(ii) If the cracking is found in an area that is not specified in Lockheed Repair Drawing LCC-7622-385, repair in accordance with a method approved by the Manager, Atlanta Aircraft Certification Office (ACO), FAA, Small Airplane Directorate.

(2) Replace the entire web with a new web in accordance with Lockheed L-1011 Service Bulletin 093-53-277, dated July 2, 1996, or Revision 1, dated November 19, 1998. Such replacement constitutes terminating action for the repetitive inspections required by paragraph (a) of this AD.

Alternative Methods of Compliance

(c)(1) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Atlanta ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Atlanta ACO.

(c)(2) Alternative methods of compliance, approved previously in accordance with AD 96-20-10, amendment 39-9776, are approved as alternative methods of compliance with paragraph (b) of this AD.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Atlanta ACO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on September 29, 1999.

D.L. Riggan,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 99-25934 Filed 10-5-99; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-NM-221-AD]

RIN 2120-AA64

Airworthiness Directives; Lockheed Model L-1011-385 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Lockheed Model L-1011-385 series airplanes. This proposal would require modification of the high pressure bleed valve controller of each engine. This proposal is prompted by reports of failure of the bleed air system components such as the thermal compensators and bleed air ducts. The actions specified by the proposed AD are intended to prevent such failures of the bleed air system components, which could result in high temperature air leaking into the cabin and/or cargo areas and could possibly require an emergency landing and evacuation.

DATES: Comments must be received by November 22, 1999.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-221-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Lockheed Martin Aircraft & Logistics Center, 120 Orion Street, Greenville, South Carolina 29605. This information