

(for Model 767 series airplanes); or Boeing Service Bulletin 777-35-0005, dated September 3, 1998, including Appendix A (for Model 777 series airplanes); as applicable.

Note 2: For the purposes of this AD, a general visual inspection is defined as: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or drop-light, and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

Corrective Action

(b) If the oxygen mask is manufactured by Puritan-Bennett between May 1986 and July 1998 inclusive: Prior to further flight, replace the lanyards on the masks with new lanyards in accordance with Boeing Service Bulletins 737-35-1049, dated September 17, 1998, including Appendix A (for Model 737 series airplanes); 757-35-0014, dated September 10, 1998, including Appendix A (for Model 757 series airplanes); 767-35-0033, dated September 10, 1998, including Appendix A (for Model 767 series airplanes); or 777-35-0005, dated September 3, 1998, including Appendix A (for Model 777 series airplanes); as applicable.

Spare

(c) As of the effective date of this AD, no person shall install an oxygen mask manufactured by Puritan-Bennett between May 1986 and July 1998 inclusive, on any airplane, unless the lanyard has been replaced with a new lanyard in accordance with paragraph (b) of this AD.

Alternative Methods of Compliance

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(e) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on November 16, 1999.

D.L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 99-30368 Filed 11-19-99; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-NM-246-AD]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas MD-11 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain McDonnell Douglas MD-11 series airplanes. This proposal would require replacement of the upper and lower reading lights in the forward crew rest area with a redesigned light fixture. This proposal is prompted by reports of burning and smoldering blankets in the forward crew rest area due to a reading light fixture that came into contact with the blankets after the light was inadvertently left on. The actions specified by the proposed AD are intended to prevent a possible flammable condition, which could result in smoke and fire in the crew rest area.

DATES: Comments must be received by January 6, 2000.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-246-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Aircraft Group, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Technical Publications Business Administration, Dept. C1-L51 (2-60). This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Transport Airplane Directorate, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California.

FOR FURTHER INFORMATION CONTACT:

Albert Lam, Aerospace Engineer, Systems and Equipment Branch, ANM-130L, FAA, Transport Airplane Directorate, Los Angeles Aircraft

Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5346; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 99-NM-246-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-246-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The FAA has received reports indicating that burning and smoldering blankets were found in the forward crew rest area on McDonnell Douglas Model MD-11 series airplanes. Investigation revealed that a reading light fixture came into contact with the blankets after the light was inadvertently left on. This condition, if not corrected, could result in smoke and fire in the crew rest area.

Explanation of Relevant Service Information

The FAA has reviewed and approved McDonnell Douglas Alert Service Bulletin MD11-25A233, dated June 9, 1999, which describes procedures for

replacement of the upper and lower reading lights in the forward crew rest area with a redesigned light fixture. The redesigned light fixture allows a halogen light bulb with lower wattage to be recessed within the fixture to avoid any contact with combustible materials. Accomplishment of the action specified in the service bulletin is intended to adequately address the identified unsafe condition.

McDonnell Douglas Alert Service Bulletin MD11-25A233 refers to AIM Aviation Service Incorporated Service Bulletin AIM-MD11-25-2, Revision C, dated March 8, 1999; as an additional source of service information for accomplishment of the replacement.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require accomplishment of the action specified in the service bulletin described previously.

Cost Impact

There are approximately 71 airplanes of the affected design in the worldwide fleet. The FAA estimates that 14 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 1 work hour per airplane to accomplish the proposed replacement, and that the average labor rate is \$60 per work hour. Required parts would cost approximately \$238 per airplane. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$4,172, or \$298 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action"

under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

McDonnell Douglas: Docket 99-NM-246-AD.

Applicability: Model MD-11 series airplanes, as listed in McDonnell Douglas Alert Service Bulletin MD11-25A233, dated June 9, 1999; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent a possible flammable condition, which could result in smoke and fire in the crew rest area, accomplish the following:

Replacement

(a) Within 6 months after the effective date of this AD, replace the upper and lower reading lights in the forward crew rest area

with a redesigned light fixture, in accordance with McDonnell Douglas Alert Service Bulletin MD11-25A233, dated June 9, 1999.

Note 2: McDonnell Douglas Alert Service Bulletin MD11-25A233 refers to AIM Aviation Service Incorporated Service Bulletin AIM-MD11-25-2, Revision C, dated March 8, 1999; as an additional source of service information for accomplishment of the replacement of the upper and lower reading light in the forward crew rest area.

Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

Special Flight Permits

(c) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on November 16, 1999.

D.L. Riggan,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 99-30367 Filed 11-19-99; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 99-AAL-19]

Proposed Establishment of Class E Airspace; Scammon Bay, AK

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This action proposes to establish Class E airspace at Scammon Bay, AK. The establishment of Global Positioning System (GPS) instrument approach procedures at Scammon Bay Airport have made this action necessary. The Scammon Bay Airport status will change from Visual Flight Rules (VFR) to Instrument Flight Rules (IFR). Adoption of this proposal would result in adequate controlled airspace for aircraft flying IFR procedures at Scammon Bay, AK.

DATES: Comments must be received on or before January 6, 2000.