

required by this paragraph, the Manager's approval letter must specifically reference this AD.

#### Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

#### Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

#### Incorporation by Reference

(e) The inspections shall be done in accordance with British Aerospace Service Bulletin SB.53-152, dated October 8, 1998. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from British Aerospace Regional Aircraft American Support, 13850 Mclearen Road, Herndon, Virginia 20171. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**Note 3:** The subject of this AD is addressed in British airworthiness directive 015-10-98.

(f) This amendment becomes effective on February 1, 2000.

Issued in Renton, Washington, on December 1, 1999.

#### D.L. Riggin,

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 99-31676 Filed 12-27-99; 8:45 am]

**BILLING CODE 4910-13-U**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 99-CE-13-AD; Amendment 39-11479; AD 99-26-19]

RIN 2120-AA64

#### Airworthiness Directives; The New Piper Aircraft, Inc. J-2 Series Airplanes That Are Equipped With Wing Lift Struts

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD) that applies to certain The New Piper Aircraft, Inc. (Piper) J-2 series airplanes equipped with wing lift struts. This AD requires repetitively inspecting the wing lift struts for dents and corrosion and the wing lift strut forks for cracks; replacing any strut found with corrosion or dents, or forks with cracks; and repetitively replacing the wing lift strut forks. This AD also requires incorporating a "NO STEP" placard on the lift strut. This AD is the result of the Federal Aviation Administration (FAA) inadvertently omitting the J-2 series airplanes from the applicability of AD 99-01-05. The actions specified by this AD are intended to prevent in-flight separation of the wing from the airplane caused by wing lift struts with dents or corrosion or wing lift forks with cracks, which could result in loss of control of the airplane.

**DATES:** Effective February 14, 2000.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of February 14, 2000.

**ADDRESSES:** Service information that applies to this AD may be obtained from The New Piper Aircraft, Inc., Customer Services, 2926 Piper Drive, Vero Beach, Florida 32960. Copies of the instructions to the F. Atlee Dodge supplemental type certificate (STC) may be obtained from F. Atlee Dodge, Aircraft Services, Inc., P.O. Box 190409, Anchorage, Alaska 99519-0409. Copies of the instructions to the Jensen Aircraft STC's may be obtained from Jensen Aircraft, Inc., 9225 County Road 140, Salida, Colorado 81201. This information may also be examined at the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 99-CE-13-AD, 901 Locust, Room 506, Kansas City, Missouri 64106;

or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Mr. William O. Herderich, Aerospace Engineer, FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia 30349; telephone: (770) 703-6084; facsimile: (770) 703-6097.

#### SUPPLEMENTARY INFORMATION:

#### Events Leading to the Issuance of This AD

A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to certain Piper J-2 series airplanes of the same type design that are equipped with wing lift struts was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on July 12, 1999 (64 FR 37465). The NPRM proposed to require repetitively inspecting the wing lift struts for dents and corrosion and the wing lift strut forks for cracks; replacing any strut found with corrosion or dents, or forks with cracks; and repetitively replacing the wing lift strut forks. The NPRM also proposed to require installing a placard on the lift strut, and would provide the option of installing certain wing lift strut and wing lift strut fork assemblies, as terminating action for repetitive inspection and replacement requirements. Accomplishment of the proposed action as specified in the NPRM would be required in accordance with Piper Service bulletin No. 528D, dated October 19, 1990.

The NPRM was the result of the Federal Aviation Administration (FAA) inadvertently omitting the J-2 series airplanes from the applicability of AD 99-01-05.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposed rule or the FAA's determination of the cost to the public.

#### The FAA's Determination

After careful review of all available information related to the subject presented above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed except for minor editorial corrections. The FAA has determined that these minor corrections will not change the meaning of the AD and will not add any additional burden upon the public than was already proposed.

### Cost Impact

The FAA estimates that 91 airplanes in the U.S. registry will be affected by this AD.

It will take approximately 8 workhours per airplane to accomplish the initial inspection, and the average labor rate is approximately \$60 an hour. Based on these figures, the total cost impact of the initial inspection on U.S. operators is estimated to be \$43,680, or \$480 per airplane. These figures are based only on the cost of the initial inspection and do not take into account the costs of any repetitive inspections. The FAA has no way of determining how many repetitive inspections each owner/operator will incur over the life of the airplane.

It will take approximately 4 workhours per airplane to accomplish the initial wing lift strut fork replacements, and the average labor rate is approximately \$60 an hour. Fork assemblies cost approximately \$110 each and four are required for each airplane. Based on these figures, the total cost impact of the initial wing lift strut fork replacements on U.S. operators is estimated to be \$61,880, or \$680 per airplane.

Airplane operators who do not incorporate the improved design wing lift strut assemblies will have to repetitively replace the wing lift strut forks. The FAA has no way of determining how many airplanes do not have the improved design wing lift strut assemblies installed and will need repetitive strut fork replacements.

### Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the final evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### **§ 39.13 [Amended]**

2. Section 39.13 is amended by adding a new airworthiness directive (AD) to read as follows:

99-26-19 The New Piper Aircraft, Inc.:  
Amendment 39-11479; Docket No. 99-CE-13-AD.

**Applicability:** J-2 series airplanes, serial numbers 500 through 1975, certificated in any category; that are equipped with wing lift struts.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (f) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated in the body of this AD, unless already accomplished.

To prevent in-flight separation of the wing from the airplane caused by wing lift struts with dents or corrosion or wing lift forks with cracks, which could result in loss of control of the airplane, accomplish the following:

**Note 2:** The paragraph structure of this AD is as follows:

Level 1: (a), (b), (c), *etc.*

Level 2: (1), (2), (3), *etc.*

Level 3: (i), (ii), (iii), *etc.*

Level 4: (A), (B), (C), *etc.*

Level 2, Level 3, and Level 4 structures are designations of the Level 1 paragraph they immediately follow.

(a) Within 1 calendar month after the effective date of this AD or within 24 calendar months after the last inspection accomplished per AD 93-10-06, whichever occurs later, remove the wing lift struts in accordance with Piper Service Bulletin (SB)

No. 528D, and accomplish one of the following (the actions in either paragraph (a)(1), (a)(2), (a)(3), or (a)(4), including subparagraphs, of this AD):

(1) Inspect the wing lift struts for perceptible dents (as defined in the service bulletin referenced below) and corrosion in accordance with the "INSTRUCTIONS" section in part I of Piper SB No. 528D, dated October 19, 1990.

(i) If no perceptible dents are found in the wing lift strut and no corrosion is externally visible, prior to further flight, apply corrosion inhibitor to each strut in accordance with the SB referenced above. Reinspect the lift struts at intervals not to exceed 24 calendar months.

(ii) If a perceptible dent is found in the wing lift strut or external corrosion is found, prior to further flight, accomplish one of the installations (and subsequent actions presented in each paragraph) specified in paragraph (a)(3) or (a)(4) of this AD.

(2) Inspect the wing lift struts for corrosion in accordance with the Appendix to this AD. The inspection procedures in this Appendix must be accomplished by a Level 2 inspector certified using the guidelines established by the American Society for Non-destructive Testing, or MIL-STD-410.

(i) If no corrosion is found that is externally visible and all requirements in the Appendix to this AD are met, prior to further flight, apply corrosion inhibitor to each strut in accordance with the SB referenced above. Reinspect the lift struts at intervals not to exceed 24 calendar months.

(ii) If external corrosion is found or if any of the requirements in the Appendix of this AD are not met, prior to further flight, accomplish one of the installations (and subsequent actions presented in each paragraph) specified in paragraph (a)(3) or (a)(4) of this AD.

(3) Install original equipment manufacturer (OEM) part number wing struts (or FAA-approved equivalent part numbers) that have been inspected in accordance with the specifications presented in either paragraph (a)(1) or (a)(2) of this AD, and are found to be airworthy according to the inspection requirements included in these paragraphs. Thereafter, inspect these wing lift struts at intervals not to exceed 24 calendar months in accordance with the specifications presented in either paragraph (a)(1) or (a)(2) of this AD.

(4) Install new sealed wing lift strut assemblies, part numbers as specified in Piper SB No. 528D (or FAA-approved equivalent part numbers), on each wing as specified in the INSTRUCTIONS section in part II of the above-referenced SB. These sealed wing lift strut assemblies also include the wing lift strut forks. Installation of these assemblies constitutes terminating action for the inspection and replacement requirements of both paragraphs (a) and (b) of this AD.

(b) Within the next 100 hours time-in-service (TIS) after the effective date of this AD or within 500 hours TIS after the last inspection, whichever is later, remove the wing lift strut forks and accomplish one of the following (the actions in either paragraph (b)(1), (b)(2) or (b)(3); including subparagraphs, of this AD):

(1) Inspect the wing lift strut forks for cracks using FAA-approved magnetic particle procedures.

(i) If no cracks are found, reinspect at intervals not to exceed 500 hours TIS provided that the replacement requirements of paragraphs (b)(1)(ii)(B) and (b)(1)(ii)(C) of this AD have been met.

(ii) Replace the wing lift strut forks at whichever of the following is applicable:

(A) *If cracks are found on any wing lift strut fork:* Prior to further flight;

(B) *If the airplane is equipped with floats or has been equipped with floats within the last 2,000 hours TIS and no cracks are found during the above inspections:* Upon accumulating 1,000 hours TIS on the wing lift strut forks or within the next 100 hours TIS after the effective date of this AD, whichever occurs later; or

(C) *If the airplane has not been equipped with floats within the last 2,000 hours TIS and no cracks are found during the above inspections:* Upon accumulating 2,000 hours TIS on the wing lift strut forks or within the next 100 hours TIS after the effective date of this AD, whichever occurs later.

(iii) Replacement parts shall be of the same part numbers of the existing part (or FAA-approved equivalent part numbers) and shall be manufactured with rolled threads. Lift strut forks manufactured with machined (cut) threads shall not be utilized.

(iv) The 500-hour TIS interval repetitive inspections are still required when the above replacements are accomplished.

(2) Install new OEM part number wing lift strut forks (or FAA-approved equivalent part numbers). Reinspect and replace these wing lift strut forks at the intervals specified in paragraphs (b)(1)(i), (b)(1)(ii), (b)(1)(iii), and (b)(1)(iv), including all subparagraphs, of this AD.

(3) Install new sealed wing lift strut assemblies, part numbers as specified in Piper SB No. 528D (or FAA-approved equivalent part numbers), on each wing as specified in the INSTRUCTIONS section in part II of the above-referenced SB.

(i) This installation may have "already been accomplished" through the actions specified in paragraph (a)(4) of this AD.

(ii) No repetitive inspections are required after installing these sealed wing lift strut assemblies.

(c) If holes are drilled in wing lift strut assemblies installed in accordance with (a)(4) or (b)(3) of this AD to attach cuffs, door clips, or other hardware, inspect the wing lift struts at intervals not to exceed 24 calendar months using the procedures specified in paragraph (a)(1) or (a)(2), including all subparagraphs, of this AD.

(d) Within 1 calendar month after the effective date of this AD and thereafter prior to further flight after the installation of any lift strut assembly, accomplish one of the following:

(1) Install "NO STEP" decal, Piper part number (P/N) 80944-02, on each wing lift strut approximately 6 inches from the bottom of the struts in a way that the letters can be read when entering and exiting the aircraft; or

(2) Paint the statement "NO STEP" approximately 6 inches from the bottom of

the struts in a way that the letters can be read when entering and exiting the aircraft. Use a minimum of 1-inch letters utilizing a color that contrasts with the color of the airplane.

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(f) An alternative method of compliance or adjustment of the initial and repetitive compliance times that provides an equivalent level of safety may be approved by the Manager, FAA, Atlanta Aircraft Certification Office (ACO), One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia 30349. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Atlanta ACO.

**Note 3:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Atlanta ACO.

(g) The removals, inspections, modifications, and installations required by this AD shall be done in accordance with Piper Service Bulletin No. 528D, dated October 19, 1990. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from The New Piper Aircraft, Inc., Customer Services, 2926 Piper Drive, Vero Beach, Florida 32960. Copies may be inspected at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

#### **Appendix to Docket No. 99-CE-13-AD—Procedures and Requirements for Ultrasonic Inspection of Piper Wing Lift Struts**

##### **Equipment Requirements**

1. A portable ultrasonic thickness gauge or flaw detector with echo-to-echo digital thickness readout capable of reading to 0.001-inch and an A-trace waveform display will be needed to accomplish this inspection.

2. An ultrasonic probe with the following specifications will be needed to accomplish this inspection: 10 MHz (or higher), 0.283-inch (or smaller) diameter dual element or delay line transducer designed for thickness gauging. The transducer and ultrasonic system shall be capable of accurately measuring the thickness of AISI 4340 steel down to 0.020-inch. An accuracy of +/− 0.002-inch throughout a 0.020-inch to 0.050-inch thickness range while calibrating shall be the criteria for acceptance.

3. Either a precision machined step wedge made of 4340 steel (or similar steel with equivalent sound velocity) or at least three shim samples of same material will be needed to accomplish this inspection. One thickness of the step wedge or shim shall be less than or equal to 0.020-inch, one shall be greater than or equal to 0.050-inch, and at

least one other step or shim shall be between these two values.

4. Glycerin, light oil, or similar non-water based ultrasonic couplants are recommended in the setup and inspection procedures.

Water-based couplants, containing appropriate corrosion inhibitors, may be utilized, provided they are removed from both the reference standards and the test item after the inspection procedure is completed and adequate corrosion prevention steps are then taken to protect these items.

• **Note:** Couplant is defined as "a substance used between the face of the transducer and test surface to improve transmission of ultrasonic energy across the transducer/strut interface."

• **Note:** If surface roughness due to paint loss or corrosion is present, the surface should be sanded or polished smooth before testing to assure a consistent and smooth surface for making contact with the transducer. Care shall be taken to remove a minimal amount of structural material. Paint repairs may be necessary after the inspection to prevent further corrosion damage from occurring. Removal of surface irregularities will enhance the accuracy of the inspection technique.

##### **Instrument Setup**

1. Set up the ultrasonic equipment for thickness measurements as specified in the instrument's user's manual. Because of the variety of equipment available to perform ultrasonic thickness measurements, some modification to this general setup procedure may be necessary. However, the tolerance requirement of step 13 and the record keeping requirement of step 14, must be satisfied.

2. If battery power will be employed, check to see that the battery has been properly charged. The testing will take approximately two hours. Screen brightness and contrast should be set to match environmental conditions.

3. Verify that the instrument is set for the type of transducer being used, i.e. single or dual element, and that the frequency setting is compatible with the transducer.

4. If a removable delay line is used, remove it and place a drop of couplant between the transducer face and the delay line to assure good transmission of ultrasonic energy. Reassemble the delay line transducer and continue.

5. Program a velocity of 0.231-inch/microsecond into the ultrasonic unit unless an alternative instrument calibration procedure is used to set the sound velocity.

6. Obtain a step wedge or steel shims per item 3 of the **Equipment Requirements**. Place the probe on the thickest sample using couplant. Rotate the transducer slightly back and forth to "ring" the transducer to the sample. Adjust the delay and range settings to arrive at an A-trace signal display with the first backwall echo from the steel near the left side of the screen and the second backwall echo near the right of the screen. Note that when a single element transducer is used, the initial pulse and the delay line/steel interface will be off of the screen to the left. Adjust the gain to place the amplitude of the first backwall signal at approximately 80% screen height on the A-trace.

7. "Ring" the transducer on the thinnest step or shim using couplant. Select positive half-wave rectified, negative half-wave rectified, or filtered signal display to obtain the cleanest signal. Adjust the pulse voltage, pulse width, and damping to obtain the best signal resolution. These settings can vary from one transducer to another and are also user dependent.

8. Enable the thickness gate, and adjust the gate so that it starts at the first backwall echo and ends at the second backwall echo. (Measuring between the first and second backwall echoes will produce a measurement of the steel thickness that is not affected by the paint layer on the strut). If instability of the gate trigger occurs, adjust the gain, gate level, and/or damping to stabilize the thickness reading.

9. Check the digital display reading and if it does not agree with the known thickness of the thinnest thickness, follow your instrument's calibration recommendations to produce the correct thickness reading. When a single element transducer is used this will usually involve adjusting the fine delay setting.

10. Place the transducer on the thickest step of shim using couplant. Adjust the thickness gate width so that the gate is triggered by the second backwall reflection of the thick section. If the digital display does not agree with the thickest thickness, follow your instruments calibration recommendations to produce the correct thickness reading. A slight adjustment in the velocity may be necessary to get both the thinnest and the thickest reading correct. Document the changed velocity value.

11. Place couplant on an area of the lift strut which is thought to be free of corrosion and "ring" the transducer to surface. Minor adjustments to the signal and gate settings may be required to account for coupling improvements resulting from the paint layer. The thickness gate level should be set just high enough so as not to be triggered by irrelevant signal noise. An area on the upper surface of the lift strut above the inspection area would be a good location to complete this step and should produce a thickness reading between 0.034-inch and 0.041-inch.

12. Repeat steps 8, 9, 10, and 11 until both thick and thin shim measurements are within tolerance and the lift strut measurement is reasonable and steady.

13. Verify that the thickness value shown in the digital display is within  $\pm 0.002$ -inch of the correct value for each of the three or more steps of the setup wedge or shims. Make no further adjustments to the instrument settings.

14. Record the ultrasonic versus actual thickness of all wedge steps or steel shims available as a record of setup.

#### Inspection Procedure

1. Clean the lower 18 inches of the wing lift struts using a cleaner that will remove all dirt and grease. Dirt and grease will adversely affect the accuracy of the inspection technique. Light sanding or polishing may also be required to reduce surface roughness as noted in the **Equipment Requirements** section.

2. Using a flexible ruler, draw a  $\frac{1}{4}$ -inch grid on the surface of the first 11 inches from the lower end of the strut as shown in Piper Service Bulletin No. 528D or 910A, as applicable. This can be done using a soft (#2) pencil and should be done on both faces of the strut. As an alternative to drawing a complete grid, make two rows of marks spaced every  $\frac{1}{4}$ -inch across the width of the strut. One row of marks should be about 11 inches from the lower end of the strut, and the second row should be several inches away where the strut starts to narrow. Lay the flexible ruler between respective tick marks of the two rows and use tape or a rubber band to keep the ruler in place. See Figure 1.

3. Apply a generous amount of couplant inside each of the square areas or along the edge of the ruler. Re-application of couplant may be necessary.

4. Place the transducer inside the first square area of the drawn grid or at the first  $\frac{1}{4}$ -inch mark on the ruler and "ring" the transducer to the strut. When using a dual element transducer, be very careful to record the thickness value with the axis of the transducer elements perpendicular to any curvature in the strut. If this is not done, loss of signal or inaccurate readings can result.

5. Take readings inside each square on the grid or at  $\frac{1}{4}$ -inch increments along the ruler and record the results. When taking a thickness reading, rotate the transducer slightly back and forth and experiment with the angle of contact to produce the lowest thickness reading possible. Pay close attention to the A-scan display to assure that the thickness gate is triggering off of maximized backwall echoes.

• **Note:** A reading shall not exceed .041-inch. If a reading exceeds .041-inch, repeat steps 13 and 14 of the **Instrument Setup** section before proceeding further.

6. If the A-trace is unsteady or the thickness reading is clearly wrong, adjust the signal gain and/or gate setting to obtain reasonable and steady readings. If any instrument setting is adjusted, repeat steps 13 and 14 of the **Instrument Setup** section before proceeding further.


7. In areas where obstructions are present, take a data point as close to the correct area as possible.

• **Note:** The strut wall contains a fabrication bead at approximately 40% of the strut chord. The bead may interfere with accurate measurements in that specific location.

8. A measurement of 0.024-inch or less shall require replacement of the strut prior to further flight

9. If at any time during testing an area is encountered where a valid thickness measurement cannot be obtained due to a loss of signal strength or quality, the area shall be considered suspect. These areas may have a remaining wall thickness of less than 0.020-inch, which is below the range of this setup, or they may have small areas of localized corrosion or pitting present. The latter case will result in a reduction in signal strength due to the sound being scattered from the rough surface and may result in a signal that includes echoes from the pits as well as the backwall. The suspect area(s) shall be tested with a Maule "Fabric Tester" as specified in Piper Service Bulletin No. 528D or 910A.

10. Record the lift strut inspection in the aircraft log book.



(h) This amendment becomes effective on February 14, 2000.

Issued in Kansas City, Missouri, on December 16, 1999.

**James Jackson,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 99-33166 Filed 12-27-99; 8:45 am]

BILLING CODE 4910-13-U

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 99-NM-166-AD; Amendment 39-11476; AD 99-26-16]

RIN 2120-AA64

#### **Airworthiness Directives; Bombardier Model CL-600-1A11 (CL-600), CL-600-2A12 (CL-601), and CL-600-2B16 (CL-601-3A, CL-601-3R, and CL-604) Series Airplanes**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD), applicable to certain Bombardier Model CL-600-1A11 (CL-600), CL-600-2A12 (CL-601), and CL-600-2B16 (CL-601-3A, CL-601-3R, and CL-604) series airplanes, that requires, for certain airplanes, removing the hydraulic tube assemblies from the main landing gear (MLG) bay, installing new re-routed hydraulic tube assemblies, and

repositioning a fuel line, as applicable. For certain other airplanes, this amendment requires a general visual inspection to determine the routing of certain hydraulic and fuel lines, and repair, if necessary. This amendment is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by this AD are intended to prevent damage to hydraulic and fuel lines resulting from failure of an MLG, which could cause a fire in the MLG wheel well.

**DATES:** Effective February 1, 2000.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of February 1, 2000.

**ADDRESSES:** The service information referenced in this AD may be obtained from Bombardier, Inc., Canadair, Aerospace Group, P.O. Box 6087, Station Centreville, Montreal, Quebec H3C 3G9, Canada. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Engine and Propeller Directorate, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** James E. Delisio, Aerospace Engineer, Airframe and Propulsion Branch, ANE-

171, FAA, Engine and Propeller Directorate, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York 11581; telephone (516) 256-7521; fax (516) 568-2716.

**SUPPLEMENTARY INFORMATION:** A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Bombardier Model CL-600-1A11 (CL-600), CL-600-2A12 (CL-601), and CL-600-2B16 (CL-601-3A, CL-601-3R, and CL-604) series airplanes was published in the **Federal Register** on October 27, 1999 (64 FR 57798). For certain airplanes, that action proposed to require removing the hydraulic tube assemblies from the main landing gear (MLG) bay, installing new re-routed hydraulic tube assemblies, and repositioning a fuel line, as applicable. For certain other airplanes, that action proposed to require a general visual inspection to determine the routing of certain hydraulic and fuel lines, and repair, if necessary.

#### **Comments**

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.