

Order 12866, since it is not likely to have an annual economic effect of \$100 million or more, result in a major increase in costs or prices, or have a significant adverse effect on competition or the U.S. economy.

SBA certifies that this proposed rule will not have a significant economic impact on a substantial number of small entities within the meaning of the Regulatory Flexibility Act, 5 U.S.C. 601-612.

This regulation concerns the ability of SBA to sell disaster loans as part of SBA's Asset Sales Programs. There will be no economic impact upon the small businesses that received those loans because the loans that will be sold are merely changing ownership, so no new funding is involved. The purchaser of the loans will be bound by the terms of the loan documents in the same manner as SBA. The Agency does not anticipate that any additional costs will be placed upon small entities. Therefore, SBA believes that there will be no economic impact on small businesses.

Nevertheless, even if it is assumed that there is an economic impact, this rule would still only have a minimal effect on an insubstantial number of small businesses. This is because SBA's total disaster business loan portfolio at the end of FY 1999 was 64,832 loans, as contrasted with an estimated total of 24 million small businesses in the United States (as estimated by SBA's Office of Advocacy).

SBA certifies that this proposed rule does not impose any additional reporting or recordkeeping requirements under the Paperwork Reduction Act, 44 U.S.C., chapter 35.

For purposes of Executive Order 13132, SBA certifies that this proposed rule has no federalism implications warranting preparation of a Federalism Assessment.

For purposes of Executive Order 12988, SBA certifies that this proposed rule is drafted, to the extent practicable, to accord with the standards set forth in paragraph 3 of that Order.

List of Subjects in 13 CFR Part 120

Loan programs—business.

For the reasons stated in the preamble, SBA proposes to amend 13 CFR part 120 as follows:

PART 120—BUSINESS LOANS

1. The authority citation for part 120 continues to read as follows:

Authority: 15 U.S.C. 634 (b)(6) and 636(a) and (h).

2. Revise the section heading in § 120.540 and amend the first sentence of paragraph (b)(4) as follows:

§ 120.540 What are SBA's policies concerning the liquidation of collateral and the sale of business loans and physical disaster assistance loans, physical disaster business loans and economic injury disaster loans?

* * * * *

(b) * * *

(4) Sell direct and purchased 7(a) and 501, 502, 503 and 504 loans and physical disaster home loans, physical disaster business loans and economic injury disaster loans in asset sales. * * *

* * * * *

Dated: December 23, 1999.

Aida Alvarez,

Administrator.

[FR Doc. 00-426 Filed 1-7-00; 8:45 am]

BILLING CODE 8025-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-NM-349-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A319, A320, A321, A330, and A340 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Airbus Model A319, A320, A321, A330, and A340 series airplanes. This proposal would require revising the Airplane Flight Manual to provide the flight crew with certain instructions associated with the Global Positioning System (GPS). This proposal also would require modification of the Global Positioning System Signal Unit (GPSSU) of the satellite navigational system. This proposal is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by the proposed AD are intended to prevent position and altitude errors due to bad oscillator warm-up characteristics of the GPSSU, which could result in navigational errors that may exceed 0.5 nautical mile.

DATES: Comments must be received by February 9, 2000.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114,

Attention: Rules Docket No. 99-NM-349-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT:

Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 99-NM-349-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-349-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The Direction Generale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, notified the FAA that an unsafe condition may exist on certain Airbus Model A319, A320, A321, A330, and A340 series airplanes. The DGAC advises that the navigational satellite signals of the Global Positioning System (GPS) (located in the cockpit) may be incorrectly measured by the Global Positioning System Signal Unit (GPSSU) (located in the fuselage) due to bad oscillator warm-up characteristics of the GPSSU. In the event that only one GPS in the cockpit is operative, the erroneous GPS position computation may not be detected. This condition, if not corrected, could result in navigational errors that may exceed 0.5 nautical mile.

Explanation of Relevant Service Information

The manufacturer has issued Airbus Service Bulletins A320-34-1191, dated July 12, 1999, and A320-34-1196, dated July 15, 1999 (for Model A319, A320 and A321 series airplanes); A330-34-3082, Revision 01, dated September 28, 1999, and A330-34-3086, Revision 01, dated September 28, 1999 (for Model A330 series airplanes); and A340-34-4089, Revision 01, dated September 28, 1999, and A340-34-4092, Revision 01, dated September 28, 1999 (for Model A340 series airplanes). These service bulletins describe procedures for modification of the GPSSU of the satellite navigational system. The modification involves modifying the hardware and software in order to minimize synchronization conditions, accommodate an automatic reset and the GPS week number rollover, and provide failure recording capabilities in the non-volatile memory.

In addition, these service bulletins identify related service bulletins that must be accomplished prior to or concurrent with the applicable service bulletin. These additional service bulletins are as follows:

- A320-34-1119
- A330-34-3015
- A340-34-4022
- A340-34-4078

The Airbus service bulletins described previously also reference LITTON Service Bulletin 2001-34-13, dated July 8, 1999, and 2001-34-14, dated July 5, 1999, as additional sources of service information for modification of the GPSSU the satellite navigational system.

Accomplishment of the actions specified in the Airbus service bulletins

is intended to adequately address the identified unsafe condition. The DGAC classified these Airbus service bulletins as mandatory and issued French airworthiness directives 1999-361-138(B), dated September 8, 1999 (for Models A319, A320, and A321 series airplanes); 1999-354-101(B), dated September 8, 1999 (for Model A330 series airplanes); and 1999-355-123(B), dated September 8, 1999 (for Model A340 series airplanes); in order to assure the continued airworthiness of these airplanes in France.

The French airworthiness directives also require revising the applicable Airplane Flight Manual (AFM) to provide the flight crew with certain instructions regarding deselection of the GPS navigational system.

FAA's Conclusions

These airplane models are manufactured in France and are type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require accomplishment of the actions specified in the Airbus service bulletins described previously. The proposed AD also requires revising the FAA-approved AFM to provide the flight crew with certain instructions associated with the GPS.

Cost Impact

The FAA estimates that 1 airplane of U.S. registry would be affected by this proposed AD.

It would take approximately 1 work hour per airplane to accomplish the proposed Airplane Flight Manual (AFM) revision, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the AFM revision proposed by this AD on U.S. operators is estimated to be \$60, or \$60 per airplane.

It would take approximately 1 work hour per airplane to accomplish the proposed modification, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the modification proposed by this AD on U.S. operators is estimated to be \$60, or \$60 per airplane.

It would take between 3 to 14 work hours per airplane to accomplish the proposed additional modifications required to be accomplished prior to or concurrent with the proposed modification, at an average labor rate of \$60 per work. Required parts would be provided by the vendor or manufacturer at no cost to the operators. Based on these figures, the cost impact of the additional modifications proposed by this AD on U.S. operators is estimated to be between \$180 to \$840 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation

Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Airbus Industrie: Docket 99–NM–349–AD.

Applicability: Model A319, A320, A321, A330, and A340 series airplanes, certificated in any category, as follows:

- Model A319, A320, and A321 series airplanes on which Airbus Modification 28578 (Airbus Service Bulletin A320–34–1191, dated July 12, 1999), or Airbus Modification 28579 (Airbus Service Bulletin A320–34–1196, dated July 15) has not been accomplished; equipped with a LITTON Global Positioning Satellite Signal Unit (GPSSU) having Part Number (P/N) 465205–0302–0303 installed in accordance with Airbus Service Bulletin A320–34–1119 (Airbus Modification 23885).

- Model A330 series airplanes on which Airbus Modification 46961 (Airbus Service Bulletin A330–34–3082, Revision 01, dated September 28, 1999), or Airbus Modification 47327 (Airbus Service Bulletin A330–34–3086, Revision 01, dated September 28, 1999) has not been accomplished; equipped with a LITTON GPSSU having P/N 465205–0302–0302 or 465205–0302–0303.

- Model A340 series airplanes on which Airbus Modification 46961 (Airbus Service Bulletin A340–34–4089, Revision 01, dated September 28, 1999), or Airbus Modification 47327 (Airbus Service Bulletin A340–34–4092, Revision 01, dated September 28, 1999) has not been accomplished; equipped with a LITTON GPSSU having P/N 465205–0302–0302 or 465205–0302–0303.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent position and altitude errors due to bad oscillator warm-up characteristics of the GPSSU, which could result in navigational errors that may exceed 0.5 nautical mile, accomplish the following:

AFM Revision

(a) Within 10 days after the effective date of this AD, revise the Limitations Section of the FAA-approved Airplane Flight Manual (AFM) to include the following procedures. This may be accomplished by inserting a copy of this AD in the AFM.

“Operation:

- GPS Stand-alone and GPS overlay non-precision approaches are not allowed.
- The GPS must be deselected before non-precision approach.
- The GPS must be deselected for the remainder of the flight if ‘NAV FM/GPS POS DISAGREE’ ECAM warning is triggered (in all phases of flight)

Dispatch:

- If one GPS is inoperative, GPS must be deselected.”

Note 2: The AFM revision may be accomplished by inserting a copy of Airbus Temporary Revision (TR) 2.05.00/40 (for Model A319, A320, and A321 series airplanes); TR 2.05.00/38 (for Model A330 series airplanes); or TR2.05.00/47 (for A340 series airplanes); into the applicable AFM.

Modification

(b) Within 2 months after the effective date of this AD, modify the GPSSU of the satellite navigational system, in accordance with (b)(1), (b)(2), or (b)(3) of this AD, as applicable. After accomplishment of the modification, the AFM revision required by paragraph (a) of this AD may be removed from the AFM.

(1) For Model A319, A320, and A321 series airplanes: Modify the GPSSU in accordance with either Airbus Service Bulletin A320–34–1191, dated July 12, 1999, or Airbus Service Bulletin A320–34–1196, dated July 15, 1999.

(i) If modification of the GPSSU is accomplished in accordance with Airbus Service Bulletin A320–34–1191, prior to or concurrent with accomplishment of the modification, accomplish either Airbus Service Bulletin A320–34–1119, Revision 02, dated April 30, 1997, or A320–34–1196, dated July 15, 1999.

(ii) If modification of the GPSSU is accomplished in accordance with Airbus Service Bulletin A320–34–1196, prior to or concurrent with accomplishment of the modification, accomplish Airbus Service Bulletin A320–34–1119, Revision 02, dated April 30, 1997.

(2) For Model A330 series airplanes: Modify the GPSSU in accordance with either Airbus Service Bulletin A330–34–3082, Revision 01, dated September 28, 1999, or Airbus Service Bulletin A330–34–3086, Revision 01, dated September 28, 1999.

(i) If modification of the GPSSU is accomplished in accordance with Airbus Service Bulletin A330–34–3082, Revision 01, prior to or concurrent with accomplishment of the modification, accomplish either Airbus Service Bulletin A330–34–3015, dated April 3, 1995, or Airbus Service Bulletin A330–34–3086, Revision 01, dated September 28, 1999.

(ii) If modification of the GPSSU is accomplished in accordance with Airbus Service Bulletin A330–34–3086, Revision 01, prior to or concurrent with accomplishment

of the modification, accomplish Airbus Service Bulletin A330–34–3015, dated April 3, 1995.

(3) For Model A340 series airplanes: Modify the GPSSU in accordance with either Airbus Service Bulletin A30–34–4089, Revision 01, dated September 28, 1999, or Airbus Service Bulletin A330–34–4092, Revision 01, dated September 28, 1999.

(i) If modification of the GPSSU is accomplished in accordance with Airbus Service Bulletin A330–34–4089, Revision 01, prior to or concurrent with accomplishment of the modification, accomplish either Airbus Service Bulletin A330–34–4022, dated April 3, 1995, or Airbus Service Bulletin A330–34–4092, Revision 01, dated September 28, 1999.

(ii) If modification of the GPSSU is accomplished in accordance with Airbus Service Bulletin A330–34–4092, Revision 01, prior to or concurrent with accomplishment of the modification, accomplish either Airbus Service Bulletin A330–34–4022, dated April 3, 1995, or Airbus Service Bulletin A340–34–4078, Revision 01, dated November 26, 1999, including Appendix 01, dated November 26, 1999.

Note 3: The Airbus service bulletins reference LITTON Service Bulletin 2001–34–13, dated July 8, 1999, and LITTON Service Bulletin 2001–34–14, dated July 5, 1999, as additional sources of service information for modifying the GPSSU.

(c) As of the effective date of this AD, no person shall install on any airplane a GPSSU having P/N 465205–0302–0302 or 465205–0302–0303.

Alternative Methods of Compliance

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM–116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance and Operations Inspector, who may add comments and then send it to the Manager, International Branch, ANM–116.

Note 4: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM–116.

Special Flight Permits

(e) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 5: The subject of this AD is addressed in French airworthiness directives 1999–361–138(B), dated September 8, 1999; 1999–354–101(B), dated September 8, 1999; and 1999–355–123(B), dated September 8, 1999; in order to assure the continued airworthiness of these airplanes in France.

Issued in Renton, Washington, on January 4, 2000.

Donald L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-503 Filed 1-7-00; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-SW-14-AD]

Airworthiness Directives; Eurocopter France Model SA-366G1 Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) applicable to Eurocopter France Model SA-366G1 helicopters. This proposal would require replacing certain electrical modules with airworthy electrical modules. This proposal is prompted by the discovery of several defective electrical modules. The actions specified by the proposed AD are intended to prevent loss of electrical continuity, which could cause loss of critical systems and subsequent loss of control of the helicopter.

DATES: Comments must be received on or before March 10, 2000.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Office of the Regional Counsel, Southwest Region, Attention: Rules Docket No. 99-SW-14-AD, 2601 Meacham Blvd., Room 663, Fort Worth, Texas. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: Robert McCallister, Aerospace Engineer, FAA, Rotorcraft Directorate, Rotorcraft Standards Staff, Fort Worth, Texas 76193-0110, telephone (817) 222-5121, fax (817) 222-5961.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified

above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 99-SW-14-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Office of the Regional Counsel, Southwest Region, Attention: Rules Docket No. 99-SW-14-AD, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

Discussion

The Direction Generale De L'Aviation Civile (DGAC), the airworthiness authority for France, has notified the FAA that an unsafe condition may exist on Eurocopter France Model SA-366G1 helicopters. The DGAC advises of the discovery of malfunctions due to faulty "CONNECTRAL" modules on electrical circuits of a Super Puma AS332 helicopter. Model AS332 and SA-366G1 helicopters use the same type of "CONNECTRAL" modules.

Eurocopter France has issued Eurocopter Service Bulletin No. 01.25, dated May 28, 1998, (SB) for Model SA-366G1 helicopters. The SB specifies inspecting and replacing each "CONNECTRAL" green electrical module manufactured between week 95/16 through 96/21. The manufacturing codes identify the year and week of module production. Only green electrical modules without a white dot on the face need to be replaced. The DGAC classified this SB as mandatory and issued AD 98-251-022(A), dated July 1, 1998, to ensure the continued airworthiness of these helicopters in France.

This helicopter model is manufactured in France and is type certificated for operation in the United

States under the provisions of § 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Since an unsafe condition has been identified that is likely to exist or develop on other Eurocopter France Model SA-366G1 helicopters of the same type design registered in the United States, the proposed AD would require replacing each "CONNECTRAL" green electrical module that does not have a white dot on the face and that has a manufacturing code of 95/16 through 96/21 with an airworthy electrical module. Those manufacturing codes identify modules manufactured between the beginning of the 16th week of 1995 and the end of the 21st week of 1996. Replacing the electrical modules with a white dot on the face is not required because the manufacturer has verified the proper functioning of these units.

The FAA estimates that 94 helicopters of U.S. registry would be affected by this proposed AD, that it would take approximately 100 work hours per helicopter to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Required parts would cost approximately \$2,969 for the maximum number of modules replaced per helicopter, but the helicopter manufacturer has stated that the parts will be provided at no cost. Based on these figures, the total cost impact of the proposed AD on U.S. operators is estimated to be \$564,000.

The regulations proposed herein would not have substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications to warrant the preparation of a Federalism Assessment under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative,