

**New Requirements of This AD***Modifications*

(c) Within 36 months after the effective date of this AD, accomplish the requirements of paragraphs (c)(1), (c)(2), and (c)(3) of this AD. Accomplishment of the actions required by this paragraph constitutes terminating action for the repetitive tests required by paragraph (a) of this AD.

(1) Install an additional locking system on each thrust reverser in accordance with the Accomplishment Instructions of Boeing Service Bulletin 747-78-2152, Revision 1, dated December 12, 1996; Revision 2, dated December 18, 1997; or Revision 3, dated August 26, 1999.

(2) Remove the thrust reverser sequencing mechanism and install a solenoid operated shutoff valve in accordance with Boeing Service Bulletin 747-78-2052, Revision 5, dated February 22, 1996.

(3) Install provisional wiring for the additional locking system on the thrust reversers, in accordance with the Accomplishment Instructions of Boeing Service Bulletin 747-78-2134, Revision 3, dated March 19, 1998.

**Repetitive Tests**

(d) Within 3,000 flight hours after accomplishment of paragraph (c) of this AD: Perform a functional test to detect discrepancies of the additional locking system on each thrust reverser in accordance with the procedures described in the Boeing 747 Airplane Maintenance Manual (AMM), Section 78-34-11, dated October 25, 1997. Prior to further flight, correct any discrepancy detected and repeat the functional test of that repair in accordance with the procedures described in the AMM. Repeat the functional tests thereafter at intervals not to exceed 3,000 flight hours.

**Alternative Methods of Compliance**

(e)(1) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

(2) Alternative methods of compliance, approved previously in accordance with paragraphs (a) and (b) of AD 95-16-02, amendment 39-9321, are approved as alternative methods of compliance with the corresponding paragraphs in this AD.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

**Special Flight Permits**

(f) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on January 20, 2000.

**Donald L. Riggins,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*  
[FR Doc. 00-1778 Filed 1-25-00; 8:45 am]

**BILLING CODE 4910-13-U**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. 99-NM-215-AD]**

**RIN 2120-AA64**

**Airworthiness Directives; McDonnell Douglas Model DC-10 Series Airplanes**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain McDonnell Douglas Model DC-10 series airplanes. This proposal would require a one-time detailed visual inspection of the galley power feeder cables and fuselage structure at a certain station to detect chafing or arcing damage to the cables and structure or to detect arcing damage to the insulation blankets; and corrective actions, if necessary. This proposal also would require installation of spacers between the galley power feeder cable clamps and fuselage structure. This proposal is prompted by reports indicating that the galley power feeder cables chafed against a certain fuselage frame in the forward lower cargo compartment, which resulted in electrical arcing. The actions specified by the proposed AD are intended to prevent such chafing and arcing due to insufficient clearance between the cables and the airplane structure, which could result in smoke and fire in the forward lower cargo compartment.

**DATES:** Comments must be received by March 13, 2000.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-215-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from

Boeing Commercial Aircraft Group, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Technical Publications Business Administration, Dept. C1-L51 (2-60). This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Transport Airplane Directorate, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California.

**FOR FURTHER INFORMATION CONTACT:**

Natalie Phan-Tran, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Transport Airplane Directorate, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5343; fax (562) 627-5210.

**SUPPLEMENTARY INFORMATION:****Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 99-NM-215-AD." The postcard will be date stamped and returned to the commenter.

**Availability of NPRMs**

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-215-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

## Discussion

As part of its practice of re-examining all aspects of the service experience of a particular aircraft whenever an accident occurs, the FAA has become aware of two incidents in which the galley power feeder cables chafed against the fuselage station Y=635.000 frame in the forward lower cargo compartment, which resulted in electrical arcing. These incidents occurred on McDonnell Douglas Model DC-10 series airplanes. Investigation revealed that there was insufficient clearance between the cables and the airplane structure. This condition, if not corrected, could cause arcing of the galley power feeder cables against the airplane structure, which could result in smoke and fire in the forward lower cargo compartment.

## Other Related Rulemaking

The FAA, in conjunction with Boeing and operators of Model DC-10 series airplanes, is continuing to review all aspects of the service history of those airplanes to identify potential unsafe conditions and to take appropriate corrective actions. This proposed AD is one of a series of actions identified during that process. The process is continuing and the FAA may consider additional rulemaking actions as further results of the review become available.

## Explanation of Relevant Service Information

The FAA has reviewed and approved McDonnell Douglas Alert Service Bulletin DC10-24A162, dated July 28, 1999, which describes procedures for a one-time detailed visual inspection of the galley power feeder cables and fuselage structure at station Y=635.000 to detect chafing or arcing damage to the cables and structure or to detect arcing damage to the insulation blankets; and corrective actions, if necessary. The corrective actions include repair or replacement of chafed cables with new cables; repair of damaged frames; and replacement of damaged insulation blankets with new insulation blankets. This service bulletin also describes procedures for installation of spacers between the galley power feeder cable clamps and fuselage structure. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition.

## Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, this proposed AD would

require accomplishment of the actions specified in the service bulletin described previously.

## Cost Impact

There are approximately 168 airplanes of the affected design in the worldwide fleet. The FAA estimates that 103 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 2 work hours per airplane to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$12,360, or \$120 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

## Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

## The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

**McDonnell Douglas:** Docket 99-NM-215-AD.

**Applicability:** Model DC-10 series airplanes, as listed in McDonnell Douglas Alert Service Bulletin DC10-24A162, dated July 28, 1999; certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent chafing and arcing of the galley power feeder cables against the airplane structure due to insufficient clearance between the cables and the airplane structure, which could result in smoke and fire in the forward lower cargo compartment, accomplish the following:

### Inspection, Installation of Spacers, and Corrective Actions, If Necessary

(a) Within 6 months after the effective date of this AD, perform a detailed visual inspection of the galley external power feeder cables and fuselage structure at station Y=635.000 to detect chafing or arcing damage to the cables and structure or to detect arcing damage to the insulation blankets, in accordance with McDonnell Douglas Alert Service Bulletin DC10-24A162, dated July 28, 1999.

**Note 2:** For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

(1) If any damage or chafing is detected, prior to further flight, accomplish the actions specified in paragraphs (a)(1)(i), (a)(1)(ii), (a)(1)(iii), and (a)(1)(iv) of this AD, as applicable, in accordance with Condition 2 of the Accomplishment Instructions of the service bulletin.

(i) Repair or replace the chafed cables with new cables.

(ii) Repair the damaged frame.

(iii) Replace the damaged insulation blanket with a new blanket; however, insulation blankets made of metallized polyethyleneterephthalate (MPET) may not be used.

(iv) Install spacers between the galley power feeder cable clamps and fuselage structure.

(2) If no damage or chafing is detected, prior to further flight, install spacers between the galley power feeder cable clamps and fuselage structure in accordance with Condition 1 of the Accomplishment Instructions of the service bulletin.

#### Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

**Note 3:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

#### Special Flight Permits

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on January 20, 2000.

**Donald L. Riggins,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*  
[FR Doc. 00-1777 Filed 1-25-00; 8:45 am]

**BILLING CODE 4910-13-U**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 99-NM-214-AD]

RIN 2120-AA64

#### Airworthiness Directives; McDonnell Douglas Model DC-10 Series Airplanes and KC-10A (Military) Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain McDonnell Douglas Model DC-10 series airplanes and KC-10A (military) airplanes. This proposal would require a general visual inspection of electrical power feeder cables, airplane structure, and insulation blankets at a certain fuselage station to detect chafing and arcing damage, and corrective actions, if necessary; and installation of a standoff and clamp. This proposal is prompted by an incident in which the power feeder cables in the cabin electrical system were found to be chafed and arced against a fuselage frame due to insufficient clearance between the cables and airplane structure. The actions specified by the proposed AD are intended to prevent such chafing and arcing, which could cause smoke and fire in the overhead of the main cabin.

**DATES:** Comments must be received by March 13, 2000.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-214-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Aircraft Group, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Technical Publications Business Administration, Dept. C1-L51 (2-60). This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Transport Airplane Directorate, Los Angeles Aircraft

Certification Office, 3960 Paramount Boulevard, Lakewood, California.

**FOR FURTHER INFORMATION CONTACT:** Natalie Phan-Tran, Aerospace Engineer, Systems and Equipment Branch, ANM-130L, FAA, Transport Airplane Directorate, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5343; fax (562) 627-5210.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 99-NM-214-AD." The postcard will be date stamped and returned to the commenter.

##### Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-214-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

##### Discussion

As part of its practice of re-examining all aspects of the service experience of a particular aircraft whenever an accident occurs, the FAA has become aware of an incident in which the power feeder cables in the cabin electrical system had chafed and arced against the fuselage frame at station Y=1099.000 between longerons 9 and 10 (right side). The cable had burned in half, damaging