

in the growth of demand and potential supply will continue, which could foster inflationary imbalances that would undermine the economy's outstanding performance. Against the background of the long-term goals of price stability and sustainable economic growth and of the information currently available, the Board and the Reserve Banks believe the risks are weighted mainly toward conditions that may generate heightened inflation pressures in the foreseeable future.

Regulatory Flexibility Act Certification

Pursuant to section 605(b) of the Regulatory Flexibility Act (5 U.S.C. 605(b)), the Board certifies that the change in the basic discount rate will not have a significant adverse economic impact on a substantial number of small entities. The rule does not impose any additional requirements on entities affected by the regulation.

Administrative Procedure Act

The provisions of 5 U.S.C. 553(b) relating to notice and public participation were not followed in connection with the adoption of the amendment because the Board for good cause finds that delaying the change in the basic discount rate in order to allow notice and public comment on the change is impracticable, unnecessary, and contrary to the public interest in fostering price stability and sustainable economic growth.

The provisions of 5 U.S.C. 553(d) that prescribe 30 days prior notice of the effective date of a rule have not been followed because section 553(d) provides that such prior notice is not necessary whenever there is good cause for finding that such notice is contrary to the public interest. As previously stated, the Board determined that delaying the changes in the basic discount rate is contrary to the public interest.

List of Subjects in 12 CFR Part 201

Banks, banking, Credit, Federal Reserve System.

For the reasons set out in the preamble, 12 CFR part 201 is amended as set forth below:

PART 201—EXTENSIONS OF CREDIT BY FEDERAL RESERVE BANKS (REGULATION A)

1. The authority citation for 12 CFR part 201 continues to read as follows:

Authority: 12 U.S.C. 343 *et seq.*, 347a, 347b, 347c, 347d, 348 *et seq.*, 357, 374, 374a and 461.

2. Section 201.51 is revised to read as follows:

§ 201.51 Adjustment credit for depository institutions.

The rates for adjustment credit provided to depository institutions under § 201.3(a) are:

Federal Reserve Bank	Rate	Effective
Boston	6.0	May 16, 2000.
New York	6.0	May 19, 2000.
Philadelphia	6.0	May 18, 2000.
Cleveland	6.0	May 16, 2000.
Richmond	6.0	May 16, 2000.
Atlanta	6.0	May 17, 2000.
Chicago	6.0	May 17, 2000.
St. Louis	6.0	May 18, 2000.
Minneapolis	6.0	May 18, 2000.
Kansas City	6.0	May 17, 2000.
Dallas	6.0	May 17, 2000.
San Francisco	6.0	May 16, 2000.

By order of the Board of Governors of the Federal Reserve System, May 23, 2000.

Jennifer J. Johnson,

Secretary of the Board.

[FR Doc. 00-13309 Filed 5-25-00; 8:45 am]

BILLING CODE 6210-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-NM-65-AD; Amendment 39-11741; AD 2000-10-17]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 747 Series Airplanes Equipped With Pratt & Whitney JT9D-70 Series Engines

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain Boeing Model 747 series airplanes, that requires inspections, tests, and certain modifications of the thrust reverser control and indication system and wiring on each engine, and corrective action, if necessary. This amendment also requires installation of a terminating modification, and repetitive functional tests of that installation to detect discrepancies, and repair, if necessary. This amendment is prompted by the results of a safety review, which revealed that in-flight deployment of a thrust reverser could result in significant reduction in airplane controllability. The actions specified by this AD are intended to ensure the integrity of the fail-safe features of the

thrust reverser system by preventing possible failure modes, which could result in inadvertent deployment of a thrust reverser during flight, and consequent reduced controllability of the airplane.

DATES: Effective June 30, 2000.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of June 30, 2000.

ADDRESSES: The service information referenced in this AD may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Larry Reising, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Transport Airplane Directorate, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2683; fax (425) 227-1181.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Boeing Model 747 series airplanes was published in the **Federal Register** on February 4, 2000 (65 FR 5459). That action proposed to require inspections, tests, and certain modifications of the thrust reverser control and indication system and wiring on each engine, and corrective action, if necessary. That action also proposed to require installation of a terminating modification, and repetitive functional tests of that installation to detect discrepancies, and repair, if necessary.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

Conclusion

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

There are approximately 7 Model 747 series airplanes of the affected design in the worldwide fleet. The FAA estimates

that 6 airplanes of U.S. registry will be affected by this AD.

It will take approximately 32 work hours (8 work hours per engine) per airplane, to accomplish the required thrust reverser inspection, modification, and test, described in 747-78A2149, Revision 1, or Revision 2, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be \$11,520, or \$1,920 per airplane.

It will take approximately 8 work hours (2 work hours per engine) per airplane, to accomplish the required 1,000-flight-hour inspections described in Boeing Service Bulletin 747-78A2159, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the inspection required by this AD on U.S. operators is estimated to be \$2,880, or \$480 per airplane, per inspection cycle.

It will take approximately 20 work hours (5 work hours per engine) per airplane, to accomplish the required 18-month thrust reverser system checks described in Boeing Service Bulletin 747-78A2159, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the test required by this AD on U.S. operators is estimated to be \$7,200, or \$1,200 per airplane, per test cycle.

It will take approximately 544 work hours per airplane, to accomplish the required provisional wiring, at an average labor rate of \$60 per work hour. Required parts will be provided by the manufacturer at no cost to the operators. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be \$195,840, or \$32,640 per airplane.

It will take approximately 593 work hours per airplane, to accomplish the required sync lock installation, at an average labor rate of \$60 per work hour. Required parts will be provided by the manufacturer at no cost to the operators. Based on these figures, the cost impact of the installation required by this AD on U.S. operators is estimated to be \$213,480, or \$35,580 per airplane.

It will take approximately 4 work hours per airplane, to accomplish the required functional test of the additional locking system, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the test required by this AD on U.S. operators is estimated to be \$1,680, or \$240 per airplane, per test cycle.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2000-10-17 Boeing: Amendment 39-11741. Docket 99-NM-65-AD.

Applicability: Model 747 series airplanes equipped with Pratt & Whitney JT9D-70 series engines; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (g) of this AD.

The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent inadvertent deployment of a thrust reverser during flight and consequent reduced controllability of the airplane, accomplish the following:

Inspection/Repair

(a) Within 200 flight hours or 50 flight cycles after the effective date of this AD, whichever occurs later: Inspect the thrust reverser wiring on each engine to detect discrepancies, in accordance with Boeing Service Bulletin 747-78A2149, Revision 1, dated May 9, 1996, or Revision 2, dated August 29, 1996. Prior to further flight, repair any discrepancy, in accordance with the service bulletin.

Modification and Tests

(b) Within 5,000 flight hours or 500 flight cycles after the effective date of this AD, whichever occurs later: Accomplish the thrust reverser wiring modification on each engine in accordance with Boeing Service Bulletin 747-78A2149, Revision 1, dated May 9, 1996, or Revision 2 dated August 29, 1996.

(1) Concurrent with accomplishment of Boeing Service Bulletin 747-78A2149, Revision 1 or Revision 2: Accomplish the modification of the thrust reverser control system wiring specified in Rohr Service Bulletin TBC-CNS 78-32, Revision 1, dated August 20, 1996.

(2) Prior to further flight following accomplishment of the modification specified in paragraphs (b) and (b)(1): Perform an operational test of the thrust reverser wiring on each engine to detect discrepancies in accordance with Boeing Service Bulletin 747-78A2149, Revision 1, dated May 9, 1996, or Revision 2 dated August 29, 1996. Prior to further flight, correct any discrepancy detected, in accordance with the service bulletin.

Repetitive Inspections and Tests

(c) Perform the inspections and tests of the thrust reverser control and indication system to detect discrepancies at the times specified in paragraphs (c)(1) and (c)(2) of this AD, in accordance with Boeing Alert Service Bulletin 747-78A2159, dated May 18, 1995.

(1) Within 90 days after the effective date of this AD, inspect in accordance with Part III, "1,000 Flight Hour Inspections" of the Accomplishment Instructions of the alert service bulletin. Repeat at intervals not to exceed 1,000 flight hours until accomplishment of paragraph (f) of this AD.

(2) Within 1,500 flight hours or 4 months after the effective date of this AD, whichever occurs later, inspect and test in accordance with Part III, "18 Month Thrust Reverser System Checks" of the Accomplishment Instructions of the alert service bulletin. Repeat at intervals not to exceed 18 months until accomplishment of paragraph (e) of this AD.

Corrective Actions

(d) If any inspection or test required by paragraph (c) of this AD cannot be successfully performed as specified in the referenced service bulletin, or if any discrepancy is detected during any inspection or test, prior to further flight, repair in accordance with Boeing Alert Service Bulletin 747-78A2159, dated May 18, 1995. Additionally, prior to further flight, any failed inspection or test required by paragraph (c) of this AD must be repeated and successfully accomplished.

Terminating Action

(e) Accomplish the requirements of paragraphs (e)(1) and (e)(2) of this AD at the times specified in those paragraphs. Accomplishment of these actions constitutes terminating action for the repetitive inspections and tests required by paragraph (c) of this AD.

(1) Within 36 months after the effective date of this AD: Install an additional locking system on each engine thrust reverser in accordance with the Accomplishment Instructions of Boeing Service Bulletin 747-78-2153, Revision 1, dated November 27, 1996.

(2) Prior to or concurrent with accomplishment of Boeing Service Bulletin 747-78-2153, Revision 1: Accomplish the installation of provisional wiring for the locking system on the thrust reversers in

accordance with Boeing Service Bulletins 747-78-2135, dated August 31, 1995; and 747-78A2149, Revision 1, dated May 9, 1996, or Revision 2, dated August 29, 1996. Additionally, concurrent with accomplishment of Boeing Service Bulletin 747-78-2153, Revision 1, accomplish the installation of the provisional wiring described previously in accordance with Rohr Service Bulletin TBC-CNS 78-33, Revision 1, dated August 20, 1996.

Repetitive Functional Tests

(f) Within 4,000 hours time-in-service after accomplishment of paragraph (e) of this AD: Perform a functional test to detect discrepancies of the additional locking system on each thrust reverser, in accordance with Appendix 1 (including Figures 1 and 2) of this AD. Prior to further flight, correct any discrepancy detected, in accordance with the procedures described in the Boeing 747 Airplane Maintenance Manual. Repeat the functional test thereafter at intervals not to exceed 4,000 hours time-in-service.

Alternative Methods of Compliance

(g) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance

Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permit

(h) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(i) Except as provided by paragraph (f) of this AD, the actions shall be done in accordance with Boeing Service Bulletin 747-78A2149, Revision 1, dated May 9, 1996; Boeing Service Bulletin 747-78A2149, Revision 2, dated August 29, 1996; Boeing Alert Service Bulletin 747-78A2159, dated May 18, 1995; Boeing Service Bulletin 747-78-2135, dated August 31, 1995; Boeing Service Bulletin 747-78-2153, Revision 1, dated November 27, 1996; Rohr Service Bulletin TBC-CNS 78-32, Revision 1, dated August 20, 1996; and Rohr Service Bulletin TBC-CNS 78-33, Revision 1, dated August 20, 1996; as applicable. Rohr Service Bulletin TBC-CNS 78-32, Revision 1, dated August 20, 1996 contains the following list of effective pages:

Page No.	Revision level shown on page	Date shown on page
1, 3, 5-8, 10-11, 13-14, 16-18	1	August 20, 1996.
2, 4, 9, 12, 15	Original	May 25, 1995.

Rohr Service Bulletin TBC-CNS 78-33, Revision 1, dated August 20, 1996 contains the following list of effective pages:

Page No.	Revision level shown on page	Date shown on page
1, 3-55	1	August 20, 1996.
2	Original	December 11, 1995.

This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(j) This amendment becomes effective on June 30, 2000.

Appendix 1

Thrust Reverser Sync-Lock Integrity Test

1. General

A. Equipment and Materials

(1) Thrust reverser flex drive adapter—196K8004-1 or 196K8004-3; Rohr Industries, Inc., Chula Vista, California 92012.

2. Thrust Reverser Sync-Lock Integrity Test

B. Prepare for the thrust reverser sync lock test.

(1) Open applicable T/R CONT & BLEED SYS circuit breaker on P12 circuit breaker panel.

(2) Open fan cowl doors (Ref 71-11-02, Maintenance Practices).

(3) Check that forward and aft circumferential latches and all tension latches are engaged and locked.

(4) Depress drive unit latch operating arm and retain by engaging latch arm (detail C).

(5) Disengage stow latch hook on left and right thrust reversers (detail D).

(6) On either lower slave actuator (detail B), either remove coverplate from forward drive pad or remove locking plug from lower drive pad.

(7) Move left-hand sync-lock lever to the unlocked position.

(8) Using appropriate drive adapter (196K8004-1 at forward drive pad or 196K8004-3 at lower drive pad), attempt to manually deploy sleeves.

CAUTION: DO NOT APPLY A TORQUE LOAD OF MORE THAN 75 POUND-INCHES TO THE ACTUATOR; A GREATER TORQUE LOAD CAN CAUSE DAMAGE TO THE MECHANISM.

(9) If sleeves move, replace the right-hand sync-lock.

(10) Move left-hand sync-lock lever to the locked position.

(11) Move right-hand sync-lock lever to the unlocked position.

(12) Repeat step (8) above.

(13) If sleeves move, replace the left-hand sync-lock.

(14) Move left-hand sync-lock lever to the unlocked position.

(15) Rotate actuator gearshaft to fully stow the sleeves.

(16) When translating sleeves reach stowed position, check that stow latch hooks have engaged fixed hooks on both sides (detail D).

(17) Depress latch operating arm and disengage latch arm (detail C); allow latch arm to raise.

(18) After releasing arm, verify latch engagement by attempting to rotate feedback gear on drive unit using 1/4-inch square drive; gear shall not rotate in excess of 0.1 of a turn.

CAUTION: DO NOT APPLY A TORQUE LOAD OF MORE THAN 25 POUND-INCHES ON FEEDBACK GEAR; A GREATER TORQUE LOAD CAN CAUSE DAMAGE TO THE MECHANISM.

(19) As applicable, install locking plug (with square section facing away from drive

pad) or coverplate on actuator drive pad. Secure plug or plate with bolts tightened to 50–70 pound-inches.

(20) Move both left-and right-hand sync-lock levers to the locked position.

(21) Close fan cowl doors (Ref 71–11–02, Maintenance Practices).

(22) Close T/R CONT & BLEED SYS circuit breaker.

(23) Repeat the sync-lock integrity test on all remaining thrust reversers.

BILLING CODE 4910-13-U




Figure 1




Figure 2

Issued in Renton, Washington, on May 16, 2000.

Donald L. Riggin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-12812 Filed 5-25-00; 8:45 am]

BILLING CODE 4910-13-C

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-NM-360-AD; Amendment 39-11743; AD 2000-10-19]

RIN 2120-AA64

Airworthiness Directives; Israel Aircraft Industries, Ltd., Model 1125 Westwind Astra and Astra SPX Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain Israel Aircraft Industries, Ltd., Model 1125 Westwind Astra and Astra SPX series airplanes, that requires replacement of the existing pneumatic de-icing boot pressure indicator switch with a newly designed switch. This amendment is prompted by an occurrence on a similar airplane model in which the pneumatic de-icing boot indication light may have provided the flightcrew with misleading information as to the proper functioning of the de-icing boots. The actions specified by this AD are intended to prevent ice accumulation on the airplane leading edges, which could result in reduced controllability of the airplane.

DATES: Effective June 30, 2000.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of June 30, 2000.

ADDRESSES: The service information referenced in this AD may be obtained from Galaxy Aerospace Corporation, One Galaxy Way, Fort Worth Alliance Airport, Fort Worth, Texas 76177. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Norman B. Martenson, Manager, International Branch, ANM-116, FAA,

Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to all Israel Aircraft Industries, Ltd., Model 1125 Westwind Astra and Astra SPX series airplanes was published in the **Federal Register** on January 24, 2000 (65 FR 3617). That action proposed to require replacement of the existing pneumatic de-icing boot pressure indicator switch with a newly designed switch.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

Changes to the Proposed AD

Since issuance of the proposed AD, the manufacturer has issued Astra Alert Service Bulletin 1125-30A-199, dated April 17, 2000, which describes procedures for replacement of the wing and tail de-icing boot pressure indicator switches with improved switches. The Civil Aviation Administration of Israel (CAAI), which is the airworthiness authority for Israel, classified this service bulletin as mandatory. Additionally, the CAAI previously issued Israeli airworthiness directive 30-00-02-05, dated February 24, 2000, in order to assure the continued airworthiness of these airplanes in Israel.

The FAA has determined that the replacement described in the service bulletin provides an adequate method of addressing the unsafe condition identified in this AD. Paragraph (a) of the AD has been revised to include that replacement as an acceptable means of compliance to the requirements of the AD. The applicability of the AD has also been revised to exclude airplanes having serial number 116 and up, on which the replacement will be installed in production.

The FAA has also revised the "Cost Impact" section of the AD to provide the estimated cost of the replacement in accordance with the previously described service bulletin, and to revise the number of affected airplanes of U.S. registry.

Conclusion

After careful review of the available data, the FAA has determined that air safety and the public interest require the adoption of the rule with the changes described previously. The FAA has

determined that these changes will neither increase the economic burden on any operator nor increase the scope of the AD.

Cost Impact

The FAA estimates that 89 airplanes of U.S. registry will be affected by this AD.

Should an operator elect to accomplish the replacement in accordance with Astra Alert Service Bulletin 1125-30A-199, it will take approximately 2 work hours per airplane to accomplish it, at an average labor rate of \$60 per work hour.

Required parts may cost as much as \$1,455 per airplane. Based on these figures, the cost impact of the replacement on U.S. operators is estimated to be as much as \$1,575 per airplane.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows: