

b. Redesignating paragraphs (a)(5), (a)(6), and (a)(7) as paragraphs (a)(4), (a)(5), and (a)(6), respectively; and revising newly designated paragraph (a)(4) to read as follows:

§ 614.4325 Purchase and sale of interests in loans.

* * * * *

(a)(4) *Participating institution* means an institution that purchases a participation interest in a loan originated by another lender.

* * * * *

§ 614.4330 [Amended]

10. Amend § 614.4330 as follows:

a. Remove the words “an undivided” and add in their place the words “a participation” in paragraph (a)(9); and

b. Remove paragraph (b) and redesignate existing paragraph (c) as paragraph (b).

Subpart J—Lending and Leasing Limits

§ 614.4358 [Amended]

11. Amend § 614.4358 as follows:

a. Remove paragraph (b)(4)(i); and
b. Redesignate paragraphs (b)(4)(ii) and (b)(4)(iii) as paragraphs (b)(4)(i) and (b)(4)(ii), respectively.

PART 619—DEFINITIONS

12. The authority citation for part 619 continues to read as follows:

Authority: Secs. 1.7, 2.4, 4.9, 5.9, 5.12, 5.17, 5.18, 7.0, 7.6, 7.7, 7.8 of the Farm Credit Act (12 U.S.C. 2015, 2075, 2160, 2243, 2246, 2252, 2253, 2279a, 2279b, 2279b-1, 2279b-2).

§ 619.9195 [Removed and Reserved]

13. Remove and reserve § 619.9195.

Dated: July 20, 2000.

Kelly Mikel Williams,

Secretary, Farm Credit Administration Board.
[FR Doc. 00-18873 Filed 7-25-00; 8:45 am]

BILLING CODE 6705-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-NM-133-AD]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB-120 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain EMBRAER Model EMB-120 series airplanes. This proposal would require a one-time inspection to detect wear of the hydraulic pump hoses, and corrective action, if necessary. This proposal would also require relocation of the clip that secures the left forward hold-open rod of both nacelles. This action is necessary to prevent chafing and consequent rupture of the hydraulic line and loss of hydraulic pressure, which could result in reduced controllability of the airplane. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by August 25, 2000.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-133-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via the Internet must contain “Docket No. 2000-NM-133-AD” in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343—CEP 12.225, Sao Jose dos Campos—SP, Brazil. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Small Airplane Directorate, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia.

FOR FURTHER INFORMATION CONTACT: Robert Capezzuto, Aerospace Engineer, Systems and Flight Test Branch, ACE-116A, FAA, Small Airplane Directorate, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia 30349; telephone (770) 703-6071; fax (770) 703-6097.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: “Comments to Docket Number 2000-NM-133-AD.” The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-133-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The Departamento de Aviação Civil (DAC), which is the airworthiness authority for Brazil, notified the FAA that an unsafe condition may exist on certain EMBRAER Model EMB-120 series airplanes. The DAC advises that it has received a report of one case of rupture of an engine-driven pump hydraulic hose, possibly due to its friction against the clip that secures the

left-hand forward cowling hold-open rod of both nacelles. The rupture led to the loss of the hydraulic fluid of the relevant system. This condition, if not corrected, could result in reduced controllability of the airplane.

Explanation of Relevant Service Information

EMBRAER has issued Service Bulletin 120-29-0047, Change 01, dated October 22, 1996, which consists of two parts. Part I describes procedures for a visual inspection of all hydraulic hoses installed in both nacelles to detect wearout, chafing, or scores. Follow-on and corrective actions include ensuring a certain distance between the cowl rod clip and the hydraulic hoses, repairing discrepant hoses, relocating the clip that secures the left hold-open rod of both nacelles to prevent further chafing, and replacing the hydraulic hoses with those having the same part number. Part II describes procedures for relocating the clip. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition. The DAC classified this service bulletin as mandatory and issued Brazilian airworthiness directive 96-12-01, dated December 13, 1996, in order to ensure the continued airworthiness of these airplanes in Brazil.

FAA's Conclusions

This airplane model is manufactured in Brazil and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DCA has kept the FAA informed of the situation described above. The FAA has examined the findings of the DAC, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require accomplishment of the actions specified in the service bulletin described previously.

Cost Impact

The FAA estimates that 200 airplanes of U.S. registry would be affected by this proposed AD.

It would take approximately 1 work hour per airplane to inspect the hydraulic hoses, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the proposed inspection on U.S. operators is estimated to be \$12,000, or \$60 per airplane.

It would take approximately 1 work hour per airplane to relocate the clip, at an average labor rate of \$60 per work hour. Required parts would cost approximately \$15 per airplane. Based on these figures, the cost impact of the proposed clip relocation on U.S. operators is estimated to be \$15,000, or \$75 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Empresa Brasileira De Aeronautica S.A. (Embraer):
Docket 2000-NM-133-AD.

Applicability: Model EMB-120 series airplanes, certificated in any category, having serial numbers listed in EMBRAER Service Bulletin 120-29-0047, Change 01, dated October 22, 1996.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent rupture of the hydraulic line and loss of hydraulic pressure due to chafing, which could result in reduced controllability of the airplane, accomplish the following:

(a) Within 75 flight hours after the effective date of this AD, perform a general visual inspection to detect discrepancies (wear, chafing, or scores) of all hydraulic pump hoses installed in both nacelles, in accordance with Part I of EMBRAER Service Bulletin 120-29-0047, Change 01, dated October 22, 1996. Prior to further flight, perform all applicable corrective actions in accordance with the service bulletin.

Note 2: Accomplishment, prior to the effective date of this AD, of the inspection in accordance with Part I of EMBRAER Service Bulletin 120-29-0047, dated August 22, 1996, is acceptable for compliance with the requirements of paragraph (a) of this AD.

Note 3: For the purposes of this AD, a general visual inspection is defined as: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or drop-light, and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

(b) Within 75 flight hours after the effective date of this AD, relocate the clip that secures the left forward hold-open rod of both nacelles in accordance with Part II of

EMBRAER Service Bulletin 120-29-0047, Change 01, dated October 22, 1996.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Atlanta Aircraft Certification Office (ACO), FAA, Small Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Atlanta ACO.

Note 4: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Atlanta ACO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 5: The subject of this AD is addressed in Brazilian airworthiness directive 96-12-01, dated December 13, 1996.

Issued in Renton, Washington, on July 20, 2000.

Donald L. Riggan,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-18915 Filed 7-25-00; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-NM-17-AD]

RIN 2120-AA64

Airworthiness Directives; Fokker Model F.28 Mark 0100 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to all Fokker Model F.28 Mark 0100 series airplanes. This proposal would require replacement of the anti-skid control boxes with improved units. This action is necessary to prevent electromagnetic interference with the anti-skid control system, which could result in reduced brake pressure during low-speed taxiing, and consequent reduced controllability and performance of the airplane. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by August 25, 2000.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-17-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via the Internet must contain "Docket No. 2000-NM-17-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Fokker Services B.V., P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (*e.g.*, reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic,

environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2000-NM-17-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-17-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The Rijksluchtvaartdienst (RLD), which is the airworthiness authority for the Netherlands, notified the FAA that an unsafe condition may exist on all Fokker Model F.28 Mark 0100 series airplanes. The RLD advises that it has previously required accomplishment of certain modifications to improve the design safety features that provide adequate electromagnetic interference (EMI) protection of the wheelspeed signal wiring. Analysis has shown that accomplishment of these modifications should be sufficient to withstand the currently known EMI sources. However, unknown sources of EMI could still exist that would adversely affect the anti-skid control system and result in reduced brake pressure during low speed taxiing. This condition, if not corrected, could result in reduced controllability and performance of the airplane.

Explanation of Related Rulemaking

The FAA has previously issued AD 99-20-07, amendment 39-11337 (64 FR 52219, September 28, 1999) which requires modification of the ground wiring to the shielding of the wheelspeed sensor wiring of the main landing gear (MLG); and installation of new electrical grounds for the wheelspeed sensor channel of the anti-skid control box of the MLG. These modifications provide additional grounds to the shielding of the wheelspeed sensor wiring and to the power supplies of the anti-skid control box. These additional grounds reduce