

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2000-17-02—British Aerospace Regional Aircraft (Formerly British Aerospace Regional Aircraft Limited, Avro International Aerospace Division; British Aerospace, PLC; British Aerospace Commercial Aircraft Limited): Amendment 39-11875. Docket 99-NM-355-AD.

Applicability: All Model BAe 146 series airplanes; and Model Avro 146-RJ series airplanes, as listed in British Aerospace Service Bulletin SB.57-56, dated September 2, 1999; certificated in any category; except those on which British Aerospace Modification HCM01307A or HCM01307B [Reference Repair Instruction (R.I.L. HC571H9033)] has been accomplished.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent increased loads on the upper wing skin due to looseness of the stringer fittings and bolts at Ribs 0 and 2 of the wings, which could result in reduced structural integrity of the wings, accomplish the following:

Inspections and Modification

(a) Prior to the accumulation of 14,000 total flight cycles, or within 4,000 flight cycles after the effective date of this AD, whichever occurs later: Perform a detailed visual inspection of the stringers and a torque check of the Jo-bolts at Ribs 0 and 2 of the wings for discrepancies (including loose Jo-bolts and stringer crown fittings, fretting of fittings and stringers, and cracking or damage of attachments); in accordance with British

Aerospace Service Bulletin SB.57-56, dated September 2, 1999.

(1) If no discrepancy is found, or, if 1, 2, or 3 loose Jo-bolts are found per rib side and no loose crown (dagger) fittings are found (Category 1 or 2, as specified in Table 2 of paragraph D. "Compliance" of the service bulletin), accomplish the actions required in paragraphs (a)(1)(i) and (a)(1)(ii) of this AD.

(i) Repeat the inspection thereafter at the applicable times specified in Table 2, until accomplishment of the actions required by paragraph (a)(1)(ii) of this AD.

(ii) Prior to accumulation of 40,000 total flight cycles, or within 4,000 flight cycles after the effective date of this AD, whichever occurs later: Modify all stringer crown fittings at Ribs 0 and 2 of the wings (including inspections, repairs, and installation of oversize interference fit fasteners per R.I.L. HC571H9033) in accordance with the service bulletin, except as required by paragraph (b) of this AD. This modification terminates the requirements of this AD.

(2) If any other discrepancy is found, as specified in Table 2 (Categories 3 through 6): At the applicable times specified in Table 2, repeat the inspection thereafter, and modify all crown fittings at Ribs 0 and 2 of the wings (including inspections, repairs, and installation of oversize interference fit fasteners per R.I.L. HC571H9033); in accordance with the service bulletin, except as required by paragraph (b) of this AD. This modification terminates the requirements of this AD.

Note 2: For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

Approved Repairs

(b) Where British Aerospace Service Bulletin SB.57-56, dated September 2, 1999, specifies to contact the manufacturer for a repair, prior to further flight, repair in accordance with a method approved by either the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate; or the Civil Aviation Authority of the United Kingdom (or its delegated agent). For a repair method to be approved by the Manager, International Branch, ANM-116, as required by this paragraph, the Manager's approval letter must specifically reference this AD.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(e) Except as provided by paragraph (b) of this AD, the actions shall be done in accordance with British Aerospace Service Bulletin SB.57-56, dated September 2, 1999, including Repair Instruction (R.I.L.) HC571H9033, Issue 3, dated April 23, 1999. (**Note:** Only the first page of Repair Instruction (R.I.L.) HC571H9033 shows the issue level and date; no other page contains this information.) This incorporation by reference was approved by the Director of the **Federal Register** in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from British Aerospace Regional Aircraft American Support, 13850 Mcclareen Road, Herndon, Virginia 20171. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 4: The subject of this AD is addressed in British airworthiness directive 004-09-99.

(f) This amendment becomes effective on October 3, 2000.

Issued in Renton, Washington, on August 17, 2000.

Donald L. Riggan,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-21460 Filed 8-28-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-NM-02-AD; Amendment 39-11876; AD 2000-17-03]

RIN 2120-AA64

Airworthiness Directives; Fokker Model F.28 Mark 0100 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment supersedes an existing airworthiness directive (AD), applicable to certain Fokker Model F.28 Mark 0100 series airplanes, that currently requires a one-time visual inspection and a one-time eddy current and/or dye penetrant inspection of the

nose landing gear (NLG) main fitting to detect cracking; and rework of the NLG main fitting, if necessary. This amendment requires new inspections (one-time detailed visual inspection and repetitive eddy current or dye penetrant inspections) to detect cracking of the NLG main fitting subassembly, and corrective actions, if necessary. This amendment also revises the applicability of the existing AD. This amendment is prompted by the issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by this AD are intended to prevent cracking of the NLG main fitting, which could lead to collapse of the NLG during takeoff and landing, and possible injury to the flightcrew and passengers.

DATES: Effective October 3, 2000.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of October 3, 2000.

ADDRESSES: The service information referenced in this AD may be obtained from Fokker Services B.V., P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) by superseding AD 98-22-01, amendment 39-10847 (63 FR 58625, November 2, 1998), which is applicable to certain Fokker Model F.28 Mark 0100 series airplanes, was published in the **Federal Register** on March 15, 2000 (65 FR 13923). The action proposed to require new inspections (one-time detailed visual inspection and repetitive eddy current or dye penetrant inspections) to detect cracking of the nose landing gear (NLG) main fitting subassembly, and corrective actions, if necessary. The action also proposed to revise the applicability of the existing AD.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the two comments received.

One commenter states that it has completed the inspections and has a repetitive inspection program already in place to comply with the requirements of this AD.

Type Certificate Holder

One commenter requests that the Explanation of Relevant Service Information section of the AD be revised to refer to the current type certificate holder (Fokker Services B.V.), rather than the now defunct airplane manufacturer, as the issuer of the relevant service information. The FAA acknowledges the accuracy of this information; however, since this section is not repeated in the final rule, no change is made to the AD.

Conclusion

After careful review of the available data, including the comments noted above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

There are approximately 87 airplanes of U.S. registry that will be affected by this AD.

The one-time detailed visual inspection required by this AD action will take approximately 1 work hour per airplane to accomplish, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the one-time inspection required by this AD on U.S. operators is estimated to be \$5,220, or \$60 per airplane.

The repetitive eddy current or dye penetrant inspections required by this AD action will take approximately 1 work hour per airplane to accomplish, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the repetitive inspection required by this AD on U.S. operators is estimated to be \$5,220, or \$60 per airplane, per inspection cycle.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the requirements of this AD, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain

access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action: (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing amendment 39-10847 (63 FR 58625, November 2, 1998), and by adding a new airworthiness directive (AD), amendment 39-11876, to read as follows:

2000-17-03 Fokker Services B.V.:

Amendment 39-11876. Docket 2000-NM-02-AD. Supersedes AD 98-22-01, Amendment 39-10847.

Applicability: Model F.28 Mark 0100 series airplanes, certificated in any category; equipped with Messier-Dowty nose landing gear (NLG) having part

number (P/N) 201071001 or 201071002, on which a main fitting subassembly (MFSA) having P/N 201071200, 201071228, 201071248, or 201071249 is installed.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (f) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent cracking of the NLG main fitting, which could lead to collapse of the NLG during takeoff and landing, and possible injury to the flightcrew and passengers, accomplish the following:

One-Time Detailed Visual Inspection

(a) Prior to the accumulation of 7,500 total flight cycles or within 50 flight cycles after the effective date of this AD, whichever occurs later: Perform a one-time detailed visual inspection of the NLG main fitting subassembly to detect cracking, in accordance with Part 1 of the Accomplishment Instructions of Fokker Service Bulletin SBF100-32-118, dated October 8, 1999.

(1) If no cracking is detected, no further action is required by this paragraph.

(2) If any cracking is detected, prior to further flight, accomplish the actions required by paragraph (b) of this AD.

Note 2: For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirrors, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

Note 3: Actions accomplished prior to the effective date of this AD, in accordance with Fokker Service Bulletin SBF100-32-112, dated November 14, 1997, which was cited in AD 98-22-01, amendment 39-10847, are not considered acceptable for compliance with any requirements of this AD.

Repetitive Eddy Current and/or Dye Penetrant Inspections

(b) Except as required by paragraph (a)(2) of this AD: Prior to the accumulation of 7,875 total flight cycles or within 375 flight cycles after the effective date of this AD, whichever occurs later, perform an eddy current or dye penetrant inspection of the NLG main fitting subassembly to detect cracking, in accordance with Part 2 of the Accomplishment Instructions of Fokker Service Bulletin SBF100-32-118, dated October 8, 1999. Such inspection within the compliance time required by paragraph (a) of this AD terminates the requirements of paragraph (a) of this AD. Repeat the inspection thereafter, using an eddy current or dye penetrant technique, at intervals not to exceed 750 flight cycles.

(c) If any cracking is detected during any inspection required by paragraph (b) of this AD: Prior to further flight, rework the main fitting of the NLG, in accordance with Part 3 of the Accomplishment Instructions of Fokker Service Bulletin SBF100-32-118, dated October 8, 1999. If, after rework, any cracking remains that exceeds the limits specified in the service bulletin, prior to further flight, accomplish the actions specified by either paragraph (c)(1) or (c)(2) of this AD.

(1) Replace the NLG in accordance with the service bulletin; and within 7,875 flight cycles after such replacement, perform the inspection as specified in paragraph (b) of this AD, and repeat the inspection thereafter at intervals not to exceed 750 flight cycles.

Or

(2) Repair in accordance with a method approved by either the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate; or the Rijksluchtvaartdienst (RLD) (or its delegated agent). For a repair method to be approved by the Manager, International Branch, ANM-116, as required by this paragraph, the Manager's approval letter must specifically reference this AD.

Note 4: The Fokker service bulletin references Messier-Dowty Service Bulletin F100-32-92, Revision 1, dated October 8, 1999, as an additional source of service information for accomplishing the inspections and rework of the NLG main fitting subassembly.

Reporting Requirements

(d) Submit a report of the detailed visual inspection findings (positive and negative) required by paragraph (a) of this AD and a report of the initial eddy current or dye penetrant inspection findings (positive and negative) required by paragraph (b) of this AD to Fokker Services B.V., P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands; at

the applicable time specified in paragraph (d)(1) or (d)(2) of this AD. Information collection requirements contained in this regulation have been approved by the Office of Management and Budget (OMB) under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501, *et seq.*) and have been assigned OMB Control Number 2120-0056.

(1) For airplanes on which the detailed visual inspection specified by paragraph (a) of this AD and the initial repetitive eddy current or dye penetrant inspection specified by paragraph (b) of this AD are accomplished after the effective date of this AD: Submit each report within 7 days after performing the applicable inspection.

(2) For airplanes on which the detailed visual inspection specified by paragraph (a) of this AD and the initial repetitive eddy current or dye penetrant inspection specified in paragraph (b) of this AD have been accomplished prior to the effective date of this AD: Submit the reports within 7 days after the effective date of this AD.

Spares

(e) As of the effective date of this AD, no person shall install a NLG having P/N 201071001 or 201071002 unless the installed MFSA has been inspected, by means of an eddy current or dye penetrant inspection, in accordance with paragraph (b) of this AD.

Alternative Methods of Compliance

(f) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 5: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(g) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(h) Except as provided by paragraph (c)(2) of this AD, the actions shall be done in accordance with Fokker Service Bulletin SBF100-32-118, dated October

8, 1999. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Fokker Services B.V., P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 6: The subject of this AD is addressed in Dutch airworthiness directive BLA 1997-116/2 (A), dated October 29, 1999.

Effective Date

(i) This amendment becomes effective on October 3, 2000.

Issued in Renton, Washington, on August 17, 2000.

Donald L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-21459 Filed 8-28-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 47

Court of Competent Jurisdiction

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Interpretive rule.

SUMMARY: The Federal Aviation Administration (FAA) interprets the phrase "court of competent jurisdiction" as used in Title 14, Code of Federal Regulations § 47.37 as meaning a court of the country where the aircraft was last registered.

EFFECTIVE DATE: August 29, 2000.

FOR FURTHER INFORMATION CONTACT:

Joseph R. Standell, Federal Aviation Administration (AMC-7), Post Office Box 25082, Oklahoma City, OK 73125. Telephone (405) 954-3296.

SUPPLEMENTARY INFORMATION: Section 37.37(b)(2) of the Code of Federal Regulations (14 CFR Part 47) requires an applicant for United States registration of an aircraft to provide evidence satisfactory to the Administrator that foreign registration of the aircraft has terminated. Satisfactory evidence included "a final judgment or decree of a court of competent jurisdiction that determines, under the law of the country concerned, that the registration has in fact become invalid." (14 CFR 47.37(b)(2)) FAA interprets the phrase "court of competent jurisdiction" to mean a court of the country where the aircraft was last registered.

Issued in Oklahoma City, OK on August 22, 2000.

Joseph R. Standell,

Aeronautical Center Counsel.

[FR Doc. 00-22037 Filed 8-28-00; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 00-ACE-15]

Amendment to Class E Airspace; Coffeyville, KS

AGENCY: Federal Aviation Administration, DOT.

ACTION: Direct final rule; confirmation of effective date.

SUMMARY: This document confirms the effective date of a direct final rule which revises Class E airspace at Coffeyville, KS.

EFFECTIVE DATE: The direct final rule published at 65 FR 38722 is effective on 0901 UTC, October 5, 2000.

FOR FURTHER INFORMATION CONTACT:

Kathy Randolph, Air Traffic Division, Airspace Branch, ACE-520C, DOT Regional Headquarters Building, Federal Aviation Administration, 901 Locust, Kansas City, MO 64106; telephone: (816) 329-2525.

SUPPLEMENTARY INFORMATION: The FAA published this direct final rule with a request for comments in the **Federal Register** on June 22, 2000 (65 FR 38722). The FAA uses the direct final rulemaking procedure for a non-controversial rule where the FAA believes that there will be no adverse public comment. This direct final rule advised the public that no adverse comments were anticipated, and that unless a written adverse comment, or a written notice of intent to submit such an adverse comment, were received within the comment period, the regulation would become effective on October 5, 2000. No adverse comments were received, and thus this notice confirms that this direct final rule will become effective on that date.

Issued in Kansas City, MO on August 16, 2000.

Herman J. Lyons, Jr.,

Manager, Air Traffic Division, Central Region.

[FR Doc. 00-22040 Filed 8-28-00; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 00-ACE-14]

Amendment to Class E Airspace; Pratt, KS; Correction

AGENCY: Federal Aviation Administration, DOT.

ACTION: Direct final rule; confirmation of effective date and correction.

SUMMARY: This document confirms the effective date of a direct final rule which revises the Class E airspace at Pratt, KS, and corrects an error in the airport name of the Pratt Municipal Airport as published in the **Federal Register** June 22, 2000 (65 FR 38721), Airspace Docket No. 00-ACE-14.

DATES: The direct final rule published at 65 FR 38721 is effective on 0901 UTC, October 5, 2000.

This correction is effective on October 5, 2000.

FOR FURTHER INFORMATION CONTACT:

Kathy Randolph, Air Traffic Division, Airspace Branch, ACE-520C, DOT Regional Headquarters Building, Federal Aviation Administration, 901 Locust, Kansas City, MO 64106; telephone: (816) 329-2525.

SUPPLEMENTARY INFORMATION:

History

On June 22, 2000, the FAA published in the **Federal Register** a direct final rule; request for comments which revises the Class E airspace at Pratt, KS, (FR document 00-15534, 65 FR 38721, Airspace Docket No. 00-ACE-14). An error was subsequently discovered in the airport name of the Pratt Municipal Airport. This action corrects that error. After careful review of all available information related to the subject presented above, the FAA has determined that air safety and the public interest require adoption of the rule. The FAA has determined that this correction will not change the meaning of the action or add any additional burden on the public beyond that already published. This action corrects the error in the name of the Pratt Municipal airport and confirms the effective date to the direct final rule.

The FAA uses the direct final rulemaking procedure for a non-controversial rule where the FAA believes that there will be no adverse public comment. This direct final rule advised the public that no adverse comments were anticipated, and that unless a written adverse comment, or a