

from Raytheon Aircraft Company, P.O. Box 85, Wichita, Kansas 67201-0085; telephone: (800) 429-5372 or (316) 676-3140. You may read this document at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106.

Issued in Kansas City, Missouri, on September 19, 2000.

Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-24628 Filed 9-25-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 94-ANE-38-AD]

Airworthiness Directives; Honeywell International Inc. (formerly AlliedSignal Inc. and Textron Lycoming Inc.) LTS101 Series Turboshaft and LTP101 Series Turboprop Engines

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This document proposes the superseding of an existing airworthiness directive (AD), applicable to certain Honeywell International Inc. (formerly AlliedSignal Inc. and Textron Lycoming Inc.) LTS101 series turboshaft and LTP101 series turboprop engines. The existing airworthiness directive (AD) superseded priority letter AD 94-19-01 and currently requires initial and repetitive inspections of the engine fuel pump internal drive splines for wear, and replacement of engine fuel pumps that exhibit wear beyond specified limits.

This proposal would require a reduction in inspection intervals for the engine fuel pump internal drive splines. This proposal is prompted by a report from the engine manufacturer that 13 percent of the pumps installed on aircraft that were returned from the field for the required 900-hour interval inspection revealed excessive internal drive spline wear. The actions specified by this proposal are intended to prevent worn splines in fuel pumps that could cause engine fuel pump failure, which can result in total engine power loss and possible loss of the aircraft.

DATES: Comments must be received by November 27, 2000.

ADDRESSES: Submit comments to the Federal Aviation Administration (FAA), New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 94-ANE-38-AD, 12 New

England Executive Park, Burlington, MA 01803-5299. Comments may also be sent via the Internet using the following address: "9-ane-adcomment@faa.gov". Comments sent via the Internet must contain the docket number in the subject line. Comments may be inspected at this location between 8:00 a.m. and 4:30 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Honeywell International, Inc., Attn: Data Distribution, M/S 64-3/2101-201, P.O. Box 29003, Phoenix, AZ 85038-9003, telephone: (602) 365-2493, fax: (602) 365-5577. This information may be examined at the FAA, New England Region, Office of the Assistant Chief Counsel, 12 New England Executive Park, Burlington, MA.

FOR FURTHER INFORMATION CONTACT:

Robert Baitoo, Aerospace Engineer, Los Angeles Aircraft Certification Office, FAA, Transport Airplane Directorate, 3960 Paramount Blvd., Lakewood, CA 90712-4137; telephone (562) 627-5245, fax (562) 627-5210.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments, as they may desire. Communications should identify the Rules Docket number and be submitted to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 94-ANE-38-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRM's

Any person may obtain a copy of this NPRM by submitting a request to the FAA, New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 94-ANE-38-AD, 12 New England Executive Park, Burlington, MA 01803-5299.

Discussion

On April 17, 1995, the Federal Aviation Administration (FAA) issued airworthiness directive (AD) 95-09-02, Amendment 39-9206 (60 FR 20189, April 25, 1995), applicable to Textron Lycoming LTS101 series turboshaft and LTP101 series turboprop engines incorporating Chandler Evans (CECO) engine fuel pumps, Part Numbers 4-301-128-01, -02, -03, -04, -05, -06, -07, -08, -09, -10. This AD superseded Priority Letter AD 94-19-01, issued on September 2, 1994. The current AD requires initial and repetitive inspections for wear of LTS101 and LTP101 engine fuel pump internal drive splines installed on single-engine aircraft and replacement with a serviceable part of engine fuel pumps that exhibit wear beyond the limits specified in the incorporated service bulletin. That action was prompted by a report of a helicopter accident that resulted in a total loss of engine power and subsequent autorotation of a helicopter powered by a Textron Lycoming Model LTS101-600A-3 turboshaft engine. Investigation of that accident and other engine failures showed that CECO Model MFP261 engine fuel pump internal drive spline teeth were worn away and failed to engage, resulting in loss of fuel delivery to the engine. That condition, if not corrected, could result in engine fuel pump failure, which can result in total engine power loss and possible loss of the aircraft.

Recent Analysis

Since the issuance of AD 95-09-02, a number of removed fuel pumps have been returned to CECO. The FAA has learned that 13 percent of the pumps that were returned from the field for the required 900-hour interval inspection revealed excessive internal drive spline wear. Accordingly, the FAA has determined that the inspection interval must be reduced to 600-hour intervals.

Service Information

The FAA has reviewed and approved the contents of AlliedSignal Service Bulletin (SB) LT 101-73-20-0203, dated August 18, 1999, that informs operators of the new inspection intervals and the drawdown schedule for in-service

pumps. This AD is applicable to pumps installed on single-engine aircraft only.

Proposed Actions

Since an unsafe condition has been identified that is likely to exist or develop on other engines of this same type design, this proposed AD would supersede AD 95-09-02 to require initial and repetitive inspections for wear of the engine fuel pump internal drive splines, and replacement of engine fuel pumps that exhibit wear beyond the limits specified in AlliedSignal Engines SB No. LT101-73-20-0203 dated August 18, 1999, with a serviceable part. Fuel pumps removed in accordance with this AD must be returned to CECO for disassembly, inspection, and repair because of the specialized tools and procedures required. These actions must be done in accordance with the SB described previously.

Economic Analysis

Because initial removal and replacement activities are scheduled at intervals compatible with existing AD 95-09-02, no additional impact on part and labor cost is anticipated.

Regulatory Impact

This proposal does not have federalism implications, as defined in Executive Order 13132, because it would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Accordingly, the FAA has not consulted with state authorities prior to publication of this proposal.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing Amendment 39-9206 (60 FR 20189, April 25, 1995) and by adding a new airworthiness directive to read as follows:

Honeywell International Inc.: Docket No. 94-ANE-38-AD. Supersedes AD 95-09-02, Amendment 39-9206.

Applicability: Honeywell International Inc. (formerly AlliedSignal Inc. and Textron Lycoming Inc.) LTS101-600A-2, -600A-3 series turboshaft and LTP101-600A-1A, -700A-1A series turboprop engines incorporating Chandler Evans (CECO) engine fuel pumps, part numbers (P/N) 4-301-128-01, -02, -03, -04, -05, -06, -07, -08, -09, and -10. These engines are installed on but not limited to the following single-engine aircraft: Eurocopter France (formerly Aerospatiale) AS350D series helicopters and Airtractor AT302, PAC Aero Cresco, and Page (Ayres S-2R) Thrush airplanes. This proposed AD is not applicable to engines installed on twin-engine aircraft.

Note 1: This airworthiness directive (AD) applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (g) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition.

Compliance: Required as indicated, unless accomplished previously.

To prevent engine fuel pump failure, which can result in total engine power loss and possible loss of the aircraft, accomplish the following:

Initial Inspection

(a) Remove from service and return to CECO for inspection, engine fuel pumps with greater than 751 hours time in service (TIS) since new or overhaul on the effective date of this airworthiness directive (AD), within the next 100 hours TIS after the effective date of this AD but prior to reaching 900 hours TIS since new or overhaul. All pumps must be inspected before 900 hours TIS since new, overhaul, time between inspection, or time since last inspection in accordance with

AlliedSignal Engines SB No. LT101-73-20-0203, dated August 18, 1999.

(b) Remove from service and return to CECO for inspection, engine fuel pumps with greater than 451 hours TIS since new or overhaul, but less than or equal to 750 hours TIS since new or overhaul on the effective date of this AD, within the next 150 hours TIS after the effective date of this AD, in accordance with AlliedSignal Engines SB No. LT101-73-20-0203, dated August 18, 1999.

(c) Remove from service and return to CECO for inspection, engine fuel pumps with less than or equal to 450 hours TIS since new or overhaul on the effective date of this AD, within the next 150 hours TIS after the effective date of this AD, or before accumulating 600 hours TIS since new, overhaul, time between inspection, or time since last inspection, whichever occurs first, in accordance with AlliedSignal Engines SB No. LT101-73-20-0203, dated August 18, 1999.

Repetitive Inspections

(d) Thereafter, remove from service and return to CECO for inspection, engine fuel pump at intervals not to exceed 600 hours TIS since the last inspection in accordance with the Accomplishment Instructions of AlliedSignal Engines SB No. LT101-73-20-0203, dated August 18, 1999.

(e) Engine fuel pumps that exhibit wear beyond the limits specified in AlliedSignal Engines SB No. LT101-73-20-0203, dated August 18, may not be returned to service.

Definition

(f) For the purposes of this AD, a serviceable part is defined as a new part, or a part that has been inspected by CECO in accordance with AlliedSignal Engines SB LT101-73-20-0203, dated August 18, 1999, and that has not accumulated 600 hours TIS since new, or since inspection by CECO.

Alternative Method of Compliance

(g) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office (ACO). Operators shall submit their request through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the ACO. The request should be forwarded through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles Aircraft Certification Office.

Ferry Flights

(h) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the aircraft to a location where the requirements of this AD can be accomplished.

Issued in Burlington, Massachusetts, on September 19, 2000.

Jay J. Pardee,

Manager, Engine and Propeller Directorate,
Aircraft Certification Service.

[FR Doc. 00-24629 Filed 9-25-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TREASURY

Internal Revenue Service

26 CFR Part 1

[REG-103805-99]

RIN 1545-AX56

Agent for Consolidated Group

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Withdrawal of previous proposed regulations; notice of proposed rulemaking; and notice of public hearing.

SUMMARY: This document contains proposed regulations regarding the agent for an affiliated group that files a consolidated return (consolidated group). The proposed regulations address certain issues raised by the current regulations concerning the agent for the group when the common parent ceases to be the common parent, as well as questions concerning the scope of the common parent's authority. These proposed regulations affect all consolidated groups. This document also provides notice of a public hearing on these proposed regulations. In addition, this document withdraws a portion of the proposed rulemaking (LR-97-79) published in the *Federal Register*, July 31, 1984.

DATES: Written and electronic comments must be received by December 26, 2000. Outlines of topics to be discussed at the public hearing scheduled for 10 a.m. on January 22, 2001, must be received by December 26, 2000.

ADDRESSES: Send submissions to: CC:M&SP:RU (REG-103805-99), room 5226, Internal Revenue Service, POB 7604, Ben Franklin Station, Washington, DC 20044. Submissions may also be hand delivered Monday through Friday between the hours of 8 a.m. and 5 p.m. to CC:M&SP:RU (REG-103805-99), Courier's Desk, Internal Revenue Service, 1111 Constitution Avenue, NW., Washington, DC. Alternatively, taxpayers may submit comments electronically via the internet by selecting the "Tax Regs" option on the IRS Home Page, or by submitting comments directly to the IRS internet site at <http://www.irs.ustreas.gov/>

tax_regs/regslst.html. The public hearing will be held in room 4718, Internal Revenue Building, 1111 Constitution Avenue, NW., Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Concerning the regulations, Gerald B. Fleming or George R. Johnson, (202) 622-7930; concerning submissions of comments, the hearing and/or to be placed on the building access list to attend the hearing, Sonya Cruse, (202) 622-7180 (not toll-free numbers).

SUPPLEMENTARY INFORMATION:

Paperwork Reduction Act

The collection of information contained in this notice of proposed rulemaking has been submitted to the Office of Management and Budget for review in accordance with the Paperwork Reduction Act of 1995 (44 U.S.C. 3507(d)).

Comments on the collection of information should be sent to the Office of Management and Budget, Attn: Desk Officer for the Department of the Treasury, Office of Information and Regulatory Affairs, Washington, DC 20503, with copies to the Internal Revenue Service, Attn: IRS Reports Clearance Officer, OP:FS:FP, Washington, DC 20224. Comments on the collection of information should be received by November 27, 2000.

Comments are specifically requested concerning:

Whether the proposed collection of information is necessary for the proper performance of the functions of the Internal Revenue Service, including whether the collection will have practical utility;

The accuracy of the estimated burden associated with the proposed collection of information;

How the quality, utility, and clarity of the information to be collected may be enhanced;

How the burden of complying with the proposed collection of information may be minimized, including through the application of automated collection techniques or other forms of information technology; and

Estimates of capital or start-up costs and costs of operation, maintenance, and purchase of services to provide information.

The collection of information in the proposed regulations is in § 1.1502-77(d). This information is required for the common parent to notify the IRS of the designation of a new agent for the consolidated group when the common parent's existence is about to terminate and for the designated corporation to confirm that it agrees to serve as the

group's new agent and qualifies to be the group's agent. The collection of information is required to obtain a benefit, i.e., to designate a new agent for the consolidated group. The likely respondents are business or other for-profit institutions.

The regulations provide that a common parent or a previously designated agent of a consolidated group should notify the Commissioner in writing, in accordance with procedures prescribed by the Commissioner, that it anticipates going out of existence and that it designates another corporation to serve as the group's agent for specified prior consolidated return years. In addition, the notification should include a statement by the designated corporation agreeing to serve as the group's agent and, if the designated corporation was not itself a member of the group, a statement that it is or will be liable for the tax. An agent designated by the Commissioner is required to give notice to each corporation (or any successor) that was a member of the group during any part of the relevant consolidated return year. The burden for the collection of information in § 1.1502-77(d) is as follows:

Estimated total annual reporting burden: 200 hours.

Estimated average annual burden per respondent: 2 hours.

Estimated number of respondents: 100.

Estimated annual frequency of responses: On occasion.

An agency may not conduct or sponsor, and a person is not required to respond to, a collection of information unless it displays a valid control number assigned by the Office of Management and Budget.

Books or records relating to a collection of information must be retained as long as their contents may become material in the administration of any internal revenue law. Generally, tax returns and tax return information are confidential, as required by 26 U.S.C. 6103.

Background

This document proposes amendments to 26 CFR part 1 under section 1502 of the Internal Revenue Code of 1986 (Code). The proposed amendments clarify and supplement existing rules under § 1.1502-77 concerning the agent for a consolidated group and the designation of a new agent to act for the group. The proposed amendments also clarify rules concerning the common parent as agent for a corporation whose income is improperly included in a consolidated return. In addition, the