

(1) The incorporation by reference of McDonnell Douglas Alert Service Bulletin MD11-25A194, Revision 06, dated January 27, 2000, is approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(2) The incorporation by reference of McDonnell Douglas Alert Service Bulletin MD11-25A194, Revision 05, dated June 21, 1999; and McDonnell Douglas Alert Service Bulletin MD11-24A068, Revision 01, dated March 8, 1999, was approved previously by the Director of the Federal Register as of March 23, 2000 (65 FR 8034, February 17, 2000).

(3) Copies may be obtained from Boeing Commercial Aircraft Group, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Technical Publications Business Administration, Dept. C1-L51 (2-60). Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles ACO, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(i) This amendment becomes effective on January 8, 2001.

Issued in Renton, Washington, on November 22, 2000.

Donald L. Riggan,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-30436 Filed 12-1-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-NM-33-AD; Amendment 39-12019; AD 2000-24-12]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model MD-11 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain McDonnell Douglas Model MD-11 series airplanes, that requires an inspection to detect chafing or damage of the electrical wires leading to the terminal strips in the center accessory compartment (CAC) area; and corrective actions, if necessary. This amendment also requires revising the wire connection stack up of certain cable terminals at the electrical power center bays in the CAC,

and replacing certain terminal strips with new strips and removing applicable nameplates at electrical power center bays. This action is necessary to prevent arcing and sparking damage to the power feeder cables, terminal strips, and adjacent structure, and consequent smoke and fire in the CAC. This action is intended to address the identified unsafe condition.

DATES: Effective January 8, 2001. The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of January 8, 2001.

ADDRESSES: The service information referenced in this AD may be obtained from Boeing Commercial Aircraft Group, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Technical Publications Business Administration, Dept. C1-L51 (2-60). This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Brett Portwood, Aerospace Engineer, Systems and Equipment Branch, ANM-130L, FAA, Transport Airplane Directorate, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5350; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain McDonnell Douglas Model MD-11 series airplanes was published in the **Federal Register** on July 27, 2000 (65 FR 46211). That action proposed to require an inspection to detect chafing or damage of the electrical wires leading to the terminal strips in the center accessory compartment (CAC) area; and corrective actions, if necessary. That action also proposed to require revising the wire connection stack up of certain cable terminals at the electrical power center bays in the CAC, and replacing certain terminal strips with new strips and removing applicable nameplates at electrical power center bays.

Comments

Interested persons have been afforded an opportunity to participate in the

making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

Conclusion

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

There are approximately 151 Model MD-11 series airplanes of the affected design in the worldwide fleet. The FAA estimates that 59 airplanes of U.S. registry will be affected by this AD, that it will take approximately between 6 and 8 work hours per airplane depending on the configuration of the airplane to accomplish the required actions, and that the average labor rate is \$60 per work hour. Required parts will cost approximately between \$1,091 and \$1,256 per airplane depending on the configuration of the airplane. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be between \$85,609 and \$102,424, or between \$1,451 and \$1,736 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has

been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2000–24–12 McDonnell Douglas:

Amendment 39–12019. Docket 2000–NM–33–AD.

Applicability: Model MD–11 series airplanes, as listed in McDonnell Douglas Alert Service Bulletin MD11–24A097, dated April 3, 2000; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent arcing and sparking damage to the power feeder cables, terminal strips, and adjacent structure, and consequent smoke and fire in the center accessory compartment, accomplish the following:

Inspection

(a) Within 12 months after the effective date of this AD, perform a one-time general visual inspection to detect chafing or damage of the electrical wires leading to the terminal strips in the center accessory compartment area, in accordance with McDonnell Douglas Alert Service Bulletin MD11–24A097, dated April 3, 2000.

Note 2: For the purposes of this AD, a general visual inspection is defined as “A

visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or drop-light, and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked.”

Condition 1 (No Chafing or Damage)

(1) If no chafing or damage is detected, no further action is required by this paragraph.

Condition 2 (Evidence of Chafing or Damage on Terminal Strips)

(2) If any chafing or damage is detected on the terminal strips, before further flight, replace the terminal strip with a like part and seal screw heads of replaced terminal strips, in accordance with the service bulletin.

Condition 3 (Chafing or Damage Within Limits)

(3) If any chafing is detected and if any damage is detected within the limits specified in the service bulletin, before further flight, repair damage in accordance with the service bulletin.

Condition 4 (Chafing or Damage Beyond Limits)

(4) If any chafing is detected and if any damage is detected beyond the limits specified in the service bulletin, before further flight, replace damaged wires with new wires in accordance with the service bulletin.

Revise Wire Connection of the Cable Terminal Strips

(b) Within 12 months after the effective date of this AD, revise the wire connection stack up of certain cable terminals at the electrical power center bays in the center accessory compartment in accordance with McDonnell Douglas Alert Service Bulletin MD11–24A097, dated April 3, 2000.

Replacement of Terminal Strips and Removal of Nameplate

(c) Within 12 months after the effective date of this AD, replace the terminal strips with new strips and remove the applicable nameplate at electrical power center bays in the center accessory compartment, in accordance with McDonnell Douglas Alert Service Bulletin MD11–24A097, dated April 3, 2000.

Alternative Methods of Compliance

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

Special Flight Permit

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(f) The actions shall be done in accordance with McDonnell Douglas Alert Service Bulletin MD11–24A097, dated April 3, 2000. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Aircraft Group, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Technical Publications Business Administration, Dept. C1–L51 (2–60). Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles ACO, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(g) This amendment becomes effective on January 8, 2001.

Issued in Renton, Washington, on November 22, 2000.

Donald L. Riggan,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00–30437 Filed 12–1–00; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000–NM–34–AD; Amendment 39–12020; AD 2000–24–13]

RIN 2120–AA64

Airworthiness Directives; McDonnell Douglas Model MD–11 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain McDonnell Douglas Model MD–11 series airplanes, that requires replacing the ground support bracket(s); and rerouting the ground cables of the galley external power and main external power, or ground cables of the main external power; as applicable. This action is necessary to prevent arcing and heat damage to the attachment points of the main external and galley power