

Unexpended funds may be used temporarily to defray expenses of the subsequent marketing year, but must be made available to the handlers from whom collected within 5 months after the end of the year (§ 984.69).

A review of historical information and preliminary information pertaining to the current marketing year indicates that the grower price for 2000–01 could range between \$0.50 and \$0.70 per kernelweight pound of assessable walnuts. Therefore, the estimated assessment revenue for the 2000–01 year as a percentage of total grower revenue could range between 2.0 and 2.7 percent.

Regarding the impact of this action on affected entities, this action will increase the assessment rate currently imposed on walnut handlers. While assessments impose some additional costs on handlers, the costs are minimal and uniform on all handlers. Some of the additional costs may be passed on to producers. However, these costs are offset by the benefits derived by the operation of the order.

In addition, the Board's meeting was widely publicized throughout the walnut industry and all interested persons were invited to attend and participate in Board deliberations on all issues. Like all Board meetings, the September 8, 2000, meeting was a public meeting and all entities, both large and small, were able to express views on this issue.

This rule imposes no additional reporting or recordkeeping requirements on either small or large California walnut handlers. As with all Federal marketing order programs, reports and forms are periodically reviewed to reduce information requirements and duplication by industry and public sectors agencies.

The Department has not identified any relevant Federal rules that duplicate, overlap, or conflict with this rule.

A proposed rule concerning this action was published in the **Federal Register** on October 23, 2000 (65 FR 63219). Copies of the proposed rule were also mailed or sent via facsimile to all walnut handlers. The proposal was made available through the Internet by the Office of the Federal Register. A 30-day comment period ending November 22, 2000 was provided for interested persons to respond to the proposal. No comments were received.

A small business guide on complying with fruit, vegetable, and specialty crop marketing agreements and orders may be viewed at: <http://www.ams.usda.gov/fv/moab.html>. Any questions about the compliance guide should be sent to Jay

Guerber at the previously mentioned address in the **FOR FURTHER INFORMATION CONTACT** section.

After consideration of all relevant material presented, including the information and recommendation submitted by the Board and other available information, it is hereby found that this rule, as hereinafter set forth, will tend to effectuate the declared policy of the Act.

Pursuant to 5 U.S.C. 553, it also found and determined that good cause exists for not postponing the effective date of this rule until 30 days after publication in the **Federal Register** because: (1) The 2000–01 marketing year began on August 1, 2000, and the order requires that the rate of assessment for each marketing year apply to all merchantable walnuts handled during the year; (2) the Board needs to have sufficient funds to pay its expenses which are incurred on a continuous basis; (3) handlers are aware of this action which was unanimously recommended at a public meeting and is similar to other assessment rate actions issued in past years; and (4) a proposed rule on this action was published in the **Federal Register** and no comments were received.

List of Subjects in 7 CFR Part 984

Marketing agreements, Nuts, Reporting and recordkeeping requirements, Walnuts.

For the reasons set forth in the preamble, 7 CFR part 984 is amended as follows:

PART 984—WALNUTS GROWN IN CALIFORNIA

1. The authority citation for 7 CFR part 984 continues to read as follows:

Authority: 7 U.S.C. 601–674.

2. Section 984.347 is revised to read as follows:

§ 984.347 Assessment rate.

On and after August 1, 2000, an assessment rate of \$0.0134 per kernelweight pound is established for California merchantable walnuts.

Dated: December 8, 2000.

Robert C. Keeney,

Deputy Administrator, Fruit and Vegetable Programs.

[FR Doc. 00–31797 Filed 12–13–00; 8:45 am]

BILLING CODE 3410–02–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000–NE–43–AD; Amendment 39–12040; AD 2000–25–06]

RIN 2120–AA64

Airworthiness Directives; Pratt & Whitney PW4000 Series Turbofan Engines.

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule, request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to certain Pratt & Whitney (PW) PW4000 turbofan engines with the current design low pressure turbine (LPT) 4th stage air seal installed. This action requires, based on engine model, replacement of the current design seal with a new design seal, or with a modified seal. This amendment is prompted by reports of cracks in LPT 4th stage air seals. The actions specified by this AD are intended to reduce stresses that could lead to LPT 4th stage air seal cracking, resulting in seal fracture, uncontained engine failure, and damage to the airplane.

DATES: Effective date December 29, 2000. Comments for inclusion in the Rules Docket must be received on or before December 29, 2000.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 2000–NE–43–AD, 12 New England Executive Park, Burlington, MA 01803–5299. Comments may also be sent via the Internet using the following address: “*9-ane-adcomment@faa.gov*”. Comments sent via the Internet must contain the docket number in the subject line. The service information referenced under the caption **SUPPLEMENTARY INFORMATION** may be obtained from Pratt & Whitney, 400 Main St., East Hartford, CT 06108; telephone: (860) 565–6600, fax: (860) 565–4503. This information may be examined at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA.

FOR FURTHER INFORMATION CONTACT: Tara Goodman, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803–5299; telephone: (781) 238–7130; fax: (781) 238–7199.

SUPPLEMENTARY INFORMATION: The FAA recently received reports of five LPT 4th stage air seals found cracked. An investigation revealed that the cracking is being caused by excessive axial loads on the air seal. The thermal environment and mechanical loads are causing the current design LPT 4th stage air seals to grow radially and axially.

This is causing insufficient distance between the LPT stage 3 disk and LPT stage 4 disk, that results in an excessive axial load leading to air seal cracks. This action requires, based on engine model, replacement of the current design seal with a new design seal, or with a modified seal. This amendment is prompted by reports of cracks in LPT 4th stage air seals. The actions specified by this AD are intended to reduce stresses that could lead to LPT 4th stage air seal cracking, resulting in seal fracture, uncontained engine failure, and damage to the airplane. Pratt & Whitney has issued two relevant Alert Service Bulletins, (ASB) No. PW4G-100-A72-155, Revision 1, dated October 27, 2000, and ASB No. PW4ENG A72-707, Revision 1, dated October 27, 2000. The ASB's introduce a new design LPT 4th stage air seal P/N 51N038, and provide instructions for modifying the current design air seal P/N 50N478 to increase service life.

Required Actions

Since the unsafe condition described is likely to exist or develop on other engines of the same type design that are certificated for operation in the United States, this AD is being issued to replace, based on engine model, the current design seal P/N 50N478 with a new design seal P/N 51N038, or modification of the current design seal. This AD is also being issued to reduce stresses that could lead to LPT 4th stage air seal cracking, resulting in seal fracture, uncontained engine failure, and damage to the airplane.

Immediate Adoption

Since a situation exists that requires the immediate adoption of this regulation, it is found that notice and opportunity for prior public comment hereon are impracticable, and that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

Although this action is in the form of a final rule that involves requirements affecting flight safety and, thus, was not preceded by notice and an opportunity for public comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or

arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2000-NE-43-AD." The postcard will be date stamped and returned to the commenter.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order (EO) No. 13132.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and is not a "significant regulatory action" under EO No. 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2000-25-06 Pratt & Whitney:

Amendment 39-12040. Docket 2000-NE-43-AD.

Applicability: This airworthiness directive is applicable to Pratt & Whitney (PW) PW4052, PW4056, PW4060, PW4060A, PW4062, PW4152, PW4156, PW4156A, PW4158, PW4164, PW4168, PW4168A, PW4460, and PW4462 turbofan engines, with low pressure turbine (LPT) 4th stage air seal, part number (P/N) 50N478 or P/N 50N478-001 installed. These engines are installed on but not limited to Boeing 747, 767, McDonnell Douglas MD-11, Airbus Industrie A300, A310, and A330 series airplanes.

Note 1: This airworthiness directive (AD) applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance

Compliance with this AD is required as indicated, unless already done.

To reduce stresses that could lead to fatigue cracking of the LPT 4th stage air seal, resulting in seal fracture, uncontained engine failure, and damage to the airplane, do the following:

(a) If the limits in Table 1 of this AD for 4th stage air seal P/N 50N478 or P/N 50N478-001 have been exceeded, replace with a serviceable part prior to further flight.

(b) Replace 4th stage air seal, P/N 50N478 or 50N478-001, with a serviceable part, based on engine model, prior to exceeding the cycles-since-new (CSN) or cycles-in-

service (CIS) time limits in Table 1 of this AD.

TABLE 1.—4TH STAGE AIR SEAL TIME LIMITS

Engine model	4th stage air seal P/N	Cycles-since-new (CSN) on effective date of this AD	Limit
(1) PW4052, PW4060, PW4060A, PW4156, and PW4158.	50N478	Fewer than or equal to 8,000 CSN	8,000 CSN.
(2) PW4056, PW4152, PW4156A, and PW4460, that have incorporated service bulletin (SB) PW4ENG 72-657, Revision 1, dated July 19, 2000.	50N478	Fewer than or equal to 8,000 CSN	8,000 CSN.
(3) PW4056, PW4152, PW4156A, and PW4460, that have not incorporated SB PW4ENG 72-657, Revision 1, dated July 19, 2000.	50N478	Fewer than or equal to 4,500 CSN	4,500 CSN.
(4) PW4062 and PW4462	50N478	Fewer than or equal to 7,000 CSN	7,000 CSN.
(5) PW4164, PW4168, and PW4168A	(i) 50N478 or 50N478-001. (ii) 50N478 or 50N478-001. (iii) 50N478 or 50N478-001.	Fewer than or equal to 3,000 CSN More than 3,000 CSN but fewer than or equal to 4,500 CSN. More than 4,500 CSN but fewer than 6,000 SCN.	4,500 CSN. 1,500 CIS after the effective date of this AD. 6,000 CSN.

For the purposes of this AD, a serviceable part is defined in Table 2 as follows:

TABLE 2.—SERVICEABLE PARTS

For engine models	Serviceable P/N
(1) PW4052, PW4056, PW4060, PW4060A, PW4062, PW4152, PW4156, PW4156A, PW4158, PW4460, and PW4462.	51N038 or 50N478-001
(2) PW4164, PW4168, and PW4168A.	51N038

Alternative Methods of Compliance

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Engine Certification Office.

Note 2: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the Engine Certification Office.

Special Flight Permits

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the aircraft to a location where the inspection and rework requirements of this AD can be accomplished.

Effective Date of This AD

(f) This amendment becomes effective December 29, 2000.

Issued in Burlington, Massachusetts, on December 5, 2000.

Diane S. Romanosky,
Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.
[FR Doc. 00-31537 Filed 12-13-00; 8:45 am]
BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 97

[Docket No. 30220; Amdt. No. 2027]

Standard Instrument Approach Procedures; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This amendment establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAP's) for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, addition of new obstacles, or changes in air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

DATES: An effective date for each SIAP is specified in the amendatory provisions.

Incorporation by reference approved by the Director of the Federal Register on December 31, 1980, and reapproved as of January 1, 1982.

ADDRESSES: Availability of matters incorporated by reference in the amendment is as follows:

- For Examination—*
 1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591;
 2. The FAA Regional Office of the region in which the affected airport is located; or
 3. The Flight Inspection Area Office which originated the SIAP.

*For Purchase—*Individual SIAP copies may be obtained from:

- 1. FAA Public Inquiry Center (APA-200), FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591; or
- 2. The FAA Regional Office of the region in which the affected airport is located.

*By Subscription—*Copies of all SIAP's, mailed once every 2 weeks, are for sale by the Superintendent of Documents, U.S. Government Printing Office, Washington, DC 20402.

FOR FURTHER INFORMATION CONTACT: Donald P. Pate, Flight Procedure Standards Branch (AMCAFS-420), Flight Technologies and Programs Division, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd., Oklahoma City,