

Rules and Regulations

Federal Register

Vol. 66, No. 5

Monday, January 8, 2001

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-CE-79-AD; Amendment 39-12066; AD 2000-26-16]

RIN 2120-AA64

Airworthiness Directives; Raytheon Aircraft Company Beech Models A36, B36TC, and 58 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that applies to certain Raytheon Aircraft Company (Raytheon) Beech Models A36, B36TC, and 58 airplanes. This AD requires you to inspect for missing rivets on the right hand side of the fuselage and, if necessary, install rivets. Raytheon has identified several instances of missing rivets on these airplanes. The actions specified by this AD are intended to install missing rivets in the right hand fuselage panel assembly in the area above the right wing and below the cabin door threshold. These rivets must be present for the fuselage to carry the ultimate load and prevent critical structural failure with loss of airplane control.

DATES: This AD becomes effective on February 16, 2001.

The Director of the **Federal Register** approved the incorporation by reference of certain publications listed in the regulations as of February 16, 2001.

ADDRESSES: You may get the service information referenced in this AD from Raytheon Aircraft Company, P.O. Box

85, Wichita, Kansas 67201-0085; telephone: (800) 429-5372 or (316) 676-3140. You may examine this information at the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 99-CE-79-AD, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: T.N. Baktha, Aerospace Engineer, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Mid-Continent Airport, Wichita, Kansas 67209; telephone: (316) 946-4155; facsimile: (316) 946-4407.

SUPPLEMENTARY INFORMATION:

Discussion

What Events Have Caused This AD?

Raytheon has identified several instances of missing rivets on these airplanes:

Model	Serial No.
Model A36 Bonanza	serials E-1 through E-3231; and E-3233.
Model B36TC Bonanza	serials EA-1 through EA-635.
Model 58 Baron	serials TH-1 through TH-1811; and TH-1813 through TH-1897.

Raytheon production and inspection personnel identified the missing rivets. The missing rivets are the result of a quality control problem.

What Are the Consequences if the Condition Is Not Corrected?

This condition results in the airplane being unable to carry the ultimate load with possible structural failure and loss of airplane control.

Has FAA Taken Any Action to This Point?

We issued a proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to certain Raytheon Beech Models A36, B36TC, and 58 airplanes. This proposal was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on September 26,

2000 (65 FR 57751). The NPRM proposed to require you to inspect for missing rivets on the right hand fuselage and if necessary, install rivets.

Was the Public Invited To Comment?

Interested persons were afforded an opportunity to participate in the making of this amendment. No comments were received on the proposed rule or the FAA's determination of the cost to the public.

The FAA's Determination

What Is FAA's Final Determination on This Issue?

After careful review of all available information related to the subject presented above, we have determined that air safety and the public interest require the adoption of the rule as

proposed except for minor editorial corrections. We determined that these minor corrections:

- Will not change the meaning of the AD; and
- Will not add any additional burden upon the public than was already proposed.

Cost Impact

How Many Airplanes Does This AD impact?

We estimate that this AD affects 3632 airplanes in the U.S. registry.

What Is the Cost Impact of This AD on Owners/Operators of the Affected Airplanes?

We estimate the following costs to accomplish the inspection:

Labor cost	Parts cost	Total cost per airplane	Total cost on U.S. operators
1 workhour × \$60 per hour = \$60	No parts required for the inspection.	\$60 per airplane	\$60 × = \$217,920.

We estimate the following costs to accomplish the modification if necessary:

Laobor cost	Parts cost	Total cost per airplane
4 workouts × \$60 per hour = \$240	\$100 per airplane	\$340 per airplane.

The manufacturer will allow warranty credit for labor and parts to the extent noted in the service bulletin.

Regulatory Impact

Does This AD Impact Various Entities?

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

Does This AD Involve a Significant Rule or Regulatory Action?

For the reasons discussed above, I certify that this action (1) is not a “significant regulatory action” under

Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the final evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator,

the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. FAA amends § 39.13 by adding a new AD to read as follows:

2000–26–16 Raytheon Aircraft Company:
Amendment 39–12066; Docket No. 99–CE–79–AD.

(a) *What airplanes are affected by this AD?*
This AD affects the following airplanes, certificated in any category:

Model	Serial No.
Model A36	E–1 through E–3231, and E–3233.
Model B36TC	EA–1 through EA–635.
Model 58	TH–1 through TH–1811, and TH–1813 through TH–1897.

(b) *Who must comply with this AD?*
Anyone who wishes to operate any of the above airplanes must comply with this AD.

(c) *What problem does this AD address?*
The actions specified by this AD are intended

to install missing rivets in the right hand fuselage panel assembly in the area above the right wing and below the cabin door threshold. These rivets must be present for the fuselage to carry the ultimate load and

prevent critical structural failure with loss of control of the airplane.

(d) *What actions must I accomplish to address this problem?* To address this problem, you must do the following actions:

Actions	Compliance times	Procedures
(1) Inspect for up to 9 missing rivets between fuselage station (F.S.) 83.00 and F.S. 91.00 at water line (W.L.) 90.3.	Inspect within the next 100 hours time-in-service after February 16, 2001 (the effective date of this AD).	Do this inspection in accordance with the AC-COMPLISHMENT INSTRUCTIONS paragraph of Raytheon Mandatory Service Bulletin SB 53–3341, Revision 1, Revised: May 2000, and the Bonanza Series Maintenance Manual or Baron Model 58 Series Maintenance Manual.
(2) If you find rivets are missing, install these rivets.	Before further flight after the inspection	Do these actions in accordance with the AC-COMPLISHMENT INSTRUCTIONS paragraph of Raytheon Mandatory Service Bulletin SB 53–3341, Revision 1, Revised: May 2000, and the Bonanza Series Maintenance Manual or Baron Model 58 Series Maintenance Manual.

(e) *Can I comply with this AD in any other way?* You may use an alternative method of compliance or adjust the compliance time if:

(1) Your alternative method of compliance provides an equivalent level of safety; and

(2) The Manager, Wichita Aircraft Certification Office (ACO), approves your alternative. Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Wichita ACO.

Note: This AD applies to each airplane identified in paragraph (a) of this AD, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(f) *Where can I get information about any already-approved alternative methods of compliance?* Contact T.N. Baktha, Aerospace Engineer, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Mid-Continent Airport, Wichita, Kansas 67209; telephone: (316) 946-4155; facsimile: (316) 946-4407.

(g) *What if I need to fly the airplane to another location to comply with this AD?* The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your airplane to a location where you can accomplish the requirements of this AD.

(h) *Are any service bulletins incorporated into this AD by reference?* Actions required by this AD must be done in accordance with Raytheon Mandatory Service Bulletin SB 53-3341, Revision 1, revised May 2000. The Director of the Federal Register approved this incorporation by reference under 5 U.S.C. 552(a) and 1 CFR part 51. You can get copies from Raytheon Aircraft Company, P.O. Box 85, Wichita, Kansas 67201-0085; telephone: (800) 429-5372 or (316) 676-3140. You can look at copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

(i) *When does this amendment become effective?* This amendment becomes effective on February 16, 2001.

Issued in Kansas City, Missouri, on December 22, 2000.

Marvin R. Nuss,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01-183 Filed 1-5-01; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-CE-55-AD; Amendment 39-12067; AD 2000-26-17]

RIN 2120-AA64

Airworthiness Directives; Pilatus Aircraft Ltd. Models PC-12 and PC-12/45 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that applies to Pilatus Aircraft Ltd. (Pilatus) Models PC-12 and PC-12/45 airplanes that are equipped with a certain windshield configuration. This AD requires you to incorporate pilot's operating handbook (POH) information that prohibits the operation of the windshield heating system in the "LIGHT" mode, and requires you to modify the windshield deicing system wiring and circuit breakers. You can remove the POH information after accomplishing the modification. This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Switzerland. The actions specified by this AD are intended to prevent loss of electrical power to the windshield deicing system due to operation in the "LIGHT" mode, which could result in icing of the windshield and loss of control of the airplane.

DATES: This AD becomes effective on February 24, 2001.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulations as of February 24, 2001.

ADDRESSES: You may get the service information referenced in this AD from Pilatus Aircraft Ltd., Customer Liaison Manager, CH-6371 Stans, Switzerland; telephone: +41 41 619 63 19; facsimile: +41 41 619 6224; or from Pilatus Business Aircraft Ltd., Product Support Department, 11755 Airport Way, Broomfield, Colorado 80021; telephone: (303) 465-9099; facsimile: (303) 465-6040. You may examine this information at the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2000-CE-55-AD, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Roman T. Gabrys, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4141; facsimile: (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Discussion

What Events Have Caused This AD?

The Federal Office for Civil Aviation (FOCA), which is the airworthiness authority for Switzerland, recently notified the FAA that an unsafe condition may exist on certain Pilatus Models PC-12 and PC-12/45 airplanes. The FOCA reports that the electrical load of the left hand (LH) and right hand (RH) windshields can become too high during flight at cruise altitudes when the "LIGHT" mode is selected on the windshield deicing system. The FOCA references eight instances where prolonged operation of the windshield deicing system in the "LIGHT" mode caused this system to temporarily shut down.

The airplanes involved in the above instances were equipped with part number (P/N) 959.81.10.107 LH and P/N/ 959.81.10.108 RH windshields.

What Are the Consequences if the Condition Is Not Corrected?

Operation of the existing design windshield deicing system in the "LIGHT" position can overload the electrical capacity of the wiring and circuit breakers. This could result in complete electrical power loss to the windshield and icing of the windshield.

Has FAA Taken Any Action to this Point?

We issued a proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to Pilatus Models PC-12 and PC-12/45 airplanes that are equipped with a certain windshield configuration. This proposal was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on October 2, 2000 (65 FR 58675). The NPRM proposed to require you to incorporate POH information that would prohibit the operation of the windshield heating system in the "LIGHT" mode, and would require you to modify the windshield deicing system wiring and circuit breakers. You could remove the POH information after accomplishing the modification.

Was the Public Invited To Comment?

Interested persons were afforded an opportunity to participate in the making of this amendment. No comments were