

Principal Maintenance Inspector, who may add comments and then send it to the Manager, Small Airplane Directorate.

**Note 1:** This AD applies to each airplane identified in paragraph (a) of this AD, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(f) *Where can I get information about any already-approved alternative methods of compliance?* Contact Mr. Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; facsimile: (816) 329-4090.

(g) *What if I need to fly the airplane to another location to comply with this AD?* The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your airplane to a location where you can accomplish the requirements of this AD.

(h) *Are any service bulletins incorporated into this AD by reference?* Actions required by this AD must be done in accordance with APPH Ltd. Service Newsletter, Issue 2, Jetstream 31 Steering Jack Part Number 618200, as referenced in British Aerospace Mandatory Service Bulletin 32-JA 981043, dated March 5, 1999. The Director of the Federal Register approved this incorporation by reference under 5 U.S.C. 552(a) and 1 CFR part 51. You can get copies from British Aerospace Regional Aircraft, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland. You can look at copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

(i) *When does this amendment become effective?* This amendment becomes effective on March 5, 2001.

**Note 2:** The subject of this AD is addressed in British AD 012-03-99.

Issued in Kansas City, Missouri, on January 4, 2001.

**Michael Gallagher,**

*Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 01-916 Filed 1-16-01; 8:45 am]

**BILLING CODE 4910-13-U**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2000-NM-48-AD; Amendment 39-12052; AD 2000-26-03]

RIN 2120-AA64

#### **Airworthiness Directives; Airbus Model A310, and Model A300 B4-600, A300 B4-600R, and A300 F4-600R (A300-600) Series Airplanes**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule; correction.

**SUMMARY:** This document corrects a typographical error that appeared in airworthiness directive (AD) 2000-26-03, which was published in the **Federal Register** on December 28, 2000 (65 FR 82262). The typographical error resulted in the misidentification of affected airplanes. This AD is applicable to Airbus Model A310, and Model A300 B4-600, A300 B4-600R, and A300 F4-600R (A300-600) series airplanes. This AD requires new wiring modifications for the engine and the fire detection system of the auxiliary power unit.

**EFFECTIVE DATE:** Effective February 1, 2001.

#### **FOR FURTHER INFORMATION CONTACT:**

Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

#### **SUPPLEMENTARY INFORMATION:**

Airworthiness Directive (AD) 2000-26-03, amendment 39-12052, was published in the **Federal Register** on December 28, 2000 (65 FR 82262). The AD requires new wiring modifications for the engine and auxiliary power unit (APU) fire detection system.

As published, AD 2000-26-03 incorrectly substituted a nonaffected group of airplanes for an affected group. Specifically, the AD substituted Model A300 B2 and B4 series airplanes for Model A310 series airplanes. The NPRM for this AD correctly identified the affected airplanes.

Since no other part of the regulatory information has been changed, the final rule is not being republished in the **Federal Register**.

The effective date of this AD remains February 1, 2001.

In AD 2000-26-03, amendment 39-12052, make the following corrections:

1. On page 82262, in the first column, the subject heading should read

“Airworthiness Directives; Airbus Model A310 Series Airplanes, and Model A30A300 B4-600, A300 B4-600R, and A300 F4-600R (A300-600) Series Airplanes.”

2. On page 82262, in the first column, under the heading **Summary**, in the fourth line, “A300 B2 and B4” should read “A310.”

3. On page 82262, in the second column, under the heading **Cost Impact**, in the second line of the first paragraph, “A300 B2 and B4” should read “A310.”

#### **§ 39.13 [Corrected]**

4. On page 82262, in the third column, the applicability of AD 2000-26-03 is corrected to read as follows:

\* \* \* \* \*

*Applicability:* Model A310 series airplanes, and Model A300 B4-600, A300 B4-600R, and A300 F4-600R (A300-600) series airplanes; certificated in any category; except those on which Airbus Modifications 06267 and 07340 have been accomplished during production.

\* \* \* \* \*

Issued in Renton, Washington, on January 8, 2001.

**Donald L. Riggan,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 01-1231 Filed 1-16-01; 8:45 am]

**BILLING CODE 4910-13-U**

## DEPARTMENT OF THE INTERIOR

### Bureau of Indian Affairs

#### 25 CFR Part 103

RIN 1076-AD73

#### **Loan Guaranty, Insurance, and Interest Subsidy**

**AGENCY:** Bureau of Indian Affairs, Interior.

**ACTION:** Final rule.

**SUMMARY:** The Department of the Interior (DOI), Bureau of Indian Affairs (BIA) is revising the regulations that implement the Loan Guaranty, Insurance, and Interest Subsidy Program. This Program authorizes the Secretary of DOI to guaranty or insure loans made by private lenders to individual Indians and to organizations of Indians, and to assist qualified borrowers with a portion of their interest payments. The new regulations clarify prior regulatory language, in keeping with the “plain language” standard required by Executive Order 12866. They also reflect evolved BIA policies, and address several issues that prior regulations did not cover.