

occurs first: Do a general visual inspection to detect chafing or arcing damage to the cable and the fuel tube assemblies on the right hand side of each engine, per Bombardier Alert Service Bulletin A8-73-23, dated November 3, 2000. Repeat the inspection every 500 flight hours or 3 months, whichever occurs first.

Note 2: For the purposes of this AD, a general visual inspection is defined as: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or drop-light, and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

Repair

(b) If any damage to the fuel tube or cable assembly is detected, before further flight, replace the damaged component per Bombardier Alert Service Bulletin A8-73-23, dated November 3, 2000. Thereafter, repeat the inspection required by paragraph (a) of this AD every 500 flight hours or 3 months, whichever occurs first.

Optional Terminating Action

(c) Accomplishment of the modification instructions described in Bombardier Alert Service Bulletin A8-73-23, dated November 3, 2000, that specifies, among other actions, rerouting the existing wire harness to the opposite side of the oil cooler, constitutes terminating action for the repetitive inspection requirements of this AD.

Alternative Methods of Compliance

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, New York Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, New York ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the New York ACO.

Special Flight Permits

(e) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(f) The actions shall be done in accordance with Bombardier Alert Service Bulletin A8-73-23, dated November 3, 2000. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Bombardier, Inc., Bombardier Regional Aircraft Division, 123 Garratt Boulevard, Downsview, Ontario M3K 1Y5, Canada. Copies may be inspected at the FAA,

Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; at the FAA, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 4: The subject of this AD is addressed in Canadian airworthiness directive CF-2000-33, dated November 14, 2000.

Effective Date

(g) This amendment becomes effective on February 6, 2001.

Issued in Renton, Washington, on January 12, 2001.

Donald L. Riggin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01-1659 Filed 1-19-01; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 00-ANM-20]

RIN 2120-AA66

Amend Legal Description of Jet Route J-501

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; correction.

SUMMARY: This action corrects a final rule published in the **Federal Register** on November 20, 2000. The legal description of Jet Route 501 (J-501) contained an inadvertent error that included the intersection of the Bethel 258° radial and the Anchorage CTA/FIR boundary. This action corrects that error by removing the reference to the intersection.

EFFECTIVE DATE: 0901 UTC, January 25, 2001.

FOR FURTHER INFORMATION CONTACT: Ken McElroy, Airspace and Rules Division, ATA-400, Office of Air Traffic Airspace Management, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591; telephone: (202) 267-8783.

SUPPLEMENTARY INFORMATION: On November 20, 2000, Airspace Docket No. 00-ANM-20 (65 FR 69664), was published amending the legal description of J-501. This description contained an inadvertent error that included the intersection of the Bethel 258° radial and the Anchorage CTA/FIR boundary. This action corrects that error by removing the reference to the intersection.

Correction to Final Rule

Accordingly, pursuant to the authority delegated to me, the legal description for J-501, as published in the **Federal Register** on November 20, 2000, (65 FR 69664), and incorporated by reference in 14 CFR 71.1, is corrected as follows:

§ 71.1 [Corrected]

On page 69665, correct the legal description of J-501, to read as follows:

Paragraph 2004—Jet Routes

* * * * *

J-501 [Amended]

From San Marcus, CA, via Big Sur, CA; Point Reyes, CA, via Rogue Valley, OR; Hoquiam, WA; INT Hoquiam 354° and Tatoosh, WA, 162° radials; Tatoosh; Tofino, BC, Canada, RBN. From Sandspit, BC, Canada; Biorca Island, AK; Yakutat, AK; Johnstone Point, AK; Anchorage, AK; Sparrevohn, AK; Bethel, AK; excluding the airspace within Canada.

* * * * *

Issued in Washington, DC, on January 10, 2001.

Reginald C. Matthews,

Manager, Airspace and Rules Division.

[FR Doc. 01-1853 Filed 1-19-01; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 00-ANM-14]

Establishment of Class E Airspace, Prineville, OR

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action establishes the Prineville, OR, Class E airspace to accommodate airspace required for the establishment of a new Standard Instrument Approach Procedure (SIAP) to the Prineville Airport, Prineville, OR.

EFFECTIVE DATE: February 21, 2001.

FOR FURTHER INFORMATION CONTACT: Brian Durham, ANM-520.7, Federal Aviation Administration, Docket No. 00-ANM-14, 1601 Lind Avenue SW, Renton, Washington 98055-4056; telephone number: (425) 227-2527.

SUPPLEMENTARY INFORMATION:

History

On October 16, 2000, the FAA proposed to amend Title 14 Code of