

nacelle strut and wing structure required by paragraph (a) of this AD; as specified in paragraph 1.D., Table 2, "Prior or Concurrent Service Bulletins," on page 8 of Boeing Service Bulletin 767-54-0081, dated July 29, 1999; accomplish the actions specified in Boeing Service Bulletin 767-29-0057, dated December 16, 1993; Boeing Service Bulletin 767-54-0069, Revision 1, dated January 29, 1998, or Revision 2, dated August 31, 2000; Boeing Service Bulletin 767-54-0083, dated September 17, 1998; Boeing Service Bulletin 767-54-0088, Revision 1, dated July 29, 1999; Boeing Service Bulletin 767-54A0094, Revision 1, dated September 16, 1999; and Boeing Service Bulletin 767-57-0053, Revision 2, dated September 23, 1999; as applicable, in accordance with those service bulletins.

**Note 2:** AD 2000-12-17, amendment 39-11795, requires accomplishment of Boeing Service Bulletin 767-57-0053, Revision 2, dated September 23, 1999. However, inspections and rework accomplished in accordance with Boeing Service Bulletin 767-57-0053, Revision 1, dated October 31, 1996, are acceptable for compliance with the applicable actions required by paragraph (b) of this AD.

**Note 3:** AD 2000-07-05, amendment 39-11659, requires accomplishment of Boeing Service Bulletin 767-54A0094, dated May 22, 1998. Inspections and rework accomplished in accordance with Boeing Service Bulletin 767-54A0094, dated May 22, 1998, are acceptable for compliance with the applicable actions required by paragraph (b) of this AD.

**Note 4:** AD 2001-02-07, amendment 39-12091, requires accomplishment of Boeing Service Bulletin 767-54-0069, Revision 1, dated January 29, 1998, or Revision 2, dated August 31, 2000. Inspections and rework accomplished in accordance with those service bulletins are acceptable for compliance with the applicable actions required by paragraph (b) of this AD.

#### Repairs

(c) If any damage to the airplane structure is found during the accomplishment of the modification required by paragraph (a) of this AD, and the service bulletin specifies to contact Boeing for appropriate action: Prior to further flight, repair in accordance with a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, or a Boeing Company Designated Engineering Representative (DER) who has been authorized by the FAA to make such findings. For a repair method to be approved by the Manager, Seattle ACO, as required by this paragraph, the Manager's approval letter must specifically reference this AD.

#### Alternative Methods of Compliance

(d)(1) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

(2) An alternative method of compliance that provides an acceptable level of safety may be used for paragraph (a) of this AD, if it is approved by a Boeing Company DER who has been authorized by the FAA to make such findings.

(3) Alternative methods of compliance, approved previously in accordance with AD 2000-12-17, amendment 39-11795; AD 2000-07-05, amendment 39-11659; AD 2001-02-07, amendment 39-12091; and AD 94-11-02, amendment 39-8918; are approved as alternative methods of compliance with the applicable actions in paragraph (b) of this AD.

**Note 5:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

#### Special Flight Permits

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

#### Incorporation by Reference

(f) Except as required by paragraph (c) of this AD, the actions shall be done in accordance with Boeing Service Bulletin 767-54-0081, dated July 29, 1999; Boeing Service Bulletin 767-29-0057, dated December 16, 1993; Boeing Service Bulletin 767-54-0069, Revision 1, dated January 29, 1998, or Revision 2, dated August 31, 2000; Boeing Service Bulletin 767-54-0083, dated September 17, 1998; Boeing Service Bulletin 767-54-0088, Revision 1, dated July 29, 1999; Boeing Service Bulletin 767-54A0094, Revision 1, dated September 16, 1999; and Boeing Service Bulletin 767-57-0053, Revision 2, dated September 23, 1999; as applicable.

(1) The incorporation by reference of Boeing Service Bulletin 767-54-0081, dated July 29, 1999, is approved by the Director of the Federal Register, in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(2) The incorporation by reference of Boeing Service Bulletin 767-57-0053, Revision 2, dated September 23, 1999, was approved previously by the Director of the Federal Register as of July 24, 2000 (65 FR 37843, June 19, 2000).

(3) The incorporation by reference of Boeing Service Bulletin 767-29-0057, dated December 16, 1993; Boeing Service Bulletin 767-54-0069, Revision 1, dated January 29, 1998; Boeing Service Bulletin 767-54-0083, dated September 17, 1998; and Boeing Service Bulletin 767-54-0088, Revision 1, dated July 29, 1999; was approved previously by the Director of the Federal Register as of October 17, 2000 (65 FR 58641, October 2, 2000).

(4) The incorporation by reference of Boeing Service Bulletin 767-54-0069, Revision 2, dated August 31, 2000; and Boeing Service Bulletin 767-54A0094, Revision 1, dated September 16, 1999, was approved previously by the Director of the Federal Register as of March 5, 2001 (66 FR 8085, January 29, 2001).

(5) Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707,

Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

#### Effective Date

(g) This amendment becomes effective on May 7, 2001.

Issued in Renton, Washington, on March 22, 2001.

**Donald L. Riggins,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 01-7701 Filed 3-30-01; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2000-NM-316-AD; Amendment 39-12158; AD 2001-06-11]

RIN 2120-AA64

#### Airworthiness Directives; Airbus Model A330-301, -321, -322, -341, and -342 Series Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule; request for comments.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD) that is applicable to certain Airbus Model A330-301, -321, -322, -341, and -342 series airplanes. This action requires replacement of the existing fasteners on the vertical web of stringers 13 and 20 of both wings with interference fasteners. This action is necessary to prevent fatigue cracking of the wing bottom skin and vertical webs, which could result in reduced structural integrity of the wing. This action is intended to address the identified unsafe condition.

**DATES:** Effective April 17, 2001.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of April 17, 2001.

Comments for inclusion in the Rules Docket must be received on or before May 2, 2001.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-316-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this

location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-iarcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2000-NM-316-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in this AD may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2125; fax (425) 227-1149.

**SUPPLEMENTARY INFORMATION:** The Direction Générale de l'Aviation Civile (DGAC), which is the airworthiness authority for, notified the FAA that an unsafe condition may exist on certain Airbus Model A330-301, -321, -322, -341, and -342 series airplanes. The DGAC advises that, wing fatigue testing, cracks were found to be initiating and propagating at the bottom skin and in the vertical web of stringers 13 and 20, between ribs 1 and 2. This condition, if not corrected, could result in reduced structural integrity of the wing.

#### Explanation of Relevant Service Information

Airbus has issued Service Bulletin A330-57-3019, Revision 02, dated September 14, 2000, which describes procedures for replacement of the existing fasteners on the vertical web of stringers 13 and 20 of both wings with interference fasteners. The replacement involves drilling and reaming of the holes; performing an eddy current test to inspect for cracks and performing corrective actions, if necessary; and installing new oversize fasteners. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition. The DGAC classified this service bulletin as mandatory and issued French airworthiness directive 2000-358-124(B), dated August 23, 2000, in order

to assure the continued airworthiness of these airplanes in France.

#### FAA's Conclusions

These airplane models are manufactured in France and are type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

#### Explanation of Requirements of the Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design that may be registered in the United States at some time in the future, this AD will require accomplishment of the actions specified in the service bulletin described previously, except as discussed below.

#### Differences Between AD and Service Bulletin

Operators should note that, although the service bulletin specifies that the manufacturer may be contacted for disposition of certain repair conditions, this AD requires the repair of those conditions to be accomplished in accordance with a method approved by either the FAA or the DGAC (or its delegated agent). In light of the type of repair that would be required to address the identified unsafe condition, and in consonance with existing bilateral airworthiness agreements, the FAA has determined that, for this AD, a repair approved by either the FAA or the DGAC would be acceptable for compliance with this AD.

#### Cost Impact

None of the airplanes affected by this action are on the U.S. Register. All airplanes included in the applicability of this rule currently are operated by non-U.S. operators under foreign registry; therefore, they are not directly affected by this AD action. However, the FAA considers that this rule is necessary to ensure that the unsafe condition is addressed in the event that any of these subject airplanes are imported and placed on the U.S. Register in the future.

Should an affected airplane be imported and placed on the U.S. Register in the future, it would require approximately 10 work hours to accomplish the required replacement, at an average labor rate of \$60 per work hour. Required parts would cost approximately \$1,030 per airplane. Based on these figures, the cost impact of this AD would be \$1,630 per airplane.

#### Determination of Rule's Effective Date

Since this AD action does not affect any airplane that is currently on the U.S. register, it has no adverse economic impact and imposes no additional burden on any person. Therefore, prior notice and public procedures hereon are unnecessary and the amendment may be made effective in less than 30 days after publication in the **Federal Register**.

#### Comments Invited

Although this action is in the form of a final rule and was not preceded by notice and opportunity for public comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2000-NM-316-AD." The postcard will be date stamped and returned to the commenter.

### Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

**2001-06-11 Airbus Industrie:** Amendment 39-12158. Docket 2000-NM-316-AD.

**Applicability:** Model A330-301, -321, -322, -341, and -342 series airplanes which have not received Airbus Modification 43283, certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent fatigue cracking of the bottom skin and vertical webs of the airplane wings, which could result in reduced structural integrity of the wings, accomplish the following:

### Modification

(a) Before the accumulation of 17,200 total flight cycles, or 53,500 total flight hours, whichever occurs first, replace the applicable existing fasteners of the vertical web of stringers 13 and 20 of both wings with interference fasteners (including performing an eddy current test to inspect for cracks and performing applicable corrective actions), according to Airbus Service Bulletin A330-57-3019, Revision 02, dated September 14, 2000.

(b) If any crack is found during any inspection required by paragraph (a) of this AD, and the applicable service bulletin specifies to contact Airbus for appropriate action: Prior to further flight, repair in accordance with a method approved by either the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, or the Direction Générale de l'Aviation Civile (or its delegated agent).

### Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

### Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

### Incorporation by Reference

(e) The actions shall be done in accordance with Airbus Service Bulletin A330-57-3019,

Revision 02, dated September 14, 2000. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**Note 3:** The subject of this AD is addressed in French airworthiness directive 2000-358-124(B), dated August 23, 2000.

### Effective Date

(f) This amendment becomes effective on April 17, 2001.

Issued in Renton, Washington, on March 22, 2001.

**Vi L. Lipski,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 01-7696 Filed 3-30-01; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

### 14 CFR Part 39

[Docket No. 2000-NM-222-AD; Amendment 39-12161; AD 2001-06-14]

RIN 2120-AA64

### Airworthiness Directives; Saab Model SAAB SF340A and SAAB 340B Series Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD), applicable to certain Saab Model SAAB SF340A and SAAB 340B series airplanes, that requires installation of a new circuit breaker and related wiring, and relocation of circuit breaker 12FG, if applicable. The actions specified by this AD are intended to prevent loss of the nose wheel steering and reduced controllability of the airplane on the ground. This action is intended to address the identified unsafe condition.

**DATES:** Effective May 7, 2001.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of May 7, 2001.

**ADDRESSES:** The service information referenced in this AD may be obtained from Saab Aircraft AB, SAAB Aircraft Product Support, S-581.88, Linköping, Sweden. This information may be