

under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Fokker Services B.V.: Docket 99–NM–220–AD.

Applicability: Model F.28 Mark 1000, 2000, 3000, and 4000 series airplanes; serial numbers 11003 through 11091 inclusive, 11094 through 11171 inclusive, 11991, and 11992; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (f) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To detect and correct cracks in the upper girder of the main landing gear (MLG) bracket, which could progress into the vertical stiffeners of the MLG bracket and result in reduced structural integrity of the landing gear, accomplish the following:

Repetitive Inspections and Corrective Actions

(a) Within 12 months after the effective date of this AD, perform an eddy current inspection of the upper girder of the MLG brackets on the left and right sides of the airplane for cracks, in accordance with the

Accomplishment Instructions of Fokker Service Bulletin F28/57–90, Revision 1, dated August 28, 2000.

(1) If no cracks are found, repeat the inspection at least every 18 months, until accomplishment of paragraph (d) of this AD.

(2) Except as provided by paragraph (c) of this AD, if any crack is found, prior to further flight, repair as specified in paragraph C.(1) of the Accomplishment Instructions of the service bulletin, in accordance with the service bulletin. Thereafter, repeat the eddy current inspection at intervals not to exceed 18 months, until accomplishment of paragraph (d) of this AD.

Note 2: Inspections accomplished before the effective date of this AD in accordance with Fokker Service Bulletin F28/57–90, dated March 1, 1999, are considered acceptable for compliance with paragraph (a) of this AD.

Reporting Requirement

(b) Within 10 days after accomplishing each inspection required by paragraph (a) of this AD, submit a report of the inspection results to: Fokker Services B.V., Technical Services, Attn: Manager Airline Support, P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands. Information collection requirements contained in this regulation have been approved by the Office of Management and Budget (OMB) under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 *et seq.*) and have been assigned OMB Control Number 2120–0056.

Replacement

(c) For airplanes on which a crack greater than 0.591 inch (15 mm) in length is found: Except as provided by paragraph (e) of this AD, prior to further flight, replace the cracked MLG bracket with a new, improved bracket (including measuring the position of the existing MLG bracket, removing the existing bracket and attachment fittings, checking alignment of the fastener holes, measuring gaps, installing a shim, and aligning the new bracket); in accordance with Fokker Proforma Service Bulletin F28/57–92, dated July 1, 1999. Such replacement constitutes terminating action for the repetitive inspections required by paragraph (a) of this AD.

Optional Terminating Action

(d) Except as provided by paragraph (e) of this AD, replacement of the MLG bracket with a new, improved bracket (including measuring the position of the existing MLG bracket, removing the existing bracket and attachment fittings, checking alignment of the fastener holes, measuring gaps, installing a shim, and aligning the new bracket), in accordance with Fokker Proforma Service Bulletin F28/57–92, dated July 1, 1999; constitutes terminating action for the repetitive inspections specified in paragraph (a) of this AD for the replaced bracket.

(e) If any discrepancy is detected during accomplishment of the replacement procedures, and the service bulletin or any appendix to the service bulletin specifies to contact Fokker for appropriate action: Prior to further flight, repair in accordance with a method approved by either the Manager,

International Branch, ANM–116, FAA, Transport Airplane Directorate; or the Rijksluchtvaartdienst (or its delegated agent).

Alternative Methods of Compliance

(f) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM–116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM–116.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM–116.

Special Flight Permits

(g) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 4: The subject of this AD is addressed in Dutch airworthiness directive 1999–045/2, dated October 31, 2000.

Issued in Renton, Washington, on April 30, 2001.

Donald L. Riggan,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01–11227 Filed 5–3–01; 8:45 am]

BILLING CODE 4910–13–U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000–NM–274–AD]

RIN 2120–AA64

Airworthiness Directives; Raytheon Model Hawker 800XP Series Airplanes and Model Hawker 800 (U–125A Military) Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Raytheon Model Hawker 800XP series airplanes and certain Model Hawker 800 (U–125A military) airplanes. This proposal would require a one-time inspection of an attachment bolt in the main landing gear (MLG) door system to determine whether the bolt's protruding threads have been peened; and corrective action, if

necessary. This action is necessary to prevent the disconnection of the retaining hook (which holds the MLG door up and locked) from its means of actuation, which could result in a gear-up landing and possible injury to passengers and crew. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by June 18, 2001.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-274-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2000-NM-274-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Raytheon Aircraft Company, Department 62, P.O. Box 85, Wichita, Kansas 67201-0085. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas.

FOR FURTHER INFORMATION CONTACT: Paul C. DeVore, Aerospace Engineer, Systems and Propulsion Branch, ACE-116W, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas 67209; telephone (316) 946-4142; fax (316) 946-4407.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained

in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket 2000-NM-274-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket 2000-NM-274-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The FAA has received results of a routine production-line inspection that identified an unsafe condition on certain Raytheon Model Hawker 800XP series airplanes and certain Model Hawker 800 (U-125A military) airplanes. The inspection concerned attachment bolts on the retaining hooks of the main landing gear (MLG) doors. The bolts are located at the interface between the retaining hooks on the right and left MLG doors and the uplock spring struts. On all of the airplanes inspected, the threads of the attachment bolts had not been peened, as required by the airplanes' type design. Peening is the only positive means specified in the design for retaining the nuts on the attachment bolts. This condition, if not corrected, could result in a gear-up landing and possible injury to passengers and crew.

Explanation of Relevant Service Information

The FAA has reviewed and approved Raytheon Service Bulletin SB 32-3386, dated June 2000. The service bulletin describes procedures for inspecting an attachment bolt of the retaining hook of the MLG door, at the interface between the retaining hook and the uplock spring strut, to determine whether the bolt's protruding threads next to the nut have been peened. Corrective actions described in the service bulletin include peening the threads of any unpeened bolt. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require accomplishment of the actions specified in the service bulletin described previously.

Cost Impact

There are approximately 167 airplanes of the affected design in the worldwide fleet. The FAA estimates that 115 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 1 work hour per airplane to accomplish the proposed inspection, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$6,900, or \$60 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this proposed AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal

would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Raytheon Aircraft Company: Docket 2000–NM–274–AD.

Applicability: Model Hawker 800XP series airplanes, and Model Hawker 800 (U–125A military) airplanes; certificated in any category; as listed in Raytheon Service Bulletin SB 32–3386, dated June 2000.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent a main landing gear (MLG) gear-up landing and possible injury to

passengers and crew, accomplish the following:

Inspection

(a) Within 100 flight hours after the effective date of this AD: Perform a general visual inspection of the MLG attachment bolt at the interface between the right and left MLG door retaining hooks and the uplock spring struts to determine whether the bolt's protruding threads next to the nuts have been peened, in accordance with Raytheon Service Bulletin SB 32–3386, dated June 2000. If the threads have not been peened, prior to further flight, peen the threads in accordance with the service bulletin.

Note 2: For the purposes of this AD, a general visual inspection is defined as: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or drop-light, and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Wichita Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Wichita ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Wichita ACO.

Special Flight Permits

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on April 30, 2001.

Donald L. Riggan,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01–11226 Filed 5–3–01; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000–NM–339–AD]

RIN 2120–AA64

Airworthiness Directives; Dornier Model 328–300 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Dornier Model 328–300 series airplanes. This proposal would require replacing the brake assemblies with modified brake assemblies. This action is necessary to prevent overheating of the brakes, which could result in cracked pistons and consequent leakage and burning of the hydraulic fluid. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by June 4, 2001.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM–114, Attention: Rules Docket No. 2000–NM–339–AD, 1601 Lind Avenue, SW., Renton, Washington 98055–4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227–1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2000–NM–339–AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Fairchild Dornier, Dornier Luftfahrt GmbH, P.O. Box 1103, D–82230 Wessling, Germany. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM–116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055–4056; telephone (425) 227–2125; fax (425) 227–1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be