

(d) If the collecting person is a brand inspector, as provided for in § 1260.311, the seller of cattle claiming non-producer status shall provide to the brand inspector at the time the physical brand inspection is completed, in lieu of the assessment that would otherwise be due, either: a Statement of Certification of Non-Producer Status or a valid brand inspection certificate which shows collection of the assessment by a brand inspector in a transaction which took place not more than 10 days prior to the sale of the cattle.

* * * * *

Dated: May 9, 2001.

Kenneth C. Clayton,

Acting Administrator, Agricultural Marketing Service.

[FR Doc. 01-12141 Filed 5-14-01; 8:45 am]

BILLING CODE 3410-02-P

FARM CREDIT ADMINISTRATION

12 CFR Parts 611 and 615

RIN 3052-AB91

Organization; Funding and Fiscal Affairs, Loan Policies and Operations, and Funding Operations; Stock Issuances; Effective Date

AGENCY: Farm Credit Administration.

ACTION: Notice of effective date.

SUMMARY: The Farm Credit Administration (FCA) published a final rule under parts 611 and 615 on March 28, 2001 (66 FR 16841). In this final rule, we amended our regulations to allow Farm Credit System (System) service corporations to sell stock to non-System entities, provide adequate disclosures to investors in service corporations, and allow System institutions to issue unlimited amounts of certain classes of equities. The purpose of our amendments is to provide System institutions additional opportunities to fulfill their borrowers' needs through service corporations and more efficient issuance of equities related to earnings distributions and transfers of capital. In accordance with 12 U.S.C. 2252, the effective date of the final rule is 30 days from the date of publication in the **Federal Register** during which either or both Houses of Congress are in session. Based on the records of the sessions of Congress, the effective date of the regulations is May 14, 2001.

EFFECTIVE DATE: The regulation amending 12 CFR parts 611 and 615 published on March 28, 2001 (66 FR 16841) is effective May 14, 2001.

FOR FURTHER INFORMATION CONTACT: Dale Aultman, Policy Analyst, Office of Policy and Analysis, Farm Credit Administration, McLean, VA 22102-5090, (703) 883-4498; or Howard Rubin, Senior Attorney, Office of General Counsel, Farm Credit Administration, McLean, VA 22102-5090, (703) 883-4020, TDD (703) 883-4444.

(12 U.S.C. 2252(a)(9) and (10))

Dated: May 9, 2001.

Jeanette C. Brinkley,

Acting Secretary, Farm Credit Administration Board.

[FR Doc. 01-12152 Filed 5-14-01; 8:45 am]

BILLING CODE 6705-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-NM-122-AD; Amendment 39-12227; AD 2001-10-02]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica, S.A. (EMBRAER) Model EMB-135 and -145 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to certain EMBRAER Model EMB-135 and -145 series airplanes. This action requires applying torque to certain tubing fittings of the fire extinguishing systems of various areas of the airplane, and applying torque paint to the fittings. This action is necessary to ensure that certain tubing fittings of the fire extinguishing systems are properly torqued. Improperly torqued tubing fittings of the fire extinguishing systems of the baggage compartment, auxiliary power units (APU), and engines, if not corrected, could become loose and cause the fire extinguisher to inadvertently discharge. Inadvertent discharge of a fire extinguisher could result in reduced fire protection or the inability to extinguish a fire in the baggage compartment, APU, or engine. This action is intended to address the identified unsafe condition.

DATES: Effective May 30, 2001.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of May 30, 2001.

Comments for inclusion in the Rules Docket must be received on or before June 14, 2001.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2001-NM-122-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-iarcomment@faa.gov. Comments sent via the Internet must contain "Docket No. 2001-NM-122-AD" in the subject line and need not be submitted in triplicate. Comments sent via fax or the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in this AD may be obtained from Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343-CEP 12.225, Sao Jose dos Campos-SP, Brazil. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Linda Haynes, Aerospace Engineer, Airframe and Propulsion Branch, ACE-117A, FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia 30349; telephone (770) 703-6091; fax (770) 703-6097.

SUPPLEMENTARY INFORMATION: The Departamento de Aviacao Civil (DAC), which is the airworthiness authority for Brazil, recently notified the FAA that an unsafe condition may exist on certain EMBRAER Model EMB-135 and -145 series airplanes. The DAC advises that it has received reports of looseness of some tubing fittings of the fire extinguishing systems of the engines located in the pylon inner area. In one event during maintenance, the fire extinguisher discharged into the pylon area. Investigation revealed the possibility that those fittings had been undertorqued during production of the airplanes. This possibility also exists for all other fittings at the fire extinguishing systems.

Improperly torqued tubing fittings of the fire extinguishing systems of the