

# Rules and Regulations

Federal Register

Vol. 66, No. 128

Tuesday, July 3, 2001

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 98-ANE-57; Amendment 39-12124; AD 2001-04-06]

RIN 2120-AA64

#### Airworthiness Directives; CFM International, S.A. CFM56-3, -3B, and -3C Series Turbofan Engines; Correction

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; correction.

**SUMMARY:** This document makes a correction to Airworthiness Directive (AD) 2001-04-06 applicable to CFM International, S.A. CFM56-3, -3B, and -3C series turbofan engines that was published in the **Federal Register** on February 28, 2001 (66 FR 12726). The information in paragraph (i) in the regulatory information is incorrect. This document corrects paragraph (i). In all other respects, the original document remains the same.

**EFFECTIVE DATE:** April 4, 2001.

**FOR FURTHER INFORMATION CONTACT:** Glorianne Niebuhr, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone (781) 238-7132, fax (781) 238-7199.

**SUPPLEMENTARY INFORMATION:** A final rule airworthiness directive applicable to CFM International, S.A. CFM56-3, -3B, and -3C series turbofan engines, was published in the **Federal Register** on February 28, 2001 (66 FR 12726). Paragraph (i) of the AD provided that inspection is not required for disks that have been rebroached "prior to exceeding the .004 inch wear limit." This was incorrect as disks that have not yet reached the wear limit will not go

through the rebroaching process. Only if a disk has exceeded the wear limit, will that disk be rebroached. Therefore, the FAA is correcting the AD by deleting reference to the wear limit in paragraph (i). Make the following correction to FR Doc. 01-4216:

#### § 39.13 [Corrected]

On page 12729, in the second column, in AD 2001-04-06, in the Compliance Section, paragraph (i) is corrected to read as follows:

#### 2001-04-06 CFM International:

Amendment 39-12124, Docket 98-ANE-57-AD.

\* \* \* \* \*  
*Compliance* \* \* \*  
\* \* \* \* \*

(i) Inspection is not required for fan disks that used lubricants identified in paragraph (g) of this AD but were then rebroached, then were not lubricated with the lubricants identified in paragraph (g) of this AD AND were equipped with fan blade configurations specified either in subparagraph (h)(1) or (h)(2) of this AD.

\* \* \* \* \*

Issued in Burlington, MA, on June 19, 2001.

Jay J. Pardee,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 01-16048 Filed 7-2-01; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 98-NM-271-AD; Amendment 39-12296; AD 2001-13-15]

RIN 2120-AA64

#### Airworthiness Directives; Boeing Model 757 Series Airplanes Equipped with Rolls Royce Engines

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD), applicable to certain Boeing Model 757 series airplanes, that requires a one-time inspection to find wire chafing of the left and right engine fuel shutoff valve wire bundles at Power Plant Station 278 on each engine strut, and repair if

necessary. This amendment also requires replacement of three wire support brackets with improved wire support brackets. This amendment is prompted by reports that such wire support brackets failed due to fatigue, which subsequently caused the fuel shutoff valve wire to chafe and to experience a short circuit. The actions specified by this AD are intended to prevent such conditions, which could result in either the possible ignition of fuel vapors in a flammable leakage zone or in the inability to stop the flow of fuel in the event of an engine fire.

**DATES:** Effective August 7, 2001.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of August 7, 2001.

**ADDRESSES:** The service information referenced in this AD may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Stephen S. Oshiro, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2793; fax (425) 227-1181.

**SUPPLEMENTARY INFORMATION:** A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Boeing Model 757 series airplanes was published in the **Federal Register** on August 4, 1999 (64 FR 42050). That action proposed to require repetitive inspections to detect wire chafing of the left and right engine fuel shutoff valve wire bundles at Power Plant Station 278 on each engine strut, and repair if necessary. That action also proposed to require repetitive replacement of three wire support brackets with improved wire support brackets.

#### Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due