

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2001-18-02 Fokker Services B.V.:

Amendment 39-12428. Docket 2001-NM-23-AD.

Applicability: All Model F.28 Mark 1000, 2000, 3000, and 4000 series airplanes, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To detect and correct cracks in the area of the emergency escape hatches, which, if undetected, could result in depressurization during flight, possibly leading to structural failure of the airplane, accomplish the following:

Inspection

(a) Prior to the accumulation of 30,000 total flight cycles, or within 12 months after the effective date of this AD, whichever occurs later: Perform a one-time eddy current inspection to detect cracks of the fuselage butt joint forward of the emergency hatches on the left- and right-hand sides of the airplane at the level of stringers 27/48, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF28/53-148, dated August 15, 2000.

Repair

(b) If any crack is found during the inspection required by paragraph (a) of this AD: Prior to further flight, repair the crack

per a method approved by either the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate; or the Rijksluchtvaartdienst (or its delegated agent).

Reporting

(c) Submit a report of inspection findings (both positive and negative) to Fokker Services B.V., P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands; and to Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; fax (425) 227-1320. The report is to be submitted at the applicable time specified in paragraph (c)(1) or (c)(2) of this AD. The report must include the inspections results, a description of any discrepancies found, the airplane serial number, and the number of landings and flight hours on the airplane. Information collection requirements contained in this regulation have been approved by the Office of Management and Budget (OMB) under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 *et seq.*) and have been assigned OMB control Number 2120-0056.

(1) For airplanes on which the inspection is accomplished after the effective date of this AD: Submit a report of findings within 10 days after performing the inspection required by paragraph (a) of this AD.

(2) For airplanes on which the inspection was accomplished prior to the effective date of this AD: Submit a report of findings within 10 days after the effective date of this AD.

Alternative Methods of Compliance

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(f) Except as specified by paragraph (b) of this AD, the actions shall be done in accordance with Fokker Service Bulletin SBF28/53-148, dated August 15, 2000. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Fokker Services B.V., P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal

Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in Dutch airworthiness directive Dutch airworthiness directive 2000-151, dated November 30, 2000

Effective Date

(g) This amendment becomes effective on October 11, 2001.

Issued in Renton, Washington, on August 27, 2001.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01-22085 Filed 9-5-01; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 2001-NM-24-AD; Amendment 39-12429; AD 2001-18-03]

RIN 2120-AA64

Airworthiness Directives; Fokker Model F27 Mark 100, 200, 300, 400, 500, 600, and 700 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to all Fokker Model F27 Mark 100, 200, 300, 400, 500, 600, and 700 series airplanes, that requires a one-time inspection for correct installation of the left- and right-hand fuel differential pressure (FDP) switches and for correct connection of the pressure sensing lines to the switches, and corrective action, if necessary. The actions specified by this AD are intended to ensure that a warning light goes on when the fuel filter is partially blocked by ice, so that the blockage of the fuel filter does not increase, leading to reduced fuel flow to the engine and possibly to an engine flame-out. This action is intended to address the identified unsafe condition.

DATES: Effective October 11, 2001.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of October 11, 2001.

ADDRESSES: The service information referenced in this AD may be obtained from Fokker Services B.V., P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands. This information may be examined at the Federal Aviation

Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington 98055-4056; telephone (425) 227-2125; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to all Fokker Model F27 Mark 100, 200, 300, 400, 500, 600, and 700 series airplanes was published in the **Federal Register** on June 27, 2001 (66 FR 34134). That action proposed to require a one-time inspection for correct installation of the left- and right-hand fuel differential pressure (FDP) switches and for correct connection of the pressure sensing lines to the switches, and corrective action, if necessary.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the single comment received.

Cite Foreign Airworthiness Directive

The commenter states that the Dutch airworthiness directive is not cited in the proposed rule, and asks that it be included in the final rule. The FAA agrees with the commenter in that the note citing the Dutch airworthiness directive was inadvertently omitted from the proposed rule. We have added the note to this final rule accordingly.

Conclusion

After careful review of the available data, including the comment noted above, the FAA has determined that air safety and the public interest require the adoption of the rule with the change described previously. The FAA has determined that this change will neither increase the economic burden on any operator nor increase the scope of the AD.

Cost Impact

The FAA estimates that 44 airplanes of U.S. registry will be affected by this AD, that it will take approximately 1 work hour per airplane to accomplish the required one-time inspection, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the AD on U.S. operators

is estimated to be \$2,640, or \$60 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2001-18-03 Fokker Services B.V.:

Amendment 39-12429. Docket 2001-NM-24-AD.

Applicability: All Model F27 Mark 100, 200, 300, 400, 500, 600, and 700 series airplanes, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To ensure that a warning light goes on when the fuel filter is partially blocked by ice, so that the blockage of the fuel filter does not increase, leading to reduced fuel flow to the engine and possibly to an engine flame-out, accomplish the following:

Inspection/Corrective Action

(a) Within 60 days from the effective date of this AD: Perform a one-time general visual inspection for correct installation of the left- and right-hand fuel differential pressure (FDP) switches and for correct connection of the pressure sensing lines to the FDP switches, in accordance with the Accomplishment Instructions of Fokker Service Bulletin F27/28-63, dated November 21, 1999. If the switches are found to be installed incorrectly, as specified in the service bulletin, prior to further flight, re-install the switches and re-connect the pressure sensing lines to the switches, in accordance with the service bulletin.

Note 2: For the purposes of this AD, a general visual inspection is defined as: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or drop-light, and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who

may add comments and then send it to the Manager, International Branch, ANM-116.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(d) The actions shall be done in accordance with Fokker Service Bulletin F27/28-63, dated November 21, 1999. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Fokker Services B.V., P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 4: The subject of this AD is addressed in Dutch airworthiness directive 1999-154, dated November 30, 1999.

Effective Date

(e) This amendment becomes effective on October 11, 2001.

Issued in Renton, Washington, on August 27, 2001.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01-22086 Filed 9-5-01; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-NM-119-AD; Amendment 39-12430; AD 2001-18-04]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 747-400 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment supersedes an existing airworthiness directive (AD), applicable to certain Boeing Model 747-400 series airplanes, that currently requires repetitive inspections to detect damage or deflection of the crew rest heat exchanger, and follow-on actions, if

necessary. This amendment adds a new requirement for a one-time inspection to determine the part number and shop code of the shell of the crew rest heat exchanger; and follow-on actions, if necessary; which terminate the currently required repetitive inspections. This action is necessary to prevent cracking and buckling of the front edge of the crew rest heat exchanger, which could result in a jam of the rudder or elevator control cables, and consequent reduced controllability of the airplane. This action is intended to address the identified unsafe condition.

DATES: Effective September 21, 2001.

The incorporation by reference of Boeing Alert Service Bulletin 747-21A2412, Revision 2, dated November 30, 2000, as listed in the regulations, is approved by the Director of the Federal Register as of September 21, 2001.

The incorporation by reference of Boeing Alert Service Bulletin 747-21A2412, dated January 20, 2000, as listed in the regulations, was approved previously by the Director of the Federal Register as of June 8, 2000 (65 FR 33444, May 24, 2000).

Comments for inclusion in the Rules Docket must be received on or before November 5, 2001.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2001-NM-119-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may also be sent via the Internet using the following address: 9-anm-iarcomment@faa.gov. Comments sent via the Internet must contain "Docket No. 2001-NM-119-AD" in the subject line and need not be submitted in triplicate.

The service information referenced in this AD may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Barbara Mudrovich, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2983; fax (425) 227-1181.

SUPPLEMENTARY INFORMATION: On May 15, 2000, the FAA issued AD 2000-10-12, amendment 39-11736 (65 FR 33444, May 24, 2000), applicable to certain Boeing Model 747-400 series airplanes, to require repetitive inspections to detect damage or deflection of the crew rest heat exchanger, and follow-on actions, if necessary. That action was prompted by reports of cracking and buckling of the front edge of the crew rest heat exchanger on several airplanes. The requirements of that AD are intended to detect and correct damage or deflection of the crew rest heat exchanger, which could result in jamming of the rudder or elevator control cables, and consequent reduced controllability of the airplane.

In the preamble to AD 2000-10-12, the FAA indicated that the actions required by that AD were considered "interim action" and that further rulemaking action was being considered. We now have determined that further rulemaking action is indeed necessary, and this AD follows from that determination.

Actions Since Issuance of Existing AD

Since the issuance of AD 2000-10-12, we have reviewed and approved Boeing Alert Service Bulletin 747-21A2412, Revision 2, dated November 30, 2000. (AD 2000-10-12 referred to the original issue of Boeing Alert Service Bulletin 747-21A2412, dated January 20, 2000, as the appropriate source of service information for the required actions.) Among other changes, Revision 2 of the service bulletin adds a new one-time inspection to determine the part number and shop code of the shell assembly of the crew rest heat exchanger. The service bulletin also describes procedures for certain follow-on actions if the shell has a certain part number and shop code, or if the shop code cannot be determined. The follow-on actions involve removing the shell assembly of the heat exchanger; measuring the thickness of the wall of the shell adjacent to the forward flange; remarking the part, if necessary; and replacing the shell assembly of the crew rest heat exchanger with a new shell assembly, if necessary. Accomplishment of the new inspection and applicable follow-on actions eliminates the need for the currently required repetitive inspections for deflection or damage of the crew rest heat exchanger.

Accomplishment of the actions specified in Revision 2 of the service bulletin is intended to adequately address the identified unsafe condition.

Additionally, paragraph (b) of AD 2000-10-12 contains a requirement to measure the thickness of the material of