

promulgated, could have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. You may obtain a copy of the complete Regulatory Flexibility Analysis (entitled "Initial Regulatory Flexibility Analysis") that was prepared for this proposed AD from the Docket file at the location listed under the ADDRESSES section of this document.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator,

the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. FAA amends Section 39.13 by adding a new airworthiness directive (AD) to read as follows:

Aerostar Aircraft Corporation: Docket No. 99-CE-86-AD.

(a) *What airplanes are affected by this AD?* This AD affects the following airplanes, all serial numbers, certificated in any category: Models PA-60-601 (Aerostar 601), PA-60-601P (Aerostar 601P), PA-60-602P (Aerostar 602P), and PA-60-700P (Aerostar 700P) airplanes.

(b) *Who must comply with this AD?* Anyone who wishes to operate any of the above airplanes on the U.S. Register must comply with this AD.

(c) *What problem does this AD address?* The actions specified by this AD are intended to replace faulty oil scavenge pumps with pumps of improved design. The faulty oil scavenge pumps have rotors that machine through the end plate, resulting in loss of engine oil and possible loss of engine power.

(d) *What must I do to address this problem?* To address this problem, you must do the following actions:

Actions	Compliance times	Procedures
(1) Replace the Roto-Master scavenge pumps, part numbers 101633-01 or -02; and Rajay scavenge pumps, part numbers RJ1025-1 or -2; with Aerostar part number 300110-001 or -002.	Within the next 50 hours time-in-service after the effective date of this AD, unless already performed.	Do this replacement following the INSTRUCTIONS paragraph of Aerostar Mandatory Service Bulletin SB600-131A, January 10, 1998, and the Aerostar Maintenance Manual.
(2) Do not install, on any affected airplane, Roto-Master scavenge pumps, part numbers 101633-01 or -02; and Rajay scavenge pumps, part numbers RJ1025-1 or -2	As of the effective date of this AD	Not applicable.

(e) *Can I comply with this AD in any other way?* You may use an alternative method of compliance or adjust the compliance time if:

- (1) Your alternative method of compliance provides an equivalent level of safety; and
- (2) The Manager, Seattle Aircraft Certification Office (ACO), approves your alternative. Send your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO, 1601 Lind Avenue, SW., Renton, Washington 98055.

Note: This AD applies to each airplane identified in paragraph (a) of this AD, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. You should include in the request an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(f) *Where can I get information about any already-approved alternative methods of compliance?* Contact Richard Simonson, Aerospace Engineer, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4065; telephone: (425) 227-2597; facsimile: (425) 227-1181.

(g) *What if I need to fly the airplane to another location to comply with this AD?* The FAA can issue a special flight permit under

sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your airplane to a location where you can do the requirements of this AD.

(h) *How do I get copies of the documents referenced in this AD?* You may get the service information referenced in the AD from Aerostar Aircraft Corporation, 10555 Airport Drive, Coeur d'Alene Airport, Hayden Lake, Idaho 83835-8742; Telephone: (208) 762-0338; facsimile: (208) 762-8349. You may read this document at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106.

Issued in Kansas City, Missouri, on October 16, 2001.

Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01-26714 Filed 10-23-01; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-NM-414-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 757 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Boeing Model 757 series airplanes. This proposal would require installation of an extender bracket for the compensator of the Simmonds fuel quantity indication system (FQIS) in the main fuel tanks. This action is necessary to prevent contact between the compensator for the Simmonds FQIS system and a flapper check valve on a baffle rib in the main fuel tanks, which—in conjunction with another wiring failure outside the fuel tank—could result in an electrical arc and a consequent potential source of ignition in the fuel tank. This action is intended

to address the identified unsafe condition.

DATES: Comments must be received by December 10, 2001.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-414-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: *9-anm-nprmcomment@faa.gov*. Comments sent via fax or the Internet must contain "Docket No. 2000-NM-414-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: John Vann, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-1024; fax (425) 227-1181.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.

- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2000-NM-414-AD." The postcard will be date-stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-414-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The FAA has received reports indicating that contact between the compensator for the Simmonds fuel quantity indication system (FQIS) and a flapper check valve on a baffle rib in a main fuel tank was found on certain Boeing Model 757 series airplanes. Further investigation revealed that such contact is not uncommon. Over time, this contact between the compensator and flapper check valve can wear through the compensator's protective finish and result in electrical contact between the compensator and airplane structure. This condition, in conjunction with another wiring failure outside the fuel tank, if not corrected, could result in an electrical arc and a consequent potential source of ignition in the fuel tank.

Explanation of Relevant Service Information

The FAA has reviewed and approved Boeing Special Attention Service Bulletins 757-28-0057 and 757-28-0059, both dated September 14, 2000. These service bulletins describe procedures for installation of extender brackets for the compensators of the Simmonds FQIS in the left and right main fuel tanks. The procedures include ensuring minimum clearance between the compensators, wiring, and components, and the fuel tank structure, and testing the electrical bond in the

fuel tank. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require accomplishment of the actions specified in the service bulletin described previously.

Cost Impact

There are approximately 938 airplanes of the affected design in the worldwide fleet. The FAA estimates that 607 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 5 work hours per airplane to accomplish the proposed installation (not including time for gaining access and closing up), and that the average labor rate is \$60 per work hour. Required parts would cost approximately \$404 per airplane. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$427,328, or \$704 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this proposed AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative,

on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Boeing: Docket 2000–NM–414–AD.

Applicability: Model 757 series airplanes listed in Boeing Special Attention Service Bulletin 757–28–0057 or 757–28–0059, both dated September 14, 2000, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent contact between the compensator for the Simmonds fuel quantity indication system (FQIS) and a flapper check valve on a baffle rib in the main fuel tanks, which—in conjunction with another wiring failure outside the fuel tank—could result in an electrical arc and a consequent potential source of ignition in the fuel tank, accomplish the following:

Installation of Brackets

(a) Within 24 months after the effective date of this AD, install an extender bracket for the compensator of the Simmonds FQIS

in the left and right main fuel tanks (including ensuring minimum clearance between the compensators, wiring, and components, and the fuel tank structure, and testing the electrical bond in the fuel tank), according to Boeing Special Attention Service Bulletin 757–28–0057 or 757–28–0059, both dated September 14, 2000, as applicable.

Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on October 17, 2001.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01–26713 Filed 10–23–01; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF LABOR

Employment and Training Administration

20 CFR Part 655

RIN 1205–AB24

Labor Certification and Petition Process for Temporary Agricultural Employment of Nonimmigrant Workers in the United States (H–2A Workers); Modification of Fee Structure; Extension of Comment Period

AGENCY: Employment and Training Administration, Labor.

ACTION: Proposed rule; extension of comment period.

SUMMARY: This document extends the period for filing comments on the proposed rule that would require employers to submit fees for labor certification and the associated H–2A petition with a consolidated application form at the time of filing. The proposed rule also would modify the fee structure for H–2A labor certification applications. This action is once again

being taken to permit additional comment from interested persons.

DATES: Interested persons are invited to submit written comments on or before December 17, 2001.

ADDRESSES: Submit written comments to the Assistant Secretary for Employment and Training, U.S. Department of Labor, 200 Constitution Avenue, NW., Room C–4318, Washington, DC 20210, Attention: Dale Ziegler, Chief, Division of Foreign Labor Certifications.

FOR FURTHER INFORMATION CONTACT: Charlene Giles; telephone 202–693–2950 (this is not a toll-free number).

SUPPLEMENTARY INFORMATION: In the **Federal Register** of July 13, 2000, (65 FR 43545) we published a notice requesting comments on a proposed rule to require employers to submit the fees for temporary foreign agricultural (H–2A) labor certification and the associated non-immigrant H–2A petition with a consolidated application form at the time of filing. The proposal also would modify the fee structure for H–2A labor certification applications. On August 17, 2000, the comment period was reopened and extended to September 18, 2000. 65 FR 50170. On September 27, 2001, the comment period was again reopened through October 29, 2001. 66 FR 49328. Because of comments received during the comment period and continuing interest in the proposal, it is desirable to extend the comment period for all interested persons. Therefore, the comment period for the proposed rule revising 20 CFR part 655, subpart B (Labor Certification Process for Temporary Agricultural Employment in the United States (H–2A Workers) is extended until December 17, 2001.

Signed at Washington, DC, this 19th day of October, 2001.

Emily Stover DeRocco,

Assistant Secretary for Employment and Training.

[FR Doc. 01–26867 Filed 10–23–01; 8:45 am]

BILLING CODE 4510–30–P