

Corrective Actions

(b) If any discrepancy is found during the inspection required by paragraph (a) of this AD, before further flight, do paragraphs (b)(1) and (b)(2) of this AD, as applicable, according to Boeing Alert Service Bulletin 767–24A0128, dated May 11, 2000.

(1) Repair chafed or damaged wire bundles.

(2) If clearance between wire bundle and stand-off is outside the limits specified in the service bulletin: Install protective sleeving over the affected wire bundle, and install cable tie mounts and panduit straps.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on October 19, 2001.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01–26954 Filed 10–25–01; 8:45 am]

BILLING CODE 4910–13–U

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 2001–NM–132–AD]

RIN 2120–AA64

Airworthiness Directives; Airbus Model A319, A320, and A321 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Airbus Model A319, A320, and A321 series airplanes. This proposal would require a one-time inspection of the forward and aft lower bogies of the left- and right-hand sliding windows of the flightcrew compartment for the presence of a lock pin. If the lock pin

is missing, this proposal would require corrective action. This action is necessary to prevent the inability of the flightcrew to open the left- or right-hand sliding window for evacuation in an emergency, due to a window jamming in the closed position. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by November 26, 2001.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM–114, Attention: Rules Docket Number 2001–NM–132–AD, 1601 Lind Avenue, SW., Renton, Washington 98055–4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227–1232. Comments may also be sent via the Internet using the following address: *9-anm-nprcomment@faa.gov*. Comments sent via fax or the Internet must contain “Docket Number 2001–NM–132–AD” in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Tim Dulin, Aerospace Engineer, International Branch, ANM–116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055–4056; telephone (425) 227–2141; fax (425) 227–1149.

SUPPLEMENTARY INFORMATION:**Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.

- For each issue, state what specific change to the proposed AD is being requested.

- Include justification (*e.g.*, reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: “Comments to Docket Number 2001–NM–132–AD.” The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM–114, Attention: Rules Docket Number 2001–NM–132–AD, 1601 Lind Avenue, SW., Renton, Washington 98055–4056.

Discussion

The Direction Générale de l’Aviation Civile (DGAC), which is the airworthiness authority for France, notified the FAA that an unsafe condition may exist on certain Airbus Model A319, A320, and A321 series airplanes. The DGAC advises that there has been an incident of the right-hand sliding window jamming in the closed position on an in-service airplane. Investigation revealed that the jamming was due to a missing lock pin in the aft lower bogie on the affected airplane and that the bogie body had no hole for installation of the lock pin. The manufacturer has indicated that there may be a batch of airplanes which are missing the lock pin in the forward or aft lower bogie. This action is necessary to prevent the inability of the flightcrew to open the left- or right-hand sliding window for evacuation in an emergency, due to a window jamming in the closed position.

Explanation of Relevant Service Information

Airbus Industrie has issued Service Bulletin A320-56-1007, Revision 01, dated February 9, 2001, which describes procedures for a one-time detailed visual inspection of the forward and aft lower bogies of the left- and right-hand sliding windows for the presence of a lock pin. The service bulletin also describes procedures for replacement or temporary repair of the bogie, if the lock pin is missing. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition. The DGAC classified this service bulletin as mandatory and issued French airworthiness directive 2000-518-157(B), dated December 13, 2000, in order to assure the continued airworthiness of these airplanes in France.

FAA's Conclusions

These airplane models are manufactured in France and are type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require accomplishment of the actions specified in the service bulletin described previously.

Cost Impact

The FAA estimates that 77 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 1 work hour per airplane to accomplish the proposed inspection, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$4,620, or \$60 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD

action, and that no operator would accomplish those actions in the future if this proposed AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Airbus Industrie: Docket 2001-NM-132-AD.

Applicability: Model A319, A320, and A321 series airplanes, certificated in any

category, as listed in Airbus Service Bulletin A320-56-1007, Revision 01, dated February 9, 2001.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent the inability of the flightcrew to open the left- or right-hand sliding window for evacuation in an emergency, due to a window jamming in the closed position, accomplish the following:

Inspection

(a) Within one year after the effective date of this AD: Perform a one-time detailed visual inspection of the forward and aft lower bogie of the left-hand and right-hand sliding windows to check for the presence of a lock pin, in accordance with Airbus Service Bulletin A320-56-1007, Revision 01, dated February 9, 2001.

Note 2: For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

Corrective Action

(b) If the inspection required by paragraph (a) of this AD reveals that a lock pin is missing: Prior to further flight, perform the action required by either paragraph (b)(1) or (b)(2) of this AD.

(1) Install a new bogie equipped with a lock pin, in accordance with paragraph C.(1) of the Accomplishment Instructions of Airbus Service Bulletin A320-56-1007, Revision 01, dated February 9, 2001, or

(2) Perform a temporary repair in accordance with paragraph C.(2) of the Accomplishment Instructions of Airbus Service Bulletin A320-56-1007, Revision 01, dated February 9, 2001. Within 500 flight hours of the temporary repair, install a new bogie equipped with a lock pin, in accordance with paragraph C.(1) of the Accomplishment Instructions of the service bulletin.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be

used if approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 4: The subject of this AD is addressed in French airworthiness directive 2000-518-157(B), dated December 13, 2000.

Issued in Renton, Washington, on October 19, 2001.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01-26955 Filed 10-25-01; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF THE TREASURY

31 CFR Part 1

[Docket No. 00-19]

RIN 1557-AB83

Office of the Comptroller of the Currency; Privacy Act of 1974; Proposed Implementation

AGENCY: Office of the Comptroller of the Currency, Treasury.

ACTION: Notice of proposed rulemaking.

SUMMARY: With the concurrence of the Department of the Treasury (Department), the Office of the Comptroller of the Currency (OCC) issues a proposed rulemaking to amend this part to exempt five Privacy Act systems of records from certain provisions of the Privacy Act of 1974 pursuant to 5 U.S.C. 552a(j)(2) and/or 5 U.S.C. 552a(k)(2).

DATES: Comments will be accepted until November 26, 2001.

ADDRESSES: You should direct comments to the Office of the Comptroller of the Currency, Public Information Room, Docket No. 01-19, 250 E Street, SW., Mailstop 1-5, Washington, DC 20219. You may inspect comments received at the same location. You may send your comments by facsimile transmission to FAX number 202-874-4448 or by electronic mail to regs.comments@occ.treas.gov.

FOR FURTHER INFORMATION CONTACT:

Harold J. Hansen, Assistant Director, Administrative and Internal Law Division, (202) 874-4460 or Ellen S. Warwick, Special Counsel, Administrative and Internal Law Division, (202) 874-4460.

SUPPLEMENTARY INFORMATION: Under the Privacy Act of 1974, 5 U.S.C. 552a, as amended, a Federal agency is required, among other things, to: (1) Maintain only information about an individual that is relevant and necessary to accomplish an authorized purpose; (2) Notify an individual whether information about him or her is maintained in a system of records; (3) Provide an individual with access to the records containing information about him or her, including an accounting of disclosures made of that information; (4) Permit an individual to request amendment of records about him or her; and (5) Describe in system notices the sources of information maintained about individuals and the procedures under which notice, access and amendment rights may be exercised. Under certain circumstances, however, the head of a Federal agency may issue rules to exempt a particular system of records from these requirements (5 U.S.C. 552a(j) and (k)). Two of the six systems that the OCC proposes to alter are currently exempt from certain of the Privacy Act's requirements pursuant to 5 U.S.C. 552a(j)(2) and (k)(2). These systems, Treasury/Comptroller .013-Enforcement and Compliance Information System (to be renamed "Reports of Suspicious Activities") and Treasury/Comptroller .500-Chief Counsel's Management Information System will remain exempt from certain of the Privacy Act's requirements.

Notices of Proposed New and Altered Systems of Records

The Department and the OCC have published separately in the **Federal Register** a notice establishing five new systems of records, and a notice altering six existing systems of records.

In further regard to the proposal to alter six existing systems, the OCC proposes by this rulemaking to exempt two of the remaining four systems from certain of the Privacy Act's requirements pursuant to 5 U.S.C. 552a(j)(2) and/or (k)(2). These systems are: (1) Treasury/Comptroller .510-Litigation Information System; and (2) Treasury/Comptroller .600-Consumer Complaint and Inquiry Information System.

Additionally, the OCC has proposed to establish five new systems of records, three of which are proposed by this rulemaking to be exempted from certain

of the Privacy Act's requirements pursuant to 5 U.S.C. 552a(j)(2) and/or (k)(2). The new systems of records that are proposed to be exempted by this rulemaking are: (1) Treasury/Comptroller .100—Enforcement Action Report System; (2) Treasury/Comptroller .120—Bank Fraud Information System; and (3) Treasury/Comptroller .220—Section 914 Tracking System.

Proposed Exemptions

The systems of records that are proposed to be exempted under 5 U.S.C. 552a(j)(2) are: (1) Treasury/Comptroller .510—Litigation Information System; and (2) Treasury/Comptroller .120—Bank Fraud Information System.

The provisions of the Privacy Act of 1974 from which exemption is proposed pursuant to 5 U.S.C. 552a(j)(2) are:

5 U.S.C. 552a(c)(3) and (4);
5 U.S.C. 552a(d)(1), (2), (3), and (4);
5 U.S.C. 552a(e)(1), (2), and (3);
5 U.S.C. 552a(e)(4)(G), (H), and (I);
5 U.S.C. 552a(f); and
5 U.S.C. 552a(g).

The systems of records that are proposed to be exempted under 5 U.S.C. 552a(k)(2) are: (1) Treasury/Comptroller .100—Enforcement Action Report System; (2) Treasury/Comptroller .120—Bank Fraud System; (3) Treasury/Comptroller .220—Section 914 Tracking System; (4) Treasury/Comptroller .510—Litigation Information System; and (5) Treasury/Comptroller .600—Consumer Complaint and Inquiry Information System.

The provisions of the Privacy Act of 1974 from which exemption is proposed pursuant to 5 U.S.C. 552a(k)(2) are:

5 U.S.C. 552a(c)(3);
5 U.S.C. 552a(d)(1), (2), (3), and (4);
5 U.S.C. 552a(e)(1); (e)(4)(G), (H), and (I); and
5 U.S.C. 552a(f).

Reasons for Exemptions Under 5 U.S.C. 552a(j)(2) and (k)(2)

(1) 5 U.S.C. 552a(e)(4)(G) and (f)(1) enable individuals to inquire whether a system of records contains records pertaining to them. Application of these provisions to the systems of records would allow individuals to learn whether they have been identified as suspects or subjects of investigation. Access to such knowledge would impair the OCC's ability to carry out its mission, since individuals could:

- Take steps to avoid detection;
- Inform associates that an investigation is in process;
- Learn the nature of the investigation;
- Learn whether they are only suspects or identified as law violators;