

the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and that it is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Safety.

**Adoption of the Amendment**

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

**2001-26-52 Eurocopter Deutschland GMBH:** Amendment 39-12604. Docket No. 2001-SW-64-AD.

**Applicability:** Model EC135 helicopters with a Smart Multifunction Display (SMD45H) as the primary flight display (PFD) or navigation display (ND), certificated in any category.

**Note 1:** This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance

of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required before further Instrument Flight Rule (IFR) flight, unless accomplished previously.

To prevent erroneous flight or navigation display information, produced by a faulty SMD45H, and subsequent loss of control of the helicopter, accomplish the following:

(a) Insert a copy of this AD into the Limitations Section of the Rotorcraft Flight Manual (RFM) to prohibit IFR flight until the old part-numbered SMD45Hs listed in Table 1 of this AD are replaced.

(b) Replace each old part-numbered SMD45H with the corresponding new part-numbered SMD45H as specified in Table 1 of this AD.

**TABLE 1.—RETROFIT KIT EC135-31A-002-2.C SMD45H**

Old Part Number	New Part Number
(1) C19209VF11 .....	C19209VG11
(2) C19267VF11 .....	C19267VG11
(3) C19209SF10 .....	C19209SG10
(4) C19267SF10 .....	C19267SG10
(5) C19267RF10 .....	C19267RG10
(6) C19209NF10 .....	C19209NG10
(7) C19267NF10 .....	C19267NG10
(8) C19209HF09 .....	C19209VG11
(9) C19267GF09 .....	C19267GG09
(10) C19267DF10 .....	C19267DG10

(c) After replacing the old part-numbered SMD45Hs in accordance with paragraph (b) of this AD, remove this AD from the RFM.

(d) Replacing each specified SMD45H and removing this AD from the RFM are terminating actions for the requirements of this AD.

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Regulations Group, Rotorcraft Directorate, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Regulations Group.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Regulations Group.

(f) Special flight permits will not be issued.

(g) This amendment becomes effective on February 6, 2002, to all persons except those persons to whom it was made immediately effective by Emergency AD 2001-26-52, issued December 19, 2001, which contained the requirements of this amendment.

**Note 3:** The subject of this AD is addressed in Luftfahrt-Bundesamt (Federal Republic of Germany) AD 2001-306/3, dated November 15, 2001.

Issued in Fort Worth, Texas, on January 11, 2002.

**David A. Downey,**

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 02-1451 Filed 1-18-02; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

**[Docket No. 2001-SW-70-AD; Amendment 39-12605; AD 2001-26-53]**

**RIN 2120-AA64**

**Airworthiness Directives; Eurocopter France Model AS350B, B1, B2, B3, BA, D, and AS355E Helicopters**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule; request for comments.

**SUMMARY:** This document publishes in the **Federal Register** an amendment adopting Airworthiness Directive (AD) 2001-26-53, which was sent previously to all known U.S. owners and operators of Eurocopter France (ECF) Model AS350B, B1, B2, B3, BA, D, and AS355E helicopters by individual letters. This AD requires, before further flight, removing certain serial-numbered servocontrols. This AD is prompted by a report of manufacturing defects in a batch of main servocontrol rods. The actions specified by this AD are intended to prevent failure of a main servocontrol in the flight control system and subsequent loss of control of the helicopter.

**DATES:** Effective February 6, 2002 to all persons except those persons to whom it was made immediately effective by Emergency AD 2001-26-53, issued on December 21, 2001, which contained the requirements of this amendment.

Comments for inclusion in the Rules Docket must be received on or before March 25, 2002.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Office of the Regional Counsel, Southwest Region, Attention: Rules Docket No. 2001-SW-70-AD, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137. You may also send comments electronically to the Rules Docket at the following address: [9-asw-adcomments@faa.gov](mailto:9-asw-adcomments@faa.gov).

**FOR FURTHER INFORMATION CONTACT:** Uday Garadi, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Rotorcraft Standards Staff, Fort Worth, Texas

76193-0110, telephone (817) 222-5123, fax (817) 222-5961.

**SUPPLEMENTARY INFORMATION:** On December 21, 2001, the FAA issued Emergency AD 2001-26-53, for ECF Model AS350B, B1, B2, B3, BA, D, and AS355E helicopters, which requires, before further flight, removing certain serial-numbered servocontrols. That action was prompted by a report of manufacturing defects in a batch of main servocontrol rods. This condition, if not corrected, could result in failure of a main servocontrol in the flight control system and subsequent loss of control of the helicopter.

The FAA has reviewed ECF Alert Telex Nos. 01.00.52 and 01.00.18, both dated November 15, 2001, which advise replacing certain servocontrols.

The Direction General De L'Aviation Civile (DGAC), the airworthiness authority for France, notified the FAA that an unsafe condition may exist on ECF Model AS350B, B1, B2, B3, BA, D, and AS355E helicopters. The DGAC advises of the discovery of a manufacturing defect on a batch of rods of the main servocontrol, the failure of which would lead to the loss of control of the helicopter. The DGAC classified the ECF Alert Telexes as mandatory and issued AD No. T2001-590-087(A) (for AS 350 helicopters) and No. T2001-591-065(A) (for AS 355 helicopters), both dated November 28, 2001, to ensure the continued airworthiness of these helicopters.

These helicopter models are manufactured in France and are type certificated for operation in the United States under the provisions of 14 CFR 21.29 and the applicable bilateral agreement. Pursuant to the applicable bilateral agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of these type designs that are certificated for operation in the United States.

The unsafe condition is likely to exist or develop on other helicopters of the same type design. Therefore, the FAA issued Emergency AD 2001-26-53 to prevent failure of a main servocontrol, failure of the flight control system, and subsequent loss of control of the helicopter. The AD requires, before further flight, removing certain serial-numbered servocontrols. This AD does not apply to certain reconditioned servocontrols identified by the letter "V" engraved on the identification plate on the right-hand side of the part number. The short compliance time

involved is required because the previously described critical unsafe condition can adversely affect the structural integrity and controllability of the helicopter. Therefore, removing certain serial-numbered servocontrols is required before further flight, and this AD must be issued immediately.

Since it was found that immediate corrective action was required, notice and opportunity for prior public comment thereon were impracticable and contrary to the public interest, and good cause existed to make the AD effective immediately by individual letters issued on December 21, 2001 to all known U.S. owners and operators of ECF Model AS350B, B1, B2, B3, BA, D, and AS355E helicopters. These conditions still exist, and the AD is hereby published in the **Federal Register** as an amendment to 14 CFR 39.13 to make it effective to all persons.

The FAA estimates that 540 helicopters of U.S. registry will be affected by this AD. It will take approximately 2 work hours per helicopter to remove a main servocontrol. The average labor rate is \$60 per work hour. Required parts will cost approximately \$9200 per main servocontrol. Based on these figures, the total cost impact of the AD on U.S. operators is estimated to be \$5,032,800 (\$9320 per helicopter), assuming that at least one main servocontrol is replaced on each helicopter.

#### Comments Invited

Although this action is in the form of a final rule that involves requirements affecting flight safety and, thus, was not preceded by notice and an opportunity for public comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available in the Rules

Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their mailed comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 2001-SW-70-AD." The postcard will be date stamped and returned to the commenter.

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and that it is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

**2001-26-53 Eurocopter France:**

Amendment 39-12605. Docket No. 2001-SW-70-AD.

*Applicability:* Model AS350B, B1, B2, B3, BA, D, and AS355E helicopters, with TRW-SAMM main servocontrols, part number (P/N) SC 5083, serial number (S/N) from 1500 to 1515, inclusive, or P/N SC 5084, S/N from 722 to 726, inclusive, installed, except those reconditioned and identified by the letter "V" engraved on the identification plate on the right-hand side of the P/N, certificated in any category.

**Note 1:** This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

*Compliance:* Required before further flight, unless accomplished previously.

To prevent failure of a main servocontrol, failure of the flight control system, and subsequent loss of control of the helicopter, accomplish the following:

(a) Remove each affected main servocontrol.

**Note 2:** Eurocopter France Alert Telex Nos. 01.00.52 and 01.00.18, both dated November 15, 2001, pertain to the subject of this AD.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Regulations Group, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Regulations Group.

**Note 3:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Regulations Group.

(c) Special flight permits will not be issued.

(d) This amendment becomes effective on February 6, 2002, to all persons except those persons to whom it was made immediately effective by Emergency AD 2001-26-53, issued December 21, 2001, which contained the requirements of this amendment.

**Note 4:** The subject of this AD is addressed in Direction Generale De L'Aviation Civile, France, AD Nos. T2001-590-087(A) and T2001-591-065(A), both dated November 28, 2001.

Issued in Fort Worth, Texas, on January 11, 2002.

**David A. Downey,**

*Manager, Rotorcraft Directorate, Aircraft Certification Service.*

[FR Doc. 02-1450 Filed 1-18-02; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 71**

[Airspace Docket No. 01-ASO-12]

**Establishment of Class D Airspace; Titusville, NASA Shuttle Landing Facility, FL**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action establishes Class D airspace at Titusville, NASA Shuttle Landing Facility, FL. A federal contract tower with a weather reporting system is in operation at the National Aeronautics and Space Administration (NASA) Shuttle Landing Facility. Therefore, the airport meets the criteria for establishment of Class D airspace. Class D surface area airspace is required when the control tower is open to contain existing Standard Instrument Approach Procedures (SIAPs) and other Instrument Flight Rules (IFR) operations at the airport. This action establishes Class D airspace extending upward from the surface to and including 1,900 feet MSL within a 5.7-mile radius of the NASA Shuttle Landing Facility.

**EFFECTIVE DATE:** 0901 UTC, April 18, 2002.

**FOR FURTHER INFORMATION CONTACT:** Walter R. Cochran, Manager, Airspace Branch, Air Traffic Division, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305-5586.

**SUPPLEMENTARY INFORMATION:**

**History**

On December 3, 2001, the FAA proposed to amend part 71 of the Federal Aviation Regulations (14 CFR Part 71) by establishing Class D airspace at Titusville, NASA Shuttle Landing Facility, FL, (66 FR 60162) to provide adequate controlled airspace to contain IFR operations at the NASA Shuttle Landing Facility. Class D airspace designations for airspace areas extending upward from the surface of the earth are published in FAA Order 7400.9J, dated August 31, 2001, and effective September 16, 2001, which is

incorporated by reference in 14 CFR 71.1. The Class D designation listed in this document will be published subsequently in the Order.

Interested parties were invited to participate in this rulemaking proceeding by submitting written comments on the proposal to the FAA. No comments objecting to the proposal were received.

**The Rule**

The amendment to Part 71 of the Federal Aviation Regulations (14 CFR part 71) establishes Class D airspace at Titusville, NASA Shuttle Landing Facility, FL.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 71**

Airspace, Incorporation by Reference, Navigation (air)

**Adoption of the Amendment**

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR Part 71 as follows:

**PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS**

1. The authority citation for 14 CFR Part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(g); 40103, 40113, 40120; EO 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389; 14 CFR 11.69.

**§ 71.1 [Amended]**

2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9J, Airspace Designations and Reporting Points, dated August 31, 2001, and effective September 16, 2001, is amended as follows: