

current wire to the inverter, installing the return current wire from pitot tube #1 to the AC current sensor, and grounding the AC current sensor), according to Fokker Service Bulletin SBF100-30-025, Revision 1, dated March 14, 2001. Such modification terminates the repetitive operational tests required by paragraph (a) of this AD.

Alternative Methods of Compliance

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(f) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(g) The actions shall be done in accordance with Fokker Service Bulletin SBF100-30-025, Revision 1, dated March 14, 2001. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Fokker Services B.V., P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(h) This amendment becomes effective on March 6, 2002.

Issued in Renton, Washington, on January 17, 2002.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 02-1963 Filed 1-29-02; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-NM-382-AD; Amendment 39-12617; AD 2002-01-23]

RIN 2120-AA64

Airworthiness Directives; Raytheon Model Beech 400, 400A, and 400T Series Airplanes; Model Beech MU-300-10 Airplanes; and Model Mitsubishi MU-300 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to certain Raytheon Model Beech 400, 400A, and 400T series airplanes; Model Beech MU-300-10 airplanes; and Model Mitsubishi MU-300 airplanes. This action requires repetitive inspections to detect cracking in the radius of the cutout of the aft flange of the left engine forward carry-through mount bracket, and replacement with a new bracket and fitting if necessary. This action is necessary to prevent failure of the engine mount and possible loss of the engine, and consequent loss of control of the airplane. This action is intended to address the identified unsafe condition.

DATES: Effective February 14, 2002.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of February 14, 2002.

Comments for inclusion in the Rules Docket must be received on or before April 1, 2002.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2001-NM-382-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-iarcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2001-NM-382-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must

be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in this AD may be obtained from Raytheon Aircraft Company, Department 62, P.O. Box 85, Wichita, Kansas 67201-0085. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

David Ostrodka, Senior Aerospace Engineer, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas 67209; telephone (316) 946-4129; fax (316) 946-4407.

SUPPLEMENTARY INFORMATION: The FAA has been advised that certain engine mounts on affected airplanes have developed cracks. One operator discovered cracking during a routine inspection on the aft flange of the left engine forward carry-through mount bracket. Additional airplanes were subsequently inspected, and cracking was discovered in the same location on four airplanes. At the time of the crack findings, all of those airplanes had accumulated between 2,000 and 3,000 total flight hours, and all were equipped with thrust reversers. The cracks originate in the radius of the cutout of the aft flange of the engine mount brackets. The purpose of the cutout is to provide clearance for certain engine components. Because all of these airplanes were equipped with thrust reversers, it was initially determined that the condition would be found only on airplanes with thrust reversers. However, similar cracking was later discovered on a number of airplanes without thrust reversers. The cause of the cracking has not been determined. This condition, if not corrected, could result in failure of the engine mount and possible loss of the engine, and consequent loss of control of the airplane.

Explanation of Relevant Service Information

The FAA has reviewed and approved Raytheon Safety Communiqué No. 189, Revision 1, dated January 2002, which describes procedures for a one-time visual inspection to detect evidence of cracking of the left engine forward carry-through mount bracket, and a subsequent one-time fluorescent penetrant inspection to detect cracking

in the same area. The communiqué recommends immediate replacement of any cracked bracket with a new bracket and fitting.

Explanation of the Requirements of the Rule

Since an unsafe condition has been identified that is likely to exist or develop on other Raytheon Model Beech 400, 400A, and 400T series airplanes; Model Beech MU-300-10 airplanes; and Model Mitsubishi MU-300 airplanes of the same type design, this AD is being issued to prevent failure of the engine mount and possible loss of the engine, and consequent loss of control of the airplane. This AD requires repetitive inspections to detect cracking in the radius of the cutout of the aft flange of the left engine forward carry-through mount bracket, and replacement with a new bracket and fitting if necessary. The actions are required to be accomplished in accordance with the service information described previously, except as discussed below.

Requirements for Ferry Flight Permit

The FAA has determined that a ferry flight permit, if granted, must include certain limitations for airplanes equipped with thrust reversers, due to the increased loads and vibration levels associated with thrust reverser operation.

Differences Between AD and Relevant Service Information

The applicability of this AD and the manufacturer's Safety Communiqué No. 189 are identical with the exception of one serial number. For Beech MU-300-10 airplanes, the communiqué specifies serial numbers A1001SA through 1010SA inclusive. The type certification data sheet for this model specifies A1011SA as the last serial number. The FAA assumes serial number A1011SA may have been converted to a different model and reidentified and therefore has determined that it is necessary to include serial number A1011SA in the applicability of this AD to ensure the inclusion of all airplanes subject to the identified unsafe condition.

In addition, Safety Communiqué No. 189 recommends inspection of the subject area via a one-time visual inspection within 25 flight hours (for airplanes with more than 1,500 total flight hours) and a one-time fluorescent penetrant inspection within 50 flight hours. However, in light of the potential severity of the unsafe condition and the uncertainty of the cause of the premature cracking, the FAA finds these recommendations inadequate to address the identified unsafe condition in a

timely manner. The FAA has determined that a fluorescent penetrant inspection could detect cracking that a visual inspection might miss. Also, the FAA has determined that the initial inspection must be performed at the earlier of 14 days or 25 flight hours, and that the inspections must be repetitively performed, to timely detect cracking that could contribute to the unsafe condition.

In developing appropriate actions and compliance times for this AD, the FAA considered not only the manufacturer's recommendations, but the availability of parts, the average utilization of the affected fleet, the time necessary to perform an inspection (2 work hours), and the degree of urgency associated with addressing the identified unsafe condition. In light of all of these factors, the FAA finds initial and repetitive fluorescent penetrant inspections to be warranted, in that they will provide more detailed data, allow operators to detect cracking before it becomes a hazard to the structure, and provide the necessary continued operational safety for the fleet.

Interim Action

This is considered to be interim action until final action is identified, at which time the FAA may consider further rulemaking.

Determination of Rule's Effective Date

Since a situation exists that requires the immediate adoption of this regulation, it is found that notice and opportunity for prior public comment hereon are impracticable, and that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

Although this action is in the form of a final rule that involves requirements affecting flight safety and, thus, was not preceded by notice and an opportunity for public comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether

additional rulemaking action would be needed.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket 2001-NM-382-AD." The postcard will be date-stamped and returned to the commenter.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and that it is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation

Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2002-01-23 Raytheon Aircraft Company (Formerly Beech): Amendment 39-12617. Docket 2001-NM-382-AD.

Applicability: The following airplanes, certificated in any category:

TABLE 1.—APPLICABILITY

Model	Serial Numbers
Beech 400 series airplanes	RJ-1 through RJ-65 inclusive.
Beech 400A series airplanes	RK-1 and subsequent.
Beech 400T series airplanes	TT-1 through TT-180 inclusive.
Beech 400T-1 airplanes	TX-1 through TX-11 inclusive.
Beech MU-300-10 airplanes	A1001SA through A1011SA inclusive.
Mitsubishi MU-300 airplanes	A003SA through A091SA inclusive.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of the engine mount and possible loss of the engine, and consequent loss of control of the airplane, accomplish the following:

Repetitive Inspections

(a) At the later of the times specified by paragraphs (a)(1) and (a)(2) of this AD: Perform a fluorescent penetrant inspection to detect cracking in the radius of the cutout of the aft flange of the left engine forward carry-through mount bracket, in accordance with Raytheon Safety Communiqué No. 189, Revision 1, dated January 2002. Repeat the inspection thereafter at least every 200 flight hours.

(1) Inspect prior to the accumulation of 1,500 total flight hours; or

(2) Inspect within 25 flight hours or 14 days after the effective date of this AD, whichever occurs first.

Note 2: Accomplishment of a fluorescent penetrant inspection before the effective date of this AD in accordance with Raytheon Safety Communiqué No. 189, dated November 2001, is acceptable for compliance with the requirements for the initial inspection of paragraph (a) of this AD; however, accomplishment of only a visual inspection is not acceptable.

Corrective Action

(b) If any cracking is detected during any inspection required by paragraph (a) of this AD: Prior to further flight, replace the cracked part with a new bracket and fitting in accordance with Raytheon Maintenance Manual, Chapter 54-40-00. The replacement parts are identified in Raytheon Safety Communiqué 189, dated November 2001, or Revision 1, dated January 2002.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Wichita Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Wichita ACO, FAA.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Wichita ACO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished, provided the limitations specified by paragraphs (d)(1) and (d)(2) of this AD are included in the special flight permit.

(1) If any cracking is detected during any inspection required by paragraph (a) of this AD, but all cracks are less than one inch in length: Operation of the airplane is permitted to the nearest repair facility, provided the thrust reversers (if installed) are pinned or deactivated during operation.

(2) If a crack of one inch or longer is detected during any inspection required by paragraph (a) of this AD: Operation of the airplane is permitted to the nearest repair facility provided a temporary repair is first accomplished in accordance with a method approved by the Manager, Wichita ACO.

Incorporation by Reference

(e) Except as required by paragraph (b) of this AD: The actions must be done in accordance with Raytheon Safety Communiqué No. 189, Revision 1, dated January 2002. (Only page 1 of this document is dated; no other page contains this information.) This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Raytheon Aircraft Company, Department 62, P.O. Box 85, Wichita, Kansas 67201-0085. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(f) This amendment becomes effective on February 14, 2002.

Issued in Renton, Washington, on January 18, 2002.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 02-1965 Filed 1-29-02; 8:45 am]

BILLING CODE 4910-13-P