

Actions	Compliance	Procedures
Replace emergency exit window sealant.	Within the next 50 hours time-in-service after March 29, 2002 (the effective date of this AD), unless already performed.	In accordance with the Action section of B-N Service Bulletin Number SB 277, Issue 1, dated 03/08/2001.

(e) *Can I comply with this AD in any other way?* You may use an alternative method of compliance or adjust the compliance time if:

(1) Your alternative method of compliance provides an equivalent level of safety; and

(2) The Manager, Standards Office, Small Airplane Directorate, approves your alternative. Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standards Office, Small Airplane Directorate.

**Note 1:** This AD applies to each airplane identified in paragraph (a) of this AD, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph 4(e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(f) *Where can I get information about any already-approved alternative methods of compliance?* Contact Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; facsimile: (816) 329-4090.

(g) *What if I need to fly the airplane to another location to comply with this AD?* The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your airplane to a location where you can accomplish the requirements of this AD.

(h) *Are any service bulletins incorporated into this AD by reference?* Actions required by this AD must be done in accordance with B-N Service Bulletin Number SB 277, Issue 1, dated 03/08/2001. The Director of the Federal Register approved this incorporation by reference under 5 U.S.C. 552(a) and 1 CFR part 51. You can get copies from Pilatus Britten-Norman Limited, Bembridge, Isle of Wight, United Kingdom PO35 5PR. You can look at copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

**Note 2:** The subject of this AD is addressed in British AD 001-08-2001, dated August 3, 2001.

(i) *When does this amendment become effective?* This amendment becomes effective on March 29, 2002.

Issued in Kansas City, Missouri, on February 4, 2002.

**Michael Gallagher,**

*Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 02-3165 Filed 2-14-02; 8:45 am]

**BILLING CODE 4910-13-U**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 98-ANE-66-AD; Amendment 39-12649; AD 2002-03-08]

RIN 2120-AA64

#### Airworthiness Directives; Pratt & Whitney PW4000 Series Turbofan Engines

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment supersedes an existing airworthiness directive (AD), that is applicable to Pratt & Whitney PW4000 series turbofan engines. That AD currently requires revisions to the Time Limits Section of the manufacturer's Engine Manuals (EM's) to include required enhanced inspection of selected critical life-limited parts at each piece-part exposure. This amendment modifies the airworthiness limitations section of the manufacturer's manual and an air carrier's approved continuous airworthiness maintenance program to incorporate additional inspection requirements. An FAA study of in-service events involving uncontained failures of critical rotating engine parts has indicated the need for mandatory inspections. The mandatory inspections are needed to identify those critical rotating parts with conditions, which if allowed to continue in service, could result in uncontained failures. The actions specified by this AD are intended to prevent critical life-limited rotating engine part failure, which could result in an uncontained engine failure and damage to the airplane.

**DATES:** Effective date April 16, 2002.

**ADDRESSES:** This information may be examined, by appointment, at the Federal Aviation Administration (FAA), New England Region, Office of the

Regional Counsel, 12 New England Executive Park, Burlington, MA.

**FOR FURTHER INFORMATION CONTACT:**

Robert McCabe, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone (781) 238-7138, fax (781) 238-7199.

**SUPPLEMENTARY INFORMATION:** A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) by superseding AD 2000-12-02, Amendment 39-11780 (65 FR 37473, June 15, 2000), which is applicable to Pratt & Whitney PW4000 series turbofan engines was published in the **Federal Register** on October 5, 2001 (66 FR 50888). That action proposed to modify the airworthiness limitations section of the manufacturer's manual and an air carrier's approved continuous airworthiness maintenance program to incorporate additional inspection requirements. An FAA study of in-service events involving uncontained failures of critical rotating engine parts has indicated the need for mandatory inspections. The mandatory inspections are needed to identify those critical rotating parts with conditions, which if allowed to continue in service, could result in uncontained failures.

#### Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the comments received.

Two commenters state that EM part numbers 50A345, 50A751, and 50A882 are incorrect and should be changed to the correct part numbers of 51A345, 51A751, and 50A822, respectively.

The FAA agrees. The correct manual part numbers are included in this final rule.

One commenter requests that the comment period of this AD be extended until the manufacturer issues the new inspection requirements in the EM's or, that the operator's compliance to the final rule of this AD be delayed for 30 days after the manufacturer publishes the new inspection procedures in the manufacturer's EM's.

The FAA disagrees. The manufacturer has confirmed its ability to issue Temporary Revisions to the affected EM's within several weeks after the

effective date of this AD. The FAA believes that the nature and scope of the added inspections will not be significantly different from existing inspections. In addition, the effective date of this AD (and therefore the operator's compliance time period) has been extended to 60 days after publication to allow ample time for the specific inspection procedures and requirements to be published by the manufacturer and then incorporated into the operator's maintenance programs. Operators may submit comments to the docket on the specific procedures once they are published, and the FAA will consider extending the effective date further or additional rulemaking, as necessary. The FAA does not believe, however, that this final rule need be delayed pending the publication of the inspection procedures, or that the initial compliance time be extended to accommodate the manufacturer's manual revision cycle.

One commenter concurs with the intent of the AD as proposed.

After careful review of the available data, including the comments noted above, the FAA has determined that air safety and the public interest require the adoption of the rule with the changes described previously. The FAA has determined that these changes will neither increase the economic burden on any operator nor increase the scope of the AD.

**Economic Analysis**

No comments were received on the economic analysis contained in the proposed rules. The FAA has determined that the annual cost of complying with this AD does not create a significant economic impact on small entities.

**Regulatory Analysis**

This final rule does not have federalism implications, as defined in Executive Order 13132, because it would not have a substantial direct effect on the States, on the relationship between the national government and

the States, or on the distribution of power and responsibilities among the various levels of government. Accordingly, the FAA has not consulted with state authorities prior to publication of this final rule.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Safety.

**Adoption of the Amendment**

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

2. Section 39.13 is amended by removing Amendment 39-11780 (65 FR 37473, June 15, 2000) and by adding a new airworthiness directive, Amendment 39-12649, to read as follows:

**2002-03-08 Pratt & Whitney:** Amendment 39-12649. Docket No. 98-ANE-66-AD. Supersedes AD 2000-12-02, Amendment 39-11780.

**Applicability:** Pratt & Whitney (PW) Model PW4050, PW4052, PW4056, PW4060,

PW4060A, PW4060C, PW4062, PW4152, PW4156, PW4156A, PW4158, PW4160, PW4460, PW4462, PW4650, PW4164, PW4168, PW4168A, PW4074, PW4074D, PW4077, PW4077D, PW4084, PW4084D, PW4090, PW4090D, and PW4098 turbofan engines, installed on but not limited to Airbus A300, A310, and A330 series, Boeing 747, 767, and 777 series, and McDonnell Douglas MD-11 series airplanes.

**Note 1:** This airworthiness directive (AD) applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless already done.

To prevent critical life-limited rotating engine part failure, which could result in an uncontained engine failure and damage to the airplane, accomplish the following:

**Inspections**

(a) Within the next 60 days after the effective date of this AD, revise the Time Limits Section (TLS) of the Engine Manuals (EM's), part numbers 50A443, 50A605, 50A822, 51A342, 51A345, and 51A751, as applicable, for Pratt & Whitney PW4050, PW4052, PW4056, PW4060, PW4060A, PW4060C, PW4062, PW4152, PW4156, PW4156A, PW4158, PW4160, PW4460, PW4462, PW4650, PW4164, PW4168, PW4168A, PW4074, PW4074D, PW4077, PW4077D, PW4084, PW4084D, PW4090, PW4090D, and PW4098 series turbofan engines; and for air carrier operations revise the approved mandatory inspections section of the continuous airworthiness maintenance program, to read as follows:

**"MANDATORY INSPECTIONS**

(1) Perform inspections of the following parts at each piece-part opportunity in accordance with the instructions provided in the PW4000 series Engine Cleaning, Inspection and Repair (CIR) Manuals:

For Engine Manuals 50A443, 50A605, and 50A822, add the following table data:

Part nomenclature	Part No.	CIR manual section	CIR manual inspection	CIR manual
Hub, Front Compressor .....	All .....	72-31-07	Insp/Check-02 .....	51A357
Hub, Turbine, Front Assy (Stage 1) .....	All .....	72-52-05	Insp/Check-02 .....	51A357
Hub, Turbine, Intermediate Rear (Stage 2) .....	All .....	72-52-06	Insp/Check-02 .....	51A357

For Engine Manual 51A342, add the following table data:

Part nomenclature	Part No.	CIR manual section	CIR manual inspection	CIR manual
Hub, LPC Assembly .....	All .....	72-31-07	Insp/Check-02 .....	51A357
Hub, Turbine, Front Assembly (Stage 1) .....	All .....	72-52-05	Insp/Check-02 .....	51A357
Seal—Air, HPT Stage 2 .....	All .....	72-52-22	Insp/Check-02 .....	51A357
Hub, Turbine, Rear (Stage 2) .....	All .....	72-52-06	Insp/Check-02 .....	51A357

For Engine Manuals 51A345 and 51A751, add the following table data:

Part nomenclature	Part No.	CIR manual section	CIR manual inspection	CIR manual
Hub, LPC Assembly .....	All .....	72-31-07	Insp/Check-02 .....	51A750
Seal—Air, HPT Stage 1 .....	All .....	72-52-19	Insp/Check-02 .....	51A750
Hub, Turbine, Front Assembly (Stage 1) .....	All .....	72-52-05	Insp/Check-02 .....	51A750
Seal—Air, HPT Stage 2 Assembly .....	All .....	72-52-22	Insp/Check-02 .....	51A750
Hub, Turbine rear Assembly (Stage 2) .....	All .....	72-52-06	Insp/Check-02 .....	51A750

For Engine Manuals 50A443, 50A605, and 50A822, add the following table data:

Part nomenclature	Part No.	CIR manual section	CIR manual inspection	CIR manual
HPC Stage 5 Disk .....	All .....	<sup>1</sup> 72-35-06	Insp/Check-02 .....	51A357
HPC Front Drum Rotor .....	All .....	<sup>1</sup> 72-35-07	Insp/Check-02 .....	51A357
HPC Rear Drum Rotor .....	All .....	<sup>2</sup> 72-35-08	Insp/Check-02 .....	51A357
HPC Rear Drum Rotor .....	All .....	<sup>3</sup> 72-35-10	Insp/Check-02 .....	51A357

<sup>1</sup> For PW4000-94" Phase I & III ONLY.

<sup>2</sup> For PW4000-94" Phase I ONLY.

<sup>3</sup> For PW4000-94" Phase III ONLY.

For Engine Manual 51A342, add the following table data:

Part nomenclature	Part No.	CIR manual section	CIR manual inspection	CIR manual
HPC Stage 5 Disk .....	All .....	72-35-06	Insp/Check-02 .....	51A357
HPC Front Drum Rotor .....	All .....	72-35-07	Insp/Check-02 .....	51A357
HPC Rear Drum Rotor .....	All .....	72-35-10	Insp/Check-02 .....	51A357

For Engine Manuals 51A345 and 51A751, add the following table data:

Part nomenclature	Part No.	CIR manual section	CIR manual inspection	CIR manual
HPC Stage 5 Disk .....	All .....	72-35-06	Insp/Check-02 .....	51A750
HPC Front Drum Rotor .....	All .....	72-35-07	Insp/Check-02 .....	51A750
HPC Rear Drum Rotor .....	All .....	72-35-10	Insp/Check-02 .....	51A750
HPC Stage 15 Disk .....	All .....	72-35-92	Insp/Check-02 .....	51A750
HPT Stage 1 Airseal .....	All .....	72-52-19	Insp/Check-02 .....	51A750
HPT Front Hub .....	All .....	72-52-05	Insp/Check-02 .....	51A750
HPT Stage 2 Airseal .....	All .....	72-52-22	Insp/Check-02 .....	51A750
HPT Rear Hub .....	All .....	72-52-06	Insp/Check-02 .....	51A750

For Engine Manuals 50A443, 50A605 and 50A822, add the following table data:

Part nomenclature	Part No.	CIR manual section	CIR manual inspection	CIR Manual
Stage 3 LPT Disk .....	All .....	72-53-13	Insp/Check-02 .....	51A357
Stage 4 LPT Disk .....	All .....	72-53-14	Insp/Check-02 .....	51A357
Stage 5 LPT Disk .....	All .....	72-53-15	Insp/Check-02 .....	51A357
Stage 6 LPT Disk .....	All .....	72-53-16	Insp/Check-02 .....	51A357

For Engine Manual 51A342, add the following table data:

Part nomenclature	Part No.	CIR manual section	CIR manual inspection	CIR manual
Stage 3 LPT Disk .....	All .....	72-53-13	Insp/Check-02 .....	51A357
Stage 4 LPT Disk .....	All .....	72-53-14	Insp/Check-02 .....	51A357
Stage 5 LPT Disk .....	All .....	72-53-15	Insp/Check-02 .....	51A357
Stage 6 LPT Disk .....	All .....	72-53-16	Insp/Check-02 .....	51A357
Stage 7 LPT Disk .....	All .....	72-53-61	Insp/Check-02 .....	51A357

For Engine Manual 51A345, add the following table data:

Part nomenclature	Part No.	CIR manual section	CIR manual inspection	CIR manual
Stage 3 LPT Disk .....	All .....	72-53-13	Insp/Check-02, Config-1 .....	51A750
Stage 4 LPT Disk .....	All .....	72-53-14	Insp/Check-02 .....	51A750
Stage 5 LPT Disk .....	All .....	72-53-60	Insp/Check-02 .....	51A750
Stage 6 LPT Disk .....	All .....	72-53-16	Insp/Check-02, Config-1 .....	51A750
Stage 7 LPT Disk .....	All .....	72-53-72	Insp/Check-02 .....	51A750
Stage 8 LPT Disk .....	All .....	72-53-62	Insp/Check-02, Config-1 .....	51A750
Stage 9 LPT Disk .....	All .....	72-53-63	Insp/Check-02 .....	51A750

For Engine Manual 51A751, add the following table data:

Part nomenclature	Part No.	CIR manual section	CIR manual inspection	CIR manual
Stage 3 LPT Disk .....	All .....	72-53-13	Insp/Check-02, Config-2 See Note (1).	51A750
Stage 4 LPT Disk .....	All .....	72-53-14	Insp/Check-02 .....	51A750
Stage 5 LPT Disk .....	All .....	72-53-60	Insp/Check-02 .....	51A750
Stage 6 LPT Disk .....	All .....	72-53-16	Insp/Check-02, Config-2 See Note (1).	51A750
Stage 7 LPT Disk .....	All .....	72-53-72	Insp/Check-02 .....	51A750
Stage 8 LPT .....	All .....	72-53-62	Insp/Check-02, Config-2 See Note (1).	51A750
Stage 9 LPT Disk .....	All .....	72-53-63	Insp/Check-02 .....	51A750

<sup>1</sup> FPI method only.

(2) For the purposes of these mandatory inspections, piece-part opportunity means:

(i) The part is considered completely disassembled when accomplished in accordance with the disassembly instructions in the manufacturer's EM's to either the part

detail or part assembly level part numbers for the parts listed in the Tables above, and

(ii) The part has accumulated more than 100 cycles in service since the last piece-part opportunity inspection, provided that the part was not damaged or related to the cause for its removal from the engine."

(b) Except as provided in paragraph (c) of this AD, and notwithstanding contrary provisions in § 43.16 of the Federal Aviation Regulations (14 CFR 43.16), these mandatory inspections must be performed only in accordance with the Time Limits Section of the manufacturer's EM's.

**Alternative Methods of Compliance**

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office (ECO). Operators must submit their request through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, ECO.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the ECO.

**Special Flight Permits**

(d) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be done.

**Continuous Airworthiness Maintenance Program**

(e) FAA-certificated air carriers that have an approved continuous airworthiness maintenance program in accordance with the record-keeping requirement of § 121.369(c) of the Federal Aviation Regulations (14 CFR 121.369(c)) must maintain records of the mandatory inspections that result from revising the Time Limits Section of the EM's and the air carrier's continuous airworthiness program. Alternatively, certificated air carriers may establish an approved system of record retention that provides a method for preservation and retrieval of the maintenance records that include the inspections resulting from this AD, and include the policy and procedures for implementing this alternate method in the air carrier's maintenance manual required by § 121.369(c) of the Federal Aviation Regulations (14 CFR 121.369(c)); however, the alternate system must be accepted by the appropriate PMI and require the maintenance records be maintained either indefinitely or until the work is repeated. Records of the piece-part inspections are not required under § 121.380(a)(2)(vi) of the Federal Aviation Regulations (14 CFR 121.380(a)(2)(vi)). All other operators must maintain the records of mandatory inspections required by the applicable regulations governing their operations.

**Note 3:** The requirements of this AD have been met when the EM changes are made and air carriers have modified their continuous airworthiness maintenance plans to reflect the requirements in the applicable EM's.

(f) This amendment becomes effective on April 16, 2002.

Issued in Burlington, Massachusetts, on February 5, 2002.

**Jay J. Pardee,**

*Manager, Engine and Propeller Directorate, Aircraft Certification Service.*

[FR Doc. 02-3579 Filed 2-14-02; 8:45 am]

**BILLING CODE 4910-13-U**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 71**

[Airspace Docket No. 01-ANM-09]

**Revision of Class E Airspace, Pasco, WA**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action revises the Class E airspace at Pasco, WA. An area of uncontrolled airspace exists in the Tri-Cities terminal area. Additional Class E 1,200-foot controlled airspace, above the surface of the earth is required to contain aircraft conducting IFR operations at Pasco, Tri-Cities Airport. The intended effect of this proposal is to provide adequate controlled airspace for Instrument Flight Rules (IFR) operations at Pasco, Tri-Cities Airport, Pasco, WA.

**EFFECTIVE DATE:** 0901 UTC, April 18, 2002.

**FOR FURTHER INFORMATION CONTACT:** Brian Durham, ANM-520.7, Federal Aviation Administration, Docket No. 01-ANM-09, 1601 Lind Avenue SW., Renton, Washington 98055-4056; telephone number: (425) 227-2527.

**SUPPLEMENTARY INFORMATION:****History**

On July 10, 2001, the FAA proposed to amend Title 14 Code of Federal Regulations, part 71 (14 CFR part 71) by revising Class E at Pasco, WA, in order to provide a safer IFR environment at Pasco, Tri-Cities Airport, Pasco, WA (66 FR 35916). This amendment provides additional Class E5 1,200-foot controlled airspace at Pasco, WA, to contain IFR aircraft operating in the Pasco, Tri-Cities terminal area. Interested parties were invited to participate in the rulemaking proceeding by submitting written comments on the proposal. A revision to the legal description as written in the Notice for Proposed Rule Making (NPRM) was required for charting purposes to amend an error in the Class E 700 foot airspace at Richland, WA. This correction does not change the existing airspace at Richland, WA, as charted. This is considered an insignificant modification to the airspace description as the dimension of the proposed airspace described in the NPRM did not change.

**The Rule**

This amendment to Title 14 Code of Federal Regulations, part 71 (14 CFR

part 71) revises Class E airspace at Pasco, WA, in order to provide adequate controlled airspace for Instrument Flight Rules (IFR) operations at Pasco, Tri-Cities Airport, Pasco, WA. This amendment revises Class E5 airspace at Pasco, WA, to enhance safety and efficiency of IFR flight operations in the Tri-Cities terminal area. The FAA establishes Class E airspace where necessary to contain aircraft transitioning between the terminal and en route environments. This rule is designed to provide for the safe and efficient use of the navigable airspace and to promote safe flight operations under Instrument Flight Rules (IFR) at the Pasco, Tri-Cities Airport and between the terminal and en route transition stages.

The area will be depicted on aeronautical charts for pilot reference. The coordinates for this airspace docket are based on North American Datum 83. Class E airspace areas extending upward from 700 feet or more above the surface of the earth, are published in Paragraph 6005, of FAA Order 7400.9J dated August 31, 2001, and effective September 16, 2001, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document will be published subsequently in the Order.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 71**

Airspace, Incorporation by reference, Navigation (air).

**Adoption of the Amendment**

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows: