

(a)(1), (a)(2), and (a)(3) of this AD. If any discrepancy is detected, prior to further flight, perform corrective actions, as applicable, in accordance with the AOT or service bulletin. Repeat the inspection thereafter at intervals not to exceed 1,000 flight cycles or 15 months, whichever occurs first, unless the terminating action of paragraph (c) of this AD is accomplished. After June 30, 2000 (the effective date of AD 2000-10-16, amendment 39-11740), only Airbus Service Bulletin A320-32-1187, Revision 01, dated February 17, 1999, shall be used for compliance with this paragraph.

(1) Within 30 months since the airplane's date of manufacture or prior to the accumulation of 2,000 total flight cycles, whichever occurs first.

(2) Within 15 months or 1,000 flight cycles after the last gear replacement or accomplishment of Airbus Service Bulletin A320-32-1119, Revision 1, dated June 13, 1994, whichever occurs first.

(3) Within 500 flight cycles after August 12, 1998 (the effective date of AD 98-14-11, amendment 39-10644).

Note 3: For the purposes of this AD, a detailed inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

One-Time Follow-on Actions

(b) For airplanes on which the actions described in paragraph 2.B.(2)(c) of Airbus Service Bulletin A320-32-1187, Revision 01, dated February 17, 1999, have not been accomplished: At the time of the initial inspection or the next repetitive inspection required by paragraph (a) of this AD, perform the applicable one-time follow-on actions (including retorquing the forward pintle pin lock bolt and applying sealant to the head of the lock bolt), in accordance with section 2.B.(2)(c) of the Accomplishment Instructions of Airbus Service Bulletin A320-32-1187, Revision 01, dated February 17, 1999.

New Actions Required by This AD

Terminating Modification

(c) Within 5 years from the effective date of this AD, or at the next MLG overhaul, whichever occurs later, modify the forward pintle pin cross bolt on both the left and right MLG (including a detailed inspection to ensure that the bolts are in proper position and are not broken, and repair if necessary; and removal and installation of the lock bolts), in accordance with Airbus Service Bulletin A320-32-1213, Revision 02, dated February 9, 2001. This modification constitutes terminating action for the requirements of this AD.

Note 4: Accomplishment of the actions required in paragraph (c) of this AD, prior to the effective date of this AD, in accordance with Airbus Service Bulletin A320-32-1213, dated March 21, 2000, or Revision 01, dated

November 15, 2000, is considered acceptable for compliance with paragraph (c) of this AD.

Alternative Methods of Compliance

(d)(1) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

(2) Alternative methods of compliance, approved previously in accordance with AD 2000-10-16, amendment 39-11740, are approved as alternative methods of compliance with this AD.

Note 5: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Manager, International Branch, ANM-116.

Special Flight Permits

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(f) The actions shall be done in accordance with Airbus All Operator Telex (AOT) 32-17, Revision 01, dated November 6, 1997, Airbus Service Bulletin A320-32-1187, dated June 17, 1998, or Airbus Service Bulletin A320-32-1187, Revision 01, dated February 17, 1999; and Airbus Service Bulletin A320-32-1213, Revision 02, dated February 9, 2001; as applicable.

(1) The incorporation by reference of Airbus Service Bulletin A320-32-1213, Revision 02, dated February 9, 2001, is approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(2) The incorporation by reference Airbus Service Bulletin A320-32-1187, dated June 17, 1998; and Airbus Service Bulletin A320-32-1187, Revision 01, dated February 17, 1999; was approved previously by the Director of the Federal Register, as of June 30, 2000 (65 FR 34059, May 26, 2000).

(3) The incorporation by reference of Airbus All Operator Telex (AOT) 32-17, Revision 01, dated November 6, 1997, was approved previously by the Director of the Federal Register as of August 12, 1998 (63 FR 36834, July 8, 1998).

(4) Copies of any of these service documents may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 6: The subject of this AD is addressed in French airworthiness directive 2000-428-153(B), Revision 1, dated November 29, 2000.

Effective Date

(g) This amendment becomes effective on May 28, 2002.

Issued in Renton, Washington, on April 11, 2002.

Vi L. Lipski,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-9573 Filed 4-22-02; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-NM-209-AD; Amendment 39-12723; AD 2002-08-15]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 767 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain Boeing Model 767 series airplanes, that requires an inspection of the tripod strut assembly of the inboard support of the leading edge slat of the wing for a preload condition, and follow-on actions. For certain airplanes, this AD also requires inspection and replacement of the existing tripod struts with new, adjustable struts, if necessary. This action is necessary to prevent damage to the tripod strut assembly due to a preload condition, which could result in loss of control of the inboard leading edge slat or separation of the slat from the airplane, and consequent reduced controllability of the airplane. This action is intended to address the identified unsafe condition.

DATES: Effective May 28, 2002.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of May 28, 2002.

ADDRESSES: The service information referenced in this AD may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: John Craycraft, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2782; fax (425) 227-1181.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Boeing Model 767 series airplanes was published in the **Federal Register** on January 2, 2002 (67 FR 35). That action proposed to require an inspection of the tripod strut assembly of the inboard support of the leading edge slat of the wing for a preload condition, and follow-on actions. For certain airplanes, that action also proposed to require inspection and replacement of the existing tripod struts with new, adjustable struts, if necessary.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

Conclusion

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

There are approximately 379 Model 767 series airplanes of the affected design in the worldwide fleet. The FAA estimates that 136 airplanes of U.S. registry will be affected by this AD.

It will take approximately 1 work hour per airplane to accomplish the required inspections of the tripod strut assembly and bushing holes, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the inspections required by this AD on U.S. operators is estimated to be \$8,160, or \$60 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Should an operator be required to accomplish the rework of the fitting assembly, it will take approximately 4 work hours per airplane, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of this rework, if accomplished, will be \$240 per airplane.

Should an operator be required to accomplish the high frequency eddy current inspection, it will take approximately 5 work hours per airplane, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of this inspection, if accomplished, will be \$300 per airplane.

Should an operator be required to accomplish the replacement of the main strut support fitting, it will take approximately 14 work hours per airplane to accomplish the replacement (on both the left and right wings of the airplane, excluding the time for gaining access and closing up), at an average labor rate of \$60 per work hour. Required parts will cost approximately \$12,380 per airplane. Based on these figures, the cost impact of the replacement, if accomplished, will be \$13,220 per airplane.

Should an operator be required to accomplish the inspection for improperly cut and spliced struts, it will take approximately 1 work hour per airplane, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of this inspection, if accomplished, will be \$60 per airplane.

Should an operator be required to accomplish the replacement of a cut and spliced strut with a new, adjustable tripod strut, it will take approximately 4 work hours per airplane, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of this replacement, if accomplished, will be \$240 per airplane.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a

substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2002-08-15 Boeing: Amendment 39-12723. Docket 2001-NM-209-AD.

Applicability: Model 767 series airplanes, line numbers 160 through 541 inclusive, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent damage to the tripod strut assembly due to a preload condition, which could result in loss of control of the inboard leading edge slat or separation of the slat from the airplane, and consequent reduced controllability of the airplane, accomplish the following:

Inspections

(a) For all airplanes: Before the accumulation of 5,000 total flight cycles or within 24 months after the effective date of this AD, whichever is later: Do a general visual inspection (check) of the tripod strut assembly of the inboard leading edge slat of

each wing for a preload condition, per Figure 2 of Boeing Service Bulletin 767-57A0058, Revision 1, dated May 27, 1999.

Note 2: For the purposes of this AD, a general visual inspection is defined as: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or drop-light and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

(1) If no preload condition is found, before further flight, inspect the fitting assembly bushing holes for roundness, per Figure 5 of the Accomplishment Instructions of the service bulletin.

(i) If all the bushing holes are round, before further flight, do the inspection required by paragraph (c) of this AD.

(ii) If any bushing hole is not round, before further flight, do the inspections required by paragraphs (b) and (c) of this AD.

(2) If a preload condition is found, before further flight, do the inspections required by paragraphs (b) and (c) of this AD.

Follow-on Actions

(b) For airplanes subject to paragraph (a)(1)(ii) or (a)(2) of this AD: Do a high frequency eddy current inspection of the fitting assembly lug for cracking, per Figure 6 of the Accomplishment Instructions of Boeing Service Bulletin 767-57A0058, Revision 1, dated May 27, 1999.

(1) If no cracking is found, or if cracking is found in the lug bore only, before further flight, rework the fitting assembly lug, per Figure 7 of the Accomplishment Instructions of the service bulletin.

(2) If cracking is found in the fitting lug base or the lug bore and base, before further flight, purge the auxiliary fuel tank and replace the fitting assembly lug, per Figure 8 of the Accomplishment Instructions of the service bulletin.

(c) For airplanes subject to paragraph (a)(1)(i), (a)(1)(ii), or (a)(2) of this AD: Do a general visual inspection of the bushing holes of the main strut assembly to determine if the bushing holes are round, per Figure 9 of the Accomplishment Instructions of Boeing Service Bulletin 767-57A0058, Revision 1, dated May 27, 1999.

(1) If the bushing holes are round, before further flight, assemble the tripod assembly, per Figure 11 or Figure 12, as applicable, of the Accomplishment Instructions of the service bulletin.

(2) If the bushing holes are not round, before further flight, replace the main strut fitting assembly, per Figure 10 of the Accomplishment Instructions of the service bulletin; then assemble the tripod assembly, per Figure 11 or Figure 12, as applicable, of the Accomplishment Instructions of the service bulletin.

Note 3: Inspections and follow-on actions done before the effective date of this AD per Boeing Alert Service Bulletin 767-57A0058, dated June 11, 1998, are considered acceptable for compliance with the applicable actions specified in this AD.

Inspection/Replacement of Tripod Struts

(d) For Group 2 airplanes that have not accomplished Boeing Service Bulletin 767-57-0037, dated January 14, 1993: Before further flight after doing the inspections and follow-on actions required by paragraphs (a), (b), and (c) of this AD, do a general visual inspection of the tripod struts to determine if they have been cut and spliced, per the Accomplishment Instructions of the service bulletin.

(1) If the tripod struts have been cut and spliced with fewer than six hi-loks, before further flight, replace with new, adjustable struts, per Figure 1 of the Accomplishment Instructions of the service bulletin.

(2) If the tripod struts have not been cut and spliced, or they have been cut and spliced with six hi-loks, no further action is required by this paragraph.

Alternative Methods of Compliance

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 4: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(f) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(g) The actions shall be done in accordance with Boeing Service Bulletin 767-57A0058, Revision 1, dated May 27, 1999; and Boeing Service Bulletin 767-57-0037, dated January 14, 1993; as applicable. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(h) This amendment becomes effective on May 28, 2002.

Issued in Renton, Washington, on April 15, 2002.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-9613 Filed 4-22-02; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-ANE-47-AD; Amendment 39-12719; AD 2002-08-11]

RIN 2120-AA64

Airworthiness Directives; Pratt & Whitney JT9D Series Turbofan Engines

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment supersedes an existing airworthiness directive (AD), that is applicable to certain Pratt & Whitney JT9D series turbofan engines. That AD currently requires revisions to the Airworthiness Limitations Section (ALS) of the manufacturer's Instructions for Continued Airworthiness (ICA) to include required enhanced inspection of selected critical life-limited parts at each piece-part exposure. This action adds additional critical life-limited parts for enhanced inspection. This amendment is prompted by an FAA study of in-service events involving uncontained failures of critical rotating engine parts. The actions specified by this AD are intended to prevent critical life-limited rotating engine part failure, which could result in an uncontained engine failure and damage to the airplane.

DATES: Effective date May 28, 2002.

ADDRESSES: The information referenced in this AD may be examined, by appointment, at the Federal Aviation Administration (FAA), New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Tara Goodman, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone (781) 238-7130, fax (781) 238-7199.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) by superseding AD 2000-01-13, Amendment 39-11511 (65 FR 2864, January 19, 2000), which is applicable to Pratt & Whitney (PW) JT9D series turbofan engines, was published in the **Federal Register** on November 20, 2001, (66 FR 58075). That action proposed to require revisions to the Airworthiness Limitations Section (ALS) of the