

TABLE 1.—SERVICE BULLETINS

Service bulletin	Date
Aeronautical Engineers Inc. Service Bulletin AEI 00-01, Revision A.	May 7, 2001.
Aircraft Technical Service, Inc., Service Bulletin ATS 727-001.	May 7, 2001.
Federal Express Corporation Service Bulletin 00-029, Revision A, including Attachment A.	May 16, 2001.
PEMCO Service Bulletin, 727-53-0007, Revision 1.	June 6, 2001.

**Repair**

(k) If any cracking is found during any inspection required by paragraph (f), (g), (h), or (i) of this AD: Before further flight, repair per the applicable service bulletin as provided in Table 1 in paragraph (j) of this AD. Where cracks exceed the limits provided in the service bulletin, and the bulletin specifies to contact the provider of the service bulletin for repair instructions, prior to further flight, repair per a method approved by the Manager, Seattle ACO. If any cracking is found during any inspection required by paragraph (j) of this AD: Before further flight, repair per a method approved by the Manager, Seattle ACO. For a repair method to be approved by the Manager, Seattle ACO, as required by this paragraph, the approval letter must specifically reference this AD.

**Alternative Methods of Compliance**

(l)(1) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle ACO. Operators shall submit their requests through an appropriate FAA PMI, who may add comments and then send it to the Manager, Seattle ACO.

(2) Alternative methods of compliance, approved previously per AD 99-04-22, amendment 39-11047, are approved as alternative methods of compliance with this AD.

**Note 7:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

**Special Flight Permits**

(m) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

**Incorporation by Reference**

(n) Except as provided by paragraphs (c), (e), and (k) of this AD, the actions shall be done in accordance with the following service bulletins, as applicable:

TABLE 2.—SERVICE BULLETINS

Service bulletin	Date
Aeronautical Engineers Inc. Service Bulletin AEI 00-01, Revision A.	May 7, 2001.
Aircraft Technical Service, Inc., Service Bulletin ATS 727-001.	May 7, 2001.
Boeing Service Bulletin 727-53A0222, Revision 1, including Appendix A.	March 15, 2001.
Federal Express Corporation Service Bulletin 00-029, Revision A, including Attachment A.	May 16, 2001.
PEMCO Service Bulletin 727-53-0007, Revision 1.	June 6, 2001.

This incorporation by reference was approved previously by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51 as of May 17, 2002 (67 FR 17923, April 12, 2002). Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**Effective Date**

(o) The effective date of this amendment remains May 17, 2002.

Issued in Renton, Washington, on May 6, 2002.

**Kalene C. Yanamura,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 02-11803 Filed 5-10-02; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

[Docket No. 2001-SW-20-AD; Amendment 39-12680; AD 2002-06-04]

**RIN 2120-AA64**

**Airworthiness Directives; Eurocopter France Model AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350C, AS350D, AS350D1, AS355E, AS355F, AS355F1, AS355F2, and AS355N Helicopters; Correction**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule; correction.

**SUMMARY:** This document corrects Airworthiness Directive (AD) 2002-06-

04 for the specified Eurocopter France helicopters that was published in the **Federal Register** on March 20, 2002 (67 FR 12858). The effective date as stated in paragraph (f) of the AD is incorrect, and this document corrects that effective date. In all other respects, the original document remains the same.

**DATES:** Effective April 24, 2002.

**FOR FURTHER INFORMATION CONTACT:** Jim Grigg, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Rotorcraft Standards Staff, Fort Worth, Texas 76193-0110, telephone (817) 222-5490, fax (817) 222-5961.

**SUPPLEMENTARY INFORMATION:** The FAA issued a final rule AD 2002-06-04 on March 11, 2002 (67 FR 12858, March 20, 2002) for the specified Eurocopter France helicopters. The following correction is needed:

The effective date given in paragraph (f) of the AD was intended to be the same effective date of April 24, 2002, as stated in the "Effective Date" line. Therefore, the date in paragraph (f) needs correcting.

Since no other part of the regulatory information has been revised, the final rule is not being republished.

**Correction of Publication**

Accordingly, the publication on March 20, 2002 of the final rule (AD 2002-06-04) which was the subject of FR Doc. 02-6626 is corrected as follows:

**§ 39.13 [Corrected]**

On page 12859, in the second column, in AD 2002-06-04, paragraph (f), correct "April 4, 2002" to read "April 24, 2002".

Issued in Fort Worth, Texas, on April 29, 2002.

**David A. Downey,**

*Manager, Rotorcraft Directorate, Aircraft Certification Service.*

[FR Doc. 02-11805 Filed 5-10-02; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

[Docket No. 2000-SW-46-AD; Amendment 39-12674; AD 2002-05-06]

**RIN 2120-AA64**

**Airworthiness Directives; Sikorsky Aircraft Corporation Model S-76A Helicopters; Correction**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule; correction.