

**§ 39.13 [Amended]**

2. Section 39.13 is amended by adding the following new airworthiness directive:

**2002-17-05 Boeing:** Amendment 39-12871. Docket 2002-NM-154-AD.

*Applicability:* All Model 727 series airplanes, certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

*Compliance:* Required as indicated, unless accomplished previously.

To find and fix discrepancies of the wire bundles and hydraulic tubing in the aft stairwell area, which could result in electrical arcing between the wiring and hydraulic tubing and consequent fire and damage to adjacent structure, accomplish the following:

**General Visual Inspection/Corrective Action**

(a) Within 120 days after the effective date of this AD: Do a general visual inspection to find discrepancies (including inadequate clearance between the wire bundles and hydraulic tubing and/or structure, missing clamps, chafing, fire damage to structure, or damage to wire bundles) of the wire bundles and hydraulic tubing in the aft stairwell area, per the Work Instructions of Boeing Alert Service Bulletin 727-29A0068, dated May 30, 2002.

(1) If no discrepancy is found, no further action is required by this AD.

(2) If any discrepancy is found, before further flight, fix the discrepancy (includes repositioning of the wire bundles and clamps to ensure a minimum clearance of 0.25 inch between the wire bundles and hydraulic tubing and/or structure and installing clamps; repairing or replacing any damaged wiring and tubing; if evidence of fire damage, inspecting adjacent structural area for damage, and repairing any damage), per Figure 1 of the service bulletin.

**Note 2:** For the purposes of this AD, a general visual inspection is defined as: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to enhance visual access to all exposed surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors.

Stands, ladders, or platforms may be required to gain proximity to the area being checked."

**Alternative Methods of Compliance**

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

**Note 3:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

**Special Flight Permits**

(c) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

**Incorporation by Reference**

(d) The actions shall be done in accordance with Boeing Alert Service Bulletin 727-29A0068, dated May 30, 2002. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**Effective Date**

(e) This amendment becomes effective on September 16, 2002.

Issued in Renton, Washington, on August 22, 2002.

**Vi L. Lipski,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 02-22007 Filed 8-29-02; 8:45 am]

**BILLING CODE 4910-13-U**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. 2002-CE-11-AD; Amendment 39-12870; AD 2002-15-01 R1]**

**RIN 2120-AA64**

**Airworthiness Directives; Diamond Aircraft Industries GmbH Models HK 36 R "Super Dimona", HK 36 TC, HK 36 TS, HK 36 TTC, HK 36 TTC-ECO, HK 36 TTC-ECO (Restricted Category), and HK 36 TTS Sailplanes**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule; correction.

**SUMMARY:** This amendment clarifies information contained in Airworthiness Directive (AD) 2002-15-01, which currently requires you to inspect the long aileron push rods in both wings for damage and modify the push rods on all Diamond Aircraft Industries GmbH (Diamond) Models H-36 "Dimona", HK 36 R "Super Dimona", HK 36 TC, HK 36 TS, HK 36 TTC, HK 36 TTC-ECO, HK 36 TTC-ECO (Restricted Category), and HK 36 TTS sailplanes. The Model H-36 "Dimona" sailplane has a different flight control system than the rest of the affected sailplanes. This particular flight control system makes it impossible for the Model H-36 "Dimona" sailplanes to be in compliance with AD 2002-15-01. This document deletes these sailplanes from the AD applicability. The actions specified by this AD are intended to detect and correct damage in the long aileron push control rods, which could result in failure of the aileron push rods and decreased control. Such failure could lead to aeroelastic flutter.

**DATES:** This AD becomes effective on September 3, 2002.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulations as of September 3, 2002.

**ADDRESSES:** You may get the service information referenced in this AD from Diamond Aircraft Industries GmbH, N.A. Otto-Strasse 5, A-2700 Wiener Neustadt, Austria; telephone: 43 2622 26 700; facsimile: 43 2622 26 780. You may view this information at the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2002-CE-11-AD, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:**

Mike Kiesov, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4144; facsimile: (816) 329-4090.

**SUPPLEMENTARY INFORMATION:****Discussion**

*What Prior Action Did FAA Take on This Subject?*

We issued AD 2002-15-01, Amendment 39-12829 (67 FR 47680, July 22, 2002), in order to detect and correct damage in the long aileron push control rods on all Diamond Models H-36 "Dimona", HK 36 R "Super Dimona", HK 36 TC, HK 36 TS, HK 36 TTC, HK 36 TTC-ECO, HK 36 TTC-ECO (Restricted Category), and HK 36 TTS

sailplanes. This AD currently requires you to inspect the long aileron push rods in both wings for damage and modify the push rods.

*What Has Happened To Necessitate Further AD Action?*

The Model H-36 "Dimona" sailplane has a different flight control system than the rest of the affected sailplanes. This particular flight control system makes it impossible for the Model H-36 "Dimona" sailplanes to be in compliance with AD 2002-15-01.

Consequently, FAA sees a need to clarify AD 2002-15-01 to assure that every owner/operator of the affected sailplanes is able to comply with the AD action. This is possible by removing the Model H-36 "Dimona" sailplanes from the AD applicability.

**Correction of Publication**

*What Is the Purpose of This Document?*

This document clarifies AD 2002-15-01 by removing the Model H-36 "Dimona" sailplanes from the AD applicability and adds the amendment to section 39.13 of the Federal Aviation Regulations (14 CFR 39.13).

*Is It Necessary To Seek Public Input?*

Since this action only clarifies the intent of the compliance time, it has no adverse economic impact and imposes no additional burden on any person than would have been necessary to comply with AD 2000-23-01. Therefore, FAA has determined that prior notice and opportunity for public comment are unnecessary.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by Reference, Safety.

**Adoption of the Amendment**

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

2. FAA amends § 39.13 by removing Airworthiness Directive (AD) 2002-15-01, Amendment 39-12829 (67 FR 47680, July 22, 2002), and by adding a new AD to read as follows:

**2002-15-01 R1 Diamond Aircraft Industries GmbH:** Amendment 39-12870; Docket No. 2002-CE-11-AD; Revises AD 2002-15-01, Amendment 39-12829.

(a) *What sailplanes are affected by this AD?* This AD affects Models HK 36 R "Super Dimona", HK 36 TC, HK 36 TS, HK 36 TTC, HK 36 TTC-ECO, HK 36 TTC-ECO (Restricted Category), and HK 36 TTS sailplanes, all serial numbers, that are certificated in any category.

(b) *Who must comply with this AD?* Anyone who wishes to operate any of the sailplanes identified in paragraph (a) of this AD must comply with this AD.

(c) *What problem does this AD address?* The actions specified by this AD are intended to detect and correct damage in the long aileron push control rods, which could result in failure of the aileron push rods and decreased control. Such failure could lead to aeroelastic flutter.

(d) *What actions must I accomplish to address this problem?* To address this problem, you must accomplish the following:

Actions	Compliance	Procedures
(1) Inspect the long aileron push rods in both wings.	Within the next 10 hours time-in-service (TIS) after September 3, 2002 (the effective date of this AD), unless already accomplished.	In accordance with paragraph 1.8 Measures of Diamond Aircraft Industries GmbH Service Bulletin No. MSB36-72, dated February 1, 2002; Diamond Aircraft Industries GmbH Work Instruction No. WI-MSB36-72, dated February 1, 2002; and the applicable sailplane maintenance manual.
(2) If any long aileron push rods are found damaged during the inspection required in paragraph (d)(1) of this AD, modify the push rods.	Before further flight, after the inspection required in paragraph (d)(1) of this AD, unless already accomplished.	In accordance with paragraph 1.8 Measures of Diamond Aircraft Industries GmbH Service Bulletin No. MSB36-72, dated February 1, 2002; Diamond Aircraft Industries GmbH Work Instruction No. WI-MSB36-72, dated February 1, 2002; and the applicable sailplane maintenance manual.
(3) If no damage is found during the inspection required in paragraph (d)(1), modify the push rods.	Within the next 25 hours TIS after September 3, 2002 (the effective date of this AD), unless already accomplished.	In accordance with paragraph 1.8 Measures of Diamond Aircraft Industries GmbH Service Bulletin No. MSB36-72, dated February 1, 2002; Diamond Aircraft Industries GmbH Work Instruction No. WI-MSB36-72, dated February 1, 2002; and the applicable sailplane maintenance manual.

(e) *Can I comply with this AD in any other way?* You may use an alternative method of compliance or adjust the compliance time if:

- (1) Your alternative method of compliance provides an equivalent level of safety; and
- (2) The Standards Office Manager, Small Airplane Directorate, approves your alternative. Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Standards Office Manager.

**Note 1:** This AD applies to each sailplane identified in paragraph (a) of this AD, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For sailplanes that have been modified, altered, or repaired so that the performance of the requirements of

this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(f) *Where can I get information about any already-approved alternative methods of compliance?* Contact Mike Kiesov, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4144; facsimile: (816) 329-4090.

(g) *What if I need to fly the sailplane to another location to comply with this AD?* The

FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your sailplane to a location where you can accomplish the requirements of this AD.

(h) *Are any service bulletins incorporated into this AD by reference?* Actions required by this AD must be done in accordance with Diamond Aircraft Industries GmbH Service Bulletin No. MSB36-72, dated February 1, 2002; and Diamond Aircraft Industries GmbH Work Instruction No. WI-MSB36-72, dated February 1, 2002. The Director of the Federal Register approved this incorporation by reference under 5 U.S.C. 552(a) and 1 CFR part 51. You may get copies from Diamond Aircraft Industries GmbH, N.A. Otto-Strasse

5, A-2700 Wiener Neustadt, Austria; telephone: 43 2622 26 700; facsimile: 43 2622 26 780. You may view copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**Note 2:** The subject of this AD is addressed in Austrian AD No. 111, dated February 26, 2002.

(i) *Does this AD action affect any existing AD actions?* This amendment revises 2002-15-01, Amendment 39-12829 (67 FR 47680, July 22, 2002).

(j) *When does this amendment become effective?* This amendment becomes effective on September 3, 2002.

Issued in Kansas City, Missouri, on August 21, 2002.

**David R. Showers,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 02-22129 Filed 8-29-02; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2000-CE-35-AD; Amendment 39-12869; AD 2002-17-04]

RIN 2120-AA64

#### **Airworthiness Directives; Ballonbau Worner GmbH Model K-630/1-Stu Manned Free Gas Balloons**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule; request for comments.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD) that applies to all Ballonbau Worner GmbH (Ballonbau) Model K-630/1-Stu manned free gas balloons. This AD requires you to replace the PVC tubes that cover the steelwire loops of the basket with an electrostatic conductive braided rope. This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Germany. The actions specified by this AD are intended to prevent the chance of an electrostatic charge buildup between the steelwire loops of the basket and the balloon envelope, which could result in ignition of combustible lifting gas fumes in the balloon envelope. Such a condition could lead to gas explosion and fire.

**DATES:** This AD becomes effective on September 30, 2002.

The Director of the Federal Register approved the incorporation by reference

of certain publications listed in the regulation as of September 30, 2002.

The Federal Aviation Administration (FAA) must receive any comments on this rule on or before October 10, 2002.

**ADDRESSES:** Submit comments to FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2000-CE-35-AD, 901 Locust, Room 506, Kansas City, Missouri 64106. You may view any comments at this location between 8 a.m. and 4 p.m., Monday through Friday, except Federal holidays. You may also send comments electronically to the following address: 9-ACE-7-Docket@faa.gov. Comments sent electronically must contain "Docket No. 2000-CE-35-AD" in the subject line. If you send comments electronically as attached electronic files, the files must be formatted in Microsoft Word 97 for Windows or ASCII text.

You may get the service information referenced in this AD from Ballonbau Worner GmbH, Zirbelstr 57c, 86154 Augsburg, Federal Republic of Germany; telephone: ++ 49 821-421590; facsimile: ++ 49 821-419641. You may view this information at FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2000-CE-35-AD, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Roger Chudy, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4140; facsimile: (816) 329-4090.

#### **SUPPLEMENTARY INFORMATION:**

##### **Discussion**

##### *What Events Have Caused This AD?*

The Luftfahrt-Bundesamt (LBA), which is the airworthiness authority for Germany, notified FAA that an unsafe condition may exist on all Ballonbau Model K-630/1-Stu manned free gas balloons. The LBA reports the potential of an electrostatic build up between the steelwire loops of the basket and the balloon envelope.

Ballonbau has designed an electrostatic conductive braided rope to address this condition.

##### *What Are the Consequences if the Condition Is Not Corrected?*

This condition, if not prevented, could result in ignition of combustible lifting gas fumes in the balloon envelope. Such a condition could lead to gas explosion and fire.

##### *Is There Service Information That Applies to This Subject?*

Ballonbau has issued Technical Note Nr. 8002-13, dated January 14, 2000.

This service information includes procedures for removing the PVC tubes that cover the steelwire loops of the basket and installing an electrostatic conductive braided rope.

##### *What Action Did the LBA Take?*

The LBA classified this service bulletin as mandatory and issued German AD Number 2000-063, dated February 24, 2000, in order to ensure the continued airworthiness of these balloons in Germany.

##### *Was This in Accordance With the Bilateral Airworthiness Agreement?*

This balloon model is manufactured in Germany and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement.

Pursuant to this bilateral airworthiness agreement, the LBA has kept us informed of the situation described above.

#### **The FAA's Determination and an Explanation of the Provisions of This AD**

##### *What Has FAA Decided?*

The FAA has examined the findings of the LBA; reviewed all available information, including the service information referenced above; and determined that:

- The unsafe condition referenced in this document exists or could develop on other Ballonbau Model K-630/1-Stu manned free gas balloons of the same type design;
- The actions specified in the previously-referenced service information (as specified in this AD) should be accomplished on the affected balloons; and
- AD action should be taken in order to correct this unsafe condition.

##### *What Does This AD Require?*

This AD requires you to incorporate the actions in the previously-referenced service bulletin.

##### *Will I Have the Opportunity To Comment Prior to the Issuance of the Rule?*

Since this AD action does not affect any balloon that is currently on the U.S. register, it has no adverse economic impact and imposes no additional burden on any person. Therefore, notice and opportunity for public prior