

39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

2. Section 39.13 is amended by removing amendment 39-6232 (54 FR 24161, June 6, 1989), and by adding a new airworthiness directive (AD), to read as follows:

**Boeing:** Docket 2002-NM-28-AD. Supersedes AD 89-12-07, Amendment 39-6232.

**Applicability:** All Model 747 series airplanes, certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (f)(1) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent ice accumulation on the lateral flight control cables due to water entering the wheel well of the main landing gear and freezing, which could restrict or jam control cable movement, resulting in loss of controllability of the airplane; accomplish the following:

### Restatement of Requirements of AD 89-12-07

#### Repetitive Inspections/Cleaning

(a) Within 15 months after July 10, 1989 (the effective date of AD 89-12-07, amendment 39-6232), unless accomplished 3 months before July 10, 1989, and thereafter at intervals not to exceed 18 months: Gain access to the cavity aft of the wing center section and remove all debris and foreign material, clean the cavity, and verify all drains are open and clean.

#### New Requirements of This AD

#### Repetitive Tests of the Drainage System/Corrective Action

(b) Within 18 months after the effective date of this AD, do the actions required by paragraphs (b)(1), (b)(2), and (b)(3) of this AD, as applicable, per the Work Instructions of Boeing Alert Service Bulletin 747-51A2057, dated February 21, 2002.

(1) Do a test (including a general visual inspection of the external drains, reducer, and drain lines, and sending 3 to 5 pounds per square inch (PSI) compressed air through

the drain line) of the drainage system of the canted pressure deck for discrepancies (including damage, holes, signs of frozen water, and signs of blockage), per Work Package 1 of the service bulletin. Repeat the test at least every 18 months.

(2) Clean the drainage system for the canted pressure deck and do a general visual inspection of the system for discrepancies per Work Package 2 of the Work Instructions of the service bulletin. Repeat the cleaning and inspection at least every 18 months. Accomplishment of this paragraph terminates the requirements in paragraph (a) of this AD.

(3) Except as required by paragraph (e) of this AD: If any discrepancy is found during any inspection or test required by paragraphs (b)(1) and (b)(2) of this AD, before further flight, repair per the Work Instructions of the service bulletin.

#### Repetitive Inspections of the Canted Pressure Deck/Corrective Action

(c) *Within 36 months after the effective date of this AD:* Do a general visual inspection of the canted pressure deck for discrepancies (including loose or missing fasteners; loose, missing, or cracked sealant; and leak paths), per Work Package 3 of the Work Instructions of Boeing Alert Service Bulletin 747-51A2057, dated February 21, 2002. If any discrepancy is found, before further flight, repair (including replacing any loose or missing fastener or loose, missing, or cracked sealant; and repair of any leak found) per the service bulletin; except as required by paragraph (e) of this AD. Repeat the inspection at least every 36 months.

**Note 2:** For the purposes of this AD, a general visual inspection is defined as: “A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to enhance visual access to all exposed surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked.”

#### Repetitive Cabin Pressurization Tests/Corrective Action

(d) Within 72 months after the effective date of this AD: Do a cabin pressurization test to check for leaks in the canted pressure deck per Work Package 4 of the Work Instructions of Boeing Alert Service Bulletin 747-51A2057, dated February 21, 2002. If any leak is found, before further flight, repair per the service bulletin; except as required by paragraph (e) of this AD. Repeat the cabin pressurization test at least every 72 months.

#### Corrective Action per Seattle Aircraft Certification Office (ACO)

(e) If any discrepancy is found during any inspection or test required by this AD and the service bulletin specifies to contact Boeing for appropriate action: Before further flight, repair per a method approved by the

Manager, Seattle ACO, FAA; or per data meeting the type certification basis of the airplane approved by a Boeing Company Designated Engineering Representative who has been authorized by the Manager, Seattle ACO, to make such findings. For a repair method to be approved, the approval must specifically reference this AD.

#### Alternative Methods of Compliance

(f)(1) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

(2) Alternative methods of compliance, approved previously in accordance with AD 89-12-07, amendment 39-6232, are approved as alternative methods of compliance with paragraph (b)(2) of this AD.

**Note 3:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

#### Special Flight Permits

(g) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on October 8, 2002.

**Ali Bahrami,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 02-26203 Filed 10-15-02; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

#### Airspace Docket No. 02-ASO-25]

#### Proposed Amendment of Class E5 Airspace; Tampa, FL

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking.

**SUMMARY:** This notice proposes to amend Class E5 airspace at Tampa, FL. A Localizer Runway 23 Standard Instrument Approach Procedure (SIAP) has been developed for Vandenberg Airport. As a result, additional controlled airspace extending upward from 700 feet Above Ground Level (AGL) northeast of Vandenberg Airport is needed to contain the SIAP.

**DATES:** Comments must be received on or before November 15, 2002.

**ADDRESSES:** Send comments on the proposal in triplicate to: Federal Aviation Administration, Docket No. 02-ASO-25, Manager, Airspace Branch, ASO-520, P.O. Box 20636, Atlanta, Georgia 30320.

The official docket may be examined in the Office of the Regional Counsel for Southern Region, Room 550, 1701 Columbia Avenue, College Park, Georgia 30337, telephone (404) 305-5586.

**FOR FURTHER INFORMATION CONTACT:** Walter R. Cochran, Manager, Airspace Branch, Air Traffic Division, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305-5586.

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify the airspace docket number and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Airspace Docket No. 02-ASO-25." The postcard will be date/time stamped and returned to the commenter. All communications received before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of the comments received. All comments submitted will be available for examination in the Office of the Regional Counsel for Southern Region, Room 550, 1701 Columbia Avenue, College Park, Georgia 30337, both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

**Availability of NPRMs**

Any person may obtain a copy of this Notice of Proposed Rulemaking (NPRM) by submitting a request to the Federal Aviation Administration, Manager, Airspace Branch, ASO-520, Air Traffic Division, P.O. Box 20636, Atlanta, Georgia 30320. Communications must identify the notice number of this NPRM. Persons interested in being placed on a mailing list for future NPRMs should also request a copy of Advisory Circular No. 11-2A which describes the application procedure.

**The Proposal**

The FAA is considering an amendment to Part 71 of the Federal Aviation Regulations (14 CFR part 71) to amend Class E5 airspace at Tampa, FL. Class E airspace designations for airspace areas extending upward from 700 feet or more above the surface of the earth are published in Paragraph 6005 of FAA Order 7400.9K dated August 30, 2002, and effective September 16, 2002, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 71**

Airspace, Incorporation by reference, Navigation (Air)

**The Proposed Amendment**

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR Part 71 as follows:

**PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D, AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS**

1. The authority citation for Part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

**§ 71.1 [Amended]**

2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9K, Airspace Designations and Reporting Points, dated August 30, 2002, and effective September 16, 2002, is amended as follows:

*Paragraph 6005 Class E Airspace Areas Extending Upward From 700 feet or More Above the Surface of the Earth.*

\* \* \* \* \*

**ASO FL E5 Tampa, FL [Revised]**

Tampa International Airport, FL

(Lat. 27°58'32"N, long. 82°31'59"W)

St. Petersburg-Clearwater International

Airport

(Lat. 27°54'39"N, long. 82°41'14"W)

MacDill AFB

(Lat. 27°50'57"N, long. 82°31'17"W)

Peter O Knight Airport

(Lat. 27°54'56"N, long. 82°26'57"W)

Albert-Whitted Airport

(Lat. 27°45'54"N, long. 82°37'38"W)

Vandenberg Airport

(Lat. 28°00'33"N, long. 82°20'59"W)

Clearwater Air Park

(Lat. 27°58'35"N, long. 82°45'31"W)

Vandenberg Localizer

(Lat. 28°00'40"N, long. 82°20'55"W)

That airspace extending upward from 700 feet above the surface within a 7-mile radius of Tampa International Airport, St. Petersburg-Clearwater International Airport, MacDill AFB, and Peter O Knight Airport, and within a within a 6.3-mile radius of Albert-Whitted Airport, and Clearwater Air Park, and within a 6.7-mile radius of Vandenberg Airport and within 4 miles south and 8 miles north of the Vandenberg Localizer northeast course extending from the 6.7-mile radius to 16 miles northeast of the airport; excluding that airspace within the Zephyrhills, FL, and Lakeland, FL, Class E airspace areas.

\* \* \* \* \*

Issued in College Park, Georgia, on October 4, 2002.

**Walter R. Cochran,**

*Acting Manager, Air Traffic Division, Southern Region.*

[FR Doc. 02-26277 Filed 10-15-02; 8:45 am]

**BILLING CODE 4910-13-M**