

which could result in reduced structural integrity of the airplane, and loss of system function for flaps, controls, and landing gear, accomplish the following:

#### Inspection for Ravenstone Jackson Bolts

(a) Perform a general visual inspection to identify the type of bolts installed at specified locations of the wing and fuselage, in accordance with paragraphs (a)(1), (a)(2), (a)(3), (a)(4), and (a)(5), as applicable, of this AD.

**Note 2:** For the purposes of this AD, a general visual inspection is defined as: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to enhance visual access to all exposed surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

(1) For Model Hawker 800XP airplanes identified in the effectivity of Raytheon Service Bulletin SB 51-3408, dated October 2000: Inspect within 12 months after the effective date of this AD in accordance with the service bulletin.

(2) For Model Hawker 800XP airplanes identified in the effectivity of Raytheon Service Bulletin SB 51-3426, Revision 1, dated November 2001: Inspect within 18 months after the effective date of this AD in accordance with the service bulletin. Inspection before the effective date of this AD in accordance with Raytheon Service Bulletin SB 51-3426, dated December 2000, is acceptable for compliance with the inspection requirements only for those locations identified in the original service bulletin; this AD requires inspections at additional locations in accordance with Revision 1 of the service bulletin.

(3) For Model Hawker 800 (including variant U-125A) airplanes identified as Group A airplanes in Raytheon Service Bulletin SB 51-3421, Revision 1, dated November 2001: Inspect within 12 months after the effective date of this AD in accordance with the service bulletin. Inspection before the effective date of this AD in accordance with Raytheon Service Bulletin SB 51-3421, dated December 2000, is acceptable for compliance with this inspection requirement for Group A airplanes.

(4) For Model Hawker 800 (including variant U-125A) airplanes identified as Group B airplanes in Raytheon Service Bulletin SB 51-3421, Revision 1, dated November 2001: Inspect within 18 months after the effective date of this AD in accordance with the service bulletin. Inspection before the effective date of this AD in accordance with Raytheon Service Bulletin SB 51-3421, dated December 2000, is acceptable for compliance with the inspection requirement only for those locations identified in the original service bulletin; this AD requires inspections at

additional locations in accordance with Revision 1 of the service bulletin.

(5) For Model Hawker 800 (including variant U-125A) airplanes identified as Group C airplanes in Raytheon Service Bulletin SB 51-3421, Revision 1, dated November 2001: Inspect within 12 months after the effective date of this AD in accordance with the service bulletin. Inspection before the effective date of this AD in accordance with Raytheon Service Bulletin SB 51-3421, dated December 2000, is acceptable for compliance with the inspection requirement only for those locations identified in the original service bulletin; this AD requires inspections at additional locations in accordance with Revision 1 of the service bulletin.

#### Inspection for Broken Bolts

(b) For any discrepant bolt (any Ravenstone Jackson DHS bolt or any bolt that cannot be identified) found during the inspection required by paragraph (a) of this AD: Before further flight following detection of the discrepant bolt, perform an ultrasonic inspection to determine if the bolt is broken, in accordance with the applicable service bulletin identified in paragraph (a) of this AD. Replace any broken bolt with a new bolt before further flight, in accordance with the applicable service bulletin.

#### Reporting Requirement

(c) If any broken bolt is found during the inspection specified in paragraph (b) of this AD: Send an inspection report at the applicable time specified in paragraph (c)(1) or (c)(2) of this AD to the Manager, Wichita Aircraft Certification Office (ACO), 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas 67209; fax (316) 946-4407. The report must include the inspection results, a description of all discrepancies found, and the airplane serial number. Information collection requirements contained in this AD have been approved by the Office of Management and Budget (OMB) under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 *et seq.*) and have been assigned OMB Control Number 2120-0056.

(1) For airplanes on which the inspection is accomplished after the effective date of this AD: Submit the report within 30 days after performing the inspection required by paragraph (a) of this AD.

(2) For airplanes on which the inspection has been accomplished prior to the effective date of this AD: Submit the report within 90 days after the effective date of this AD.

#### Part Installation

(d) As of the effective date of this AD, no person may install on any airplane a Ravenstone Jackson DHS bolt having a batch number identified in paragraph 3.B. of Raytheon Service Bulletin SB 51-3426, Revision 1, dated November 2001; paragraph 3.A. Raytheon Service Bulletin SB 51-3421, Revision 1, dated November 2001; or paragraph 2.B. of Raytheon Service Bulletin SB 51-3408, dated October 2000.

#### Alternative Methods of Compliance

(e) An alternative method of compliance or adjustment of the compliance time that

provides an acceptable level of safety may be used if approved by the Manager, Wichita ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Wichita ACO.

**Note 3:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Wichita ACO.

#### Special Flight Permits

(f) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on November 22, 2002.

**Ali Bahrami,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 02-30346 Filed 11-29-02; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Airspace Docket No. 02-ASO-27]

#### Proposed Establishment of Class D Airspace; Shaw AFB, SC

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking.

**SUMMARY:** This notice proposes to establish Class D airspace at Shaw AFB, SC. Shaw Radar Approach Control (RAPCON) is closed daily from 0330 UTC to 1100 UTC. Shaw AFB Airport Traffic Control Tower (ATCT) is open continuously. Therefore, when the RAPCON is closed Class D airspace must be established for the ATCT. Class D surface area airspace is required when the control tower is open to contain Standard Instrument Approach Procedures (SIAPs) and other Instrument Flight Rules (IFR) operations at the airport. This action would establish Class D airspace extending upward from the surface to and including 2,700 feet MSL within a 4.4-mile radius of the airport.

**DATES:** Comments must be received on or before January 2, 2003.

**ADDRESSES:** Send comments to the proposal in triplicate to: Federal Aviation Administration, Docket No. 02-ASO-27, Manager, Airspace Branch, ASO-520, P.O. Box 20636, Atlanta, Georgia 30320.

The official docket may be examined in the Office of the Regional Counsel for Southern Region, Room 550, 1701 Columbia Avenue, College Park, Georgia 30337, telephone (404) 305-5627.

**FOR FURTHER INFORMATION CONTACT:**

Walter R. Cochran, Manager, Airspace Branch, Air Traffic Division, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305-5627.

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify the airspace docket number and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Airspace Docket No. 02-ASO-27." The postcard will be date/time stamped and returned to the commenter. All communications received before the specified closing date for comments will be considered before taking action on the proposal rule. The proposal contained in this notice may be changed in light of the comments received. All comments submitted will be available for examination in the Office of the Regional Counsel for Southern Region, Room 550, 1701 Columbia Avenue, College Park, Georgia 30337, both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with the rulemaking will be filed in the docket.

**Availability of NPRMs**

Any person may obtain a copy of this Notice of Proposed Rulemaking (NPRM) by submitting a request to the Federal Aviation Administration, Manager, Airspace Branch, ASO-520, Air Traffic Division, P.O. Box 20636, Atlanta, Georgia 30320. Communications must identify the notice number of this NPRM. Persons interested in being placed on a mailing list for future

NPRMs should also request a copy of Advisory Circular No. 11-2A, which describes the application procedure.

**The Proposal**

The FAA is considering an amendment to part 71 of the Federal Aviation Regulations (14 CFR part 71) to establish Class D airspace at Shaw AFB, SC. Class D airspace designations for airspace areas extending upward from the surface of the earth are published in Paragraph 5000 of FAA Order 7400.9K, dated August 30, 2002, and effective September 16, 2002, which is incorporated by reference in 14 CFR 71.1. The Class D airspace designation listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 71**

Airspace, Incorporation by reference, Navigation (Air).

**The Proposed Amendment**

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

**PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D, AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS**

1. The authority citation for part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

**§ 71.1 [Amended]**

2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation August 30, 2002, and effective September 16, 2002, is amended as follows:

*Paragraph 5000 Class D Airspace.*

\* \* \* \* \*

**ASO SC D Shaw AFB, SC [NEW]**

Shaw AFB, SC

(Lat. 33°58'23" N, long. 80°28'22" W)

That airspace extending upward from the surface to and including 2,700 feet MSL within a 4.4-mile radius of the Shaw AFB, excluding that airspace contained within Restricted Area R-6002 when it is in use. This Class D airspace area is effective during the specific days and times established in advance by a Notice to Airmen. The effective days and times will thereafter be continuously published in the Airport/Facility Directory.

\* \* \* \* \*

Issued in College Park, Georgia, on November 21, 2002.

**Walter R. Cochran,**

*Acting Manager, Air Traffic Division, Southern Region.*

[FR Doc. 02-30328 Filed 11-29-02; 8:45 am]

**BILLING CODE 4910-13-M**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 71**

[Airspace Docket No. 01-ANM-16]

**Proposed Establishment of Class E Airspace, Richfield, UT**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This action proposes to establish Class E airspace at the Richfield Municipal Airport, Richfield, UT. A newly developed Area Navigation (RNAV) Standard Instrument Approach Procedure (SIAP) at the Richfield Municipal Airport has made this action necessary. The intended effect of this proposal is to provide adequate controlled airspace for Instrument Flight Rule (IFR) operations at Richfield Municipal Airport, Richfield, UT.

**DATES:** Comments must be received on or before January 16, 2003.

**ADDRESSES:** Send comments on the proposal in triplicate to: Manager, Airspace Branch, ANM-520, Federal Aviation Administration, Docket No. 01-ANM-16, 1601 Lind Avenue SW, Renton, Washington 98055-4056.

**FOR FURTHER INFORMATION CONTACT:** Ed Haeseker, ANM-520.7, Federal Aviation Administration, Docket No. 01-ANM-16, 1601 Lind Avenue SW, Renton, Washington 98055-4056; telephone number: (425) 227-2527.