

submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2002-NE-37-AD." The postcard will be date stamped and returned to the commenter.

Regulatory Analysis

This final rule does not have federalism implications, as defined in Executive Order 13132, because it would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Accordingly, the FAA has not consulted with state authorities prior to publication of this final rule.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2002-24-06 Rolls-Royce Deutschland Ltd. & Co KG: Amendment 39-12971. Docket No. 2002-NE-37-AD.

Applicability

This airworthiness directive (AD) is applicable to Rolls-Royce Deutschland Ltd. & Co KG (RRD), Model Tay 620-15 and 650-15 turbofan engines with low pressure (LP) fuel tube part number, (P/N) JR33021A, installed. These engines are installed on, but not limited to Fokker F.28 Mark 0100 airplanes.

Note 1: This AD applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance

Compliance with this AD is required as indicated, unless already done.

To prevent a dual-engine flameout due to fuel exhaustion which could lead to forced landing and possible damage to the airplane, do the following:

(a) Within 300 hours time-in-service (TIS) after the effective date of this AD or one month after the effective date of this AD, whichever occurs first, inspect LP fuel tube, P/N JR33021A, for fretting in accordance with 3.C.1. through 3.C.10. of the Accomplishment Instructions of RRD service bulletin (SB) TAY-73-1540, Revision 1, dated September 13, 2002.

(b) Thereafter, inspect the LP fuel tube, P/N JR33021A, for fretting in accordance with 3.C.1. through 3.C.10. of the Accomplishment Instructions of RRD SB TAY-73-1540, Revision 1, dated September 13, 2002; at intervals not to exceed 2,000 hours TIS since the last inspection.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office (ECO). Operators must submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, ECO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the ECO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be done.

Documents That Have Been Incorporated By Reference

(e) The inspections must be done in accordance with Rolls-Royce Deutschland Ltd. & Co KG service bulletin TAY-73-1540, Revision 1, dated September 13, 2002. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Rolls-Royce Deutschland Ltd. & Co KG, Eschenweg 11, D-15827 DAHLEWITZ, Germany; telephone 49 (0) 33-7086-1768; fax 49 (0) 33-7086-3356. Copies may be inspected at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in LBA airworthiness directive 2002-331, dated September 13, 2002.

Effective Date

(f) This amendment becomes effective on December 18, 2002.

Issued in Burlington, Massachusetts, on November 21, 2002.

Jay J. Pardee,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 02-30345 Filed 12-2-02; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 00-ANM-32]

Revision of Class E Airspace, Holyoke, CO

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action revises the Class E airspace at Holyoke, CO. This change is necessary because the Airport Reference Point (ARP) coordinates for the Class E5 airspace at the Holyoke Airport have been changed. The legal description of the Holyoke Airport Class E airspace must be changed to reflect the new coordinates. The intended effect of this rule is to provide adequate controlled airspace for Instrument Flight Rules (IFR) operations at Holyoke Airport, Holyoke, CO.

EFFECTIVE DATE: 0901 UTC, October 3, 2002.

FOR FURTHER INFORMATION CONTACT: Ed Haeseker, ANM-520.7 Federal Aviation Administration, Docket No. 00-ANM-32, 1601 Lind Avenue SW, Renton, Washington 98055-4056; telephone number: (425) 227-2527.

SUPPLEMENTARY INFORMATION:**History**

On August 29, 2001, the FAA proposed to amend Title 14 Code of Federal Regulations, part 71 (14 CFR part 71) by revising Class E airspace at Holyoke, CO, to reflect a change in the ARP at the Holyoke Airport, Holyoke, CO (66 FR 45659). This action creates Class E5 airspace at Holyoke, CO, to meet current airspace requirements for IFR flight in Holyoke, Colorado. Interested parties were invited to participate in the rulemaking proceeding by submitting written comments on the proposal. No comments were received.

The Rule

This amendment to Title 14 Code of Federal Regulations, part 71 (14 CFR part 71) revises the description of Class E5 airspace at Holyoke, CO, to reflect the change to the ARP coordinates in the legal description of Holyoke Airport. Class E5 controlled airspace is required to contain aircraft executing IFR procedures at Holyoke Airport. The FAA establishes Class E airspace where necessary to contain aircraft transitioning between the terminal and en route environments. This rule is designed to provide for the safe and efficient use of the navigable airspace and to promote safe flight operations under IFR at the Holyoke Airport and between the terminal and en route transition stages.

The area will be depicted on aeronautical charts for pilot reference. The coordinates for this airspace docket are based on North American Datum 83. Class E5 airspace areas extending upward from 700-feet or more above the surface of the earth, are published in Paragraph 6005, of FAA Order 7400.9K dated August 30, 2002, and effective September 16, 2002, which is incorporated by reference in 14 CFR 71.1. The Class E5 airspace designation listed in this document will be published subsequently in the Order.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it

is certified that this rule, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D, AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS

1. The authority citation for 14 CFR part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§ 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9K, Airspace Designations and Reporting Points, dated August 30, 2002, and effective September 16, 2002, is amended as follows:

Paragraph 6005 Class E5 airspace areas extending upward from 700-feet or more above the surface of the earth.

* * * * *

ANM CO E5 Holyoke, CO [Revised]

Holyoke Airport, CO
(Lat. 40°34'10"N., long. 102°16'22"W.)
Heginbotham NDB
(Lat. 40°34'53"N., long. 102°16'52.7"W.)

That airspace extending upward from 700-feet above the surface within the 6.7-mile radius of the Holyoke Airport, and within 2.5 miles each side of the 325° bearing from the Heginbotham NDB extending from the 6.7-mile radius to 7 miles northwest of the NDB; excluding that airspace within Federal Airways.

Issued in Seattle, Washington, on October 10, 2002.

Raul C. Trevino,

*Assistant Manager, Air Traffic Division,
Northwest Mountain Region.*
[FR Doc. 02–30611 Filed 12–2–02; 8:45 am]

BILLING CODE 4910–13–M

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 97**

[Docket No. 30341; Amdt. No. 3033]

Standard Instrument Approach Procedures; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This amendment establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, addition of new obstacles, or changes in air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

DATES: This rule is effective December 3, 2002. The compliance date for each SIAP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of December 3, 2002.

ADDRESSES: Availability of matters incorporated by reference in the amendment is as follows:

For Examination—

1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591;

2. The FAA Regional Office of the region in which the affected airport is located;

3. The Flight Inspection Area Office which originated the SIAP; or,

4. The Office of Federal Register, 800 North Capitol Street, NW., Suite 700, Washington, DC.

*For Purchase—*Individual SIAP copies may be obtained from:

1. FAA Public Inquiry Center (APA–200), FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591; or

2. The FAA Regional Office of the region in which the affected airport is located.

*By Subscription—*Copies of all SIAPs, mailed once every 2 weeks, are for sale