

PART 110—CONTRIBUTION AND EXPENDITURE LIMITATIONS AND PROHIBITIONS

Authority: 2 U.S.C. 431(8), 431(9), 432(c)(2), 437d, 438(a)(8), 441a, 441b, 441d, 441e, 441f, 441g, 441h and 441k.

citation or phrase indicated in the middle column, and replace it with the citation or phrase indicated in the right column:

3. The authority citation for part 110 continues to read as follows:

§ 110.19 [Amended]

4. In the table below, for each section indicated in the left column, remove the

Section	Remove	Add
110.19(e) paragraph heading	maintain, finance	finance, maintain.
110.19(e)	maintain, finance	finance, maintain.

Dated: January 14, 2003.
Ellen L. Weintraub,
 Chair, Federal Election Commission.
 [FR Doc. 03-1184 Filed 1-21-03; 8:45 am]
 BILLING CODE 6715-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-CE-80-AD; Amendment 39-13019; AD 2003-02-03]

RIN 2120-AA64

Airworthiness Directives; Raytheon Aircraft Company 65, 90, 99, 100, 200, and 300 Series, and Model 2000 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that applies to certain Raytheon Aircraft Company (Raytheon) 65, 90, 99, 100, 200, and 300 series, and Model 2000 airplanes. This AD requires you to install new exterior operating instruction placards for the airstair door and emergency exits. This AD is the result of Raytheon improving the visibility and understandability of the door operating instruction placards. This was done as a result of difficulty opening the emergency exits of a similar type design airplane. The actions specified by this AD are intended to assure that clear and complete operating instructions are visible for opening the airstair door and emergency exits. If the operating instructions are not visible or understandable, this could result in the inability to open the airstair door or emergency exits during an emergency situation.

DATES: This AD becomes effective on March 7, 2003.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulations as of March 7, 2003.

ADDRESSES: You may get the service information referenced in this AD from Raytheon Aircraft Company, 9709 E. Central, Wichita, Kansas 67201-0085; telephone: (800) 429-5372 or (316) 676-3140. You may view this information at the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2000-CE-80-AD, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW., Suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Mr. Steven E. Potter, Aerospace Engineer, Wichita Aircraft Certification Office, FAA, 1801 Airport Road, Wichita, Kansas 67209; telephone: (316) 946-4124; facsimile: (316) 946-4407.

SUPPLEMENTARY INFORMATION:

Discussion

What events have caused this AD? FAA believes that the instructions for opening the airstair door and emergency exits are either not visible or not easy to understand on Raytheon 65, 90, 99, 100, 200, and 300 series, and Model 2000 airplanes. This is based on an accident that resulted in the issuance of AD 97-04-02. AD 97-04-02 was later superseded by AD 98-21-20 to incorporate more visible and understandable instructions.

What is the potential impact if FAA took no action? If the exterior door operating instruction placards are not visible or understandable, this could result in the inability to open the airstair door or emergency exits during an emergency situation.

Has FAA taken any action to this point? We issued a proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to certain Raytheon 65, 90, 99, 100, 200, and 300 series, and Model 2000 airplanes. This proposal was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on August 9, 2002 (67 FR 51791). The NPRM proposed to require you to install new exterior

operating instruction placards for the airstair door and emergency exits.

Was the public invited to comment? The FAA encouraged interested persons to participate in the making of this amendment. The following presents the comments received on the proposal and FAA's response to each comment:

Comment Issue No. 1: AD Is Unjustified

What is the commenter's concern? The commenter believes that in the accident that resulted in the earlier ADs, the damage to the airplane prevented the doors from opening. Therefore, the commenter believes that if the new placards had been present in this situation, they still would not have prevented injuries or loss of life. We infer that the commenter wants the NPRM withdrawn based on no compelling evidence that the presence of the placards addresses the unsafe condition.

What Is FAA's response to the concern? We do not concur. In an emergency situation, exiting the airplane is of the utmost importance, especially if the postcrash scenario includes a cabin fire. The cabin crew and/or passengers may become incapacitated. Therefore, the exterior emergency exit door operating instructions must be extremely clear and complete so that any person will be able to open the exit door.

We are not changing the final rule AD action based on this comment.

Comment Issue No. 2: Placards Are Not Durable

What is the commenter's concern? The commenter states that the placards supplied by Raytheon do not adhere to the airplane surface properly. The placards often begin to peel-off either in flight or while washing the airplane. We infer that the commenter wants the NPRM withdrawn because the placards will eventually come off on their own.

What is FAA's response to the concern? We are aware that durability and adherence of the placards to the airplane surface may be a problem. However, it is not a valid reason for withdrawing the NPRM. The owners/

operators of the affected airplanes may choose to apply one or two coats of clear coating to seal the edges of the placard.

We are not changing the final rule AD action based on this comment.

Comment Issue No. 3: Placards Degrade the Airplane's Appearance

What is the commenter's concern? The commenter states that the affected airplanes are chiefly used in private, charter, and corporate service where appearance is especially important to the owners/operators. The commenter states that the placards are out of proportion to the size of the airplanes, look very ugly, and the contrasting colors of the placards cause a problem because of stripe locations on the airplane's paint job. We infer that the

commenter wants the NPRM withdrawn because the placards degrade the airplane's appearance.

What is FAA's response to the concern? We understand that appearance of the aircraft is a key element for owners/operators. However, cosmetic issues cannot be given higher priority than addressing the unsafe condition and exiting the airplane in an emergency situation.

We are not changing the final rule AD action based on this comment.

FAA's Determination

What is FAA's final determination on this issue? After careful review of all available information related to the subject presented above, we have determined that air safety and the

public interest require the adoption of the rule as proposed except for minor editorial corrections. We have determined that these minor corrections:

- Provide the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Cost Impact

How many airplanes does this AD impact? We estimate that this AD affects 3,587 airplanes in the U.S. registry.

What is the cost impact of this AD on owners/operators of the affected airplanes? We estimate the following costs to accomplish the modification:

Labor cost	Parts cost	Total cost per airplane	Total cost on U.S. operators
2 workhours × \$60 per hour = \$120	Approximately \$190 per airplane	\$120 + \$190 = \$310	\$310 × 3,587 = \$1,111,970.

The manufacturer will provide warranty credit for labor and parts to the extent noted under MANPOWER and MATERIAL in Raytheon Mandatory Service Bulletin SB 52-3096, Rev. 1, Revised: June, 2002.

Compliance Time of This AD

What is the compliance time of this AD? The compliance time of this AD is "within the next 200 hours time-in-service (TIS) after the effective date of this AD or within the next 12 months after the effective date of this AD, whichever occurs first."

Why is the compliance time of this AD presented in both hours TIS and calendar time? The unsafe condition on these airplanes is not a result of the number of times the airplane is operated. Airplane operation varies among operators. For example, one operator may operate the airplane 50 hours TIS in 3 months while it may take another operator 12 months or more to accumulate 50 hours TIS. For this reason, the FAA has determined that the compliance time of this AD should be specified in both hours time-in-service (TIS) and calendar time in order to assure this condition is not allowed to go uncorrected over time.

Regulatory Impact

Does this AD impact various entities? The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

Does this AD involve a significant rule or regulatory action? For the reasons discussed above, I certify that this action (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the final evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. FAA amends § 39.13 by adding a new AD to read as follows:

2003-02-03 Raytheon Aircraft Company:
Amendment 39-13019; Docket No. 2000-CE-80-AD.

(a) *What airplanes are affected by this AD?* This AD affects the following airplane models and serial numbers that are certificated in any category:

Model	Serial Nos.
(1) 65-90, 65-A90, B90, C90, and C90A	LJ-1 through LJ-1530.
(2) 65-A90-1 (U-21A)	LM-1 through LM-125.
(3) 65-A90-1 (U-21G)	LM-126 through LM-141.
(4) 65-A90-2 (RU-21B)	LS-1 through LS-3.
(5) 65-A90-3 (RU-21C)	LT-1 and LT-2.
(6) 65-A90-4 (RU-21E)	LU-1 through LU-16.
(7) E90	LW-1 through LW-347.
(8) F90	LA-2 through LA-236.

Model	Serial Nos.
(9) H90 (T-44A)	LL-1 through LL-61.
(10) 99, 99A, A99A, B99, and C99	U-1 through U-239.
(11) 100 and A100	B-1 through B-94 and B-100 through B-247.
(12) A100 (U-21F)	B-95 through B-99.
(13) A100-1 (U-21J)	BB-3 through BB-5.
(14) A200 (C-12A) and (C-12C)	BC-1 through BC-75 and BD-1 through BD-30.
(15) A200C (UC-12B)	BJ-1 through BJ-66.
(16) A200CT (C-12D)	BP-1, BP-22, and BP-24 through BP-51.
(17) A200CT (C-12F)	BP-52 through BP-63.
(18) A200CT (FWC-12D)	BP-7 through BP-11.
(19) A200CT (RC-12D)	GR-1 through GR-12.
(20) A200CT (RC-12G)	FC-1 through FC-3.
(21) A200CT (RC-12H)	GR-14 through GR-19.
(22) A200CT (RC-12K)	FE-1 through FE-9.
(23) A200CT (RC-12P)	FE-25 through FE-31, FE-33, and FE-35.
(24) A200CT (RC-12Q)	FE-32, FE-34, and FE-36.
(25) B100	BE-1 through BE-137.
(26) 200 and B200	BB-2, BB-6 through BB-1313, BB-1315 through BB-1384, and BB-1389 through BB-1662.
(27) 200C and B200C	BL-1 through BL-72, and BL-124 through BL-140.
(28) B200C (C-12F)	BL-73 through BL-112, BL-118 through BL-123, and BP-64 through BP-71.
(29) B200C (C-12R)	BW-1 through BW-29.
(30) B200C (UC-12F)	BU-1 through BU-10.
(31) B200C (UC-12M)	BV-1 through BV-10.
(32) 200CT and B200CT	BN-1 through BN-4.
(33) 200T and B200T	BT-1 through BT-38, and BB-1314.
(34) 300	FA-1 through FA-230, and FF-1 through FF-19.
(35) B300	FL-1 through FL-252.
(36) B300C	FM-1 through FM-9, and FN-1.
(37) 2000	NC-4 through NC-53.

(b) *Who must comply with this AD?*
 Anyone who wishes to operate any of the airplanes identified in paragraph (a) of this AD must comply with this AD.

(c) *What problem does this AD address?*
 The actions specified by this AD are intended

to assure that clear and complete operating instructions are visible for opening the airstair door and emergency exits. If the operating instructions are not visible or understandable, this could result in the inability to open the airstair door or

emergency exits during an emergency situation.

(d) *What actions must I accomplish to address this problem?* To address this problem, you must accomplish the following:

Actions	Compliance	Procedures
Modify the exterior door operating procedures by incorporating the applicable kit as specified in the service bulletin.	Within the next 200 hours time-in-service (TIS) after March 7, 2003 (the effective date of this AD) or within the next 12 calendar months after the effective date of this AD, whichever occurs first.	In accordance with the applicable kit instructions as specified in the Accomplishment Instructions section in Raytheon Mandatory Service Bulletin SB 52-3096, Rev. 1, Revised: June, 2002. Use Paragraph (7) of the Accomplishment Instructions section in Raytheon Mandatory Service Bulletin SB 52-3096, Rev. 1, Revised: June, 2002, to accomplish this action on the Model 2000 airplanes.

(e) *Can I comply with this AD in any other way?* You may use an alternative method of compliance or adjust the compliance time if:

(1) Your alternative method of compliance provides an equivalent level of safety; and

(2) The Manager, Wichita Aircraft Certification Office (ACO), approves your alternative. Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Wichita ACO.

Note: This AD applies to each airplane identified in paragraph (a) of this AD, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of

compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(f) *Where can I get information about any already-approved alternative methods of compliance?* Contact Mr. Steven E. Potter, Aerospace Engineer, Wichita Aircraft Certification Office, FAA, 1801 Airport Road, Mid-Continent Airport, Wichita, Kansas 67209; telephone: (316) 946-4124; facsimile: (316) 946-4407.

(g) *What if I need to fly the airplane to another location to comply with this AD?* The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and

21.199) to operate your airplane to a location where you can accomplish the requirements of this AD.

(h) *Are any service bulletins incorporated into this AD by reference?* Actions required by this AD must be done in accordance with Raytheon Mandatory Service Bulletin SB 52-3096, Rev. 1, Revised: June, 2002, including Accomplishment Kit Nos. 101-4080-1, 101-4310-1, 101-4310-3, 90-4119-1, and 99-4032-1. The Director of the Federal Register approved this incorporation by reference under 5 U.S.C. 552(a) and 1 CFR part 51. You may get copies from Raytheon Aircraft Company, 9709 E. Central, Wichita, Kansas 67201-0085; telephone: (800) 429-5372 or (316) 676-3140. You may view copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri, or at the *Office of the Federal*

Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(i) *When does this amendment become effective?* This amendment becomes effective on March 7, 2003.

Issued in Kansas City, Missouri, on January 8, 2003.

Dorenda D. Baker,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-676 Filed 1-21-03; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 02-ASO-27]

Establishment of Class D Airspace; Shaw AFB, SC

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action establishes Class D airspace at Shaw AFB, SC. Shaw Radar Approach Control (RAPCON) is closed daily from 0330 UTC to 1100 UTC. Shaw AFB Airport Traffic Control Tower (ATCT) is open continuously. Therefore, when the RAPCON is closed Class D airspace must be established for the ATCT. Class D surface area airspace is required when the control tower is open to contain Standard Instrument Approach Procedures (SIAPs) and other Instrument Flight Rules (IFR) operations at the airport. This action establishes Class D airspace extending upward from the surface to and including 2,700 feet MSL within a 4.4-mile radius of the airport.

EFFECTIVE DATE: 0901 UTC, March 20, 2003.

FOR FURTHER INFORMATION CONTACT:

Walter R. Cochran, Manager, Airspace Branch, Air Traffic Division, Federal Aviation Administration, PO Box 20636, Atlanta, Georgia 30320; telephone (404) 305-5627.

SUPPLEMENTARY INFORMATION:

History

On December 2, 2002, the FAA proposed to amend Part 71 of the Federal Aviation Regulations (14 CFR Part 71) by establishing Class D airspace at Shaw AFB, SC, (67 FR 71507). Class D airspace designations for airspace areas extending upward from the surface of the earth are published in Paragraph 5000 of FAA Order 7400.9K, dated August 30, 2002, and effective September 16, 2002, which is

incorporated by reference in 14 CFR 71.1. The Class D airspace designations listed in this document will be published subsequently in the Order.

Interested parties were invited to participate in this rulemaking proceeding by submitting written comments on the proposal to the FAA. No comments objecting to the proposal were received.

The Rule

This amendment to Part 71 of the Federal Aviation Regulations (14 CFR part 71) establishes Class D airspace at Shaw AFB, SC.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation, as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS

1. The authority citation for 14 CFR part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g); 40103, 40113, 40120; EO 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389; 14 CFR 11.69.

§ 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9K, Airspace Designations and Reporting Points, dated August 30, 2002, and effective September 16, 2002, is amended as follows:

Paragraph 5000 Class D Airspace.

* * * * *

ASO SC D Shaw AFB, SC [New]

Shaw AFB, SC

(Lat. 33°58'23" N, long. 80°28'22" W)

That airspace extending upward from the surface to and including 2,700 feet MSL within a 4.4-mile radius of the Shaw AFB, excluding that airspace contained within Restricted Area R-6002 when it is in use. This Class D airspace area is effective during the specific days and times established in advance by a Notice to Airmen. The effective days and times will thereafter be continuously published in the Airport/Facility Directory.

* * * * *

Issued in College Park, GA, on January 7, 2003.

Walter R. Cochran,

Acting Manager, Air Traffic Division, Southern Region.

[FR Doc. 03-1315 Filed 1-21-03; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF LABOR

Pension and Welfare Benefits Administration

29 CFR Part 2575

RIN 1210-AA95

Final Rule Relating to Adjustment of Civil Monetary Penalties

AGENCY: Pension and Welfare Benefits Administration, Department of Labor.

ACTION: Final rule.

SUMMARY: This document contains a final rule that adjusts the civil monetary penalties under title I of the Employee Retirement Income Security Act of 1974, as amended (ERISA), pursuant to the requirements of the Federal Civil Penalties Inflation Adjustment Act of 1990 (1990 Act), as amended by the Debt Collection Improvement Act of 1996 (Act). The Act amended the 1990 Act to require generally the adjustment of civil monetary penalties for inflation no later than 180 days after the enactment of the Act, and at least once every four years thereafter, in accordance with the guidelines specified in the 1990 Act, as amended. The final rule affects employee benefit plans, plan administrators, plan sponsors, fiduciaries of employee benefit plans, plan participants and beneficiaries, and other persons subject to the civil monetary penalties under title I of ERISA.

DATES: This final rule is effective on March 24, 2003, and applies only to violations occurring after March 24, 2003.

FOR FURTHER INFORMATION CONTACT: Eric A. Raps, Office of Regulations and